From (Person	Sun Pin Assignment Ass	ENT (Office)	Date/Time: 23 %. 19
CSUIT HEULO	OSU	Bill to:	
To inspect V	ehicle No: SLJ 3318 V	In	sured: SDA 6000H Tel: 63974615
at Workshop	m/s JAS Auto Service alan Lom Huat Carnes Contra		Tel: 63974615
of 60 30	alan Lom Huat Carnes Contra	7 05-06/	-
Policy No:		Claim No: S9	mo247N
Sum Insured:		Excess:	
Make of Veh (Client's Recor			D.O.A. 12-10-2019
*	1400		
Date/Time:	KEI. / KEY 24 HRS	Gibson	H.O.D. Endorsement:Vehicle IN 1 BUT
Date/Time	Action/Instruction (X) Estimate	2	
	SLJ3318U-X		
	20A 6000H-X		
	Dismartle: 25/10/2019		
	23/10/2019		

ASSIGNMENT

Prem: Dale: 24.10.2011	Veh No: SLJ 33/84 Yr Regn: 31/May/2014.
Estimated Fost:	Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or
To Inspect Vehicle No: SLJ 3318 U	Make: BMW M6 4.4 AT c.c 4395
at Workshop m/s JAS Auto Services	Golour Blue. A/C: Insured / Std / NI / NA
of 60 Jalan Lam Huat Carres Centre \$105-06/0]	Sp.Reading 83498. T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: WBS6C92030PV74404
Claims No.	Gen. Cond: Good (Fail) / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil /S/Rim / STD A/Rim or
	Tyre Size: F: 265/35 ZR 20
(Policy Condition)	R: 265/35 ZR20
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA (MIC) OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent?: Yes or No	R/Bal. 5 mm R/Bal. 5 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 5 mm L/Bal. 5 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 12/10/2019 D.O.I. 24/10/2019 078
Lum Sum: % 3 Val.: Yes or No	Survey held at JAS Auto Services.
my	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
PRS Case.	
MV: 232,000.	Repair day - 3 days
	Repur Range - 2K-3K
	pura Je
	V 5/1)
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 3
; Final Report	Resurvey No. of Trip: Survey Fee: 100
Date/Time, File Return to?	Transportation:
2) Add Fe	e: : Site Insp (\$)S+RSSI
	: Interview (\$) Photos
Rep Formal: PRS	: Tech, Invs (\$) Others
Lump Sum / LP.E.Cs	: Weet end (S
	TOTAL 100





JAS Auto Sewias



Service Request Details

Claim

S9M0247N

Reference

None @

Loss Date

October 12, 2019

Report Date

Oct 18, 2019 12:00:00 AM

Request Date

October 23, 2019

Due Date

October 31, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLJ3318U

LKK AUTO CONSULTANTS PTE LTD (TP) -

Menu

Model M6 COUPE

, , ,

Service Address

Primary Contact/Insured

CHOO GIM SENG TONY
24 UPPER SERANGOON VIEW, #12-28 RIO VISTA, 534205, Singapore
96739730
TONYGSCHOO@SINGNET.COM.SG

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

New Message

DHIWAR Namrata

DID:6397 4615

From: Sent: To: Subject: Attachments:	Jas Auto <jasautoservices@gmail.com> Monday, October 21, 2019 10:34 AM SG AXA Insurance SM AXA SGP - Motor Survey [EXTERNAL] Pre Repair Inspection SLJ3318U(TP Claim) SDA6000H TP Insurer Enquiry.pdf; SLJ3318U NOA.pdf; SLJ3318U GIA Report.PDF</jasautoservices@gmail.com>
Categories:	Namrata
Dear Sir / Madam,	
We are filing a third party claim	n in behalf of our client with vehicle SLJ3318U against your insured SDA6000H. (Accident on 12/9/2019)
We would like to request your	good office to conduct a pre-repair inspection for our client's vehicle.
Enclosed are the following doct	uments for your perusal.
A) GIA Report	
B) TP Insurer E	Enquiry(SDA6000H)
Our client's vehicle will be @ 60	0 Jalan Lam Huat Carros Centre #05-06/07 Singapore 737869.
Thank you very much.	
Regards,	
Gibson Soh	
60 Jalan Lam Huat	
#05-06/07 Carros Centre	
Singapore 737869	



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 625

To: AXA Insurance Pte Ltd

11/11/2019

Survey details

Date of loss	12-Oct-19	
Date of appointment	23-Oct-19	
Date of survey	24-Oct-19	
Location of survey	JAS AUTO SERVICES	

Vehicle Details:

Claim Type:	Third Party			
Vehicle number	SLJ 3318U			
Make and Model	B.M.W. M6 4.4 AT ABS AIRBAGS 2WD 4DR			
Date of registration	31-May-14			
Excess				
Market Value	\$232,000			
Parf Rebate	\$185,168			
Nett Loss	\$46,832			

Repair details

Initial Estimate	
Proposed/Revised repair cost:	
Parts	
Check item	5
Labour	
Total	
Lump Sum(if applicable)	
Number of days of repair	3
Remarks:	The estimated repair cost of the damaged vehicle is in the region of \$2,000.00 - \$3,000.00

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	272D
Vehicle No.;	SLJ3318U
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2019
Vehicle Make:	B.M.W.
Vehicle Model:	M6 4.4 AT ABS AIRBAGS 2WD 4DR
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	20470766S63B44B
Chassis No.:	WBS6C92030DV74404
Maximum Power Output:	412.0 kW (552 bhp)
Open Market Value:	\$135,028.00
Original Registration Date:	31 May 2014 / 4413 6 mths / 54 mths
First Registration Date:	31 May 2014
Transfer Count:	2
Actual ARF Paid: Intended PARF Rebate Details	\$215,051.00 0 7,000
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 May 2024
PARF Rebate Amount:	\$150,535.00
Intended COE Rebate Details	
COE Expiry Date:	30 May 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$75,300.00
COE Rebate Amount:	\$34,633.00
Total Rebate Amount:	\$185,168.00

The information contained herein is correct as at 24 Oct 2019

28,000/12=2,333

2,3]] × 54 = 125,982

125,982+107,000 = 232,982

MV=232,982

OK

SGCARMART.COM

Login Sign up

New Cars

Sell My Car

Directory

Products

Insurance

Articles

Map

Forum

Resources

SELL YOUR CAR TODAY

List car till sold & let us handle the paperwork.



POST AN AD NOW!

BMW M Series M6 Gran Coupe

Price Range

▼ Depreciation ▼ Year Reg ▼ Vehicle Type

PREMILEM AD

Home » Used Cars » Munich Automobiles (2018) Pte Ltd » BMW M Series M6 Gran Coupe

BMW M Series M6 Gran Coupe

	Financial	Insurance	Accessories	Similar	Research	Photos	
Price	\$240,00	0					
Depreciation	\$30,360 Niew mod	/yr dels with similar dep	Reg Date		02-Oct-2014 (4yrs 10mths 24da	ys COE left)	
Mileage	99,500 ki	m (19.5k /yr)	Manufactu	ired	2013		
Road Tax	\$4,568 /	r	Transmiss	ion	Auto		
Dereg Value	\$164,045	as of today (chang	ge) OMV		\$116,791		
COE	\$74,403		ARF		\$182,224		
Engine Cap	4,395 cc		Power		412.0 kW (552 bhp))	
Curb Weight	1,875 kg		No. of Own	ners	1		

Features

Type of Vehicle

Sports Car

BMW's M Twin Turbo 4.4L V8 Producing An Overwhelming 552 Hp And 680 Nm Of Torque. 7 Speed M DCT Transmission With Drive Logic. 0 To 100Km/H In 4.3s. View specs of the BMW M Series M6 Gran Coupe (2013-

Accessories

Carbon Fibre Roof, Bluetooth/Aux/USB Input, 360 Parking Assistance Camera, Navigation, Soft Closing Doors, Electric Seats With Memory, 2 Remote Keys.

Description

BMW Management Unit! Beautiful 4 Door M6 Gran Coupe Which Strikes A Nice Balance Between Raw Power And Performance As Well As Accessibility For Day To Day Driving, Stunning Good Looks, Customizable Driving Options To Suit All Occasions. Luxurious Leather Interior With Carbon Fibre Trims. Call Now!

Category

PARF Car, Premium Ad Car

Status

Available

Resources



Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started

Posted on: 01-Nov-2019 | Last Updated on: 01-Nov-2019

Transf---

Dc compare

\$25

\$96,000 (change)

Maximum 60% Loan

















Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company	Munich Automobiles (2018) Pte
	Ltd
	 dealer's pricelist
	■ 1 vehs sold 4 vehs available
Address	30 Teban Gardens Crescent

Search cars nearby this location

Office No 68963933

Contact Marcus Chew Person(s)

Ryan Kan

83669826 84483773

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	\sim 1	n	- 1	-	ст			- 0	ш
AC	u	ы	- 1		31	ΑI	11/1	EΝ	

Date Of Report 16/10/2019 12:46

Date Of Accident 12/10/2019 18:40

Exact Location Of Accident CARPARK LOT AT RIO VISTA CONDO

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLJ3318U

Insured/Policyholder

Name Of Registered Owner ANG SOON BING KENNY

NRIC No S7529272D Email Address NOEMAIL

 Mobile Phone No
 (LOCAL) +65-96424445

 Alternative Phone No
 OTHERS-96424445

Vehicle Particulars

Manufacturer BMW

Model M6 COUPE

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 1800032312-01

Cover Note Number

Driver

Name of Driver GLORIA TAN SIOW TENG

 NRIC No
 \$7617210B

 Date Of Birth
 14/06/1976

 Occupation
 INDOOR

 Date Of Driving Pass
 08/06/2000

Driving Experience 19 YEARS AND 4 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-97996191

Fax Number

Contact Number

EMail Address GLORIAANG1515@HOTMAIL.COM

Address 8 JALAN MUTIARA #11-07

Postcode 249188

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLIDED INTO PARKED VEHICLE

NO

YES

NO

0

NO

NO

YES

NO

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident

ivolved in the accident

Was any body injured in the Accident?
Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

s (Including Driver)

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?

Was there any video captured by Car Camera? NO

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SDA6000H

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

16 OCT 2019

7019

12-46hrs

Driver's Signature (If driver is not 作者 和何如何)

Date & Time:

12 = 46 hrs

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No. 5 ... Kwee Choo S6840583A

GIARMC SketchPlanForm V3

Sketch Plan Pg. 2

SKETCH PLAN A-SLJ3318U B-SDA6000H

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 12 Oct 2019, Sat 6-40 pm, my car SLJ 3318U was parked at a parking lot at Rio Vista Condo. when I returned to my car at around 8 pm on the same day. I was shocked to see the
was parked at a parking lot at Rio Vista Condo.
when I returned to my car at around 8pm on
the same day. I was shocked to see the
damages on my car. The vehicle involved
was SDA 6000H. The driver, Stephane woo
damages on my car. The vehicle involved was SDA 6000H. The driver, Stephanie who has also admitted her mistake.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time: 1 6 OCT 2019

Driver's Signature 117 2019 (If driver is not the policyholder)

Date & Time:

Reportier Centre Personnel's Signature NRIC/FIN No.: Poh Kwee Choo S6840583A

GIARMC SketchPlanForm_V3

CERTIFICATE OF INSURANCE Pg. 1



CERTIFICATE OF INSURANCE

AUTOPLAN PRIVATE VEHICLE

Period of Insurance

Name of Policyholder : Ang Soon Bing Kenny

: 30 May 2019 To 29 May 2020

: 20470766S63B44B

Engine No. Chassis No. : WBS6C92030DV74404 Vehicle No.

: SLJ3318U

Policy No.

: 1800032312-01

Endorsement No.

Issued Date

: 29 May 2019

ABOUT THE COVER

Make/Model

: BMW M6 COUPE

Engine Capacity/Tonnage : 4,395.00 CC Driver Restriction

Sum Insured : Market Value : Named Driver Basis Off Peak Car : No

Insuring with COE/PARF : Yes

First Year of Registration : 2014

Person or Classes of Persons Entitled to Drive*:

Age Condition

Not Applicable

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for him or reveard, driving tail, noting test, racing, poce-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1 Fire - \$2500 Own Damage - \$2500 Theft - \$2500 Flood Cover - \$2500

Section 2 Property Damage - \$0

Windscreen: \$500

Named Driver and Excess (where applicable)

Gloria Tan Slow Teng - \$2500 (Fire) \$2500 (Own Damage) \$2500 (Theft). \$2500 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorised Repairers (For claims related repairs)

Any accident repairs to the Vehicle can be carried out at the repairer of Your choice (unless specifically excluded by Us).

For Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 5200. Alternatively, you may refer to AIG website even alig com. ag or AIG SG Mobile App. Simply search and download "AIG SG" from ITunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 169), Part IV of the Road Transport Act, 1987 (Melaysia) and Motor Vehicles (Third Party Risks) Ruses, 1959 (Melaysia)

0504080000

GAM PTE LTD

8 SHENTON WAY #13-03 AXA TOWER

SINGAPORE 068811

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.


AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

8 Sterage Way 907-16 AIG Building S079120 [T +65 6419 3000] w











LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6258 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

	PRE-REPAIR INSP	PECTION REPORT	
INSURANCE PTE	LTD	Ref: CS3/ASM19018878	/Qcf3e2
	-01 AXA TOWERSINGAPORE	Date: 13-11-2019	
N: RICHARD ANG	6	Code: ASM	
	Policy Particulars	- (THIRD PARTY CLAIM)	
Insured Veh.	SDA 6000H	Veh. Inspected	SLJ 3318U
Policy No.		Coverage (\$)	0.00
Claim No.	S9M0247N	Excess (\$)	0.00
Assign From	RICHARD ANG	Assign Date	23/10/2019
	Vehicle Parti	culars & Condition	
Make & Model	B.M.W. M6 4.4 AT	c.c	4395
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WBS6C92030DV74404	Colour	BLUE
Odometer	83498 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
	Condit	ions of Tyres	
	Size	Make	Balance
R/H Front Tyre	265/35Z R20	MICHELIN	5 mm
L/H Front Tyre	265/35Z R20	MICHELIN	5 mm
R/H Rear Tyre	265/35Z R20	MICHELIN	5 mm
L/H Rear Tyre	265/35Z R20	MICHELIN	5 mm
	Descripti	on of Damages	
THE VEHICLE SU	STAINED DAMAGES AT THE FRO	ONT O/S PORTION.	
	Genera	I Information	
Accident Date	12/10/2019	Inspect Date / Time	24/10/2019 (02:18 PM)
Survey held at	60 JALAN LAM HUAT #05-06/07		
Repairer	JAS AUTO SERVICES		
	R	emarks	
B) THE REPAIR E THE REPAIRER W C) ENCLOSED PL	STIMATE WAS NOT PRESENTED VAS TOLD TO PREPARE THE ES EASE FIND DAMAGED VEHICLE	O AT THE TIME OF INSPECT TIMATE. PHOTOGRAPHS.	ION.
	Fetimate	Days of Repair	MISSING PRINCIPLE BIVINGS
	Louinate	Days of Repair	
	Insured Veh. Policy No. Claim No. Assign From Make & Model Engine No. Chassis No. Odometer Brakes General R/H Front Tyre L/H Front Tyre L/H Rear Tyre L/H Rear Tyre L/H Rear Tyre THE VEHICLE SU. Accident Date Survey held at Repairer A) THE INSPECTION THE REPAIRE WE CON ENCLOSED PL	INSURANCE PTE LTD JENTON WAY #24-01 AXA TOWERSINGAPORE JIN : RICHARD ANG Policy Particulars Insured Veh. SDA 6000H Policy No. Claim No. S9M0247N Assign From RICHARD ANG Vehicle Particulars Make & Model B.M.W. M6 4.4 AT Engine No. HIDDEN Chassis No. WBS6C92030DV74404 Odometer 83498 KM Brakes IN ORDER General FAIR Condition Size R/H Front Tyre 265/35Z R20 L/H Front Tyre 265/35Z R20 L/H Rear Tyre 265/35Z R20 ACCIDENT SUSTAINED DAMAGES AT THE FROM General Accident Date 12/10/2019 Survey held at 60 JALAN LAM HUAT #05-06/07 Repairer JAS AUTO SERVICES R A) THE INSPECTION WAS CONDUCTED ON A "WIED THE REPAIRE ESTIMATE WAS NOT PRESENTED THE REPAIRE REPAIRE STIMATE WAS NOT PRESENTED THE REPAIRE REPAIRE WAS TOLD TO PREPARE THE ESC.) ENCLOSED PLEASE FIND DAMAGED VEHICLE	IENTON WAY #24-01 AXA TOWERSINGAPORE Date: 13-11-2019 Insured Veh. SDA 6000H Veh. Inspected Policy No. Coverage (\$) Claim No. S9M0247N Excess (\$) Assign From RICHARD ANG Assign Date

Report Ref No. CS3/ASM19018878/Qcf3e2

Inspected By

1

OI SUN PIN

L

K.K.LAU CPT(RET)

Asst. Automotive Assessor

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.