

22/03/2007

ASS. REC. BY:

REF: CS/FCJ 19018891/ E4f312

Special Instruction:

Surveyor

Steve

ASSIGNMENT (Office)

From (Person): Jason Tan chee kiat of FCI

Date/Time: 24.10.19 2.51p.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBE 73612

Insured: SH 7239 R

at Workshop m/s ASM Automotive

Tel: 92368218

of MD 13 Pioneer Sector 1

Policy No:

Claim No: D19006736MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A 21.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

sup

Jaclyn Lin

H.O.D. Endorsement:

Date/Time: 24.10.19 2.51p.m.

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBE 73612 - X

SH 7239 R - CS/FCJ 15017033/ Gbcel DOA - 03/10/2015

4/11/19 - Sent email preli advise via email

Survivor *Steve*

REF: *FCI*

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP.RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: *G0E 7361L*

Yr Regn: *15/3/16*

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *FIAT 00610*

c.c *1598*

Colour *Grey*

A/C: Insured / Std / NI / NA

Sp. Reading *183809*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

Ci/No: *2FA26309006078720*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD / A/Rim or

Tyre Size: F: _____

F: *205 160R16*

R: _____

R: *11*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *5*

mm

R/Bal. *5*

mm

L/Bal. *5*

mm

L/Bal. *5*

mm

D.O.A. *21/10/19*

D.O.I. *24/10/19*

Survey held at *ASM Automotive*

Des. of Damages: Frt / Rear O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*MV - 39K
 PV - 28 793
 NV - 19277*

24/10/19 Inform Jacyln repair limit 10K

20/11/19 Finalize Confir \$8850, 9 chys (Jacyln)

21/11- confirm - Lump Sum \$8850 (Red: 3270-531 26%)

RECEIVED 21 NOV 2019

Date/Time, File Pass to?

☐

: Proll. Report

21/11 Typist

☒

: Final Report

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Days Of Repair: *9*

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

)

TOTAL

2115: 30

1704 30

50

50

78

378

Report Format: *TP*

Lump Sum / I.B.I: (\$ *8850*)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006736MFSH

Date: 4/11/2019

Our Ref: CS/FCI19018891/ETf3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBE 7361L

Please be informed that we had conducted the inspection of the abovementioned vehicle
24/10/2019 at the premises of M/s ASM Automotive have the following to report: -

Workshop Estimate Amount	: S\$ <u>9,959.33</u>
Revised Estimate Amount	: S\$ <u>8,675.33</u>
"Check" Items Amount	: S\$ <u>00.00</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the
o/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully
Steve Chen
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	22-10-2019	Our Ref No. D19006736MFSH
Accident Date	21-10-2019	Claim Type. Third Party
Insured Vehicle	SH7239R	Third Party Vehicle. GBE7361L
Survey Location	NO 13 PIONEER SECTOR 1	
Contact Person.	JACLYN LAI	
Contact No.	6265 0026/ 92368218	Fax No. 6265 6068
Survey Type	DIRECT SETTLEMENT: EST. COR \$9959.33	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ASM AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JASON TEA CHEE KIAT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: ASM Jaclyn <jaclynlai@asmauto.com.sg>
Sent: Thursday, 21 November 2019 10:18 AM
To: Denise Tay (LKKAuto)
Cc: SUR; Steve Chen (LKK Auto); ASM Yandy
Subject: RE: GBE7361L Repair limit

Dear Denise,

COR confirmed.

Thank you.

Best Regards,
Jaclyn Lai
ASM Automotive Services Pte Ltd

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Thursday, 21 November 2019 10:01 AM
To: ASM Jaclyn
Cc: SUR; Steve Chen (LKK Auto)
Subject: RE: GBE7361L Repair limit

Dear Jaclyn,

Lump-sum \$8850/- (before GST) and repair days 9 days.

Please check and confirm.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ASM Jaclyn [mailto:jaclynlai@asmauto.com.sg]
Sent: Wednesday, November 20, 2019 3:57 PM
To: Steve Chen (LKK Auto)
Subject: RE: GBE7361L Repair limit

Dear Steve,

Kindly refer calculation below for the COR:

Spare parts (1 st Q)	:	\$	5,699.33
(+) Special nett item (1 st Q)	:	\$	126.00
		\$	5,825.33
(+) Labour charge (1 st Q)	:	\$	2,860.00
		\$	8,685.33
(+) Spare parts (2 nd Q)	:	\$	2,221.20

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 4 November 2019 2:33 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments; SUR
Cc: 'Jason Tea'
Subject: RE: SURVEY ASSESSMENT - D19006736MFSH/1
Attachments: PRELI ADVISED OF GBE 7361L.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **GBE 7361L**
Number of days (estimated) : 8 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Thursday, 24 October 2019 2:56 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006736MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Thursday, 24 October, 2019 2:51 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Jason Tea <JasonTea@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006736MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

sgCARMART CONNECT
SINGAPORE'S #1 CAR MARKET

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

License SS230C (COE 100 09/2029) View To Believe!



Drive Comfortable With Large
Foot Space (Veh Condition)
Powerful Engine
Direct Owner (Sole)

YONG LEE SENG MOTOR PTE LTD

- Free VECOM evaluation
- Free grooming and 6 months maintenance
- 24-hour workshop ensures quality service
- Member of SITA and his purchase association
- 100% deposit refund for unapproved loan

Browse by Category

8 vehicles

Fiat Doblo

Sort by Date Posted 20 results/page

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection Fiat Doblo	Any	Any	2016	Any	Any	Any	Available
 Fiat Doblo Cargo Maxi 1.6A	\$41,800	\$6,690 /yr	21-Jan-2016	1,598 cc	89,826 km	Van	Available
Fuel Type: Diesel Cheapest In The Market, For Personal Usage Only, No Cargos Etc. Hence The Car Looks And Drive Like New. No Scratches Etc. Condition Is Like Brand New. There's No Motoring Posted: 16-Oct-2019 Tags: 2016 Fiat Doblo, 2016 Fiat Doblo, Fiat Doblo, Fiat Doblo, Fiat Doblo, Fiat Doblo, Used Fiat							
 Fiat Doblo Cargo Maxi 1.6A	\$37,680	\$6,040 /yr	01-Feb-2016	1,598 cc	31,099 km	Van	Available
Fuel Type: Diesel 3 Free Servicing And 1.5 Years Of Warranty Left! Management Car For Director Only, Seldom Used. Very Low Mileage. Comes With 2 Rear Benches For Comfortable Seating Arrangements. Serviced Regularly. Excellent For Many Uses Like Start Up, Delivery, And More. Posted: 16-Sep-2019 Tags: 2016 Fiat Doblo, 2016 Fiat Doblo, Fiat Doblo, Fiat Doblo, Fiat Doblo, Fiat Doblo, Used Fiat							
 Fiat Doblo Cargo Maxi 1.6A	\$39,800	\$6,070 /yr	16-May-2016	1,598 cc	-	Van	Available
Fuel Type: Diesel Powerful And Fuel Efficient! Ideal Van For Small Start-up Businesses! Genuine Low Mileage! Previous Lady Owner Selling Due To Upgrade! Condition 10/10! Competitive Insurance Quotations! High Loan/Trade-in Available! Viewing Strictly Via Appointments Only! Call... Posted: 13-Sep-2019 Tags: 2016 Fiat Doblo, 2016 Fiat Doblo, Fiat Doblo, Fiat Doblo, Fiat Doblo, Fiat Doblo, Used Fiat							
 Fiat Doblo Cargo Maxi 1.6A	\$44,200	\$6,610 /yr	30-Jun-2016	1,598 cc	43,900 km	Van	Available
Fuel Type: Diesel Under Warranty And Free Servicing Till 2021 By Agent. Accident Free. No Dents, Original Paint Work. Very Low Mileage. No Additional Drivers, Only Driven By Myself For Personal Usage. In Very New Condition. All Genuine Mileage And Servicing Records Can Be Verified B... Posted: 29-Sep-2019 Tags: 2016 Fiat Doblo, 2016 Fiat Doblo, Fiat Doblo, Fiat Doblo, Fiat Doblo, Fiat Doblo, Used Fiat							
 Fiat Doblo to be sold in the US as Ram							
Fiat will market its Doblo van under the Ram badge in the US and Canada, as part of the alliance agreement between Fiat and Chrysler Read this article							
 Fiat Doblo Cargo Maxi 1.6A	\$39,800	\$5,840 /yr	17-Aug-2016	1,598 cc	76,000 km	Van	Available
Fuel Type: Diesel Full Agent Maintained Unit! Servicing Done There Since Day 1. Condition Look Like New Vehicle! Flexible Bank/In House Loan Available. Call Now. Posted: 22-Oct-2019 Tags: 2016 Fiat Doblo, 2016 Fiat Doblo, Fiat Doblo, Fiat Doblo, Fiat Doblo, Fiat Doblo, Used Fiat							
 Fiat Doblo Cargo Maxi 1.6M	\$39,800	\$5,770 /yr	16-Sep-2016	1,598 cc	-	Van	Available
Fuel Type: Diesel 1 Owner Only, Fully Agent Servicing & Maintained, Spacious Long Wheel Base Van, Come With In-build GPS Screen, Powerful Yet Fuel Efficient. Call Us Now To View. SG Motor Link Pte Ltd Posted: 18-Oct-2019 Tags: 2016 Fiat Doblo, 2016 Fiat Doblo, Fiat Doblo, Fiat Doblo, Fiat Doblo, Fiat Doblo, Used Fiat							
 Fiat Doblo Cargo Maxi 1.6A	\$46,888	\$6,710 /yr	17-Oct-2016	1,598 cc	28,000 km	Van	Available
Fuel Type: Diesel Service And Warranty By Agent Motorvive Pte Ltd. Posted: 24-Aug-2019 Tags: 2016 Fiat Doblo, 2016 Fiat Doblo, Fiat Doblo, Fiat Doblo, Fiat Doblo, Fiat Doblo, Used Fiat							
 Fiat Doblo Cargo Maxi 1.6A	\$44,800	\$6,410 /yr	20-Oct-2016	1,598 cc	-	Van	Available
Fuel Type: Diesel Auto Geartrain, Full Agent Maintained Unit! Still Under Agent Warranty! Call Us Now! Yes Motoring Posted: 16-Sep-2019 Tags: 2016 Fiat Doblo, 2016 Fiat Doblo, Fiat Doblo, Fiat Doblo, Fiat Doblo, Fiat Doblo, Used Fiat							

Save this search criteria, to get email alerts whenever a match is found.

Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BWM. There are plenty of cars for sale, from vans, trucks, utility cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, 10 COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Fiat Doblo, Fiat Doblo Singapore, used Fiat Doblo Singapore, used Fiat Doblo, Used vehicles Singapore or even they used Fiat Doblo Singapore. We have now car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, move, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that the information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	464R
Vehicle Details	
Vehicle No.:	GBE7361L
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2019
Vehicle Make:	FIAT
Vehicle Model:	DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	263A50007472806
Chassis No.:	ZFA26300006B78720
Maximum Power Output:	-
Open Market Value:	\$19,326.00
Original Registration Date:	15 Mar 2016
First Registration Date:	15 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$967.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Mar 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$45,001.00
COE Rebate Amount:	\$28,723.00
Total Rebate Amount:	\$28,723.00

The information contained herein is correct as at 24 Oct 2019

OK

ASM Automotive Services Pte Ltd



Unit 13 Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Reg. No.: 201203813C



FROM: Jaclyn Lai
TEL. NO: 6265-0026 / 9236-8218
EMAIL: jacynlai@asmauto.com.sg

DATE : 23.10.2019

VEHICLE NO. : GBE 7361 L
MODEL NO. : FIAT DOBLO CARGO MAXI 1.6
CHASSIS NO. : ZFA26300006B78720
ENGINE NO. : 263A50007472806
LTA REG DATE : 15/3/2016

TO : MS First Capital Insurance Ltd
ATTN : Motor Claim Department
TEL. NO. : 6507-3848
EMAIL : motor_claims@first-insurance.com.sg

CLAIM TYPE : Third Party - SH 7239 R
D.O.A : 21.10.2019
CLAIM REF NO. : asm/AC19097/JL

CC : Rejoice Container Services (Pte) Ltd

Quotation for Accident Repair

S/N	SPARE PARTS	QUANTITY	UNIT PRICE	AMOUNT
1	Front fender, RH / DD	1	\$ 245.02	\$ 245.02
2	Front mudguard protection, RH / CR4	1	\$ 145.89	\$ 145.89
3	Front wheel rim cover, RH / CUT	1	\$ 86.34	\$ 86.34
4	Front door, RH / DD	1	\$ 1,239.32	\$ 1,239.32
5	Front door outer moulding, RH / CUT	1	\$ 179.21	\$ 179.21
6	Sliding door, RH / DD	1	\$ 2,060.00	\$ 2,060.00
7	Sliding door outer moulding, RH / CUT	1	\$ 120.94	\$ 120.94
8	Sliding door bottom track, RH / BT	1	\$ 157.70	\$ 157.70
9	Rear mudguard, RH / DD	1	\$ 525.42	\$ 525.42
10	Rear bumper / CR4	1	\$ 542.50	\$ 542.50
11	Rear wheel rim 16", RH / BT	1	\$ 310.65	\$ 310.65
12	Rear wheel rim cover, RH / RR	1	\$ 86.34	\$ 86.34

SUB-TOTAL : \$ 5,699.33

S/N	SPARE PARTS (SPECIAL NETT ITEMS)	QUANTITY	UNIT PRICE	AMOUNT
1	Front wheel 205/60R x 16, RH X NM	1	\$ 180.00	\$ 180.00
2	Rear wheel 205/60R x 16, RH / (70%) TM	1	\$ 180.00	\$ 180.00

S/N ITEMS TOTAL : \$ 360.00

TOTAL PARTS : \$ 6,059.33

LABOUR CHARGES

1	To remove and replace damaged parts, realignment both doors etc. (\$350 x 7 days)	\$ 2,450.00	1500
2	Spray painting	\$ 1,200.00	
3	Towing fee	\$ 100.00	
4	Check and adjust 4 wheels alignment	\$ 150.00	60

TOTAL LABOUR : \$ 3,900.00

GRAND TOTAL : \$ 9,959.33

Total - 8685.33

L/S - 6948.26



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C



FROM : Jaclyn Lai
TEL. NO. : 6265-0026 / 9236-8218
EMAIL : jaclynlai@asmauto.com.sg

DATE : 08.11.2019

TO : MS First Capital Insurance Ltd
ATTN : Motor Claim Department
TEL. NO. : 6507-3848
EMAIL : motor_claims@first-insurance.com.sg

VEHICLE NO. : GBE 7361 L
MODEL NO. : FIAT DOBLO CARGO MAXI 1.6
CHASSIS NO. : ZFA26300006B78720
ENGINE NO. : 263A50007472806
LTA REG DATE : 15/3/2016

CC : Rejoice Container Services (Pte) Ltd

CLAIM TYPE : Third Party - SH 7239 R
D.O.A : 21.10.2019
CLAIM REF NO. : asm/AC19097/JL

Steve (LKK) 8/11/19

Quotation for Accident Repair - SUPPLEMENTARY

S/N	SPARE PARTS	QUANTITY	UNIT PRICE	AMOUNT
1	Headlamp, RH <i>DR</i>	1	\$ 747.18	\$ 747.18
2	Steering rack assy <i>BT</i>	1	\$ 1,474.02	\$ 1,474.02
SUB-TOTAL :				\$ 2,221.20

S/N	SPARE PARTS (SPECIAL NETT ITEMS)	QUANTITY	UNIT PRICE	AMOUNT
1	Steering oil (per Litre) <i>ACC</i>	2	\$ 10.00	\$ 20.00
S/N ITEMS TOTAL :				\$ 20.00

TOTAL PARTS : \$ 2,241.20

LABOUR CHARGES

1 Dismantle front 2 wheels to remove and replace steering rack assy. \$ 280.00 *150*

TOTAL LABOUR : \$ 280.00

GRAND TOTAL : \$ 2,521.20

Total - 2391.20

L/S - 1921.96

12/20.63



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19018891/Elf3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 25-11-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7239R	Veh. Inspected	GBE 7361L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006736MFSH	Excess (\$)	0.00	
Assign From	JASON TEA CHEE KIAT	Assign Date	24/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	FIAT DOBLO	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZFA26300006B78720	Colour	GREY	
Odometer	183809	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	BRIDGESTONE	5 mm	
L/H Front Tyre	205/60 R16	BRIDGESTONE	5 mm	
R/H Rear Tyre	205/60 R16	BRIDGESTONE	5 mm	
L/H Rear Tyre	205/60 R16	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/10/2019	Inspection Date	24/10/2019	
Survey held at	ASM AUTOMOTIVE SERVICES PTE LTD 13 PIONEER SECTOR 1 SINGAPORE 628424			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 7361L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER,RH (SN)	DENTED	245.02	245.02
1	FRONT MUDGUARD PROTECTION,RH (SN)	CRUSHED	145.89	145.89
1	FRONT WHEEL RIM COVER,RH (SN)	CUT	86.34	86.34
1	FRONT DOOR,RH (SN)	DENTED	1,239.32	1,239.32
1	FRONT DOOR OUTER MOULDING,RH (SN)	CUT	179.21	179.21
1	SLIDING DOOR,RH (SN)	DENTED	2,060.00	2,060.00
1	SLIDING DOOR OUTER MOULDING,RH (SN)	CUT	120.94	120.94
1	SLIDING DOOR BOTTOM TRACK,RH (SN)	BENT	157.70	157.70
1	REAR MUDGUARD,RH (SN)	DENTED	525.42	525.42
1	REAR BUMPER (SN)	CRUSHED	542.50	542.50
1	REAR WHEEL RIM 16" RH (SN)	BENT	310.65	310.65
1	REAR WHEEL RIM COVER,RH (SN)	BROKEN	86.34	86.34
1	HEADLAMP,RH (ADDITIONAL) (SN)	BROKEN	747.18	747.18
1	STEERING RACK ASSY (ADDITIONAL) (SN)	BENT	1,474.02	1,474.02
1	FRONT WHEEL 205/60RX16,RH (SN)	NOT NECESSARY	180.00	-
1	REAR WHEEL 205/60RX16,RH (70%)(SN)	TORN	180.00	126.00
2	STEERING OIL (PER LITRE) @\$10.00 (ADDITIONAL)(SN)	NECESSARY	20.00	20.00
			8,300.53	8,066.53
LABOUR				
TO REMOVE AND REPLACE DAMAGED PARTS,REALIGNMENT BOTH DOORS ETC.			2,450.00	1,500.00
SPRAY PAINTING.			1,200.00	1,200.00
TOWING FEE.			100.00	100.00
CHECK AND ADJUST 4 WHEELS ALIGNMENT.			150.00	60.00
DISMANTLE FRONT 2 WHEELS TO REMOVE AND REPLACE STEERING RACK ASSY.(ADDITIONAL).			280.00	150.00
			4,180.00	3,010.00
GRAND TOTAL			12,480.53	11,076.53
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,850.00

Report Ref No. CS/FCI19018891/Etf3n2



Report Ref No. CS/FCI19018891/Etf3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.