

22/07/2002

ASS. REC. BY:

REF: CS/CT1 19018911 / Q4 f302

Special Instruction:

Supervisor: Sun Pin

ASSIGNMENT (Office)

From (Person):

Tan Kah Loong

of

CT1

Date/Time:

24.10.19 16.43pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

CB 7831B

Insured:

XE 2744M

at Workshop m/s

Connect 3

Tel:

98509666

of

566 wawaland Road

Policy No:

DMCRSN19075819011

Claim No:

SNM190705032002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24.10.19

CA / REV / REP. / REV 24 HRS

mp?

25.10.2019

H.O.D. Endorsement:

Date/Time:

25.10.19 4.59pm

Person Contacted:

Winnie

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

CB 7831B - X

XE 2744M - X

L/S = 7,100

Repair days - 6 days. (Red: 60/51 45%)

Confirm with winnie.

ASS. REC. BY Sun Pm

REF: CTE

ASSIGNMENT

From

Date:

25/10/2019

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

CB7831 B

at Workshop m/s

Connect 3

of

566 woodland Road

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

10am (sharp) waiting

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

CB7831 B

Yr Regn:

16/dec/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Golden DRAGON

c.c 3759.

Colour

Multicolour

A/C:

Insured / Std / NI / NA

Sp. Reading

90784

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

LL313DADE9G/A001069

Gen. Cond: Good Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or Steel Rim

Tyre Size:

F:

215/75 R17-5

R:

215/75 R17.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Triangle

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A. 24/10/2019

D.O.I.

25/10/2019

Survey held at

Connect 3.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Sun Pm,

Pls see my remarks.

MV:

RECEIVED 15 OCT 2019

Date/Time, File Pass to?

1) 14/11 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B. #

7100/-



Prel. Report



Final Report

Days Of Repair:

6

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Week-end (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Oct 2019		24 Oct 2019 16:43 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

Main Claimant: **HONG YUN BUS SERVICES PTE LTD**

Vehicle Reg. No.: **CB7831B** Date of Loss: 24/10/2019 07:00 - :59

Claim Type: **TP / SNM19D205032C02** Policy/Cover Note No.: DMCVSN18075819011

Vehicle Reg. No. (Insured): **XE2744M** Policy No. (Claimant):

Excess: S\$0.00

Repairer: **Connect3 (HQ) 566 Woodlands Road, 728697 Woodlands - Tel: 98509666**

Handling Insurer: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]**

Adjuster: **LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/11/2019]**

Adj Asg. Remarks: PLEASE SURVEY AND REVERT

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Oi Sun Pin (LKK Auto)

From: Winnie Chai <connect3winnie@gmail.com>
Sent: Saturday, 9 November, 2019 9:07 AM
To: Oi Sun Pin (LKK Auto)
Cc: Denise Tay (LKKAuto)
Subject: Re: Finalization for CB7831B

Yes, please proceed.

On Fri, Nov 8, 2019 at 6:07 PM Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com> wrote:

Dear Winnie,

Good day, please refer our finalize adjustment estimate update. L/S amount COR \$ 7100, DOR 6 DAYS. (Lump sum repair, before gst).

Please refer the adjustment the amount and repair day, if agree please update ASAP. THANK YOU.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Winnie Chai [mailto:connect3winnie@gmail.com]
Sent: Friday, 8 November, 2019 5:22 PM
To: Oi Sun Pin (LKK Auto); Admin-D (LKKAuto)
Subject: 2ND Reminder - Finalization for CB7831B

Hi Sunpin

Pls kindly revert on the finalization.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	457Z
Vehicle Details	
Vehicle No.:	CB7831B
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Oct 2019
Vehicle Make:	GOLDEN DRAGON
Vehicle Model:	XML6772J18 AUTO
Primary Colour:	Multicolor
Manufacturing Year:	2016
Engine No.:	ISF385516889832136
Chassis No.:	LL3BDADE9GA001069
Maximum Power Output:	-
Open Market Value:	\$69,254.00
Original Registration Date:	16 Dec 2016 ✓
First Registration Date:	16 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$3,463.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 25 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/10/2019 11:12
Date Of Accident	24/10/2019 07:30
Exact Location Of Accident	BEDOK NORTH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	CB7831B
Insured/Policyholder	
Name Of Registered Owner	HONG YUN BUS SERVICES PTE LTD
Co Reg No	201433457Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98315851

Vehicle Particulars

Manufacturer	GOLDEN DRAGON
Model	XML6772J18

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTSCBU000778
Cover Note Number	

Driver

Name of Driver	BOON TAM PENG
NRIC No	S2010482A
Date Of Birth	02/02/1954
Occupation	OUTDOOR
Date Of Driving Pass	13/03/1988
Driving Experience	31 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81138378
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 346 ANG MO KIO AVENUE 3 #05-2274 S(550346)
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE2744M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed.
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 24/10/19 around 07:30hrs I was driving my bus CS 78318,
along Bedok North Rd. Vph B XF 2744M collided onto my rear portion

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time



Driver's Signature _____

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/TIN No.:

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

QT19/CB7831B/TPC-587

QUOTATION

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

Dear Sir

Cost of Repair to Vehicle CB7831B

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$\$)	AMOUNT (\$\$)	
1.	Rear windscreen / CRA	1	2,950.00	2,950.00	2,600
2.	Rear windscreen moulding / Nec.	1	550.00	550.00	400
3.	Rear bumper / dd	1	1,650.00	1,650.00	/
4.	Rear tailgate / dd	1	2,800.00	2,800.00	1574
5.	Rear tailgate outer handle / SCR	1	350.00	350.00	200
6.	RH taillamp / CRA	1	1,050.00	1,050.00	750
7.	XML6772J18 emblem X NN	1	180.00	180.00	
8.	Logo emblem X NN	1	195.00	195.00	
9.	A.W.C ROV sticker / Nec	1	15.00	15.00	/
10.	60KM/H sticker / Nec	1	15.00	15.00	/
11.	Children crossing sign / SCR	1	380.00	380.00	150
12.	Rear RH passenger seat upholstery / BCF	1	180.00	180.00	/
13.	Sealant / Nec.	4	40.00	160.00	/
14.	Labour to remove & refit rear windscreen / Nec	1	400.00	400.00	300
15.	Check wiring / Nec.	1	40.00	40.00	/

16.	Labour charges	1	1,200.00	1,200.00
17.	Spray painting	1	1,000.00	1,000.00
	SUB-TOTAL			S\$13,115.00

800



800

- Price before 7% gst

1 days - 300

Repair day - 6 days.

Thank you
Yours faithfully,

Winnie Chai
HP: 9850-9666

Sun Pm

Lump Sum Repair

After paint photo.

25/10/2011 @ 10.20pm.

TP without Prejudice.

$$P = 7,534$$

$$-10\% = 6780.6$$

$$L = 2,100$$

$$8,880.6$$

$$-20\%$$

$$7,104.48$$

$$L/S = 7,100$$

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Oct 2019		24 Oct 2019 16:43 Edit Adj Rpt	S\$7,100.00 Edit Estimates	S\$7,100.00 View Rpt		Pending for Survey Report Cancel Case











































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: HONG YUN BUS SERVICES PTE LTD									
Vehicle Reg. No.: CB7831B		Date of Loss: 24/10/2019 07:00 - :59 [34 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D205032C02		Policy/Cover Note No.: DMCVSN18075819011							
Vehicle Reg. No. (Insured): XE2744M		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Connect3 (HQ) 566 Woodlands Road, 728697 Woodlands - Tel: 98509666									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Final Rpt due 05/11/2019]									
Adj Asg. Remarks: PLEASE SURVEY AND REVERT									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*CB7831B (SNM19D205032C02)
[XE2744M]
TP
HONG YUN BUS SERVICES PTE LTD
Oct 24 2019 7:00AM
[-]
Connect3

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Photos/Images			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
2	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
3	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
6	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
7	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
13	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
14	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
15	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
16	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
17	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
18	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
19	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
20	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
21	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
22	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
23	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
24	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
25	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
26	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
27	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
28	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
29	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
30	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
31	25/10/19 17:02	General View	 Load JPG	<input checked="" type="checkbox"/>
32	25/10/19 17:02	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
33	25/10/19 17:02	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
34	14/11/19 11:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
35	14/11/19 11:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
36	14/11/19 11:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
37	14/11/19 11:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
38	14/11/19 11:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
39	14/11/19 11:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
40	14/11/19 11:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
41	14/11/19 11:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
42	14/11/19 11:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19018911/QTF3E2

Date: 18/11/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN18075819011

Claimant
Vehicle No : CB7831BInsured
Vehicle No : XE2744M

Date of Loss: 24/10/2019

Nature of Claim: TP

Claim
No: SNM19D205032C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: CB7831B

Make & Model: GOLDEN DRAGON XML6772J18, 3.8 D (M)

Engine No: ISF38S516889832136

Reg. Date: 16/12/2016 (Man. Year: 2016)

Chassis No: LL3BDADE9GA001069

Colour: Multi-colour

Odometer: 90784 km

Engine Capacity: 3759 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/75 R17.5	Rear Tyre Size:	215/75 R17.5
Front Left Side:	Triangle 5 mm	Rear Left Side:	Triangle 5 mm
Front Right Side:	Triangle 5 mm	Rear Right Side:	Triangle 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,475.00	6,940.60	3,534.40	33.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,640.00	1,940.00	700.00	26.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,115.00	8,880.60	4,234.40	32.29
Approved Total (Overridden) (S\$)		7,100.00		
(S\$)	13,115.00	7,100.00	6,015.00	45.86
+ GST 7.00/7.00% (S\$)	918.05	497.00	421.05	45.86
Nett Amount (S\$)	14,033.05	7,597.00	6,436.05	45.86

INSPECTION

Date of Assignment: 24/10/2019

Date Inspected: 25/10/2019

Inspected At:

Connect3 (HQ)
566 Woodlands Road
Singapore 728697

Estimated Period of Repair: 6.0 days

Adjuster: OI SUN PIN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 18 Nov 2019)	
Parts:	N/A	GOLDEN DRAGON XML6772J18 3.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for CB7831B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Cracked	2,950.00 F	*2,600.00 FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	550.00 F	*400.00 FL
3	1		*REAR BUMPER	Dented	1,650.00 F	*1,650.00 FL
4	1		*REAR TAILGATE	Dented	2,800.00 F	*1,574.00 FL
5	1		*REAR TAILGATE OUTER HANDLE	Scratched	350.00 F	*200.00 FL
6	1		*RH TAILLAMP	Cracked	1,050.00 F	*750.00 FL
7	1		*XML6772J18 EMBLEM	Not Necessary	180.00 F	*- FL
8	1		*LOGO EMBLEM	Not Necessary	195.00 F	*- FL
9	1		*A.W.C ROV STICKER	Necessary	15.00 F	*15.00 FL
10	1		*60KM/H STICKER	Necessary	15.00 F	*15.00 FL
11	1		*CHILDREN CROSSING SIGN	Scratched	380.00 F	*150.00 FL
12	1		*REAR RH PASSENGER SEAT UPHOLSTERY	Cut	180.00 F	*180.00 FL
13	4		*SEALANT	Necessary	160.00 FS	*160.00 FS
					Sub Total (S\$)	10,475.00
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00
					Total Parts (S\$)	10,475.00
						6,940.60

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT REAR WINDSCREEN	New	400.00	300.00
2	CHECK WIRING	New	40.00	40.00
3	LABOUR CHARGES	New	1,200.00	800.00
4	SPRAY PAINTING	New	1,000.00	800.00
Gross Labour Cost (\$\$)			2,640.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >