

INS. CASE OWNER:

Surveyor:

ADRIAN

DOI: 13/11/2019

Date / Time: 23/10/2019

Registered in Merimen:

Pre-assign / CCU / FTE:



Insured Vehicle No. : SGR 2228U
 Name of Insured : TEO KUAN BING
 Insured Tel No. : HP: +65-93686328
 Excess Sec II :SS D.O.A: 16/10/2019

Claim No. : 19/19/19/VP00/022556
 Policy No. : Z/19/VP00/102980
 Make / Model : TOYOTA CAMRY
 Place of Accident : 27 MOULMEIN RISE SHOW FLAT CARPARK

Is driver the owner? (YES / NO) Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SLU 9630U



INSRS:
WSP: CHNG BROTHERS
Tel:
Liability:
RMKS: 11706 (31-12-2019) (31/12)



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
SLU 9630U	Non-Reporting hr (1st):	
SGR 2228U	Non-Reporting hr (2nd):	
NA/AIG19018343/h4; DOA: 16.10.2019	Non-Reporting hr (Final):	
- CC6/AXA11014665/Uq1dc1; DOA: 23.7.11	Notification hr (if non-pickup):	
21.11.19	Call Ot:	
	After call hr to Ot:	
20.12.20	Documentation Check List:	Handler Typist
SLU 9630U	Notification hr (if non-pickup)	
SGR 2228U	After call hr to Ot:	
NA/AIG19018343/h4; DOA: 16.10.2019	Authorisation To Act:	
- CC6/AXA11014665/Uq1dc1; DOA: 23.7.11	Release Voucher:	
21.11.19	Final Repair Bill:	
	Car Rental Invoice:	
20.12.20	Towing Invoice:	
	LTA / GIA :	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	S\$	(days) Reduction: %
FINAL SETTLEMENT	Date/Time:	Confirm with:
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : 23
Repair Cost:	S\$	On hr TP PROCEED YEN.
Loss of Rental (LOR):	S\$	(days)
Loss of Use (LOU):	S\$	(\$ a days)
Loss of Income (LOI):	S\$	(\$ a days)
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>		[Tick only one]
GIA/LTA Search	S\$	
Medical:	S\$	
Disbursement:	S\$	(e.g. Tow/ Independent)
Legal Cost	S\$	
Total:	S\$	Global Sum S\$:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	S\$	Name 1:
Payee 2: (Strike if N.A.)	S\$	Name 2:
Payee 3: (Strike if N.A.)	S\$	Name 3:

ASS. REC. BY

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SL496304 Yr Regn: 2017 / DecType: M.Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Cerato K3 cc 1591Colour: White A/C: Insured / Std / NI / NASp. Reading: 36222 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAF 2411 MJ 5756173Gen. Cond: Good Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/45R17R: 215/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Nexen

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 13/11/19Survey held at Chng BrothersDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Con Pac

4s: 2600 (USD: 23,067.60 54%)

MV:

PV:

Nett:

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

3)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : Witness (\$

Survey Fee:

Transportation:

S - RS - SI

Photos

Notes

TOTAL

Report Format: _____

Lump Sum / LBJ: (\$

CHNG BROTHERS MOTOR SERVICES

2 Kaki Bukit Avenue 2, #02-32 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67470407 Fax: +65 67426933

E-mail: info@chngbrothers.com

QUOTATION

AIG ASIA PACIFIC INSURANCE PTE. LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Attn: Motor Claims Department

Tel: +65 64193000 Fax:

Your Ref. SGR2228U
Vehicle No. : SLU9630U
Make & model : KIA K3
Chasis No. KNAFZ411MJ5756173
Engine No. G4FGHH688280
Accident Date 16/10/2019
Policy No. 1700089260
Date 13/11/2019
Page : 1 of 2

Thank you for your inquiry. We are pleased to submit

Item	Description	Qty	U/Price S\$	Amount S\$
1	REAR BUMPER <i>del</i>	1.0 PCS	738.00	738.00 ✓
2	REAR BUMPER REINFORCEMENT <i>del</i>	1.0 PCS	344.00	344.00 ✓
3	REAR BUMPER LIP <i>del</i>	1.0 PCS	375.00	375.00 ✓
4	BUMPER BRACKET (R/H) <i>del</i>	1.0 PCS	88.00	88.00 ✓
5	REAR BUMPER CLIP <i>m</i>	1.0 PCS	5.00	5.00 ✓
6	REAR BUMPER REFLECTOR (R/H) <i>del</i>	1.0 PCS	109.00	109.00 ✓
7	BUMPER CLIP <i>m</i>	10 PCS	5.00	50.00 <i>30</i>
8	BUMPER SIDE RETAINER (L/H/R) <i>3m</i>	1.0 PCS	43.00	43.00 ✓
9	BUMPER SIDE RETAINER (R/H/R) <i>2060</i>	1.0 PCS	43.00	43.00 ✓
10	LAMP (R/H/R) <i>new</i>	1.0 PCS	588.00	588.00 ✓
11	REVERSE SENSOR <i>del</i>	2.0 PCS	197.00	394.00 ✓
12	SENSOR (KEY) <i>new</i>	1.0 PCS	295.00	295.00 ✓
13	DISCOUNT <i>20% 10%</i>			-614.40
14	Subtotal (L)			2,457.60
15	REAR END SEALANT <i>new</i>	1 BTL	50.00	50.00 ✓
16	REAR BUMPER LIP <i>del</i>	1.0 PCS	800.00	800.00 <i>500</i>
17	SPEAKER <i>new</i>	1.0 PCS	500.00	500.00 ✓
18	Subtotal (S)			1,350.00
19	TO PROVIDE UBDER TURFCODE	1.0 X		120.00 ✓
20	TO CHECK WIRING SYSTEM, FOCUS LIGHTHING	1.0 X		50.00 <i>20</i> ✓
21	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	1.0 X		60.00 <i>30</i>
22	TO REMOVE REVERSE SENSOR	1.0 X		80.00 <i>50</i>

CHNG BROTHERS MOTOR SERVICES

2 Kaki Bukit Avenue 2, #02-32 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67470407 Fax: +65 67426933

E-mail: info@chngbrothers.com

QUOTATION

NTUC INCOME INSURANCE COOPERATIVE LIMITED
75 BRAS BASAH ROAD
NTUC INCOME CENTRE
SINGAPORE 189557

Attn: Motor Claims Department
Tel: +65 63462663 Fax: +65 63381500

Your Ref. SKR1969Z
Vehicle No. : SMP1886R
Make & model : HONDA FIT
Chasis No. GK3-3414673
Engine No. DBA-GK3
Accident Date 21-09-2019
Policy No. SD19V11634/VPL/R00
Date 02/10/2019
Page : 2 of 2

Thank you for your inquiry. We are pleased to submit

Item	Description	Qty	U/Price S\$	Amount S\$
23	PANEL BEATING & REPLACING OF THE ABOVE	1.0 X		800.00
24	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0 X	780	750.00
25	Subtotal (LABOUR)			1860.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and
is subject to final approval from insurance Company

Acknowledged by Rep:
Signature:
Date:

Adrian Ling
H/c 13/10/19.
0402
Total: 3334
h/s: 2-6K ✓

SINGAPORE DOLLAR FIVE THOUSAND SIX HUNDRED AND SIXTY SEVEN AND CENTS SIXTY ONLY.

E. & O.E

Total S\$ 5667.60
Discount S\$ 0
Net Total S\$ 5667.60

Customer's Signature/Co. Stamp



CHNG BROTHERS MOTOR SERVICES

Terms: C.O.D

18921 / e

Nivitha (LKK Auto)

From: ONG LI LI <liling@lonpac.com>
Sent: Wednesday, 23 October 2019 2:24 PM
To: jactan@visionlawllc.com; assignments; Admin-D (LKKAuto)
Cc: MT_Claim_SG
Subject: Vision Law Ref: AM.jt.Ins.C136.111906.19(sj) Our Ref: 19/19/19/VP00/022556
Attachments: 1725_001.pdf

4:10pm @ 23/10/19
VNI
P: Mr Chng
Weep say do (PS)
Never go by lauye

Without Prejudice
Save as to Costs


Dear Jac

Thank you for confirming the appointment of a Single Joint Expert.

Dear Nivitha

Please see attached and arrange Adrian Ling to conduct TP survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: ct-admin@visionlawllc.com [mailto:ct-admin@visionlawllc.com]
Sent: Wednesday, 23 October 2019 2:18 PM
To: ONG LI LI; MT_Claim_SG
Subject: Scan Image

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LIONG RAYNEY
AUDREY WONG SU-HEIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAN YINGXIAN, SELWYN
CHEONG YUNKU, CLARISSA
SONIA LIM WEE LEE

Unique Entity Number :200721148H
✓HEAD OFFICE: 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.ins.C136.111906.19 (sj)
Your Ref: 19/19/VP00/022556

23 October 2019

LONPAC INSURANCE BERHAD

300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Attention: Motor Claims Department

BY FAX: 6296 2706

Email: llong@lonpac.com

Email: mt_claim@lonpac.com

Dear Sirs,

ACCIDENT INVOLVING SLU 9630 U & SGR 2228 U ON 16 OCTOBER 2019 ALONG 27 MOULMEIN RISE SHOW FLAT CARPARK AT ABOUT 1300 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We refer to your email 23 October 2019 of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Adrian Ling as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue:

Chng Brothers Motor Services
Blk 2 Kaki Bukit Avenue 2
#02-32 Kaki Bukit Auto Hub
Singapore 417921

Contact Person:

Mr Chng (6747-0407/ 9274-5169)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you.

1st Survey on _____
Appointed surveyor :
(Name & Signature)

2nd Survey on _____
Appointed surveyor
(Name & Signature)

3rd Survey on _____
Appointed Surveyor
(Name & signature)

cc: SLU 9630 U – by fax: 6742 6933 only

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Thursday, 21 November 2019 2:30 PM
To: info@chngbrothers.com
Subject: ACCIDENT INVOLVING SLU 9630U & SGR 2228U ON 16/10/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir/Madam,

ACCIDENT INVOLVING SLU 9630U & SGR 2228U ON 16/10/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Asher Sng (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 20 February 2020 1:01 PM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG; Admin A; Asher Sng (LKKAUTO)
Subject: RE: Vision Law Ref: AM.jt.ins.C136.111906.19(sj) Our Ref: 19/19/19/VP00/022556 [External General]

Follow Up Flag: Follow up
Flag Status: Flagged


Lonpac External - General

Dear Mei Kwan

We have received LOD from TP lawyer.

Please submit your report and close file.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: ONG LI LI
Sent: Friday, 25 October 2019 2:29 PM
To: 'Mei Kwan (LKKAUTO)' <Meikwan@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Subject: RE: Vision Law Ref: AM.jt.ins.C136.111906.19(sj) Our Ref: 19/19/19/VP00/022556

Dear Mei Kwan

Our Insured has not reported the accident to us.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555



From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Thursday, 24 October 2019 6:31 PM
To: ONG LI LI
Cc: MT_Claim_SG; Admin A; Asher Sng (LKKAuto)
Subject: RE: Vision Law Ref: AM.jt.Ins.C136.111906.19(sj) Our Ref: 19/19/VP00/022556

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

LPC ref: 19/19/19/VP00/022556
LKK REF: CC4/LPC19018921/ea3

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of insured's accident report for our necessary action.

Please take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 23 October, 2019 4:11 PM
To: 'ONG LI LI' <long@lonpac.com>; assignments <assignments@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Vision Law Ref: AM.jt.Ins.C136.111906.19(sj) Our Ref: 19/19/VP00/022556

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:llong@lonpac.com>]

Sent: Wednesday, 23 October 2019 2:24 PM

To: jactan@visionlawllc.com; assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: Vision Law Ref: AM.jt.Ins.C136.111906.19(sj) Our Ref: 19/19/19/VP00/022556

Without Prejudice

Save as to Costs

Dear Jac

Thank you for confirming the appointment of a Single Joint Expert.

Dear Nivitha

Please see attached and arrange Adrian Ling to conduct TP survey.

Regards,


Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse

Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706




From: ct-admin@visionlawllc.com [<mailto:ct-admin@visionlawllc.com>]

Sent: Wednesday, 23 October 2019 2:18 PM

To: ONG LI LI; MT_Claim_SG

Subject: Scan Image



This email has been checked for viruses by AVG antivirus software.
www.avg.com




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC19018921/Aea3q2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 26-02-2020	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGR 2228U	Veh. Inspected	SLU 9630U	
Policy No.	Z/19/VP00/102980	Coverage (\$)	0.00	
Claim No.	19/19/19/VP00/022556	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	23/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	KIA CERATO K3	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KNAFZ411MJ5756173	Colour	WHITE	
Odometer	36222	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	NEXEN	6 mm	
L/H Front Tyre	215/45 R17	NEXEN	6 mm	
R/H Rear Tyre	215/45 R17	NEXEN	6 mm	
L/H Rear Tyre	215/45 R17	NEXEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/10/2019	Inspection Date	13/11/2019	
Survey held at	CHNG BROTHER MOTOR SERVICE 2 KAKI BUKIT AVENUE 2 #02-32 KAKI BUKIT AUTOHUB SINGAPORE 417921.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 9630U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	738.00	738.00
1	REAR BUMPER REINFORCEMENT	DEFORMED	344.00	344.00
1	REAR BUMPER LIP	DEFORMED	375.00	375.00
1	BUMPER BRACKET (R/H)	BENT	88.00	88.00
1	REAR BUMPER CLIP	NECESSARY	5.00	5.00
1	REAR BUMPER REFLECTOR (R/H)	NOT NECESSARY	109.00	-
10	BUMPER CLIP @\$5.00	NECESSARY	30.00	30.00
1	BUMPER SIDE RETAINER (L/H/R)	NECESSARY	43.00	43.00
1	BUMPER SIDE RETAINER (R/H/R)	NECESSARY	43.00	43.00
1	LAMP (R/H/R)	NOT NECESSARY	588.00	-
2	REVERSE SENSOR @\$197.00	DAMAGED	394.00	394.00
1	SENSOR (KEY)	NOT NECESSARY	295.00	-
	LESS 10% DISCOUNT		-305.20	-206.00
			2,746.80	1,854.00
SPECIAL NETT ITEMS				
1	BTL REAR END SEALANT (SN)	NOT NECESSARY	50.00	-
1	REAR BUMPER LIP (SN)	DEFORMED	800.00	500.00
1	SPEAKER (SN)	NOT NECESSARY	500.00	-
			1,350.00	500.00
LABOUR				
	TO PROVIDE UBDER TURFCODE.	NOT NECESSARY	120.00	-
	TO CHECK WIRING SYSTEM ,FOCUS LIGHTING .	NOT NECESSARY	50.00	-
	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT.		60.00	30.00
	TO REMOVE REVERSE SENSOR .		80.00	50.00
	PANEL BEATING & REPLACING OF THE ABOVE.		800.00	300.00
	TO PUTTY AND RESPRAY AFFECTED PORTION .		750.00	600.00
			1,860.00	980.00
GRAND TOTAL			5,956.80	3,334.00

Report Ref No. CC4/LPC19018921/Aea3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,600.00
---	--	--	----------

Report Ref No. CC4/LPC19018921/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.