

REC. BY:

REF: CS/SM019018958 | Ev f3 | 12  
Special Instruction:

Neyor Sleek ASSIGNMENT (Office)

from (Person): Hwang Shiang Yi of SMD Date/Time: 25.10.19 10:53A.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XE 4518L Insured: SBD 959

at Workshop m/s Vfix Auto Tel: 64552957

at 26 Chia Ping Road

Policy No: D18MTPV01019527 Claim No: (MTI) M04799

Sum Insured: Excess:

Make of Veh: D.O.A. 8.10.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS "up" 29.10.2019 H.O.D. Endorsement:

Date/Time: 25.10.19 11:54.m Person Contacted: Wen Zhen Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	XE 4518L - X
	SBD 959 - NA / FC (10029227/R) Roq - 14/12/2010
1/11/19	Send preli revised via merimen
1/11/19	LS \$ 1700 confirmed by email (Ref 446195, 729)

ASS. REC. BY: Steve Lau

REF: SMD

ASSIGNMENT

From: \_\_\_\_\_ Date: 31.10.2019

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XE 4518L

at Workshop m/s V FIX AUTO  
of 26 chia ping Road

Insured:

Policy No.

Claims No.

Sum Insured. Excess:

(Client's Record)

Make of Veh: 10-004-n amr waty

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Sal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repair: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp'

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: XE 4518L Yr Regn: 29/11/18  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz Arocs 3336K c.c. 10677

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 44947 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: W0896421620274955

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim or

Tyre Size: F: 315/80R225

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TRIANGLE

Front

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 8/10/19 D.O.I. 31/10/19

Survey held at V-fix

Des. of Damages Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31/10/19 Pending Estimate

RECEIVED 04 NOV 2019

Date/Time, File Pass to?  : Prel. Report

: Final Report

Date/Time, File Return to?

3) 4/11 - typist

Pop. Form: merimen

1700/p

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech. Insp (\$)

: Meet Insp (\$)

Survey Fee:

Transportation:

3 + RS. \$

Folio:

Other:

TOTAL

250
11
261

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

<b>To:</b> Sompo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	<b>From:</b> LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
<b>Attn:</b> Hwang Shiang Yi	<b>Date:</b> 01 Nov 2019
<b>Preliminary Advice</b>	

Insured Vehicle No	: SBD95G	Accident Date	: 08/10/2019
TP Vehicle No	: XE4518L	Assignment Date	: 25/10/2019
Make	: MERCEDES BENZ AROCS 3336K	Est. Duration of Repair	: 2
Date of Inspection	: 31/10/2019		
Inspection At	: VFIX AUTO PTE LTD		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:SS	6,161.95
Revised Amount	:SS	2,404.45
Check Items (Estimated)	:SS	0.00
<b>Total</b>	<b>:SS</b>	<b>2,404.45</b>
Lump Sum Repair	:SS	

### **Total Loss Consideration**

New for Old Value	:SS	
Pre-Accident Value	:SS	
COE / PARF Rebate	:SS	
Salvage Value	:SS	
Margin for Repair	:SS	

### Remarks

- The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- Other comments :The above survey was conducted on a 'Without Prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Oct 2019		25 Oct 2019 10:53 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>				<a href="#">[Created by insurer]</a>					
Insured:	<b>MARY SYBIL SILVA</b> , ID: S2016657F, Tel: +6597815495, Email: marysundarason@yahoo.com.sg								
Main Claimant:	<b>HE GUANGYU</b> , ID: G8370606L								
Vehicle Reg. No.:	<b>XE4518L</b>	Date of Loss:	08/10/2019 12:00 - :59						
Claim Type:	<b>TP / CMTD1904799</b>	Policy/Cover Note No.:	D18MTPV01019527 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SBD95G</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Vfix Auto Pte Ltd (HQ)</b> 26 Chia Ping Road, 619977 Boon Lay - Tel:								
Handling Insurer:	<b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>Hwang Shiang Yi</b> - 6329 5205]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Final Rpt due 06/11/2019]</b>								
Driver/Custodian (Insured):	<b>MARY SYBIL SILVA</b> (67 / Female), NRIC: S2016657F, Tel: +6597815495 Email: marysundarason@yahoo.com.sg								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a> <a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Steve Chen (LKK Auto)**

---

**From:** wskoh@vfixauto.com.sg  
**Sent:** Friday, November 01, 2019 1:54 PM  
**To:** Steve Chen (LKK Auto)  
**Cc:** jessicassy@vfixauto.com.sg; jeffbz@vfixauto.com.sg; ybsim@vfixauto.com.sg; kentsh@vfixauto.com.sg; alanclk@vfixauto.com.sg  
**Subject:** RE: ACCIDENT INVOLVING XE4518L AND SBD95G ON 08.10. 2019  
**Attachments:** LOD.pdf

Dear Steve,

Good day.

We accept your offer \$1700 (L/S, before GST) & 2 repair days.

Original LOD copies we will post up to Sompo Insurance.

Thank You.



Remark: W.e.f 22<sup>nd</sup> April 2019, our office has been relocated to 26, Chia Ping Road, Singapore 619977. Please update your record with the following: Company contact number - 6455 2957 ; Company general email - [contact@vfixauto.com.sg](mailto:contact@vfixauto.com.sg)

Thanks & Regards,

**Weng Sheng**  
Motor Claim Operation Admin  
Vfix Auto Pte Ltd | Vfix Auto Service Pte Ltd | Vfix Leasing Pte Ltd  
26 Chia Ping Road Singapore 619977  
Contact: 6455 2957 | E: [wskoh@vfixauto.com.sg](mailto:wskoh@vfixauto.com.sg)

---

**From:** Steve Chen (LKK Auto) <[SteveChen@lkkauto.com](mailto:SteveChen@lkkauto.com)>  
**Sent:** Thursday, 31 October 2019 6:31 PM  
**To:** [wskoh@vfixauto.com.sg](mailto:wskoh@vfixauto.com.sg); [alanclk@vfixauto.com.sg](mailto:alanclk@vfixauto.com.sg)  
**Subject:** ACCIDENT INVOLVING XE4518L AND SBD95G ON 08.10. 2019

Dear Alan,

Kindly refer our finalize \$1700 (L/S, before GST). 2 repair days.

Kindly confirm.

Thanks

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	117E
Vehicle Details	
Vehicle No.:	XE4518L
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Oct 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	AROC5 3336K 6X4 3300 S-CAB (AUTO, ABS)
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	470913C0411031
Chassis No.:	WDB96421620274955
Maximum Power Output:	-
Open Market Value:	\$109,746.00
Original Registration Date:	29 Nov 2018
First Registration Date:	29 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$5,488.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Nov 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$27,104.00
COE Rebate Amount:	\$24,604.00
<b>Total Rebate Amount:</b>	<b>\$24,604.00</b>

The information contained herein is correct as at 31 Oct 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/10/2019 14:25
Date Of Accident	08/10/2019 12:30
Exact Location Of Accident	ALONG NEW UPP CHANGI RD TOWARDS BEDOK SOUTH AVE 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE4518L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD
Co Reg No	199904117E
Email Address	MRNGKINHOE@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-91483054

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	AROCS 3336K 6X4 3300 S-CAB (AUTO,ABS)
Exact Purpose for which vehicle was being used at time of accident	

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	2018-V0106431-VCV
Cover Note Number	29/11/2019 TO 28/11/2019

### Driver

Name of Driver	HE GUANGYU
NRIC No	G8370606L
Date Of Birth	22/07/1976
Occupation	OUTDOOR
Date Of Driving Pass	27/08/2012
Driving Experience	7 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91493054
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 27 PANDAN CRESENT S128476

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

refer with attach.

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SBD95G

Vehicle Make/Model/Colour TOYOTA CAMRY

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

# Accident Sketch Plan Pg. 1

## KEY PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurers companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false information may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any complaints by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve the issuing of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law or administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in the accident and the Insurers' lawyers/law firm, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

2019.10.8 賴子余  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature  
Name:  
NRIC/IN No.:

Accident Sketch Plan Pg. 1

A: XE4518L

B: SBD95G

DRIVER'S NAME



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 8th October 2019 at 1230hrs, I was driving XE4518L along New Changi Road towards Bedok South Avenue 1 in the middle lane, suddenly a car(SBD95G) dashed out from my left and hit to my from left front portion. No one injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Name & Title:

2019.10.8: 贺广余  
Driver's Signature:  
(If driver is not the policyholder)  
Date & Time:

Reporting Officer's Signature  
Name:  
NIC/IN No.:

For Customer Service please visit  
 1 Pickering Street  
 #01-01 Great Eastern Centre  
 Tel: +65 8248 2888 Fax: +65 6327 3060



**Certificate of Insurance**

**ORIGINAL**

Road Transport Act 1987 (Federation of Malaysia);  
 The Motor Vehicles (Third-Party Risks) Rules, 1959 (Federation of Malaysia);  
 The Motor Vehicles (Third-Party Risks and Compensation) Act, (Cap.189 of the Revised Edition) (Republic of Singapore);  
 The Motor Vehicles (Third Party Risks and Compensation) Rules, 1960. (Republic of Singapore)

0084 X2300

Policy No. : 2019 VD109431-VCV Risk# : 0001  
 Policy Type : Commercial Vehicle Cover : Comprehensive

**DESCRIPTION OF VEHICLES:**

Vehicle Registration : XE1518L  
 Vehicle Make & Model : MERCEDES BENZ AROCS 3336K EX4 3300 5-CAB

Name of insured : KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD

Period of Insurance : 29 11 2018 (0000HRS ) to 28 11 2019

**PERSONS OR CLASS OF PERSONS ENTITLED TO DRIVE \***

Any person who is driving on the Policyholder's order or with their permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

**LIMITATIONS AS TO USE**

- (1) Use in Connection with the Policyholder's business.
  - (2) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.
  - (3) Use for social, domestic and pleasure purposes.
- The policy does not cover :-
- (1) Use for racing, pace-making, reliability trial or speed-testing.
  - (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.
  - (3) Use for the carriage of passengers for hire or reward.

Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Signed for and on behalf of the Company

Authorized Signature

0401028

04-12-2018

Accident Photo





**Vfix Auto Pte Ltd**  
26 Chia Ping Rd  
Singapore 619977  
E-mail: [wskoh@vfixauto.com.sg](mailto:wskoh@vfixauto.com.sg)  
Tel: 64552957 Fax: 68628669  
UEN/GST Reg. No.: 201830761R

Your Vehicle No. : SBD95G

Our Vehicle No. : XE4518L

25.10.2019

M/S SOMPO INS S'PORE PTE LTD  
50 RAFFLES PLACE  
#05-01/06 S'PORE LAND TOWER  
SINGAPORE 048623

Dear Sir / Madam

**ACCIDENT INVOLVING XE4518L AND SBD95G ON 08.10. 2019**

We refer to the above matter.

We hereby give 2 days' notice to conduct a pre-repair inspection of Vehicle Number XE4518L at 26 Chia Ping Rd, Singapore 619977.

Please take note vehicle will check in on 29/10/2019 10.00am and driver will waiting.

Thank you.

Yours faithfully

**Vfix Auto Pte Ltd**



Vfix Auto Pte Ltd  
26 Chia Ping Road  
Singapore 619977  
Email : contact@vfixauto.com.sg  
Tel : 6448 9268 Fax: 6445 2368  
UEN / GST Reg No. : 201830761R

**ESTIMATE**

DATE :  
ACC DATE :  
REF NO :  
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO :XE4518L MERCEDES AROCS

DESCRIPTION	AMOUNT S\$
1 1 HEAD LAMP RIM LH X <i>MAI</i>	432.00
2 1 FRONT SIDE BUMPER LH / <i>CUT</i>	<i>1393</i> / 1,692.50
3 1 FRONT SIDE BUMPER BOTTOM GARNISH LH / <i>CUT</i>	<i>344</i> / 368.00
4 1 FRONT STEP GARNISH LH X <i>MAI</i>	1,970.00
5 1 FRONT STEP PLATE LH X <i>MAI</i>	270.00
6 1 FRONT BOTTOM STEP LH X <i>R</i>	1,003.00
	<hr/>
	\$ 5,735.50
LESS 10%	\$ 5,161.95

*1737*  
*-10%*  
*15633*

DESCRIPTIONS	UNIT PRICE	AMOUNT S\$
<u>SPECAIL NETT</u>		
1		\$ -

**LABOUR & MISCELLANEOUS :** AMOUNT S\$

- |   |   |        |     |
|---|---|--------|-----|
| 1 | To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten front door pillar, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components / attachments | 500.00 | 350 |
| 2 | To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials  | 500.00 | 200 |

\$ 1,000.00

GRAND TOTAL : \$ 6,161.95

Vfix Auto Pte Ltd

Steve (LKK) with Arrival 31/10/19, 10.00am  
 8322 8813 2 days  
 L/S  
 Ry AF Spj

P- 1572.39  
 L- 550  
 2122-30  
 L/S - 1697.84  
 = 1700

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications are allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
 Signature:  
 Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19018958/EVF3N2

Date: 05/11/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01019527
Claimant Vehicle No :	XE4518L	Insured Vehicle No :	SBD95G
Date of Loss:	08/10/2019	Nature of Claim:	TP
		Claim No:	CMTD1904799

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	XE4518L		
Make & Model:	MERCEDES-BENZ ACTROS, 11.9 D 3336K 6X4 3300 (M)	Engine No:	470913C0411031
Reg. Date:	29/11/2018 (Man. Year: 2018)	Chassis No:	WDB96421620274955
Colour:	White	Odometer:	44947 km
Engine Capacity:	10677 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	315/80R22.5	Rear Tyre Size:	315/80R22.5
Front Left Side:	Triangle 5 mm	Rear Left Side:	Triangle 5 mm
Front Right Side:	Triangle 5 mm	Rear Right Side:	Triangle 5 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,161.95	1,563.30	3,598.65	69.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	550.00	450.00	45.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,161.95</b>	<b>2,113.30</b>	<b>4,048.65</b>	<b>65.70</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,700.00</b>		
<b>(S\$)</b>	6,161.95	1,700.00	4,461.95	72.41
<b>+ GST 7.00/7.00% (S\$)</b>	431.34	119.00	312.34	72.41
<b>Nett Amount (S\$)</b>	<b>6,593.29</b>	<b>1,819.00</b>	<b>4,774.29</b>	<b>72.41</b>

## INSPECTION

Date of Assignment:	25/10/2019	Inspected At:	Vfix Auto Pte Ltd (HQ)
Date Inspected:	31/10/2019		26 Chia Ping Road
			Singapore 619977

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b>	(Last Synchronised: 05 Nov 2019)
<b>Parts:</b>	N/A MERCEDES-BENZ ACTROS 11.9 D 3336K 6X4 3300 (M) (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for XE4518L)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*HEAD LAMP RIM LH	Not Necessary	432.00 FL	*- FL	
2	1		*FRONT SIDE BUMPER LH	Cut	1,692.50 FL	*1,393.00 FL	
3	1		*FRONT SIDE BUMPER BOTTOM GARNISH LH	Cut	368.00 FL	*344.00 FL	
4	1		*FRONT STEP GARNISH LH	Not Necessary	1,970.00 FL	*- FL	
5	1		*FRONT STEP PLATE LH	Not Necessary	270.00 FL	*- FL	
6	1		*FRONT BOTTOM STEP LH	Repair	1,003.00 FL	*- FL	
					<b>Sub Total (S\$)</b>	<b>5,735.50</b>	<b>1,737.00</b>
					<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>573.55</b>	<b>173.70</b>
					<b>Total Parts (S\$)</b>	<b>5,161.95</b>	<b>1,563.30</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE DAMAGED BODY PANEL WITH ALL NECESSARY COMPONENTS/ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY STRAIGHTEN FRONT DOOR PILLAR,REPAIR/RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS/ATTACHMENTS	New	500.00	350.00
2	TO SPRAY PAINT REPLACED/REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	500.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,000.00</b>	<b>550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >