

2300000

ASS. REC. BY:

REF: 033/CTI/19018966/Hcd3er Special Instruction:

Surveyor: Huzik Amir

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI Date/Time: 10:18am @ 25/10/2019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKN 9613T Insured: GBG 5699R

at Workshop n/s My Car Consultant Tel: 88668832

of 53 Ybi Avenue 1 #01-33

Policy No: DMCVSN30F55319022 Claim No: SNMKID204997C02

Sum Insured: _____ Excess: _____

Make of Vehic: _____ D.O.A. _____
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endowment: _____

Date/Time: 10:49am @ 25/10/19 Person Contacted: Hui Qin Vehicle: IN / OUT

Date/Time	Action/Instruction
	Estimate <input checked="" type="checkbox"/>
	SKN 9613T - NAVAR/19018526/04
	GBG 5699R - CS/CTI/19018751/PI/03
	Dismantle: 30/10/2019

DOA: 18/10/2019
DA: 18/10/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'ed	Status
Main	13 Feb 2020		13 Mar 2020 11:57 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant:	SINCAP GROUP LIMITED , Co. Reg. No.: 201005161G								
Vehicle Reg. No.:	SKN9613T	Date of Loss:	18/10/2019 17:00 - :59						
Claim Type:	TP / SNM19D204997C02	Policy/Cover Note No.:	DMCVSN30755319022						
Vehicle Reg. No. (Insured):	GBG5699R	Policy No. (Claimant):	2100339862-06						
		Excess:	S\$0.00						
Repairer:	My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park, 408934 Ubi - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6369 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 24/03/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 25 October 2019 10:18 AM
To: admin@mycar.sg
Cc: assignments
Subject: RE: RE: OUR REF: SNM19D204997-GBG5699R-CBS - OUR REF: SKN9613T YOURREF: GBG5699R PRE-REPAIR INSPECTION FOR SKN9613T

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK.

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: My Car Consultant [mailto:admin@mycar.sg]

Sent: Thursday, October 24, 2019 10:36 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: fw: RE: OUR REF: SNM19D204997-GBG5699R-CBS - OUR REF: SKN9613T YOURREF: GBG5699R PRE-REPAIR INSPECTION FOR SKN9613T

WITHOUT PREJUDICE

Dear Boon Sen,

Please let your appointed surveyor have the assignment ASAP.

Best Regards,

Huiqin

Claims | My Car Consultant Pte Ltd

- [+65 88668832](tel:+6588668832)
- Admin@mycar.sg
- Mycar.sg
- 53 Ubi Ave 1, Paya Ubi Industrial Park, 01-33, S408934

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

From: "My Car Consultant" <admin@mycar.sg>
Sent: Wednesday, October 23, 2019 10:19 AM
To: "Chong Boon Sen" <boonsen.chong@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D204997-GBG5699R-CBS - OUR REF: SKN9613T YOURREF: GBG5699R PRE-REPAIR INSPECTION FOR SKN9613T

WITHOUT PREJUDICE

Dear Boon Sen,

We refer to your email on even date.

We disagree to your list of surveyor and propose the use of one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

- a. Alan Cheong
- b. TT Rajan
- c. Oh Han Cheong
- d. Andrew How
- e. Dave Ho Joo Koong
- f. Lee Kok Weng
- g. Seah Kwang Boon
- h. Lee K.W.
- i. Nicky Seah
- j. Winson Goh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors.

Best Regards,

Huiqin

Claims | My Car Consultant Pte Ltd

- [+65 88668832](tel:+6588668832)
- Admin@mycar.sg
- Mycar.sg
- 53 Ubi Ave 1, Paya Ubi Industrial Park, 01-33, S408934

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

From: "Chong Boon Sen" <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, October 23, 2019 8:58 AM
To: "admin@mycar.sg" <admin@mycar.sg>

Subject: RE: OUR REF: SNM19D204997-GBG5699R-CBS - OUR REF: SKN9613T YOUR REF: GBG5699R PRE-REPAIR INSPECTION FOR SKN9613T

Without prejudice
Dear Sir,
LKK
STA
LBS

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** ???? Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Tuesday, October 22, 2019 2:26 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; admin@mycar.sg

Subject: OUR REF: SNM19D204997-GBG5699R-CBS - OUR REF: SKN9613T YOUR REF: GBG5699R PRE-REPAIR INSPECTION FOR SKN9613T

Dear Boon Sen,

Please conduct PRS for SKN9613T.

Note : officer in charge – Boon Sen 63896171.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** ???? Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: My Car Consultant [<mailto:admin@mycar.sg>]

Sent: Tuesday, October 22, 2019 10:36 AM

To: Claims Dept of CTI

Subject: OUR REF: SKN9613T YOUR REF: GBG5699R PRE-REPAIR INSPECTION FOR SKN9613T

WITHOUT PREJUDICE

OUR REF: SKN9613T
YOUR REF: GBG5699R

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SKN9613T
ACCIDENT INVOLVING SKN9613T AND GBG5699R

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction - Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention

Warm Regards,
Kai Ling

My Car Consultant Pte Ltd
53 Ubi Avenue 1
Paya Ubi Industrial Park
#01-33 S(408934)

Tel: +65 9868 6000 / Fax: 6925 5219

CONFIDENTIALITY NOTICE: This message (including any attachments) is confidential and may be privileged. It may be read, copied and used only by the intended recipient. If you have received it in error please contact the sender (by return e-mail) immediately and delete this message. Any unauthorized use or dissemination of this message in whole or in parts is strictly prohibited.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	161G
Vehicle Details	
Vehicle No.:	SKN9613T
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	S 350 CGI L
Primary Colour:	Brown
Manufacturing Year:	2012
Engine No.:	27695030127073
Chassis No.:	WDD2211572A468033
Maximum Power Output:	225.0 kW (301 bhp)
Open Market Value:	\$95,928.00
Original Registration Date:	10 Jul 2012
First Registration Date:	10 Jul 2012
Transfer Count:	1
Actual ARF Paid:	\$95,928.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jul 2022
PARF Rebate Amount:	\$57,556.00
Intended COE Rebate Details	
COE Expiry Date:	09 Jul 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$65,801.00
COE Rebate Amount:	\$17,706.00
Total Rebate Amount:	\$75,262.00

The information contained herein is correct as at 30 Oct 2019

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Classic, Premium Best Deal/Fast Selling/Hurry Down Now!



Classic Credit: 7.99% p.a.
Welcome: 30% Deposit Refund
For Approved Loan
Classic Credit: 7.99%

P PRIME MOTOR & LEASING

(SHEN YONG CREDIT ENTERPRISES) PTE. LTD. GROUP OF COMPANIES

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted

20 results/page

7 vehicles

Mercedes Benz 350

Advanced Search

Image	Model	Price	Depreciation	Year Used	Eng Cap	Mileage	Veh Type	Status
	Mercedes Benz 350	Any	Any	2012	Any	Any	Any	Available
	Mercedes-Benz S-Class S350L CGI	\$95,388	\$19,840 /yr	29-Feb-2012	3,498 cc	95,000 km	Luxury	Available
Enjoy Low Interest Rates From 2.28% For A Limited Time Only! Well Maintained And Taken Care Of By Previous Owner. 100% Accident Free. Genuine Mileage. 1 Owner Only. Trade In And High Loan Of Up To 90% Are Available Here. Call Us Now To Test Drive Today!								
Euro Performance Asia Pte Ltd								
Posted: 29-Oct-2019 Tags: 2012 Mercedes-Benz S350L, 2012 mercedes-benz s350l, Mercedes-Benz S350L, mercedes-benz s350l, Mercedes-Benz, S350L, s350l, Used Mercedes-Benz								
	Mercedes-Benz S-Class S350L CGI	\$98,000	\$20,940 /yr	02-Mar-2012	3,498 cc	115,588 km	Luxury	Available
Metalic Black. Grey Leather Interior. In Car Phone. Rear And Side Electric Roller Blinds. Suction Doors And Auto Tailgate. New Facelift. Beautiful Condition. Loan Available 2.28%. Call Me For Viewings.								
Posted: 29-Oct-2019 Tags: 2012 Mercedes-Benz S350L, 2012 mercedes-benz s350l, Mercedes-Benz S350L, mercedes-benz s350l, Mercedes-Benz, S350L, s350l, Used Mercedes-Benz								
	Mercedes-Benz S-Class S350L CGI	\$93,800	\$20,150 /yr	18-Jan-2012	3,498 cc	142,000 km	Luxury	Available
Well Maintained. Loans Available, With Lowest Interest Rates. High Trade In Welcome. Call Now To Book An Appointment To View This Beauty. Viewing Strictly Appointment Based.								
Car Search								
Posted: 27-Oct-2019 Tags: 2012 Mercedes-Benz S350L, 2012 mercedes-benz s350l, Mercedes-Benz S350L, mercedes-benz s350l, Mercedes-Benz, S350L, s350l, Used Mercedes-Benz								
	Mercedes-Benz C-Class C350 Coupe AMG	\$73,888	\$18,010 /yr	09-Feb-2012	3,498 cc	86,000 km	Sports	Available
1 And The Only One In The Market! Rare Find! Rare Breed! Low Mileage Done 86000km. Selling Cheap. Don't Ever Miss Out On This Great Deal. Enjoy The Powerful V6 Engine On This C350 With Full AMG Package Producing 3018hp. Flawless Condition Like New. Well T...								
Posted: 20-Oct-2019 Tags: 2012 Mercedes-Benz C350, 2012 mercedes-benz c350, Mercedes-Benz C350, mercedes-benz c350, Mercedes-Benz, C350, c350, Used Mercedes-Benz								
	Kressor Automotive Workshop - Specialist for Mercedes Car repair, servicing & maintenance							
Our workshop is equipped with the latest diagnostics equipment suitable for all car makes and models, though we're specialising in Mercedes-Benz.								
More info about this shop								
	Mercedes-Benz S-Class S350L CGI AMG	\$92,000	\$19,560 /yr	09-Jan-2012	3,498 cc	-	Luxury	Available
100% Accident Free, High OMV At \$98147, Superb Condition Exterior And Luxury Leather Interior, Original Mileage, New Battery With 2 Years Warranty, High Trade In, Flexible Loan Available, Viewing By Appointment Only.								
360 VR Cars								
Posted: 12-Oct-2019 Tags: 2012 Mercedes-Benz S350L, 2012 mercedes-benz s350l, Mercedes-Benz S350L, mercedes-benz s350l, Mercedes-Benz, S350L, s350l, Used Mercedes-Benz								
	Mercedes-Benz R-Class R350L	\$81,700	\$19,480 /yr	30-Mar-2012	3,498 cc	100,600 km	MPV	Available
Only 1 In The Market Now, Spacious Family 7 Seater R350L! 100% Accident Free! Excellence Condition To Drive Your Family Around, No Repair Needed! Low Mileage, STA Evaluation Welcome! In House Loan Available With 100% Approval, Act Fast Call To Discuss.								
Posted: 30-Sep-2019 Tags: 2012 Mercedes-Benz R350L, 2012 mercedes-benz r350l, Mercedes-Benz R350L, mercedes-benz r350l, Mercedes-Benz, R350L, r350l, Used Mercedes-Benz								
	Mercedes-Benz S-Class S350L	\$109,000	\$20,590 /yr	17-Oct-2012	3,498 cc	-	Luxury	Available



CGI

View To Appreciate, Viewing Strictly By Appointment Only.

360 VR Cars

Posted: 17-Sep-2019

Tags: 2012 Mercedes-Benz S350L, 2012 Mercedes-Benz s350, Mercedes-Benz S350L, mercedes-benz s350L, Mercedes-Benz, S350L, s350, Used Mercedes-Benz

Save this search criteria, to get email alerts whenever a match is found.

MOD

Model

Price

Depreciation

Reg Fees

Eng Cap

Mileage

Veh Type

TOTAL

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Mercedes Benz 350, Mercedes Benz 350 Singapore, used Mercedes Benz 350 Singapore, used Mercedes Benz 350, used vehicles Singapore or even buy used Mercedes Benz 350 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

00A - 18/10/19

MV - 97200
 PV - 75262
 NV - 21900

Blue - 2yr bank
 Purple - 18500 yr

$$18500 \div 12 = 1541 \text{ wd}$$

$$37000 + 12328$$

$$+ 47964$$

$$= 97292$$

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/10/2019 16:10
Date Of Accident	18/10/2019 17:45
Exact Location Of Accident	PIE (CHANGI) AFTER THOMSON RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN9613T
Insured/Policyholder	
Name Of Registered Owner	SINCAP GROUP LIMITED
Co Reg No	201005161G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	S 350 CGI L
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100339862-06
Cover Note Number	

Driver

Name of Driver	LONG FOO MIN
NRIC No	S1286209A
Date Of Birth	29/04/1958
Occupation	INDOOR
Date Of Driving Pass	20/07/1977
Driving Experience	42 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90275658
Fax Number	
Contact Number	OFFICE-90275658
EMail Address	NOEMAIL

Address	BLK 132 EDGEDALE PLAINS #05-24
Postcode	820132
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20191018/7033.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG5699R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJT7231E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LONG FOO MIN

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

SKN9613T

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report accurately the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind its policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false statement may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for compliance with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/ID No.:

Accident Sketch Plan

P/E towards Chong; left after Thomson exit

Veh A:
SKN 9613 T
Veh B:
G667 56002
Veh C:
SJT 7231 E



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to Police Report

DECLARATION OF ACCIDENT
I/We declare that the above particulars are true in every respect.



Policyholder's Signature
Date & Title

Driver's Signature
(If driver is not the policyholder)
Date & Title

Reporting Centre Personnel's Signature
Name:
RUC/PR No.:

Police Report



**SINGAPORE
POLICE FORCE**



T/20191018/7033

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000

1 of 3

Report No: T/20191018/7033

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/10/2019 21:46	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: LONG FOO MIN		Address: APT BLK 132 EDGEDALE PLAINS #05-24 SINGAPORE 820132	
ID Type / ID No.: NRIC NO / S1286209A		Contact No.: Home/Office:	Mobile: 90275658
Nationality: SINGAPORE CITIZEN		Email: ronaldtmlong@yahoo.com.sg	
Sex: Male	Age: 61	Date of Birth: 29/04/1958	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Clinic Manager		Driving Licence Information: Class:	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 18/10/2019 19:50	Type of Location: Straight Road
Location: PAN ISLAND EXPRESSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 80 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
GBG5699R	Lorry					0
SJT7231E	Car					0
SKN9613T	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report



**SINGAPORE
POLICE FORCE**



T/20191018/7033

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000

2 of 3
Report No. T/20191018/7033

CONTINUATION OF REPORT

Driver			
Name	LONG FOO MIN	ID No.	S1286209A
Related Vehicle	SKN9613T (Car)	Contact No.	90275658
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	18/10/2019	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

ON THE STATED TIME AND DATE
I WAS TRAVELLING MY VEHICLE BEARING CAR PLATE SKN9613T ALONG PIE TOWARDS CHANGI
AFTER THOMSON EXIT ON LANE 2
SUDDENLY I FELT A HUGE IMPACT FROM MY REAR , I ALIGHTED AND REALIZE A LORRY
BEARING CAR PLATE GBG5699R WAS COLLIDED ON MY REAR
THE IMPACT WAS SO HUGE THAT CAUSED ME PROPEL IN FRONT AND COLLIDED A VEHICLE
BEARING CAR PLATE SJT7231E
I FELT UNCOMFORTABLE SO I CONSULT A DOCTOR AND GIVEN 5 DAYS MC.

Police Report



SINGAPORE
POLICE FORCE



T/20191018/7033

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3
Report No. T/20191018/7033

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / TPHQ / ONG YONG HOCK Contact No.: 65476436

Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Date/Time: 18/10/2019 21:46
Classification Of Case:

Authentication Stamp
NP168

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Feb 2020		13 Mar 2020 11:57 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	SINCAP GROUP LIMITED , Co. Reg. No.: 201005161G								
Vehicle Reg. No.:	SKN9613T	Date of Loss:	18/10/2019 17:00 - :59 [87 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D204997C02		Policy/Cover Note No.:	DMCVSN30755319022					
Vehicle Reg. No. (Insured):	GBG5699R	Policy No. (Claimant):	2100339862-06						
		Excess:	S\$0.00						
Repairer:	My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park, 408934 Ubi - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 24/03/2020]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKN9613T (SNM19D204997C02)
 [GBG5699R]
 TP
 SINCAP GROUP LIMITED
 Oct 18 2019 5:00PM
 [-]
 My Car Consultant Pte Ltd

Upload Documents Upload Photos Compose New Letter			View <input type="button" value="View in Browser"/>
Photos/Images			3 per page <input type="button" value="v"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="checkbox"/>
1	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
2	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
3	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
4	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
5	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
6	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
7	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
8	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
9	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
10	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
11	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
12	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
13	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
14	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
15	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
16	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
17	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
18	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
19	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
20	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
21	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
22	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
23	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
24	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
25	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
26	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
27	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
28	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
29	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
30	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
31	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
32	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
33	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
34	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
35	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
36	13/03/20 12:10	General View	<input checked="" type="checkbox"/>
37	13/03/20 12:10	General View	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
39	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
40	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
41	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
42	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
43	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
44	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
45	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
46	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
47	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
48	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
49	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
50	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
51	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
52	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
53	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
54	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
55	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
56	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
57	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
58	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
59	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
60	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
61	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
62	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
63	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
64	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
65	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
66	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
67	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
68	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
69	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
70	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
71	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
72	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
73	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
74	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
75	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
76	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
77	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
78	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
79	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
80	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
81	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
82	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
83	13/03/20 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
84	13/03/20 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
85	13/03/20 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
86	13/03/20 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
87	13/03/20 12:10	General View	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	13/03/20 12:10	General View		<input checked="" type="checkbox"/>
89	13/03/20 12:10	General View		<input checked="" type="checkbox"/>
90	13/03/20 12:10	General View		<input checked="" type="checkbox"/>
91	13/03/20 12:10	General View		<input checked="" type="checkbox"/>
92	13/03/20 12:10	General View		<input checked="" type="checkbox"/>
93	13/03/20 12:10	General View		<input checked="" type="checkbox"/>
94	13/03/20 12:10	General View		<input checked="" type="checkbox"/>
95	13/03/20 12:10	General View		<input checked="" type="checkbox"/>
96	13/03/20 12:10	General View		<input checked="" type="checkbox"/>
97	13/03/20 12:10	General View		<input checked="" type="checkbox"/>
98	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
99	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
100	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
101	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
102	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
103	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
104	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
105	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
106	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
107	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
108	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
109	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
110	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
111	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
112	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
113	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
114	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
115	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
116	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
117	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
118	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
119	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
120	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
121	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
122	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
123	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
124	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
125	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
126	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
127	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
128	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
129	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
130	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
131	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
132	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
133	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
134	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
135	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
136	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
137	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
139	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
140	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
141	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
142	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
143	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
144	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
145	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
146	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
147	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
148	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
149	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
150	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
151	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
152	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
153	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
154	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
155	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
156	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
157	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
158	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
159	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
160	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
161	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
162	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
163	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
164	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
165	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
166	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
167	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
168	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
169	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
170	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
171	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
172	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
173	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
174	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
175	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
176	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
177	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
178	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
179	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
180	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
181	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
182	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
183	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
184	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
185	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
186	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
187	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
188	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
189	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
190	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
191	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
192	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
193	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
194	13/03/20 12:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>

Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	06/12/19 19:10	Accident Statement		<input type="checkbox"/>
2	06/12/19 19:11	Accident Statement		<input type="checkbox"/>
3	06/12/19 19:12	Accident Statement		<input type="checkbox"/>
4	06/12/19 19:13	Accident Statement		<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
2	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
3	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
4	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
5	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
6	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
7	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
8	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
9	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
10	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
11	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
12	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
13	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
14	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
15	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
16	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
17	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
18	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
19	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
20	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
21	21/10/19 16:19	Accident Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	21/10/19 16:19	Accident Sketch Plan		<input checked="" type="checkbox"/>
2	21/10/19 16:19	Accident Sketch Plan		<input checked="" type="checkbox"/>
3	21/10/19 16:19	Police Report		<input checked="" type="checkbox"/>
4	21/10/19 16:19	Police Report		<input checked="" type="checkbox"/>
5	21/10/19 16:19	Police Report		<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119018966/HCD3E2

Date: 19/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN30755319022	
Claimant Vehicle No: SKN9613T	Insured Vehicle No: GBG5699R	
Date of Loss: 18/10/2019	Nature of Claim: TP	Claim No: SNM19D204997C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKN9613T		Engine No: 27695030127073
Make & Model: MERCEDES-BENZ S350, 3.5 CGI (A)		Chassis No: WDD2211572A468033
Reg. Date: 10/07/2012 (Man. Year: 2012)		Odometer: 73574 km
Colour: Brown		
Engine Capacity: 3498 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/45 R18	Rear Tyre Size:	255/45 R18
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	13/03/2020	
Date Inspected:	25/10/2019 Inspected At:	My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	8.0 days	

Adjuster: LEE HOCK ANN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$19,000.00 - \$21,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Mar 2020)
Parts: 143	MERCEDES-BENZ S350 3.5 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKN9613T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >