



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19018974/Ada3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 29-05-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 7956R	Veh. Inspected	SMD 5580J
Policy No.	DMB1SN1928781900	Coverage (\$)	0.00
Claim No.	SNM19D205021/C02	Excess (\$)	0.00
Assign From		Assign Date	23/10/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN SYLPHY	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MNTBBAB17Z0032728	Colour	BLUE
Odometer	24729	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm
L/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	195/60 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	195/60 R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/10/2019	Inspection Date	23/10/2019
Survey held at	CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	18 Working Days
-------------------------------------	------------------------