

ASS. REC. BY:

REF: CSKMO19018995/UVF312 Special Instruction:

Surveyor

Marcus

ASSIGNMENT (Office)

From (Person):

Ghoh Pau Long

of

SMO

Date/Time: 25.10.19 15.53p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SME 8728B

Insured:

GBH 136B

at Workshop m/s

Fastech Auto

Tel:

67465405

of 1 Kaki Bukit Ave 6 # 01-46/48/50 Autobay

Policy No:

DIGMTRVG 001767

Claim No:

CMT121905036

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 23.10.2019

CA / REV / REP. / REV 24 HRS

Date/Time:

25.10.19 4.01p.m

Person Contacted:

Nancy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SME 8728B - X

GBH 136B - X

20/10/19

@ 15:05 pm revert pending estimate to Pau Long via merimen

11/11/19

Send preli revised via merimen

ASS. REC. BY:

Date:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen

Consistent?: Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6 yrs Park by headlamp 3369.90

11/11/19 4/5 = 5050 confirmed with client (Red 7465.20, 609)

RECEIVED 11 NOV 2019

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

11/11 - typist

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Wash and (\$

Survey Fee:

Transportation:

8 + RS \$

Photos

Client

Total

350

11

361

Report Form:

Merimen

Lump Sum / P.B. /

5050/2

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 11 Nov 2019

Preliminary Advice

Insured Vehicle No	: GBH136B	Accident Date	: 23/10/2019
TP Vehicle No	: SME8728B	Assignment Date	: 25/10/2019
Make	: MAZDA 6	Est. Duration of Repair	: 4
Date of Inspection	: 25/10/2019		
Inspection At	: FASTECH AUTO PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,515.20
Revised Amount	:S\$	5,050.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,050.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

☐ The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

☐ The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

☒ Other comments :The above survey was conducted on a 'Without Prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd Status
Main	24 Oct 2019		25 Oct 2019 15:53 Assign			New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LUM CHANG BUILDING CONTRACTORS PTE LTD, Co. Reg. No.: 197000827K		
Main Claimant:	UNKNOWN5036		
Vehicle Reg. No.:	SME8728B	Date of Loss:	23/10/2019 06:00 - :59
Claim Type:	TP / CMTD1905036	Policy/Cover Note No.:	D19MTPCVE001767 (Comprehensive)
Vehicle Reg. No. (Insured):	GBH136B	Policy No. (Claimant):	
		Excess:	
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/11/2019]		
Driver/Custodian (Insured):	TAN SWEE CHOON (), NRIC: S2535614D, Tel: +6596629916 Email: -		
Adj Asg. Remarks:	Please assign to Marcus		

ASSOCIATED MAIL RECEIVED

View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SME8728B (CMTD1905036)
[GBH136B]**

TP

UNKNOWN5036

Oct 23 2019 6:00AM

[LUM CHANG BUILDING CONTRACTORS PTE LTD]

Fastech Auto Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **29/10/2019 15:09 PM.**
To pauloong.gnoh@sompo.com.sg
CC sur@lkkauto.com
Subject **SME8728B (CMTD1905036) [GBH136B] TP**

Dear Pau Loong,

Please be informed that we have inspected the vehicle SME 8728B on 25/10/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Toyota Owners please
come in!

Electric cars

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Best Bmw X2 M Sport On Sales. Pmi Warranty.



In House Loan Available. Very
Low Mileage. High Trade In. Call
Now!
Speedo Motoring StarAd

- Free VICOM evaluation
- Free grooming and 6 months maintenance
- In-house workshop ensures quality service
- Member of SVTA and hire purchase association
- 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted









20 results/page

11 vehicles

mazda 6

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	mazda 6		Any	Any	2016	Any	Any	Any	Available
	Mazda 6 2.0A		\$70,800	\$9,750 /yr	27-Jan-2016	1,998 cc	67,281 km	Luxury	Available
New Arrival, 1 Single Owner With Fully Serviced At Agent Eurokars To Date. Drive Brilliantly, Smooth Operation. Pristine Condition Inside...									
Posted: 21-Oct-2019 Tags: 2016 Mazda 6, 2016 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda									
	Mazda 6 2.0A		\$74,800	\$10,050 /yr	18-Apr-2016	1,998 cc	70,272 km	Luxury	Available
Ongoing Sales, Price Reduced! Previous Car Enthusiast Owner. Well Taken Care. Depreciation Cheaper Than New. Call Us To Have A Bet...									
Ezy-1 Pte Ltd									
Posted: 21-Oct-2019 Tags: 2016 Mazda 6, 2016 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda									
	Mazda 6 2.0A Executive		\$73,800	\$9,310 /yr	29-Jun-2016	1,998 cc	79,000 km	Luxury	Available
Graded B by STP									
Excellent Condition! High Paper Value, Buy With A Peace Of Mind From Award Accredited Company! Attractive Loan Packages Interest R...									
Autolink Holdings Pte Ltd									
Posted: 20-Oct-2019 Tags: 2016 Mazda 6, 2016 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda									
	Mazda 6 2.0A		\$71,500	\$9,250 /yr	17-Jun-2016	1,998 cc	44,000 km	Luxury	Available
CHEAPEST IN THE MARKET! 100% Loan Approval! High Loans Welcomed! 1 Year Warranty Provided! 100% Accident Free! Low Genuine...									
Posted: 20-Oct-2019 Tags: 2016 Mazda 6, 2016 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda									
	Stainless Steel Window Chrome Moulding Stainless Steel Window Chrome Moulding (For Mazda 6 2009) More info about this product								
	Mazda 6 2.0A		\$76,888	\$9,270 /yr	28-Nov-2016	1,998 cc	49,888 km	Luxury	Available
1 Owner With Low Mileage Done. Regular Serviced And Maintained Unit Still Under Agent Warranty. Still In Original Condition And Paint...									
Posted: 19-Oct-2019 Tags: 2016 Mazda 6, 2016 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda									
	Mazda 6 2.0A		\$70,800	\$9,670 /yr	19-Jan-2016	1,998 cc	72,164 km	Luxury	Available
1 Owner Only! Fully Agent Maintain. In Great Condition! Don't Miss This Unit! Bank Or In House Loan Available. Call For More Enquiries!									
Posted: 16-Oct-2019 Tags: 2016 Mazda 6, 2016 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda									
	Mazda 6 2.0A Executive		\$80,800	\$9,350 /yr	30-Dec-2016	1,998 cc	49,000 km	Luxury	Available
Graded A by STP									

Compare

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 512H

Vehicle Details

Vehicle No.: SME8728B

Vehicle to be Exported: No

Intended Deregistration Date: 25 Oct 2019

Vehicle Make: MAZDA

Vehicle Model: MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT

Primary Colour: Blue

Manufacturing Year: 2016

Engine No.: PE20787423

Chassis No.: JM6GJ1072G0239717

Maximum Power Output: 121.0 kW (162 bhp)

Open Market Value: \$22,523.00

Original Registration Date: 28 Jun 2016

First Registration Date: 28 Jun 2016

Transfer Count: 1

Actual ARF Paid: \$23,533.00 11766

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 27 Jun 2026

PARF Rebate Amount: \$17,649.00

Intended COE Rebate Details

COE Expiry Date: 27 Jun 2026

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$57,010.00

COE Rebate Amount: \$38,038.00

Total Rebate Amount: \$55,687.00

The information contained herein is correct as at 25 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/10/2019 11:26
Date Of Accident	23/10/2019 06:45
Exact Location Of Accident	BLK 489A CHOA CHU KANG AVENUE 5 CP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME8728B
Insured/Policyholder	
Name Of Registered Owner	RAYNER GOH
NRIC No	S8209512H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97600900
Alternative Phone No	OTHERS-97600900

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106730317
Cover Note Number	DRIVO PREMIUM

Driver

Name of Driver	RAYNER GOH
NRIC No	S8209512H
Date Of Birth	10/04/1982
Occupation	INDOOR
Date Of Driving Pass	24/05/2004
Driving Experience	15 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97600900
Fax Number	
Contact Number	OTHERS-97600900
Email Address	NOEMAIL

Address	BLK 489A #12-195 CHOA CHU KANG AVENUE 5 SUNSHINE GARDENS
Postcode	681489
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG DIVISION HQ
Police Station Address	ROAD: 2 JURONG WEST AVENUE 5 , POSTCODE: 649482 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 18007910000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.J/20191023/7013;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER/DRIVER (CAPTURED)
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH136B
Vehicle Make/Model/Colour	NISSAN / CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Date of Accident : 25/10/14 Accident Time: 6:54 am (24-HR-Format)
 Accident Place : Blk 489A Choa Chu Kang Ave 5 Carpark
 Vehicle No. (Car Plate No.) : SME 8728B Make/Model: Mazda 6
 Insurance Company : NTUC Policy No: 5106730317
 Owner or Company Name /IC No. : Rayner Goh S8209512H
 Owner or Company Contact No. : 97600900 Owner's Hp _____ Company Tel _____
 DRIVER'S Name / IC No. : As above
 DRIVER'S Date Of Birth : 10/04/1982 DRIVER'S License Pass Date 24/05/2004
 Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: owner
 DRIVER'S Address : Blk 489A Choa Chu Kang Ave 5 #12-195
96814 3681489
 DRIVER'S Contact No./ Alt No. : (1) _____ 2) _____
 DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
 Email Address : _____
 Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
 Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
 Number of Passengers (Including Driver): NO
 Was there any video Captured by car camera: YES \ NO
 Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
 Any Injury (If YES, Pls state): NO

Other Party Driver's Particular (if any)

Vehicle No: <u>GBH 136B</u>	Vehicle No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

* NEW - Passenger's name & gender:



IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A: SME8728B
B: GBH136B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



J/20191023/7013

1 of 2

POLICE REPORT (NP299)

Report No. J/20191023/7013

Police Station Of Origin
Jurong Division HQ
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No:1800-7910000

Date/Time Report Made 23/10/2019 09:10	Vide Report No.	Station Diary No.
Name Of Informant RAYNER GOH	Address APT BLK 489A CHOA CHU KANG AVENUE 5 #12-195 SINGAPORE 681489	
ID Type / ID No. NRIC NO / S8209512H	Contact No. Home/Office: Mobile: 97600900	
Nationality SINGAPORE CITIZEN	Email Address raynergoh@gmail.com	
Occupation TEACHER	Sex Male	Age 37
Institution/School Name	Date of Birth 10/04/1982	Race Chinese
Date/Time Of Incident 22/10/2019 19:30 - 23/10/2019 07:15	Language English	
	Location Of Incident APT BLK 489A CHOA CHU KANG AVENUE 5 #12-195 SINGAPORE 681489	

Brief details.

On 23 October 2019, at about 7.05am I was on my way to work, and when I reached my car, which is parked at 489 Choa Chu Kang ave 5 multi storey carpark level 3A lot number 127, I discovered that my front driver side headlamp was collided into. There are also dents and scratch marks on my bumper. The perpetrator did not leave any contact behind to claim responsibility.

Subjects Involved

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Signature Of Informant:

The identity of the person making this
report has been authenticated by
SingPass. No signature is required.

Date/Time:

23/10/2019 09:10

Classification Of Case:

Authentication Stamp



**SINGAPORE
POLICE FORCE**



J/20191023/7013

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20191023/7013

Victim				
Person Name	RAYNER GOH			
ID Type	NRIC NO	ID No	S8209512H	
Gender	Male	Age	37	
Race	Chinese	Language	English	
Occupation	TEACHER	Address Type		
Address	APT BLK 489A CHOA CHU KANG AVENUE 5 #12-195 SINGAPORE 681489		Mobile No	97600900
Is Informant A Victim?	Yes			
Person Name	RAYNER GOH (Informant)			

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Authentication Stamp

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:

23/10/2019 09:10

Classification Of Case:

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

VEHICLE No: SME 8728B

1PC	FRONT BUMPER	1211.90
1PC	FRONT BUMPER SIDE RETAINER O/S	14.70
1SET	FRONT BUMPER CLIPS	
1PC	FRONT BUMPER REINFORCEMENT	
1PC	FRONT BUMPER FOG LAMP COVER O/S	101.90
1PC	FRONT BUMPER FOG LAMP O/S	325.50
PC	FRONT BUMPER CHROME MOULDING O/S	
1PC	FRONT GRILLE	
1PC	BONNET	
1PC	HEADLAMP O/S	450
1PC	FRONT FENDER O/S	383.70
1PC	FRONT FENDER INNER SHIELD O/S	102.70
1SET	FRONT FENDER INNER SHIELD CLIPS	
1PC	WIPER WASHER TANK	
1PC	FRONT SPORT RIM O/S	850
1PC	FRONT KNUCKLE ARM O/S	

not Allowed
after
25/10/18
4 day. 2/5 5050
take photo after repair

Dis	\$1,488.20	✓
cre	\$66.50	✓
mer	\$50.00	✓
11	\$641.50	X
1m	\$122.50	✓
cre	\$366.20	✓
11	\$284.50	X
11	\$688.20	X
2	\$1,022.30	X
cre	\$3,220.00	✓
Bent/Gen	\$675.20	✓
re	\$211.40	✓
mer	\$50.00	✓
re	\$188.50	✓
car/bet	\$1,205.00	✓
11	\$455.20	X
202	\$10,735.20	

TO CHECK WIRING
TO SPRAY RUST PROOFING
TO CONDUCT WHEEL ALIGNMENT
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

	\$50.00	30
	\$50.00	30
	\$120.00	60
	\$680.00	400
	\$880.00	600
TOTAL	\$12,515.20	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal communication(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

6499.1
5199.28
6319.28
2052.42

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19018995/UVF3N2

Date: 14/11/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPCVE001767
Claimant Vehicle No :	SME8728B	Insured Vehicle No :	GBH136B
Date of Loss:	23/10/2019	Nature of Claim:	TP
		Claim No:	CMTD1905036

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME8728B	Engine No:	PE20787423
Make & Model:	MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A)	Chassis No:	JM6GJ1072G0239717
Reg. Date:	28/06/2016 (Man. Year: 2016)	Odometer:	57856 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,735.20	5,199.28	5,535.92	51.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	1,120.00	660.00	37.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,515.20	6,319.28	6,195.92	49.51
Approved Total (Overridden) (\$\$)		5,050.00		
(\$\$)	12,515.20	5,050.00	7,465.20	59.65
+ GST 7.00/7.00% (\$\$)	876.06	353.50	522.56	59.65
Nett Amount (\$\$)	13,391.26	5,403.50	7,987.76	59.65

INSPECTION

Date of Assignment: 25/10/2019

Date Inspected: 25/10/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Nov 2019)
Parts:	143	MAZDA 6 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME8728B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,488.20 F	*1,211.90 FL
2	1		*FRONT BUMPER SIDE RETAINER O/S	Cracked	66.50 F	*14.70 FL
3	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	641.50 F	*- FL
5	1		*FRONT BUMPER FOG LAMP COVER O/S	Twisted	122.50 F	*101.90 FL
6	1		*FRONT BUMPER FOG LAMP O/S	Cracked	366.20 F	*325.50 FL
7	1		*FRONT BUMPER CHROME MOULDING O/S	Not Necessary	284.50 F	*- FL
8	1		*FRONT GRILLE	Not Necessary	688.20 F	*- FL
9	1		*BONNET	Repair	1,022.30 F	*- FL
10	1		*HEADLAMP O/S	Cracked	3,220.00 F	*3,220.00 FL
11	1		*FRONT FENDER O/S	Bent/Buckled	675.20 F	*383.70 FL
12	1		*FRONT FENDER INNER SHIELD O/S	Deformed	211.40 F	*102.90 FL
13	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 F	*50.00 FL
14	1		*WIPER WASHER TANK	Deformed	188.50 F	*188.50 FL
15	1		*FRONT SPORT RIM O/S	Cut/Bent	1,205.00 F	*850.00 FL
16	1		*FRONT KNUCKLE ARM O/S	Not Necessary	455.20 F	*- FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	10,735.20	6,499.10
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,299.82
Total Parts (\$\$)	10,735.20	5,199.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO SPRAY RUST PROOFING	New	50.00	30.00
3	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
4	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	680.00	400.00
5	TO PUTTY & SPRAY PAINTING	New	880.00	600.00
Gross Labour Cost (S\$)			1,780.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >