

ASS. REC. BY:

REF: CS/AIG MO19035/Q+f307

Special Instruction:

Survivor Sun PinASSIGNMENT (Office)From (Person): Hor Yinnul

of

AIGDate/Time: 25.10.2019 4:35p.m

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLW 8010EInsured: SLA 9590Gat Workshop m/s Toh Ah Swee SprmTel: 63660281of 60 John Lam Hwat # 07-33/34

Policy No: _____

Claim No: _____

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. 2.10.1019

CA / REV / REP. / REV 24 HRS

Date/Time: 29.10.19 8:42a.mPerson Contacted: Sally

H.O.D. Endorsement: _____

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLW 8010E - X
	SLA 9590G - X

REF: Sun Pin

REF: A19

ASSIGNMENT

From: 30. 10. 2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 8010E

at Workshop no: Toh kh swa spray

of 60 Jalan Lam Hual #07-33/34

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh: Aser 10 a.m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/> N/S	<input checked="" type="checkbox"/> O/S

Bail. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"ny"

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLW 8010E Yr Regn: 02/Mar/2018

Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Camry Hybrid 2.54 cc 2487

Colour: White. A/C: Insured / Std / NI / NA

Sp. Reading: 110251 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: AXVH701000520

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215 / 55 R17

R: 215 / 55 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 22/10/2019 D.O.I. 30/10/2019

Survey held at Toh

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Mv: 92K

RECEIVED 14 NOV 2019

One/Time. File Pass to?

☐ : Preli. Report

1) 14/11 Typist

☒ : Final Report

One/Time. File Return to?

3)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Travel and (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Rep. Format: TP

Lump Sum / R.R. : \$ 1400/-

240

11

261

PRE-REPAIR INSPECTION REQUEST – SLW8010E vs SLA9590G (OI) on D.O.A.: 22/10/2019

From: Hor, Yinnui
 To: assignments@ikauto.com, Admin A (admin-a@ikauto.com)
 Cc: Fong, Andy-SY; Fan, Winnie-LW; Abu Kassim, Noor Marissa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Div
 Sent: Friday, 25 October, 2019 4:35:07 PM
 Attachments: 1573_001.pdf; 1573_001.pdf

Hi,

Please refer to the enclosed request from Vision Law LLC.

Claim no : 7803282306SG003
 Case Owner : Loh Chee Hong

If you have any queries/concerns, please let us know.
 Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rui (Viviane)
 AIG
 FWDOL Adjuster I
 Singapore FWDOL | Claims Operations – Auto

Tel: 8001208556 | Ext: 1002208
 Yinnui.Hor@aig.com | www.aig.sg

From: Hor, Yinnui
 Sent: Friday, October 25, 2019 3:28 PM
 To: 'jactan@visionlawllc.com'
 Cc: Fong, Andy-SY; Fan, Winnie-LW; Abu Kassim, Noor Marissa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni
 Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLA9590G AND SLW8010E ON 22/10/2019

Without Prejudice

Your Reference : AM.jt.lns.T4.SLW8010E.19 (sj)
 Our Reference : 7803282306SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasid	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rui (Viviane)
 AIG
 FWDOL Adjuster I
 Singapore FWDOL | Claims Operations – Auto

Tel: 8001208556 | Ext: 1002208
 Yinnui.Hor@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths

Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNANDY
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAN YINGXIAN, BELWYN
CHEONG YUNHUI, CLARISSA
SONIA LIM WEI LIE

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com
BRANCH
TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO **HEAD OFFICE** FOR THIS MATTER

Our Ref: AM.jt.Ins.T4.SLW8010E.19 (sj)
Your Ref: SLA 9590 G

25 October 2019

AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attention: Motor Claims Department

Email: claimsdcmmanagement@aig.com
Email: noormariesa.abukassim@aig.com
Email: shengyang.lim@aig.com
Email: Syazairdina.Azlan@aig.com
Email: yinhul.hor@aig.com
Email: Lee-ying.chin@aig.com

Dear Sirs,

ACCIDENT INVOLVING SLW 8010 E & SLA 9590 G ON 22 OCTOBER 2019 ALONG YISHUN AVENUE 2 TOWARDS KHATIB MRT AT ABOUT 1905 HOURS
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We are instructed by Oh Hang Leng (Hu Hanlong) to notify you of a road traffic accident on **22 OCTOBER 2019** at about **1905 HOURS** at/along **YISHUN AVENUE 2 TOWARDS KHATIB MRT** involving our client's vehicle registration number **SLW 8010 E** and vehicle registration number **SLA 9590 G** driven by you/your insured at the material time

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully


ANJALLI M
(HEAD OFFICE)

cc: **SLW 8010 E** – By Email: claims@tohahswee.com.sg only

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHENG BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HEIEN
PAUL YAP TAI SAN
ANJALLI DIO MUNTANDY
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAN YINGDIAN, SELIYYN
CHEONG YUNHUI, CLARISSA
SONIA LIM WEE LEE

Unique Entity Number :200721148H

✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.Ins.T4.SLW8010E.19 (sj)
Your Ref: 7803282306SG-003

25 October 2019

AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attention: Motor Claims Department

Email: claimsdocmanagement@aig.com
Email: noormariesa.abukassim@aig.com
Email: shengyang.lim@aig.com
Email: Syazairdina.Azlan@aig.com
Email: yinhui.hor@aig.com
Email: Lee-ying.chin@aig.com

Dear Sirs,

ACCIDENT INVOLVING SLW 8010 E & SLA 9590 G ON 22 OCTOBER 2019 ALONG YISHUN AVENUE 2 TOWARDS KHATIB MRT AT ABOUT 1905 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We refer to your email 25 October 2019 of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Kenneth Kong from LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: Toh Ah Swee Spray Painting Co
60 Jalan Lam Huat
#07-33/34 Carros Centre
Singapore 737869
Contact Person: Toh Ah Swee: 6366-0286

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

cc: SLW 8010 E

cc: SLW 8010 E By Email: claims@tohahswee.com

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you.

1st Survey on _____
Appointed surveyor _____
(Name & Signature)

2nd Survey on _____
Appointed surveyor _____
(Name & Signature)

3rd Survey on _____
Appointed Surveyor _____
(Name & signature)

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

Oi Sun Pin (LKK Auto)

From: claims claims <claims@tohahswee.com.sg>
Sent: Wednesday, 13 November, 2019 2:51 AM
To: Oi Sun Pin (LKK Auto)
Subject: Re: FINALIZATION FOR VEHICLE SLW8010E

Dear Sun Pin,

Confirm acceptance for the finalized at L/S \$1,400.00 and 3 working days.

Please submit your surveyor report directly to AIG, this case is handling by our client's lawyer.

Thanks & Best Rgds,
Sally Ang
Toh Ah Swee Spray Painting Co.
Tel: 63660286
Fax: 63685943

P/S: Please be informed that our company will be relocate to 60 Jalan Lam Huat #07-33/34 Carros Centre S737869 with effective from 22/04/2019.

On Mon, Nov 11, 2019 at 2:53 AM Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com> wrote:

Dear Sally,

Please refer our finalize adjustment estimate update. L/S amount COR \$ 1400, DOR 3 days. (Lump sum repair, before gst).

Please refer the adjustment amount. If agree please update ASAP.

Thanks you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315

Vehicle Details

Vehicle ID:	Make / Model
SLW8010E	TOYOTA / CAMRY HYBRID 2.5G CVT
Vehicle Type :	Vehicle Attachment 1 :
Z10 - Private Hire (Chauffeur) Motor Car	No Attachment
Vehicle Scheme :	Chassis No. :
Normal	AXVH701000520
Propellant :	Engine No. :
Petrol-Electric	A25A0015435
Motor No. :	Engine Capacity :
10E117601830	2487 cc
Power Rating :	Maximum Power Output :
88.0 kW	155.0 kW (207 bhp)
Maximum Laden Weight :	Unladen Weight :
1845 kg	1570 kg
Year Of Manufacture :	Original Registration Date :
2017	02 Mar 2018
Lifespan Expiry Date :	COE Category :
-	B - Car above 1600cc or 97kW (130bhp)
Quota Premium :	COE Expiry Date :
\$39,000.00	01 Mar 2028
Road Tax Expiry Date :	PARF Eligibility Expiry Date :
01 Mar 2020	01 Mar 2028
Inspection Due Date :	Intended Transfer Date :
01 Mar 2021	25 Oct 2019
CO2 Emission :	CEV/VES Rebate Utilised Amount :
98.00 (g/km)	\$10,000.00
CO Emission :	HC Emission :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8791
Vehicle Details	
Vehicle No.:	SLW8010E
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY HYBRID 2.5G CVT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	A25A0015435
Chassis No.:	AXVH701000520
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$36,251.00
Original Registration Date:	02 Mar 2018 / 8 yrs 5 mths / 101 mths
First Registration Date:	02 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$32,752.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Mar 2028
PARF Rebate Amount:	\$24,564.00
Intended COE Rebate Details	
COE Expiry Date:	01 Mar 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,000.00
COE Rebate Amount:	\$32,510.00
Total Rebate Amount:	\$57,074.00

The information contained herein is correct as at 30 Oct 2019

OK

$$11,000 / 12 = 916.$$

$$916 \times 101 \text{ mths} = 92,516$$

$$MV = 92,516$$



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Classic - Premium Best Deal/Fast Selling/Hurry Down Now!



Personal Loan: From 2% to 11%
Interest Rate, 24 Months - 60 Months Tenure
For Repayment Plan
Classic Credit

HIN LUNG AUTO
Ho Bee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years
of car sale

[Browse by Category](#)
[Sort by Date Posted](#)
[20 results/page](#)

6 vehicles

TOYOTA CAMRY

[Advanced Search](#)

Model	Price	Depreciation	Post Date	Eng Cap	Mileage	Veh Type	Status
Search Selection TOYOTA CAMRY	Any	Any	2018	Any	Any	Any	Available
 Toyota Camry 2.5A 1 Owner, Warranty By Borneo Motors, Well Maintained, Trade In Are Welcome. Call/SMS Now For Viewing Appointment. Borneo Motors (5) Posted: 18-Oct-2019 Topic: 2018 Toyota Camry, 2018 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota	\$117,800	\$12,000 /yr	26-Feb-2018	2,494 cc	18,500 km	Luxury	Available
 Toyota Camry Hybrid 2.5A G Fuel Type: Petrol-Electric Look No Further! Cheapest Hybrid Camry In Town With Beautiful Pearl White On Black Interior! 1 Meticulous Owner! Low Mileage! Super Low Fuel Consumption At 18-21KM/L, Buy With Additional Peace Of Mind From Vantage Pre-Owned With Our Comprehensive 72 Points... Vantage Pre-Owned Posted: 26-Oct-2019 Topic: 2018 Toyota Camry, 2018 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota	\$112,800	\$11,450 /yr	20-Apr-2018	2,487 cc	13,600 km	Luxury	Available
 Toyota Camry Hybrid 2.5A G Fuel Type: Petrol-Electric 5 Years Warranty! Free 3 x Servicing! 2019 Model! Ready Stock Available For Immediate Registration. Flexible Loan Available. Kindly Call Us To Discuss! Price Inclusive Of GST. Shuang Hup Credit Posted: 27-Oct-2019 Topic: 2018 Toyota Camry, 2018 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota	\$123,800	\$12,050 /yr	17-Oct-2018	2,487 cc	41 km	Luxury	Available
 Toyota Camry Hybrid 2.5A Ascent Fuel Type: Petrol-Electric Showroom Condition. Latest Facelifted Toyota Camry Hybrid. Low Interest Rate. Flexible Loan Package. Call/SMS For More Details. Posted: 26-Oct-2019 Topic: 2018 Toyota Camry, 2018 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota	\$112,800	\$11,130 /yr	02-Nov-2018	2,487 cc	-	Luxury	Available
 New Camry awarded five-star safety rating The new Toyota Camry has been awarded a five-star safety rating from the New Car Assessment Program for Southeast Asian Countries. Read this article							
 Toyota Camry Hybrid 2.5A G Fuel Type: Petrol-Electric Auction Closing Time: 4th Nov 2019 at 05:00 PM Keys Available, Mileage 15,304, Road Tax Expiry 5/Dec/2019. Posted: 24-Oct-2019 Topic: 2018 Toyota Camry, 2018 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota	-	N.A	06-Dec-2018	2,487 cc	15,304 km	Luxury	Available
 Toyota Camry 2.5A New Car \$149.8K! Borneo Motor Unit With 5 Years Agent Warranty! Not PI Unit! Full Loan Available! We Can Help To Convert To Z10 Usage If Needed, In House Loan Or Bank Loan Available! Balloon Scheme Available! Fast, Easy And Flexible Loan Approval! We Are sgC... 88 Motor Trading Posted: 09-Oct-2019 Topic: 2018 Toyota Camry, 2018 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota	\$125,800	\$11,930 /yr	21-Dec-2018	2,494 cc	20,500 km	Luxury	Available

Save to e-mail alerts, to get email alerts whenever a match is found.

[Compare](#)

Model

Price

Depreciation

Eng Cap

Mileage

Veh Type

[Status](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/10/2019 17:28
Date Of Accident	22/10/2019 19:05
Exact Location Of Accident	YISHUN AVE 2 TOWARDS KHARTIB MRT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW8010E
Insured/Policyholder	
Name Of Registered Owner	OH HANG LENG (HU HANLONG)
NRIC No	S7310879I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98783033
Alternative Phone No	OFFICE-98783033

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY 2.4 HYBRID
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098884788-01
Cover Note Number	

Driver

Name of Driver	OH HANG LENG (HU HANLONG)
NRIC No	S7310879I
Date Of Birth	30/03/1973
Occupation	OUTDOOR
Date Of Driving Pass	04/08/1997
Driving Experience	22 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98783033
Fax Number	
Contact Number	OFFICE-98783033
Email Address	NOEMAIL

Address	BLK 116 WOODLANDS AVE 5 #12-34
Postcode	7391018
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLA9590G
Vehicle Make/Model/Colour	
Details Of Properties	REFER ATTACHED
Vehicle Category	PRIVATE CAR
Name of Driver	AUDREY
NRIC/Passport Number	
Contact Number	90094347
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/10/2019 @ approx 1907 hrs I was originally at Yishun Ave 2 toward Lantor @ the cross junction of Yishun Ave 1. I was making a U-turn back toward Yishun Ave 2 toward Khatib MRT station. After I made a U-turn, I maintain at lane 3 & cut off sudden vehicle SLA 9590G which was originally from Yishun Ave 1 filter to Yishun Ave 2 hit onto my motorcar left front door. After the hit the motorcar SLA 9590G continue driving without stopping. I chased after the motorcar & back at it then the motorcar SLA 9590G then proceed to stop at busstop. My motorcar suffered dents, scratches on left front of motorcar. I have a in-car camera & the video had been downloaded.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 23/10/19

BA 5pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 23/10/19

6:30 PM

Driver's Signature

(If driver is not the policyholder)

Date & Time: 23/10/19

6:30 PM

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

卓亚水喷漆公司

TOH AH SWEE SPRAY PAINTING CO.

NO 60 JALAN LAM HUAT #07-33/34 CARROS CENTRE SINGAPORE 737869
 TEL: 63660115 (WORKSHOP), 63660286 (OFFICE) FAX: 63685943
 EMAIL: claims@tohahswee.com.sg
 BUSINESS REG. NO: 09935300L

25/10/2019

AIG ASIA PACIFIC INSURANCE PTE LTD

AIG BUILDING
 78 SHENTON WAY #07-16
 SINGAPORE 079120
 ATTN: MOTOR CLAIMS DEPT

ESTIMATED REPAIR BILL

YOUR REF : SLA9590G
 TYPE OF CLAIM : THIRD PARTY CLAIMS
 CLAIMANT : OH HANG LENG (HU HANLONG)
 VEHICLE NO. : SLW8010E
 MAKE/ MODEL : TOYOTA CAMRY HYBRID 2.5G CVT
 ACCIDENT DATE : 22/10/2019

MATERIAL COST

IPC	FRONT FENDER LH	X R	\$	975.00
IPC	EMBLEM "HYBRID"	✓ NEC	\$	151.00 <i>66</i>
IPC	FRONT DOOR LH	X R	\$	2,140.00
IPC	SIDE MIRROR LH	✓ Turned	\$	1,216.00 <i>1094</i>
IPC	SIDE MIRROR COVER LH	X R	\$	227.00
			\$	4,709.00
LESS : DISCOUNT 25%			\$	1,177.25
			\$	3,531.75

LABOUR CHARGE :

TO REMOVE DAMAGED PARTS, TO KNOCK OUT DENTS, TO STRAIGHTEN, ADJUST, CHECK, RESHAPE INCLUDING CUTTING AND WELDING WHERE NECESSARY, TO REMOVE AND REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS, TO REPLACE AND ALIGN THE ABOVE PARTS.

\$ 600.00 *400*

PUTTY AND SPRAY PAINTING ON RHS BODY AND ABOVE NEW AND REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS

\$ 700.00 *500*

ADD : GST 7%

\$ 4,831.75

TOTAL :

\$ 338.22

\$ 5,169.97

SINGAPORE DOLLARS : FIVE THOUSAND ONE HUNDRED SIXTY NINE AND CENTS NINETY SEVEN ONLY.

NOTE: THE ESTIMATED PERIOD OF REPAIRS IS FIVE (5) DAYS

TOH AH SWEE SPRAY PAINTING CO.

SALLY ANG (TEL : 63660286)

3 days

[Signature]
 3/10/19

Sun Pm 8661 2627

Lump sum Repair

After paint photo

Tip without Prejudice

Sunpin@lkkartito.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

卓亚水喷漆公司

TOH AH SWEE SPRAY PAINTING CO.

NO 60 JALAN LAM HUAT #07-33/34 CARROS CENTRE SINGAPORE 737869
 TEL: 63660115 (WORKSHOP), 63660286 (OFFICE) FAX: 63685943
 EMAIL: claims@tohahswee.com.sg
 BUSINESS REG. NO: 09935300L

25/10/2019

AIG ASIA PACIFIC INSURANCE PTE LTD

AIG BUILDING
 78 SHENTON WAY #07-16
 SINGAPORE 079120
 ATTN: MOTOR CLAIMS DEPT

FINALISATION

YOUR REF	: SLA9590G
TYPE OF CLAIM	: THIRD PARTY CLAIMS
CLAIMANT	: OH HANG LENG (HU HANLONG)
VEHICLE NO.	: SLW8010E
MAKE/ MODEL	: TOYOTA CAMRY HYBRID 2.5G CVT
ACCIDENT DATE	: 22/10/2019

MATERIAL COST

1PC	FRONT FENDER LH	\$	-
1PC	EMBLEM "HYBRID"	\$	151.00 55
1PC	FRONT DOOR LH	\$	-
1PC	SIDE MIRROR LH	\$	1,216.00 094
1PC	SIDE MIRROR COVER LH	\$	-
		\$	1,367.00 149
		\$	341.75 287.2
		\$	1,025.25 861.1

LESS : DISCOUNT 25%

LABOUR CHARGE :

TO REMOVE DAMAGED PARTS, TO KNOCK OUT DENTS, TO STRAIGHEN, ADJUST, CHECK, RESHAPE INCLUDING CUTTING AND WELDING WHERE NECESSARY, TO REMOVE AND REINSTALL NECESSARY FITTINGS TO FACILIATE REPAIRS , TO REPLACE AND ALIGN THE ABOVE PARTS.

\$ 400.00 ✓

PUTTY AND SPRAY PAINTING ON RHS BODY AND ABOVE NEW AND REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS

\$ 500.00 ✓

\$ 1,925.25

LUMP SUM - COR
 3 WORKING DAYS

\$ 1,540.00

L/S = 1,400

P - 861.75
 L - 900
1,761.75
 -20% 352.35
1,409.4





























...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Oct 2019 Edit Reg		25 Oct 2019 00:00 Edit Adj Rpt	S\$1,400.00 Edit Estimates	S\$1,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: ANG TZE WEI , ID: 578296421									
Main Claimant: OH HANG LENG (HU HANLONG) , Co. Reg. No.: -									
Vehicle Reg. No.: SLW8010E		Date of Loss: 22/10/2019 00:00 - :59 [19 Months and 20 Days From LTA Reg Date (Man Yr)]							
Claims Type: TP / 7803282306SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SLA9590G		Policy No. (Claimant):							
		Excess:							
Repairer: Toh Ah Swee Spray Painting Co. (HQ) 60 Jalan Lam Huat, #07-33/34 Carros Centre, 737869 Sungei Kadut - Tel: 63660115, 63660286									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Final Rpt due 07/11/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (30/10/2019): TP GIA report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLW8010E (7803282306SG)
[SLA9590G]
TP
OH HANG LENG (HU HANLONG)
Oct 22 2019 12:00AM
[ANG TZE WEI]
Toh Ah Swee Spray Painting Co.

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser ▼	
Photos/Images										3 per page ▼ <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
2	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
3	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
4	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
5	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
6	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
7	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
8	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
9	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
10	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
11	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
12	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
13	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
14	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
15	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
16	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
17	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
18	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
19	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
20	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
21	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
22	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
23	14/11/19 10:54	General View							<input checked="" type="checkbox"/>		
24	14/11/19 10:54	Reinspection Photo							<input checked="" type="checkbox"/>		
25	14/11/19 10:54	Reinspection Photo							<input checked="" type="checkbox"/>		
26	14/11/19 10:54	Reinspection Photo							<input checked="" type="checkbox"/>		
27	14/11/19 10:54	Reinspection Photo							<input checked="" type="checkbox"/>		
Documentation										1 per page ▼ <input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	30/10/19 16:21	OI GIA REPORT							<input type="checkbox"/>		

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19019035/QTF3E2

Date: 14/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No: SLW8010E Insured Vehicle No: SLA9590G

Date of Loss: 22/10/2019 Nature of Claim: TP Claim No: 7803282306SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW8010E	Engine No:	A25A0015435
Make & Model:	TOYOTA CAMRY, 2.4 HYBRID (A)	Chassis No:	AXVH701000520
Reg. Date:	02/03/2018 (Man. Year: 2017)	Odometer:	110251 km
Colour:	White		
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,531.75	861.75	2,670.00	75.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	900.00	400.00	30.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,831.75	1,761.75	3,070.00	63.54
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	4,831.75	1,400.00	3,431.75	71.02
+ GST 7.00/7.00% (S\$)	338.22	98.00	240.22	71.02
Nett Amount (S\$)	5,169.97	1,498.00	3,671.97	71.02

INSPECTION

Date of Assignment: 25/10/2019

Date Inspected: 30/10/2019 Inspected At:

Toh Ah Swee Spray Painting Co. (HQ)
60 Jalan Lam Huat, #07-33/34 Carros
Centre
Singapore 737869

Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Repair	975.00 FL	*- FL
2	1		*EMBLEM HYBRID	Necessary	151.00 FL	*55.00 FL
3	1		*FRONT DOOR LH	Repair	2,140.00 FL	*- FL
4	1		*SIDE MIRROR LH	Jammed	1,216.00 FL	*1,094.00 FL
5	1		*SIDE MIRROR COVER LH	Repair	227.00 FL	*- FL
					Sub Total (S\$)	4,709.00
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,177.25
					Total Parts (S\$)	3,531.75

F=Franchise part; L=ListItemDisc.

1,149.00

287.25

861.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE DAMAGED PARTS, TO KNOCK OUT DENTS, TO STRAIGHTEN, ADJUST, CHECK, RESHAPE INCLUDING CUTTING AND WELDING WHERE NECESSARY, TO REMOVE AND REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS, TO REPLACE AND ALIGN THE ABOVE PARTS	New	600.00	400.00
2	PUTTY AND SPRAY PAINTING ON RHS BODY AND ABOVE NEW AND REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS	New	700.00	500.00
Gross Labour Cost (S\$)			1,300.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >