

ASS. REC. BY:

REF: CS3/CTI19019055/Hcf362

Special Instructions:

Surveyor: Hock Ann

ASSIGNMENT (Office)

From (Person): (Chang) Brian Sen of CTI Date/Time: 29.10.19 1.23p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMD 54285 Insured: SKW 9067Y

at Workshop n/a: Xin Yun Auto Tel: 98391555

of Blk 8 Kallie Bukit Ave 4 #05-23 Premier

Policy No: DMP/CSN 30736819000 Claim No: SVM190205057C12

Sum Insured: Excess:

Make of Veh: D.O.A. 26.10.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 29.10.19 1.23p.m Person Contacted: Li Ping H.O.D. Endorsement: Vehicle (IN) OUT


Date/Time	Action/Instruction (X) Estimate
	SMD 54285 - NBA / CTI 19019055/19 DOA - 23/10/2019
	SKW 9067Y - NBA / CTI 19019055/19 DOA - 23/10/2019
08/11/19	Submit PRS.
	Dismantle: 30/10/2019.
	After repair: 1/11/2019

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SMD 54285
 at Workshop / Ins: Vin Van Auto private limited
 of Blk 8 Haki Bulint ave 4 #05
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: _____
 IDAC Accident Report: _____ Consistent? Yes or No
 GIA - PR Seen: _____ Consistent? Yes or No
 Est. Repairs: 3 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Veh No: SMD 54285 Yr Regn: 24/08/18
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: H. Shuttle c.c. 1476
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 137092 T/Radio: Insured / Std / NI / NA

Eng/No: _____

CNo: 40712/3369

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60/R15

R: 185/60/R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Fit and for same (air)

Front

R/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 23/10/19

Survey held at Vin Van Auto

Rear

R/Bal: 6 mm

L/Bal: 6 mm

D.O.I: 29/10/19

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooflop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range → 2800 - 3500

MV - 76000

PV - 37613

NV - 38300

Date/Time For Pass up?

08/10/19

Date/Time For Pass up?

☐ : Prelim Report

☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Insp (\$)

☐ : Visual Insp (\$)

Survey Fee:

Transportation:

\$ + RS \$

Phone

Other

Total

190

190

Signature of Insurer

Signature of Insured

Pres.

Summer Lee (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 29 October, 2019 1:23 PM
To: prs.pd@slawch.com
Cc: 'Xin Yun Auto'; assignments
Subject: RE: OUR REF: SNM19D205057-SKW9067Y-CBS & YOUR REF: PD.190687/LP -TO CONDUCT PRS- SMD54285

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: prs.pd@slawch.com [mailto:prs.pd@slawch.com]
Sent: Tuesday, October 29, 2019 11:18 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: 'Xin Yun Auto' <xinyunauto1@gmail.com>
Subject: RE: OUR REF: SNM19D205057-SKW9067Y-CBS & YOUR REF: PD.190687/LP -TO CONDUCT PRS- SMD54285

WITHOUT PREJUDICE

Dear Sir/Mdm,

ACCIDENT INVOLVING SMD5428S & SKW9067Y ALONG JURONG BRICKLAND TOWARDS SUNGEI TEI

We refer to your email dated **25 October 2019** confirming your intention to conduct a pre-repair survey on our client's vel

We have instructions to reject your surveyor and propose to engage a surveyor from the list below:-

- 1) Roger S.S.Gan (Licensed Appraiser) from Rog Associates
- 2) Michael Yap from Mc-coy Appraisals Pte Ltd
- 3) Sebastian Lim (Licensed Appraiser) from Constant Appraiser Services
- 4) Alan Cheong K.H from CL Appraiser
- 5) Mr. Sim from (Licensed Appraiser) Skycam Automobile Surveyor Services

Please be informed that said vehicle can be inspected at:

Workshop:

Address:

Contact Person:

Xin Yun Auto Private Limited

Blk 8 Kaki Bukit Ave 4 #05-23 Premier @ Kaki Bul

Yi Xin (HP: 9839 1555) / Fabian (HP: 9839 1666)

In the event you fail to conduct the pre-repair survey within the next 2 working days, excluding any intervening Saturday, :

For Surveyor: To initial after Completion

1st Inspection

Appointed surveyor

(Name & Siganature)

Date & Time

2nd Inspection

Appointed surveyor

(Name & Siganature)

Date & Time

3rd Inspection

Appointed surveyor

(Name & Siganature)

Date & Time

Regards

Li Ping

Did: 6909 5194

11 Keng Cheow Street #02-03 Riverside Piazza Singapore
059608



This e-mail is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, arrive late or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message which may arise as a result of Internet transmission.

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent: Friday, 25 October 2019 5:51 PM

To: Prs.pd <prs.pd@slawch.com>

Subject: RE: OUR REF: SNM19D205057-SKW9067Y-CBS & YOUR REF: PD.190687/LP -TO CONDUCT PRS- SMD5428S

Without prejudice

Dear Sir,

LKK

STA

LBS

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Friday, October 25, 2019 4:26 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Prs.pd <prs.pd@slawch.com>

Subject: OUR REF: SNM19D205057-SKW9067Y-CBS & YOUR REF: PD.190687/LP -TO CONDUCT PRS- SMD5428S

Dear Boon Sen,

Please conduct PRS -SMD5428S soonest possible.

File with officer-in-charge Chong Boon Sen –DID 6389 6171

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website:www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: prs.pd@silawch.com [mailto:prs.pd@silawch.com]

Sent: Friday, 25 October, 2019 2:37 PM

To: Claims Dept of CTI

Cc: 'Xin Yun Auto'

Subject: Urgent accident involving SMD5428S & SKW9067Y on 23/10/2019. Our Ref: PD.190687/LP

WITHOUT PREJUDICE

Dear Sir/Mdm,

ACCIDENT INVOLVING SMD5428S & SKW9067Y ALONG BRICKLAND ROAD TOWARDS SUNGEI TENG

1. We are instructed to notify you of a road accident on 23 October 2019 at about 20:00 hours along Brickland Road. Your client's vehicle registration number SMD5428S and vehicle registration number SKW9067Y driven by your insured at the time of the accident is enclosed.

2. As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, we would like to know if you would like to conduct a pre-repair survey of the vehicle. If we do not receive your response within 7 days of your receipt of this notice, our client shall proceed to repair the vehicle without further reference to you.

Regards

Li Ping

Did: 6909 5194

11 Keng Cheow Street #02-03 Riverside Piazza Singapore 059608



This e-mail is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, arrive late or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message which may arise as a result of Internet transmission.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	032B
Vehicle Details	
Vehicle No.:	SMD54285
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	LEB6556242
Chassis No.:	GP71213369
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$21,456.00
Original Registration Date:	24 Aug 2018
First Registration Date:	24 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$12,039.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Aug 2028
PARF Rebate Amount:	\$9,029.00
Intended COE Rebate Details	
COE Expiry Date:	23 Aug 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,429.00
COE Rebate Amount:	\$28,584.00
Total Rebate Amount:	\$37,613.00

The information contained herein is correct as at 30 Oct 2019

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Price Selling \$35,800/Interest Rate From 3.88% Month



Price Selling \$35,800/Interest
Rate From 3.88% Monthly (2
\$900 New 5 Years COE
Car World Automobile



Browse by Category

< Back (1 2) Next >

Sort by Date Posted

20 results/page

22 vehicles

Honda Shuttle

Advanced Search



Search Selection

Honda Shuttle

Any

Any

2018

Any

Any

Any

Available



Honda Shuttle Hybrid 1.5A

\$79,800

\$9,170 /yr

03-Apr-2018

1,496 cc

-

Stationwagon

Available

Fuel Type: Petrol-Electric

Low Fuel Consumption, In House Loan Available, 3 Years Or 100,000km Warranty, 3 x Free Servicing. Call Our Friendly Salesperson Now!

Posted: 29-Oct-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle Hybrid 1.5A X

\$77,500

\$8,750 /yr

25-May-2018

1,496 cc

20,000 km

Stationwagon

Available

Fuel Type: Petrol-Electric

Road Tax Just Renew! Selling With Number Plate. Driven By 1 Mature Owner Only! Selling At The Same Deprecation As Petrol Model And Save More On Fuel At 25km/L! Perfect Gloss Black Paintwork In Showroom Condition! High Grade Burgundy Leathers Has Been Selected...

Posted: 29-Oct-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle Hybrid 1.5A

\$77,888

\$8,810 /yr

18-May-2018

1,496 cc

10,000 km

Stationwagon

Available

Fuel Type: Petrol-Electric

Owned This Car With 95% Loan As Indicated, One Single Underutilized Unit, Extremely Low Mileage Clocked, Hybrid Systems Making Tons Of Saving On Petrol, Body Type Design To Be A Mini Station Wagon, Allowing Ample Space Storage, 99% Brand New Feels And S...

Posted: 28-Oct-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle Hybrid 1.5A

\$75,800

\$8,750 /yr

15-Mar-2018

1,496 cc

22,000 km

Stationwagon

Available

Fuel Type: Petrol-Electric

New Arrival! (1st Owner Unit!) Cheapest In Town! Hybrid Edition! (This Is Not A P/H Vehicle!) Best Selling Stationwagon! Genuine Low Mileage Done Of 22000km Only! Full Service Record! Very Mint Condition! Interior & Exterior Looks Like New! Drives Like A New Car! S...

Posted: 27-Oct-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Fit Shuttle goes on sale in Japan

Honda has announced the launch of the much-awaited Fit Shuttle in Japan, which was delayed due to problems arising from the Japanese earthquake in March

Read this article



Honda Shuttle Hybrid 1.5A

\$77,900

\$8,760 /yr

28-May-2018

1,496 cc

-

Stationwagon

Available

Fuel Type: Petrol-Electric

Elegant Black, Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-house Loan Packages Available.

Prime Motor & Leasing

Posted: 27-Oct-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle Hybrid 1.5A

\$83,999

\$9,640 /yr

13-Apr-2018

1,496 cc

5,117 km

Stationwagon

Available

Fuel Type: Petrol-Electric

No Gimmicks! Price Negotiable, Low Mileage Done \$117KM, 100% Beautiful Condition, Low Depreciation, Low Interest Rate, Most Worthy Buy, Call Now For Viewing.

Posted: 26-Oct-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

Honda Shuttle 1.5A G

\$78,800

\$8,170 /yr

11-Dec-2018

1,496 cc

-

Stationwagon

Available

New Facelifted Honda Shuttle Midnight Blue. Low Fuel Consumption, 10 Years Repayment, In House Loan Or Balloon Scheme e. Make And Assemble In Japan, 3 Years Or 100000km Warranty, View To Appreciate, Call Our Friendly Sales Executive For View...

Compare



Trust Motoring

Posted: 26-Oct-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle 1.5A G****\$70,800****\$7,660 /yr****27-Jun-2018****1,496 cc****5,000 km****Stationwagon****Available**

2018 New Facelifted Honda Shuttle 1.5 With Fog Lamp, LED Edition. Best Fuel Efficient Stationwagon In Town. Almost New Honda Shuttle. 10 Years Repayment, In House Loan Or Balloon Scheme Available. Different Loan Schemes To Suit Your Purchase. Call Our Frie...

VIEW MORE

Trust Motoring

Posted: 26-Oct-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle 1.5A G****\$70,900****\$7,640 /yr****27-Apr-2018****1,496 cc****29,800 km****Stationwagon****Available**

2018 New Facelifted Honda Shuttle 1.5 With Fog Lamp, LED Edition. Best Fuel Efficient Stationwagon In Town. Almost New Honda Shuttle. Selling Cheap! Flexible Trade In And Loan Options Available! Call For A Viewing Appointment Today!

Posted: 25-Oct-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle Hybrid 1.5A****-****N/A****04-Oct-2018****1,496 cc****9,671 km****Stationwagon****Available****Fuel Type:** Petrol-Electric**Auction Closing Time:** 4th Nov 2019 at 03:00 PM

Keys Available, Mileage Done 9,671, Road Tax Expiry 13/Jan/2020.

VIEW MORE

Posted: 24-Oct-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



That's a fine looking car interior

Customise your ride. Replace your leather seats, door panels, steering wheels and more with quality trims of your choice. List of the best workshops available. Each with merchant information, ranking and reviews to help you make the best decision.

Find out more!

**Honda Shuttle Hybrid 1.5A****\$86,800****\$8,710 /yr****27-Dec-2018****1,496 cc****6,168 km****Stationwagon****Available****Fuel Type:** Petrol-Electric

1 Owner! Low Mileage Unit! STA Certified Unit For A Peace Of Mind! High Trade In And In House Financing Available! View Today!

Posted: 22-Oct-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle Hybrid 1.5A X****\$78,500****\$8,970 /yr****20-Apr-2018****1,496 cc****30,000 km****Stationwagon****Available****Fuel Type:** Petrol-Electric

Very Good Fuel Consumption With Good Pickup. Almost New With Full Accessories And High Spec x Model. 4 Years Warranty Remaining On Car And Hybrid Battery. Serviced By PJ Workshop And Just Completed 20k Km Servicing. Current Number Plate Will Be Retained So...

VIEW MORE

Posted: 22-Oct-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle Hybrid 1.5A X****\$74,800****\$8,680 /yr****27-Feb-2018****1,496 cc****102,000 km****Stationwagon****Available**Graded B by **STP****Fuel Type:** Petrol-Electric

X Model High Specs, Paddle Shift, 6 Airbags, Cruise Control. 1 Owner. Original Paintwork. In Beautiful Condition, Superb Fuel Consumption And Well Maintained. Low Maintenance. Please SMS Or Call To Arrange For Viewing.

VIEW MORE

Posted: 19-Oct-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle Hybrid 1.5A****\$76,500****\$8,990 /yr****11-Jan-2018****1,496 cc****-****Stationwagon****Available****Fuel Type:** Petrol-Electric

Elegant White, Almost New Condition. Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available.

Prime Motor & Leasing

Posted: 19-Oct-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle Hybrid 1.5A (OPC)****\$66,800****\$6,880 /yr****21-Sep-2018****1,496 cc****7,500 km****Stationwagon****Available****Fuel Type:** Petrol-Electric

High ARF Of Ard 11k+ Instead Of The Normal 5k Only. 100% Genuine Mileage And Guarantee Not PHV Vehicle As It's Register Under OPC Scheme. Convert To Normal Plate At Only \$81,800. In An Immaculate Condition, Almost Like New. An Opportunity To Snap Up This Car...

VIEW MORE

Posted: 13-Oct-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle 1.5A G****\$73,800****\$8,270 /yr****22-Mar-2018****1,496 cc****30,800 km****Stationwagon****Available**

2018 New Facelifted Honda Shuttle Midnight Blue, iRoad Q7 Front/Rear Recording Camera, Lufi OBD, Steelmate TPMS, Magnetic Sun Shade, Legroom LED And Scuff Plate Installed, Upgraded To 16" Inch Rims & Continental Tyre For Better Stability, Installed Spring Siffe...

VIEW MORE

Posted: 10-Oct-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

Honda Shuttle Hybrid 1.5A X**\$81,800****\$9,450 /yr****21-Mar-2018****1,496 cc****18,000 km****Stationwagon****Available****Fuel Type:** Petrol-Electric

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/10/2019 16:56
Date Of Accident	23/10/2019 20:00
Exact Location Of Accident	BRICKLAND ROAD TOWARDS SUNGEI TENGAH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD5428S
Insured/Policyholder	
Name Of Registered Owner	LEONG KAR SOON
NRIC No	S8187032B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83284936
Alternative Phone No	OTHERS-83284936

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMHCSN1930441900
Cover Note Number	

Driver

Name of Driver	LEONG KAR SOON
NRIC No	S8187032B
Date Of Birth	04/10/1981
Occupation	INDOOR
Date Of Driving Pass	16/03/2016
Driving Experience	3 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83284936
Fax Number	
Contact Number	OTHERS-83284936
Email Address	NOEMAIL

Address BLK 688A CHOA CHU KANG DRIVE
#10-346
Postcode 681688
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions DRIZZLING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 3
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 4
Passenger 1
NAME: : PASSENGER
GENDER: : MALE
Passenger 2
NAME: : PASSENGER
GENDER: : FEMALE
Passenger 3
NAME: : PASSENGER
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY: SINGAPORE
Police Station Contact TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO POLICE REPORT T/20191023/2200 AND T/20191026/7013

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKW9067Y - *Bmw 718*
Vehicle Make/Model/Colour BMW

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

PRIVATE CAR

DZULKANEAN BIN ALI

S9343448Z

81273851

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SGK3027M

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LEONG KAR SOON

Approximate Age

Injuries Sustain

SLIGHT INJURY

Injured person in which vehicle?

SMD5428S

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE




1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: 
NIC/PIN No: 

Accident Sketch Plan

SKETCH PLAN

BRICKLAND ROAD TOWARDS SULLYHILL TAILHILL ROAD



A: SMD 5428 S (stationary)

B: SKW 9067 Y

C: SGR 3027 M

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to police report 1/20191023/2200

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/PRN No.:



SINGAPORE POLICE FORCE



T/20191023/2200

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

1 of 3

Report No. T/20191023/2200

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/10/2019 22:39	Vide Report No.:	Station Diary No.: 195
--	------------------	---------------------------

Informant's Particulars

Name of Informant: LEONG KAR SOON			Address: APT BLK 688A CHOA CHU KANG DRIVE #10-346 SINGAPORE 681688		
ID Type / ID No.: NRIC NO / S8187032B			Contact No.: Home/Office: Mobile: 83284936		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 38	Date of Birth: 04/10/1981	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 23/10/2019 20:00	Type of Location: Straight Road
Location: Along Road 1 BRICKLAND ROAD				
Towards Sungei Tengah Road				
Weather: Clear		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Chained Collision			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGK3027M	Car				Seriously Damaged	0
SKW9067Y	Car				Slightly Damaged	0
SMD5428S	Car	HONDA	SHUTTLE HYBRID 1.5 AUTO	Black	Slightly Damaged	3



**SINGAPORE
POLICE FORCE**



T/20191023/2200

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

2 of 3

Report No. T/20191023/2200

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMD5428S	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMHCSN19304419 00	24/08/2019	23/08/2020

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	DZULKANEAN BIN ALI		ID No.	S9343448Z
Related Vehicle	SKW9067Y (Car)		Contact No.	81273851
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Driver				
Name	LEONG KAR SOON		ID No.	S8187032B
Related Vehicle	SMD5428S (Car)		Contact No.	83284936
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL

Brief Details.

On 23/10/2019 about 2000hrs, I was driving along Brickland Road towards Sungei Tengah Road. As there was a traffic jam, my vehicle (SMD5428S) was in stationary. Out of a sudden, my vehicle was hit on the rear by another vehicle (SKW9067Y) at the back. I then alighted from my vehicle and realised that it is a chained collision, involving 3 vehicles with SGK3027M being the third vehicle. All the drivers then decided to go for insurance claim and no vehicles were towed away. No one was injured and particulars of all drivers were exchanged as well. Subsequently, all of us drove off.

There is CCTV installed in my vehicle, both front and back.



**SINGAPORE
POLICE FORCE**



T/20191023/2200

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

3 of 3

Report No. T/20191023/2200

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2  SINGAPORE
JON K WANG

Signature Of Interpreter:

Not applicable

Signature Of Informant:

Date/Time:

23/10/2019 22:39

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Classification Of Case:

Authentication Stamp

NP155

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Oct 2019		31 Oct 2019 17:53 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	- Co. Reg. No.: -		
Main Claimant:	LEONG KAR SOON, ID: S81870328		
Vehicle Reg. No.:	SMD5428S	Date of Loss:	23/10/2019 20:00 - :59 [13 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D205057C02	Policy/Cover Note No.:	DMPCSN30736819000
Vehicle Reg. No. (Insured):	SKW9067Y	Policy No. (Claimant):	DMHCSN1930441900
		Excess:	S\$0.00
Repairer:	Xin Yun Auto Pte Ltd (HQ) BLK 8 KAKI BUKIT AVE 4 #05-23 PREMIER @KAKI BUKIT, 415675 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 11/11/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)























































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									






















































Claim Documents

*SMD54285 (SNM19D205057C02)
[SKW9067Y]

TP
LEONG KAR SOON
Oct 23 2019 8:00PM
[-]
Xin Yun Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)							Thumbnail	Print	
1	24/10/19 17:13	Accident Statement							Load HTM		
2	29/10/19 10:11	Addendum Sheet							Load JPG	<input checked="" type="checkbox"/>	
3	29/10/19 10:12	Accident Statement Addm. #1							Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)							Thumbnail	Print	
1	24/10/19 17:07	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
2	24/10/19 17:07	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
3	24/10/19 17:07	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
4	24/10/19 17:07	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
5	24/10/19 17:07	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
6	24/10/19 17:07	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
7	24/10/19 17:07	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
8	24/10/19 17:07	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
9	24/10/19 17:07	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
10	24/10/19 17:07	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	04/11/19 10:20	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>	
2	04/11/19 10:20	Chassis Number							Load JPG	<input checked="" type="checkbox"/>	
3	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
4	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
5	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
6	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
7	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
8	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
9	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
10	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
11	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
12	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
13	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
14	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
15	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
16	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
17	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
18	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
19	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
20	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
21	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
22	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
23	04/11/19 10:21	General View							Load JPG	<input checked="" type="checkbox"/>	
24	04/11/19 10:21	General View							Load JPG		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
				<input checked="" type="checkbox"/>
25	04/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
26	04/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
27	04/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
28	04/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
29	04/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
30	04/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
31	04/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
32	04/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
33	04/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
34	04/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
35	04/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
36	04/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
37	04/11/19 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
38	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
39	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
40	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
41	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
42	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
43	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
44	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
45	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
46	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
47	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
48	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
49	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
50	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
51	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
52	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
53	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
54	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
55	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
56	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
57	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
58	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
59	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
60	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
61	04/11/19 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
62	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	04/11/19 10:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
79	04/11/19 10:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
80	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	04/11/19 10:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
111	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
112	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
113	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
114	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
115	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
116	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
117	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
118	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
119	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
120	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
121	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
122	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
123	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
124	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
125	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
126	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
127	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
128	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
129	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
130	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
131	04/11/19 10:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	24/10/19 17:08	Accident Sketch Plan <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
2	24/10/19 17:08	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	24/10/19 17:08	POLICE REPORT [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	24/10/19 17:08	POLICE REPORT [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	24/10/19 17:08	POLICE REPORT [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	29/10/19 10:11	POLICE REPORT [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	29/10/19 10:11	POLICE REPORT [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	29/10/19 10:11	POLICE REPORT [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	29/10/19 10:11	POLICE REPORT [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	29/10/19 10:11	MC [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	24/10/19 17:13	Accident Statement	Load HTM	
2	29/10/19 10:11	Addendum Sheet	Load JPG	<input checked="" type="checkbox"/>
3	29/10/19 10:12	Accident Statement Addm. #1	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	24/10/19 17:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	24/10/19 17:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	24/10/19 17:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	24/10/19 17:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	24/10/19 17:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	24/10/19 17:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	24/10/19 17:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	24/10/19 17:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	24/10/19 17:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	24/10/19 17:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	24/10/19 17:08	Accident Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	24/10/19 17:08	Accident Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
3	24/10/19 17:08	POLICE REPORT	Load JPG	<input checked="" type="checkbox"/>
4	24/10/19 17:08	POLICE REPORT	Load JPG	<input checked="" type="checkbox"/>
5	24/10/19 17:08	POLICE REPORT	Load JPG	<input checked="" type="checkbox"/>
6	29/10/19 10:11	POLICE REPORT	Load JPG	<input checked="" type="checkbox"/>
7	29/10/19 10:11	POLICE REPORT	Load JPG	<input checked="" type="checkbox"/>
8	29/10/19 10:11	POLICE REPORT	Load JPG	<input checked="" type="checkbox"/>
9	29/10/19 10:11	POLICE REPORT	Load JPG	<input checked="" type="checkbox"/>
10	29/10/19 10:11	MC	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119019055/HCF3E2

Date: 13/11/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30736819000
Claimant Vehicle No :	SMD5428S	Insured Vehicle No :	SKW9067Y
Date of Loss:	23/10/2019	Nature of Claim: TP	Claim No: SNM19D205057C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD5428S	Engine No:	LEB6556242
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71213369
Reg. Date:	24/08/2018 (Man. Year: 2018)	Odometer:	137092 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	31/10/2019	
Date Inspected:	29/10/2019 Inspected At:	Xin Yun Auto Pte Ltd (HQ) BLK 8 KAKI BUKIT AVE 4 #05-23 PREMIER @KAKI BUKIT Singapore 415675
Estimated Period of Repair:	3.0 days	

Adjuster: LEE HOCK ANN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,800.00 - \$3,500.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Nov 2019)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD5428S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >