

22/03/2002

ASS. REC. BY:

REF: CS31 EQ1 19019057 / GC B307

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person):

Joe1 Goh

of

EQ

Date/Time:

29.10.19 1.45pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMJ 27084

Insured:

SLV 1136C

at Workshop m/s

Kent Auto Services

Tel:

of

2 Kaki Bukit Ave 2 #01-21

Policy No:

Claim No:

DM194002899-36

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24.10.2019

CA / REV / REP. / REV 24 HRS

mp17

30.10.2019

H.O.D. Endorsement:

Date/Time:

29.10.19 1.54p.m

Person Contacted:

Kent

Vehicle IN / OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

SMJ 27084 - X

SLV 1136C - CC4 / AIG 19012310 / TIK03

DOA - 07/07/2019

08/11/19

Submit PRs.

Dismantle: 31/10/2019

After repair: 4/11/2019



**Summer Lee (LKK Auto)**

---

**From:** Shu Pei (LKKAuto) <shupeil@lkkauto.com>  
**Sent:** Tuesday, 29 October, 2019 1:45 PM  
**To:** assignments  
**Subject:** FW: YOUR REF: DP.SL.ISK.11088.19.KAS (PRS FOR SMJ2708Y // EQ: SLV1136C // DM19HO02899-JG)  
**Attachments:** 29102019130012-0001.pdf

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Joel Goh <joel.goh@eqinsurance.com.sg>  
**Sent:** Tuesday, 29 October 2019 1:20 PM  
**To:** Daniel Poon & Co. <law@dpco.com.sg>  
**Cc:** Admin A <admin-a@lkkauto.com>  
**Subject:** YOUR REF: DP.SL.ISK.11088.19.KAS (PRS FOR SMJ2708Y // EQ: SLV1136C // DM19HO02899-JG)

Dear Sirs

We refer to attached PRS request.

We agree to 6. LKK Auto Consultants Pte Ltd and will assign accordingly.

Dear LKK

Please assist on this PRS.

Our insured has not reported this accident.

Best Regards,

Joel Goh

Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify t*





**Daniel Poon & Co.**  
Advocates & Solicitors  
Commissioners for Oaths

**RECEIVED**  
29 OCT 2019

**EQ INSURANCE CO. LTD.**  
**CLAIMS DEPT**

133 New Bridge Road  
#11-02 Chinatown Point  
Singapore 069413  
Tel: +65 6227-2469  
Fax: +65 6225-2579  
Email: law@dpc.com.sg  
(UEN: 53130838C)

Daniel Poon Choon Kew  
LL. B. (Hons), LL.M

Our Ref: DP.sl.isk.11088.19.KAS  
Your Ref: -----  
Please quote our reference number when replying

Date: 29 OCTOBER 2019

EQ INSURANCE COMPANY LIMITED  
TOWER BLOCK, MND COMPLEX  
5 MAXWELL ROAD, #17-00  
SINGAPORE 069110  
**ATTN: MOTOR CLAIMS DEPARTMENT**

FAX (6223-4190) ONLY

DEAR SIRs,

**PRE-REPAIR INSPECTION**

**YOUR INSURED VEHICLE REGISTRATION NO: SLV 1136C  
ACCIDENT ON 24 OCTOBER 2019 INVOLVING SMJ 2708Y AND SLV 1136C  
ALONG HAVELOCK ROAD**

We are instructed by Kent Auto Services to notify you of a road traffic accident on 24<sup>th</sup> October 2019 at about 13:20 along Havelock Road involving our client's vehicle registration number SMJ 2708Y and vehicle registration number SLV 1136C driven by your insured at the material time. A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair inspection of the vehicle, by the attached list of six (06) surveyor which our client deemed suitable to be appointed.

If the aforesaid is not agreeable, kindly therefore instruct your appointed surveyor for a pre-repair inspection of our client's vehicle at by making a prior appointment with the repairer stated below:-

M/S KENT AUTO SERVICES  
2 KAKI BUKIT AVENUE 2  
#01-21,  
KAKI BUKIT AUTOHUB  
SINGAPORE 417921  
**ATTN: MR KENT TAN (9754-7573)**

... 2/-


Page 2  
Messrs Daniel Poon & Co,  
Our Ref: DP.sl.isk.11088.19.KAS

---

Date: 29<sup>th</sup> October 2019

If we do not receive any agreement from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,



c.c. M/S KENT AUTO SERVICES

FAX (6741-2539) ONLY

**NAME OF MOTOR SURVEYOR**

- 1) HOW ANDREW (PROMINENT APPRAISER SERVICES)
- 2) LEE KOK WENG (LEE AUTOMOBILE APPRAISERS SERVICES)
- 3) NG SOON AIK FRANCIS (PRESTIGE APPRAISER SERVICES)
- 4) ONG AH KENG, KENT (KTO AUTOMOBILE ASSESSORS)
- 5) ONG POH MENG (AEON AUTO CONSULTANTS LLP)
- 6) LKK AUTO CONSULTANTS PTE LTD

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	332M
<b>Vehicle Details</b>	
Vehicle No.:	SMJ2708Y
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	NOAH HYBRID 1.8X CVT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	2ZR0C77739
Chassis No.:	ZWR800358327
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,109.00
Original Registration Date:	27 Feb 2019
First Registration Date:	27 Feb 2019
Transfer Count:	0
Actual ARF Paid:	\$28,353.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Feb 2029
PARF Rebate Amount:	\$21,264.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	26 Feb 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,200.00
COE Rebate Amount:	\$30,034.00
<b>Total Rebate Amount:</b>	<b>\$51,298.00</b>

The information contained herein is correct as at 31 Oct 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/10/2019 15:11
Date Of Accident	24/10/2019 13:20
Exact Location Of Accident	HAVELOCK ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ2708Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KENT AUTO SERVICES
Co Reg No	52974332M
Email Address	KENTKH530@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-81292268

### Vehicle Particulars

Manufacturer	TOYOTA
Model	NOAH
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P2203634
Cover Note Number	

### Driver

Name of Driver	LEO CHIN LEE
NRIC No	S1168883G
Date Of Birth	05/10/1956
Occupation	OUTDOOR
Date Of Driving Pass	29/09/1978
Driving Experience	41 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81292268
Fax Number	
Contact Number	
E Mail Address	NOEMAIL

Address	BLK 270 TAMPINES ST 21 #03-167
Postcode	520270
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORD BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REQUEST FROM OWNER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV1136C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Ref: CS3/EQ19019057/Gcf3e2 Date: 13-11-2019 Code: EQI	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	SLV 1136C	Veh. Inspected	SMJ 2708Y
Policy No.		Coverage (\$)	0.00
Claim No.	DM19HO02899-JG	Excess (\$)	0.00
Assign From	JOEL GOH	Assign Date	29/10/2019
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA NOAH	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	ZWR800358327	Colour	SILVER
Odometer	51295 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	HABILEAD	6 mm
L/H Front Tyre	195/65 R15	HABILEAD	6 mm
R/H Rear Tyre	195/65 R15	HABILEAD	6 mm
L/H Rear Tyre	195/65 R15	HABILEAD	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.			
<b>5. General Information</b>			
Accident Date	24/10/2019	Inspect Date / Time	30/10/2019 ( 10:30 AM )
Survey held at	KENT AUTO SERVICES 2 KAKI BUKIT AVE 2 #01-21 KAKI BUKIT AUTOHUB SINGAPORE 417921		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	

Report Ref No. CS3/EQ19019057/Gcf3e2

### Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.