

22/03/2002

ASS. REC. BY:

REF: CS3/AIG19019069/GC f32

Special Instruction:

Survivor: GQ

ASSIGNMENT (Office)

From (Person): Winnie Fan

of AIG

Date/Time: 29.10.19 2.57p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: Smm 7820G

Insured: SLJ 6021E

at Workshop m/s Messrs Derrick motor works

Tel: 96333593

of Bk 9002 Tampines St 93 #01-72, Tampines Ind Park A

Policy No:

Claim No: 916536686686

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 24.10.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 29.10.19 3.47p.m

Person Contacted:

Jeremy

H.O.D. Endorsement:

Vehicle: IN / OUT

Date/Time

Action/Instruction ( X ) Estimate

Smm 7820G - X

SLJ 6021E - CC4/AIG19003751 U203 D.O.A - 09/01/2019

Dismantle: 1/11/2019

After repair: 7/11/2019

ASS. REC. BY:

REF:

AIG

PRS

## ASSIGNMENT

From:

Date:

30.10.2019

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

Smm 78209

at Workshop m/s

Messrs Derrick motor works

of

B1169002 Tampine S1 93 #01-72

Insured:

Tampine Ind Park A

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

ASX 10-009. m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMM 78209

Yr Regn:

15 Jul 2019

Type: ☒ M.Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Avante 1.6

C.C. 1591

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

5596

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH 0841 CMK 916261

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

195/65R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NEXEN

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

D.O.I.

30-10-19

Survey held at

w/s

5:30pm

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 13 NOV 2019

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Wheel end (\$

Rep. Format:

DAR

Lump Sum / U.C. /

180

11

M1

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Oct 2019 <a href="#">Edit Reg</a>		29 Oct 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by adjuster\]](#)

Insured:	DAI JUN XIAN, ID: S8801356E		
Main Claimant:	DERRICK MOTOR RENTAL		
Vehicle Reg. No.:	SMM7820G	Date of Loss:	24/10/2019 00:00 - :59
Claim Type:	TP / 9165366866SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SLJ6021E	Policy No. (Claimant):	
		Excess:	
Repairer:	Messrs Derrick Motor Works (HQ) BLK 9002 TAMPINES ST 93, #01-72, TAMPINES IND PARK A, 528836 Tampines - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 07/11/2019]		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG\_SG (30/10/2019): TP GIA report

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Summer Lee (LKK Auto)

---

**From:** Fan, Winnie-LW <Winnie-LW.Fan@aig.com>  
**Sent:** Tuesday, 29 October, 2019 2:57 PM  
**To:** 'admin-a@lkkauto.com'; 'assignments@lkkauto.com'  
**Cc:** Fong, Andy-SY  
**Subject:** AIGENCRYP - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ6021E AND SMM7820G ON 24/10/2019

Hi LKK,

Kindly assist to survey.

Please be informed that the said vehicle can be inspected at:

**Messrs Derrick Motor Works  
Blk 9002 Tampines St 93  
#01-72, Tampines Ind Park A  
Singapore 528836  
Attention: Mr Jeromy – HP 9633 3593 (Please call before going)**

Winnie Fan  
AIG  
Claims Service Associate  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

[winnie-lw.fan@aig.com](mailto:winnie-lw.fan@aig.com) | [www.aig.sg](http://www.aig.sg)

### IMPORTANT NOTICE:

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

**From:** Elaine Toh [mailto:Elainetoh@visionlawllc.com]  
**Sent:** Tuesday, 29 October, 2019 11:32 AM  
**To:** 'Hor, Yinrul'  
**Cc:** 'Lily.Tan@aig.com'; 'Andy-SY.Fong@aig.com'; 'Lee-Ying.Chin@aig.com'; 'NoorMariesa.AbuKassim@aig.com'; 'ShengYang.Lim@aig.com'; 'Syazairdina.Azlan@aig.com'; 'yokeshi.chan@aig.com'; 'Aashweenjeetkaur.Mithoosingh@aig.com'; 'Parthiban, Theerthan'; 'nurmariahhuibrechts.mohdrizal@aig.com'  
**Subject:** PRE REPAIR INSPECTION --- YOUR REF: SLJ 6021 E --- ACCIDENT INVOLVING SMM 7820 G AND SLJ 6021 E ON 24 OCTOBER 2019 ALONG UPPER CHANGI ROAD SLIP ROAD TOWARDS PIE (TUAS) AT ABOUT 0815 HOURS  
**Importance:** High

**Our Ref: SMM 7820 G (et)  
WITHOUT PREJUDICE**

Dear Sir/Madam,

We are instructed by **DERRICK MOTOR RENTAL** to notify you of a road traffic accident on 24 October 2019 along Upper Changi Road slip road towards PIE (Tuas) at about 0815 hours involving our client's vehicle registration number SMM 7820 G and vehicle registration number SLJ 6021 E driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Thank you.

Regards,  
Elaine Toh (Secretary)  
Vision Law LLC  
Tel: 65342811 (Ext. 122)  
Fax: 65356802

cc: SMM 7820 G – By email only

---

VISION LAW LLC  
Advocates & Solicitors  
(Incorporated with limited liability)  
Unique Entity No. 200721148H  
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413  
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---

---

**DISCLAIMER:**

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---

---

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	973E
<b>Vehicle Details</b>	
Vehicle No.:	SMM7820G
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Oct 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	AD AVANTE 1.6 GLS (A)
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	G4FGKU152536
Chassis No.:	KMHD841CMKU916261
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$12,584.00
Original Registration Date:	15 Jul 2019
First Registration Date:	15 Jul 2019
Transfer Count:	0
Actual ARF Paid:	\$12,584.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jul 2029
PARF Rebate Amount:	\$9,438.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	14 Jul 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$28,589.00
COE Rebate Amount:	\$27,743.00
<b>Total Rebate Amount:</b>	<b>\$37,181.00</b>

The information contained herein is correct as at 31 Oct 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/10/2019 10:49
Date Of Accident	24/10/2019 08:15
Exact Location Of Accident	UPPER CHANGI RD SLIP RD TWDS PIE(TUAS)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMM7820G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	DERRICK MOTOR RENTAL
Co Reg No	53374973E
Email Address	JEROMYNG@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-96333593

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5096874364-01
Cover Note Number	

### Driver

Name of Driver	ONG YI HOO, KELLY (WANG YIHAO,KELLY)
NRIC No	S8412843J
Date Of Birth	02/05/1984
Occupation	INDOOR
Date Of Driving Pass	06/07/2007
Driving Experience	12 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94500775
Fax Number	
Contact Number	
EMail Address	KELLYONG.DITRO@GMAIL.COM

Address	BLK502 BEDOK NORTH STREET 3 #10-44
Postcode	460502
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

AS PER SKETCH PLAN ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	NOT AVAILABLE
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ6021E
Vehicle Make/Model/Colour	TOYOTA WISH
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	DAI JINXIAN
NRIC/Passport Number	S8801356E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	ONG YI HOO, KELLY
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SMM7820G
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan Pg. 1



SKETCH PLAN



IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time: 

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 

  
Reporting Centre Personnel's Signature  
Name:   
NRIC/FIN No.: 26/10/19 

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Upper Changi Road into PIE (TVA) Entrance when the Vehicle in front of me slowed down and came to a stop. I slowed down my Vehicle A and came to a stop. All of a sudden I felt a massive impact from the rear of my Vehicle. After I had took a while to compose myself, I exited my Vehicle and noticed Vehicle B had collided with the rear of my Vehicle A. We exchanged particulars and left the scene. There was no contact with the Vehicle in front of me.

I experience blurred vision, dizziness, neck and back pain.

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a **Fourteen (14) days clause** whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Reporting Only
Claim OD
Claim TP
Claim OD / TP at other workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched  
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary  
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

## MOTORCAR (Rear)

(1)Replace (✓) (2)Repair(X) (3)Check (✓)  
(4)Not Consistent (NC)

### Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	SCR	✓	
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	RE	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	MFC	✓	
1147	992976	Rear Bumper Bracket	BT	✓	
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement	CRA	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	Repair		
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: **SMM 78206**

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items: \_\_\_\_\_ Assessor: \_\_\_\_\_

## ...CLAIM SUBFOLDER...(Pending for Survey Report)



























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Oct 2019 <a href="#">Edit Reg</a>		29 Oct 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by adjuster]</b>							
Insured:	DAI JUN XIAN, ID: S8801356E								
Main Claimant:	DERRICK MOTOR RENTAL								
Vehicle Reg. No.:	SMM7820G	Date of Loss:	24/10/2019 00:00 - :59 [3 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9165366866SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SLJ6021E	Policy No. (Claimant):							
		Excess:							
Repairer:	Messrs Derrick Motor Works (HQ) BLK 9002 TAMPINES ST 93, #01-72, TAMPINES IND PARK A, 528836 Tampines - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by <b>MdNoor, Norsiah</b> ] Norsiah.MdNoor@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 07/11/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
<ul style="list-style-type: none"> <li>AIG_SG (30/10/2019): TP GIA report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SMM7820G (9165366866SG)  
[SLJ6021E]  
TP  
DERRICK MOTOR RENTAL  
Oct 24 2019 12:00AM  
[DAI JUN XIAN]  
Messrs Derrick Motor Works

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
<b>Photos/Images</b>						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	08/11/19 15:16	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>		
2	08/11/19 15:16	Chassis Number		Load JPG	<input checked="" type="checkbox"/>		
3	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
4	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
5	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
6	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
7	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
8	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
9	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
10	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
11	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
12	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
13	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
14	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
15	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
16	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
17	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
18	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
19	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
20	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
21	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
22	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
23	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
24	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
25	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
26	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
27	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
28	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
29	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
30	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
31	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
32	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
33	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
34	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
35	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
36	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
37	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
38	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
39	08/11/19 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
40	08/11/19 15:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>		
41	08/11/19 15:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>		
42	08/11/19 15:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>		
43	08/11/19 15:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	08/11/19 15:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	08/11/19 15:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	08/11/19 15:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	08/11/19 15:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	08/11/19 15:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	08/11/19 15:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	08/11/19 15:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	08/11/19 15:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	08/11/19 15:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	08/11/19 15:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	08/11/19 15:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	08/11/19 15:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	08/11/19 15:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	08/11/19 15:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	08/11/19 15:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	08/11/19 15:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	08/11/19 15:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	08/11/19 15:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	08/11/19 15:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	08/11/19 15:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	08/11/19 15:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	08/11/19 15:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	08/11/19 15:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	08/11/19 15:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	08/11/19 15:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	08/11/19 15:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	30/10/19 15:54	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19019069/GCF3E2

Date: 14/11/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

## Claimant

Vehicle No : SMM7820G

Insured Vehicle No : SLJ6021E

Date of Loss: 24/10/2019

Nature of Claim: TP

Claim No: 9165366866SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SMM7820G

Make &amp; Model: HYUNDAI AVANTE, 1.6 (A)

Engine No: G4FGKU152536

Reg. Date: 15/07/2019 (Man. Year: 2019)

Chassis No: KMHD841CMKU916261

Colour: Grey

Odometer: 5596 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Nexen 8 mm

Rear Left Side: Nexen 8 mm

Front Right Side: Nexen 8 mm

Rear Right Side: Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 29/10/2019

Date Inspected: 30/10/2019 Inspected At:

Messrs Derrick Motor Works (HQ)  
BLK 9002 TAMPINES ST 93, #01-72,  
TAMPINES IND PARK A  
Singapore 528836

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Scratched	0.00 F	*- F
2	1		*REAR BUMPER	Deformed	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER BRACKET	Bent	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Cracked	0.00 F	*- F
6	1		*REAR END PANEL	Repair	0.00 F	*- F
F=Franchise part.				<b>Total Parts (\$\$)</b>	<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >