

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19019127/K1vf3s2						
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	05-11-2019 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLR 5106J	т —	nspected	SHD 7309Z	
	Policy No.	5097499472-01	_	age (\$)	0.00	
	Claim No.	MT/1069369-001	Exces	s (\$)	0.00	
	Assign From		Assigr	n Date	29/10/2019	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2018	
	Chassis No.	KMHC851CVKU122028	Coloui	r	BLUE	
	Odometer	74681	Steerin	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	MICHE	LIN	8 mm	
	L/H Front Tyre	195/65 R15	MICHELIN		8 mm	
	R/H Rear Tyre	195/65 R15	MICHE	LIN	8 mm	
	L/H Rear Tyre	195/65 R15	MICHELIN		8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	. General Information					
	Accident Date	27/10/2019	Inspection Date 29/10/2019			
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					

Estimate Days of Repair

2 Working Days