

22/03/2002

ASS. REC. BY:

REF: CS3/ A2G 19019133/ Gcf30x Special Instruction:

Survivor: GA

ASSIGNMENT (Office)From (Person): Manir Fan of A2G Date/Time: 30.10.19 10:34 a.m

Estimated Cost: _____ Bill to: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: GBJ 78245 Insured: GM 8788Gat Workshop m/s Tan Eng Huat Moto Tel: 62809927of BK 6 Dahu Lane 10 #01-556Policy No: _____ Claim No: 48318363878G

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 29.10.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 30.10.19 10:40 a.m Person Contacted: Ah cat H.O.D. Endorsement: _____Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>GBJ 78245-X</u>
	<u>GM 8788G - X</u>
<u>08/11/19</u>	<u>Submit PAR.</u>
	<u>Dismantle: 30/10/2019</u>
	<u>After repair: 1/11/2019.</u>


...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Oct 2019 Edit Reg		30 Oct 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured:									
Main Claimant: YEW LEE HENG LP-GAS TRADING PTE LTD, Co. Reg. No.: A199603030M									
Vehicle Reg. No.: GBJ7824S		Date of Loss: 29/10/2019 10:00 - :59							
Claim Type: TP / 4831836387SG		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): GM8788G		Policy No. (Claimant):							
		Excess:							
Repairer: Tan Eng Huat Motor (HQ) Blk 6 Defu Lane 10, #01-556, 539187 Defu Lane - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 08/11/2019]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

- RE: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GM8788G AND GBJ7824S ON 29/10/2019

From: Fan, Winnie-LW
To:
Cc: Fong, Andy-SY
Sent: Wednesday, 30 October, 2019 10:34:26 AM
Attachments:  GBJ7824S - NOA.PDF

Hi LKK,

Kindly assist to survey, vehicle in.

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Tan Eng Huat Motor

陳榮發摩托 SERVICE CENTRE • SPRAY CENTRE

SERVICE CENTRE Block 6 Defu Lane 10 #01-556 Singapore 539187

SPRAY CENTRE Block 5 Defu Lane 10 #01-574 Singapore 539186 Tel: 6280 8927 Fax: 6280 4205

Date: 29/10/19

To: AIG ASIA PACIFIC Insurance Pte Ltd.
Motor Claims Department

78 Shenton way

#09-15 AIG Building
Singapore 079120

Dear Sir/Mdm,

NOTIFICATION OF ACCIDENT

Please be informed that an accident involving my/our vehicle no. GBJ 78248 and vehicle(s) no. Gm 8788G had taken place at /along CIE TWO Changi on date 29/10/19 at time 10.01.16 hrs.

Kindly let us have a list of ten surveyors as your nominated SJE for our consideration within the stipulated timeline under the NIMA protocol.

If we do not hear from you within 2 working days, we shall proceed to repair the vehicle without further notice and our client shall claim for the additional loss of use arising from the giving of this notification to you.

Yours Sincerely



PRI

Date / Time	
Company Name	
Surveyor	
Contact No.	
Signature	

DISMANTLED PARTS

Date / Time	
Surveyor	

AFTER REPAIR

Date / Time	
Surveyor	

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Company
Owner ID:	030M
Vehicle No.:	GBJ7824S
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	YD25054300B
Chassis No.:	JN1MC2E26Z0031395
Maximum Power Output:	-
Open Market Value:	\$25,655.00
Original Registration Date:	28 Aug 2019
First Registration Date:	28 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$1,283.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	27 Aug 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$25,089.00
COE Rebate Amount:	\$24,650.00
Total Rebate Amount:	\$24,650.00

The information contained herein is correct as at 30 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/10/2019 11:45
Date Of Accident	29/10/2019 10:00
Exact Location Of Accident	ALONG CTE TO CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBJ7824S
Insured/Policyholder	
Name Of Registered Owner	YEW LEE HENG LP-GAS TRADING PTE LTD
Co Reg No	A199603030M
Email Address	YLHLPGAS@HOTMAIL.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62825525

Vehicle Particulars

Manufacturer	NISSAN
Model	NV350 PANEL VAN 2.5 5MT 5DR

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900155770
Cover Note Number	28/08/2019 TO 27/08/2020

Driver

Name of Driver	HO KWOK FAI
NRIC No	S1649709F
Date Of Birth	22/01/1964
Occupation	OUTDOOR
Date Of Driving Pass	16/03/1984
Driving Experience	35 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97865418
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address APT BLK 415 WOODLANDS ST 41 #05-169 (S) 730415
Postcode
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : TAMAH
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

refer with attach.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GM8788G
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please complete correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any accident reporting may be referred to the Police for investigation.
6. This Form will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of this report being made available aforesaid.
8. Consistent with the Personal Data Protection Act (PDPA)

I, the undersigned, acknowledge, agree and consent that:

- (a) my insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1

A - GBJ 78245
B - GM 8788G

29/10/19 - 10.01.16

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along CTE two chang.
Suddenly I feel an impact from behind
and come down to check. I realised that
vehicle B had collided on my rear.

☒ Driver's Signature
☒ Witness
☒ Police Officer
☒ Other

Date: 29/10/19
 Time: 11:50

DECLARATION

I/We declare that the particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Center Personnel's Signature
Name:
NRIC/FIN No.:

VAN / LORRY (Rear)

Vehicle No: **6BJ7824S**

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	MC	/	
1142	993108	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side <i>chips</i>	MC	/	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Step Panel	BT	/	
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor	MC	/	
1159	993327	Rear End Panel	MC	/	
1163	993851	Rear LH Taillamp	MC	/	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate	MC	/	
2054	993700	Rear Rubber Stopper			
2055	993701	Rear Rubber Stopper Bracket			
1182	991328	Tailgate Emblem	MC	/	3
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	MC	/	
1196	994607	Tailgate Glass Sealant	MC	/	
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			

NAC	INC	Item	CON	AC	Qty
2062	993748	Rear Sidegate			
2063	994225	Rear Sidegate Lock			
2064	993749	Rear Sidegate Hinge			
2065	994226	Sidegate Lower Panel			
2066	994227	Sidegate Railing			
2067	994208	Side Cover Hook			
2068	991965	Side Step Panel			
2069	994496	Side Step Panel Stopper			
2070	992857	Rear Body Panel			
2071	992866	Rear Body Panel Inner			
2072	995329	Sliding Door LH			
2073	995328	Sliding Door RH			
2074	994295	Sliding Door Handle			
2075	994300	Sliding Door Lock			
2076	994313	Sliding Door Rubber			
2077	994291	Sliding Door Bottom Roller			
2078	994317	Sliding Door Top Roller			
2079	994306	Sliding Door Rail			
2080	994315	Sliding Door Stepboard			
2081	994316	Sliding Door Stepboard Garnish			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1136	990247	Sticker	MC	/	
		'70' sticker	MC	/	
		'8 pax' sticker	MC	/	

No of Items: _____ Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)
































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Oct 2019 Edit Reg		30 Oct 2019 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TEN & HAN TRADING PTE LTD , Co. Reg. No.: 198800049R								
Main Claimant:	YEW LEE HENG LP-GAS TRADING PTE LTD , Co. Reg. No.: A199603030M								
Vehicle Reg. No.:	GBJ7824S	Date of Loss:	29/10/2019 10:00 - :59 [2 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4831836387SG	Policy/Cover Note No.:	0999994008 (Comprehensive)						
Vehicle Reg. No. (Insured):	GM8788G	Policy No. (Claimant):							
		Excess:							
Repairer:	Tan Eng Huat Motor (HQ) Blk 6 Defu Lane 10, #01-556, 539187 Defu Lane - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 08/11/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (31/10/2019): TP GIA report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBJ7824S (4831836387SG)
[GM8788G]
TP
YEW LEE HENG LP-GAS TRADING PTE LTD
Oct 29 2019 10:00AM
[TEN & HAN TRADING PTE LTD]
Tan Eng Huat Motor

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser
Photos/Images						3 per page <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
2	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
3	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
4	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
5	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
6	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
7	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
8	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
9	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
10	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
11	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
12	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
13	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
14	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
15	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
16	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
17	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
18	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
19	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
20	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
21	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
22	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
23	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
24	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
25	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
26	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
27	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
28	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
29	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
30	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
31	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
32	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
33	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
34	31/10/19 10:15	General View		Load JPG	<input checked="" type="checkbox"/>	
35	31/10/19 10:16	Chassis Number		Load JPG	<input checked="" type="checkbox"/>	
36	31/10/19 10:16	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>	
37	31/10/19 10:16	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>	
38	31/10/19 10:16	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>	
39	31/10/19 10:16	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>	
40	31/10/19 10:16	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>	
41	31/10/19 10:16	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>	
42	31/10/19 10:16	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>	
43	31/10/19 10:16	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	31/10/19 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	31/10/19 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	31/10/19 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	31/10/19 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	31/10/19 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	31/10/19 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	31/10/19 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
52	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
53	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
54	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
55	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
56	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
57	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
58	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
59	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
60	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
61	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
62	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
63	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
64	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
65	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
66	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
67	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
68	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
69	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
70	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
71	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
72	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
73	07/11/19 09:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	31/10/19 16:49	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19019133/GCF3E2

Date: 13/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994008

Claimant

Vehicle No : GBJ7824S

Insured Vehicle No : GM8788G

Date of Loss: 29/10/2019

Nature of Claim: TP

Claim No: 4831836387SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBJ7824S

Make & Model: NISSAN NV350, 2.5 5MT 5DR EURO V (A)

Engine No: YD25054300B

Reg. Date: 28/08/2019 (Man. Year: 2019)

Chassis No: JN1MC2E26Z0031395

Colour: Silver

Odometer: 10273 km

Engine Capacity: 2488 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size:

195 R15C

Front Left Side: Dunlop 8 mm

Rear Left Side:

Dunlop 8 mm

Front Right Side: Dunlop 8 mm

Rear Right Side:

Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/10/2019

Date Inspected: 30/10/2019 Inspected At:

Tan Eng Huat Motor (HQ)
Blk 6 Defu Lane 10, #01-556
Singapore 539187

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER STEP PANEL	Bent	0.00 F	*- F
4	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
5	1		*REAR END PANEL	Buckled	0.00 F	*- F
6	1		*REAR LH TAILLAMP	Cut	0.00 F	*- F
7	1		*TAILGATE	Buckled	0.00 F	*- F
8	3		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
9	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
10	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
11	1		*STICKER	Necessary	0.00 F	*- F
12	1		*70 STICKER	Necessary	0.00 F	*- F
13	1		*8 PAX STICKER	Necessary	0.00 F	*- F
F=Franchise part.						
				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >