

2003001

ASS. REC. BY:

REP: CS3/CT219019145/ Ngf302 Special Instruction:

Surveyor: NAZ ASSIGNMENT (Office)From (Person): Etain Chong of CT2 Date/Time: 30.10.2019 11:09 a.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKZ 7356K Insured: GBG 1027Gat Workshop no/ Jd motorsports Tel: 9237 3644of 25 bati Bukit road 4 #06-38Policy No: DMCVSA30323319011 Claim No: SVM 190205026102-007

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 21.10.2019  
(Client's Record)CA / REV / REP. / REV 24 HRS <sup>11:00</sup> H.O.D. Endorsement: \_\_\_\_\_Date/Time: 30.10.19 11:09 a.m Person Contacted: Ronnie Vehicle: IN (OUT)

Date/Time:	Action/Instruction ( X ) Estimate
	SKZ 7356K - NA/INC 11/01/19/25/23 DOA - 21/10/2019
	GBG 1027G - NA/INC 11/01/19/25/23 DOA - 21/10/2019
<u>07/11/19</u>	<u>Submit PRS.</u>

Nuriman

REF: CT1

ASS. REC. BY

PRS

ASSIGNMENT

From: Date: 4.11.2019

Veh No: SKZ 7356K Yr Regn: 1 FEB/2016

Estimated Cost:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

OD: TP / NS / TP RES / OD RES / EVA / INV / MY

Make: HONDA ODYSSEY 2.0 c.c. 2356

To inspect Vehicle No: SKZ 7356K

Colour: PURPLE A/C: Insured / Std / NI / NA

at Workshop n/s: JD Motorsports

Sp. Reading: 17,482 T/Radio: Insured / Std / NI / NA

at 25 Kati Bukit Road P 7106-38

Insured:

Eng/No:

Policy No:

C/No: JHMP18806C201694

Claims No.:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh: 90% come LKK Owner.

Mod: Nil / S/Rim / STD / Rim or

(Policy Condition)

Tyre Size: F: 215/55 R17

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or F (BS), R (CONTINENTAL)

Bal. or Market Value: 88K

Front: R/Bal. 5 mm L/Bal. 5 mm

IDAC Accident Rpt: Consistent? : Yes or No

Rear: R/Bal. 5 mm L/Bal. 5 mm

GIA / PR Seen: Consistent? : Yes or No

D.O.A. 21/10/19 D.O.I. 4/11/19

Est. Repairs: days Res.: Yes or No

Survey held at LKK

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS mp'

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted:

O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	COE Rebate \$58,889
	Repair Limit \$27K
	Repair Range \$3k - \$4k
	Repair Days 3 DAY

RECEIVED 07 NOV 2019

Date/Time, File Pass In?

: Preli. Report

Days Of Repair:

1) 07/11/19

: Final Report

Resurvey No. of Trip:

Date/Time, File Return In?

Survey Fee: 150

2)

Add Fee:  : Site Insp (\$

Transportation: S + RS \$

: Interview (\$

Photo

: Tech. Invs (\$

Client

: Wheel end (\$

Report Form: PRS

Lump Sum / H.R.:

TOTAL

150

## Nivitha (LKK Auto)

---

**From:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Sent:** Wednesday, 30 October 2019 10:56 AM  
**To:** 'Anil Kumar'; assignments  
**Cc:** Claims Dept of CTI; Jeffrey Tay; Ruby Ong  
**Subject:** RE: YOUR REF: SNM19D205026-GBG1027G-CML & OUR REF: TCL.GCN.AN.50673.19.JDM - REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKZ 7356K - ACCIDENT INVOLVING SKZ7356K & GBG1027G ON 21/10/19

### WITHOUT PREJUDICE

Dear Anil,

We refer to your email of 30.10.19.

We are not agreeable to your proposed surveyor and will assign our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and arrange for the survey.

Thank you.

Regards,

**Elaine Cheong**  
Executive (Motor Claims)  
Claims Department

### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6530  
Fax: 6224 7478 / 6224 7175  
Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

**From:** Anil Kumar [mailto:[anil@htapartners.com.sg](mailto:anil@htapartners.com.sg)]  
**Sent:** Wednesday, 30 October, 2019 10:52 AM  
**To:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Cc:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>; Jeffrey Tay <[Jeffrey.Tay@sg.cntaiping.com](mailto:Jeffrey.Tay@sg.cntaiping.com)>; Ruby Ong <[ruby@htapartners.com.sg](mailto:ruby@htapartners.com.sg)>  
**Subject:** YOUR REF: SNM19D205026-GBG1027G-CML & OUR REF: TCL.GCN.AN.50673.19.JDM - REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKZ 7356K - ACCIDENT INVOLVING SKZ7356K & GBG1027G ON 21/10/19

Without Prejudice  
Save As To Cost

Dear Elaine,

We refer to your email dated even date .

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Oct 2019		30 Oct 2019 11:08 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:									
Main Claimant:	TRAVEL GSH PTE LTD, Co. Reg. No.: 199205400K								
Vehicle Reg. No.:	SKZ7356K	Date of Loss:	21/10/2019 18:00 - :59						
Claim Type:	TP / SNM19D205026C02	Policy/Cover Note No.:	DMCVSN30323319011						
Vehicle Reg. No. (Insured):	GBG1027G	Policy No. (Claimant):	S112417558						
		Excess:	S\$500.00						
Repairer:	Jd Motorsports Pte Ltd (HQ) 25 KAKI BUKIT ROAD 4, #06-38 SYNERGY@KB, 417800 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/11/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;">View All   Compose Case Mail</span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;">View All   Search Tasks   Create New Task   Complete</span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Elaine Cheong

---

**From:** Elaine Cheong  
**Sent:** Wednesday, 30 October, 2019 10:56 AM  
**To:** 'Anil Kumar'; assignments  
**Cc:** Claims Dept of CTI; Jeffrey Tay; Ruby Ong  
**Subject:** RE: YOUR REF: SNM19D205026-GBG1027G-CML & OUR REF: TCL.GCN.AN.50673.19.JDM - REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKZ 7356K - ACCIDENT INVOLVING SKZ7356K & GBG1027G ON 21/10/19

### WITHOUT PREJUDICE

Dear Anil,

We refer to your email of 30.10.19.

We are not agreeable to your proposed surveyor and will assign our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and arrange for the survey.

Thank you.

Regards,

**Elaine Cheong**  
Executive (Motor Claims)  
Claims Department

### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6530  
Fax: 6224 7478 / 6224 7175  
Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

---

**From:** Anil Kumar [mailto:[anil@htapartners.com.sg](mailto:anil@htapartners.com.sg)]  
**Sent:** Wednesday, 30 October, 2019 10:52 AM  
**To:** Elaine Cheong <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>  
**Cc:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>; Jeffrey Tay <[Jeffrey.Tay@sg.cntaiping.com](mailto:Jeffrey.Tay@sg.cntaiping.com)>; Ruby Ong <[ruby@htapartners.com.sg](mailto:ruby@htapartners.com.sg)>  
**Subject:** YOUR REF: SNM19D205026-GBG1027G-CML & OUR REF: TCL.GCN.AN.50673.19.JDM - REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKZ 7356K - ACCIDENT INVOLVING SKZ7356K & GBG1027G ON 21/10/19

Without Prejudice  
Save As To Cost

Dear Elaine,

We refer to your email dated even date .

Our client regret to reject your list of surveyors and append below our client's list of surveyors for your consideration.

1. Mr Bok - Prudent Adjusters
2. Kelvin - KAAS
3. Terrence - KAAS

If your end is not agreeable with the above list of surveyors , kindly contact the person-in-charge to arrange for the inspection of the vehicle. Please be informed that the said vehicle can be inspected at: -

Venue : JD Motorsports Pte Ltd  
25 Kaki Bukit Road 4  
#06-38 Synergy@KB  
Singapore 417800

Contact Person : Mr Ronnie : 9237 3644

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference

Best regards,  
Anil (Secretary)  
M/s Hin Tat Augustine & Partners  
20 Upper Circular Road  
#02-10/12 The Riverwalk  
Singapore 058416  
Tel : 6533 0212  
Direct Fax: 63383536  
Fax : 63383536

**From:** Elaine Cheong <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>  
**Sent:** Wednesday, 30 October 2019 10:45 AM  
**To:** Ruby Ong <[ruby@htapartners.com.sg](mailto:ruby@htapartners.com.sg)>  
**Cc:** Anil Kumar <[anil@htapartners.com.sg](mailto:anil@htapartners.com.sg)>; Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>; Jeffrey Tay <[Jeffrey.Tay@sg.cntaiping.com](mailto:Jeffrey.Tay@sg.cntaiping.com)>  
**Subject:** RE: OUR REF: SNM19D205026-GBG1027G-CML - REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKZ 7356K [OUR REF. TCL.GCN.AN.50673.19.JDM]

WITHOUT PREJUDICE

Dear Ruby,

We refer to your email of 29.10.19.

We would like to conduct pre-repair survey of the vehicle at the appointed workshop.

We propose the following list of surveyors to be nominated as the Single Joint Expert to conduct survey of the claimant's vehicle:-

1. ADRIAN LING	6. KENNETH KONG
2. Kelvin Ang	7. SIMON HO
3. SEE CHEW SENG	8. CHUA WEIJIE

4. MOHD FADHILAH BIN OSMAN	9. MARCUS CHUA
5. XING QUO QIANG	10. HENRY NG

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

As per the NIMA Protocol, the survey by our appointed surveyor would include survey of your vehicle pre-repair, after it is dismantled, and post repairs. Hence, you need to provide us / our surveyors with the list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.

As stated above, please inform us and our surveyor after the claimant's vehicle had been repaired so that our surveyor can carry out post repair inspection before the vehicle is returned to your client. Please co-ordinate with our surveyor immediately after the repair is completed.

Regards,

**Elaine Cheong**  
Executive (Motor Claims)  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co Reg No. 200208384E  
DID 6389 6530  
Fax: 6224 7478 / 6224 7175  
Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

**From:** Claims Dept of CTI  
**Sent:** Wednesday, 30 October, 2019 10:33 AM  
**To:** Ruby Ong <[ruby@htapartners.com.sg](mailto:ruby@htapartners.com.sg)>; Elaine Cheong <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>; Jeffrey Tay <[Jeffrey.Tay@sg.cntaiping.com](mailto:Jeffrey.Tay@sg.cntaiping.com)>  
**Cc:** Anil Kumar <[anil@htapartners.com.sg](mailto:anil@htapartners.com.sg)>  
**Subject:** OUR REF: SNM19D205026-GBG1027G-CML - REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKZ 7356K [OUR REF. TCL.GCN.AN.50673.19.JDM]

Dear Elaine,

Please conduct PRS for SKZ7356K.

Note: officer in Elaine Cheong 63896530.

Regards,

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
T: (65) 63896116 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平鄴城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Ruby Ong [mailto:[ruby@htapartners.com.sg](mailto:ruby@htapartners.com.sg)]  
**Sent:** Tuesday, 29 October, 2019 4:23 PM  
**To:** Claims Dept of CTI <[claimsdept@sg.entaiping.com](mailto:claimsdept@sg.entaiping.com)>  
**Cc:** Anil Kumar <[anil@htapartners.com.sg](mailto:anil@htapartners.com.sg)>  
**Subject:** REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKZ 7356K [OUR REF. TCL.GCN.AN.50673.19.JDM]  
**Importance:** High

Your ref : GBG 1027G  
Our ref : TCL.GCN.ro.50673.19.ess

**WITHOUT PREJUDICE**

29 October 2019

**China Taiping Insurance (Singapore) Pte Ltd**  
Motor Claims Department  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

**By Email Only**

**VERY URGENT**

Dear Sirs,

**CLAIMANT: TRAVEL GSH PTE LTD**  
**NOTICE OF ACCIDENT AND PRE-REPAIR SURVEY - ACCIDENT INVOLVING SKZ 7356K & GBG 1027G ALONG COLLYER QUAY ON 21 OCTOBER 2019 @ 1815 HRS**

We are instructed by Travel GSH Pte Ltd to notify you of a road traffic accident on 21 October 2019 at about 1815hrs along Collyer Quay involving our client's vehicle registration number SKZ 7356K and vehicle registration number GBG 1027G driven by your insured/insured's driver at the material time.

As a result of the accident, our clients' vehicle has been damaged. Before our clients proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,  
Ruby Ong  
Secretary  
M/s Hin Tat Augustine & Partners  
20 Upper Circular Road  
#02-10/12 The Riverwalk  
Singapore 058416  
**Tel : 6533 0212 ext 278**  
Fax : 6338 3536 / 6533 0313

[www.htapartners.com.sg](http://www.htapartners.com.sg)

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

---

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

Our client regret to reject your list of surveyors and append below our client's list of surveyors for your consideration.

1. Mr Bok - Prudent Adjusters
2. Kelvin - KAAS
3. Terrence - KAAS

If your end is not agreeable with the above list of surveyors , kindly contact the person-in-charge to arrange for the inspection of the vehicle. Please be informed that the said vehicle can be inspected at: -

Venue : JD Motorsports Pte Ltd  
25 Kaki Bukit Road 4  
#06-38 Synergy@KB  
Singapore 417800

Contact Person : Mr Ronnie : 9237 3644

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference

Best regards,  
Anil (Secretary)  
M/s Hin Tat Augustine & Partners  
20 Upper Circular Road  
#02-10/12 The Riverwalk  
Singapore 058416  
Tel : 6533 0212  
Direct Fax: 63383536  
Fax : 63383536

**From:** Elaine Cheong <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>  
**Sent:** Wednesday, 30 October 2019 10:45 AM  
**To:** Ruby Ong <[ruby@htapartners.com.sg](mailto:ruby@htapartners.com.sg)>  
**Cc:** Anil Kumar <[anil@htapartners.com.sg](mailto:anil@htapartners.com.sg)>; Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>; Jeffrey Tay <[Jeffrey.Tay@sg.cntaiping.com](mailto:Jeffrey.Tay@sg.cntaiping.com)>  
**Subject:** RE: OUR REF: SNM19D205026-GBG1027G-CML - REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKZ 7356K [OUR REF. TCL.GCN.AN.50673.19.JDM]

**WITHOUT PREJUDICE**

Dear Ruby,

We refer to your email of 29.10.19.

We would like to conduct pre-repair survey of the vehicle at the appointed workshop.

We propose the following list of surveyors to be nominated as the Single Joint Expert to conduct survey of the claimant's vehicle:-

1. ADRIAN LING	6. KENNETH KONG
2. Kelvin Ang	7. SIMON HO
3. SEE CHEW SENG	8. CHUA WEIJIE

4. MOHD FADHILAH BIN OSMAN	9. MARCUS CHUA
5. XING QUO QIANG	10. HENRY NG

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

As per the NIMA Protocol, the survey by our appointed surveyor would include survey of your vehicle pre-repair, after it is dismantled, and post repairs. Hence, you need to provide us / our surveyors with the list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.

As stated above, please inform us and our surveyor after the claimant's vehicle had been repaired so that our surveyor can carry out post repair inspection before the vehicle is returned to your client. Please co-ordinate with our surveyor immediately after the repair is completed.

Regards,

**Elaine Cheong**

Executive (Motor Claims)  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6530  
Fax: 6224 7478 / 6224 7175  
Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

**From:** Claims Dept of CTI

**Sent:** Wednesday, 30 October, 2019 10:33 AM

**To:** Ruby Ong <[ruby@htapartners.com.sg](mailto:ruby@htapartners.com.sg)>; Elaine Cheong <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>; Jeffrey Tay <[Jeffrey.Tay@sg.cntaiping.com](mailto:Jeffrey.Tay@sg.cntaiping.com)>

**Cc:** Anil Kumar <[anil@htapartners.com.sg](mailto:anil@htapartners.com.sg)>

**Subject:** OUR REF: SNM19D205026-GBG1027G-CML - REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKZ 7356K [OUR REF. TCL.GCN.AN.50673.19.JDM]

Dear Elaine,

Please conduct PRS for SKZ7356K.

Note: officer in Elaine Cheong 63896530.

Regards,

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909  
T: (65) 63896116 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](http://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Ruby Ong [mailto:[ruby@htapartners.com.sg](mailto:ruby@htapartners.com.sg)]  
**Sent:** Tuesday, 29 October, 2019 4:23 PM  
**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>  
**Cc:** Anil Kumar <[anil@htapartners.com.sg](mailto:anil@htapartners.com.sg)>  
**Subject:** REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKZ 7356K [OUR REF. TCL.GCN.AN.50673.19.JDM]  
**Importance:** High

Your ref : GBG 1027G  
Our ref : TCL.GCN.ro.50673.19.ess

**WITHOUT PREJUDICE**

29 October 2019

**China Taiping Insurance (Singapore) Pte Ltd**  
Motor Claims Department  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

**By Email Only**

**VERY URGENT**

Dear Sirs,

**CLAIMANT: TRAVEL GSH PTE LTD**  
**NOTICE OF ACCIDENT AND PRE-REPAIR SURVEY - ACCIDENT INVOLVING SKZ 7356K & GBG 1027G ALONG COLLYER QUAY ON 21 OCTOBER 2019 @ 1815 HRS**

We are instructed by Travel GSH Pte Ltd to notify you of a road traffic accident on 21 October 2019 at about 1815hrs along Collyer Quay involving our client's vehicle registration number SKZ 7356K and vehicle registration number GBG 1027G driven by your insured/insured's driver at the material time.

As a result of the accident, our clients' vehicle has been damaged. Before our clients proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,  
Ruby Ong  
Secretary  
M/s Hin Tat Augustine & Partners  
20 Upper Circular Road  
#02-10/12 The Riverwalk  
Singapore 058416  
**Tel : 6533 0212 ext 278**  
Fax : 6338 3536 / 6533 0313

[www.htapartners.com.sg](http://www.htapartners.com.sg)

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

---

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

MNA119141552 / National Assessment Centre Services - Ubi  
 ENTRY DATE & TIME: 25/10/2019 11:00  
 SUBMITTED BY: Rosinda Birte Abdul Wahab

Your NCD will be affected due to late reporting  
 Actual e-Filing Submission Date & Time: 25/10/2019 11:12

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/10/2019 11:00
Date Of Accident	21/10/2019 18:15
Exact Location Of Accident	ALONG COLLYER QUAY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ7356K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRAVEL GSH PTE LTD
Co Reg No	199205400K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-86133011
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	-
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5112417558
Cover Note Number	
<b>Driver</b>	
Name of Driver	NG TERNG YONG, JONATHAN
NRIC No	S8625876E
Date Of Birth	10/09/1986
Occupation	INDOOR
Date Of Driving Pass	23/04/2010
Driving Experience	9 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86133011

Fax Number	
Contact Number	
E-Mail Address	JONATHAN.NG@TRAVELGSH.COM
Address	BLK 271 PASIR RIS ST 21 #08-464
Postcode	510271
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - DIRECTOR
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

**General Information of the Accident**

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	Name: : XINYUN SHEN Gender: : Female
Passenger 2	Name: : HU PEIJU Gender: : Female
Passenger 3	Name: : NATHAN NG Gender: : Male

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

PLS REFER TO THE ATTACHED STATEMENT.

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	GBG1027G
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	

Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	98555025
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Accident Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time: 25/10/19

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Report Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

Accident Sketch Plan

10/25/2019

Church St - Google Maps

Google Maps Church St



Image capture: Jul 2016 © 2019 Google

Singapore

Google

Street View - Jul 2016




<https://www.google.com/maps/@1.2827574,103.8500896,3a,70.3y,146.72h,80.79t/data=!3m1!1e1!3m4!1sGxprdfUViPNN51Dha1GMQ2e07N...> 1/1

**Individual Statement**

SKETCH PLAN

A - SKZ7356K  
B - GBG10276

ALONG  
COLLYER QUAY



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Collyer Quay. The traffic was heavy and slow moving. Suddenly I felt an impact on my rear right side of my vehicle. ~~was~~ vehicle B had hit my vehicle while trying to cut into my lane and due to misjudgement hit my vehicle.


DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time: 25/10/19



Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

 25/10/19  
 Report Centre Personnel's Signature  
 Name:  
 NRIC/FIN No:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



## Enquire Vehicle Transfer Fee

### Vehicle Details

Vehicle No.  
**SKZ7356K**

Make / Model  
**HONDA / ODYSSEY 2.4 EX-S CVT**

Vehicle Type :  
**N19 - Passenger (Co) Company Station Wagon (Single Rate)**

Vehicle Scheme :  
**Normal**

Propellant :  
**Petrol**

Motor No. :  
-

Power Rating :  
-

Maximum Laden Weight :  
**2450 kg**

Year Of Manufacture :  
**2015**

Lifespan Expiry Date :  
-

Quota Premium :  
**\$61,103.00**

Road Tax Expiry Date :  
**31 Jan 2020**

Inspection Due Date :  
**31 Jan 2021**

CO2 Emission :  
**184.00 (g/km)**

CO Emission :  
-

NOx Emission :  
-

Vehicle Attachment 1 :  
**No Attachment**

Chassis No. :  
**JHMRC1880GC201694**

Engine No. :  
**K24W72010744**

Engine Capacity :  
**2356 cc**

Maximum Power Output :  
**129.0 kW (172 bhp)**

Unladen Weight :  
**1769 kg**

Original Registration Date :  
**01 Feb 2016**

COE Category :  
**B - Car above 1600cc or 97kW (130bhp)**

COE Expiry Date :  
**31 Jan 2026**

PARF Eligibility Expiry Date :  
**31 Jan 2026**

Intended Transfer Date :  
**04 Nov 2019**

CEV/VES Rebate Utilised Amount :  
-

HC Emission :  
-

PM Emission :  
-

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	400K
Vehicle No.:	SKZ7356K
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EX-5 CVT
Primary Colour:	Purple
Manufacturing Year:	2015
Engine No.:	K24W72010744
Chassis No.:	JHMRC1880CC201694
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$25,492.00
Original Registration Date:	01 Feb 2016
First Registration Date:	01 Feb 2016
Transfer Count:	0
Actual ARF Paid:	\$27,689.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Jan 2026
PARF Rebate Amount:	\$20,766.00
COE Expiry Date:	31 Jan 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,103.00
COE Rebate Amount:	\$38,123.00
<b>Total Rebate Amount:</b>	<b>\$58,889.00</b>

The information contained herein is correct as at 04 Nov 2019

OK



**Honda Odyssey 2.4A EX-S 8-Seater** \$88,800 \$12,050 /yr 22-Jan-2016 2,356 cc 48,000 km MPV Available

Graded B by **STR**

Low Monthly From \$9xx Only! New Arrival 8 Seater Honda Odyssey For Sales! Super Well Maintained By 1 Fussy Owner! New Battery! New Leather Seats! New Paintwork! Flexible Loan With The Lowest Interest Rate. Free 6 Months Servicing From Our Reputable Worksho...

**View Details**

Model: 22-Oct-2016 Tag: 2016 Honda Odyssey, 2016 Honda odyssey, Honda Odyssey, Honda odyssey, Honda, 2016 Honda odyssey, Honda odyssey, Used Honda



**Honda Odyssey 2.4A EX-S** \$97,800 \$12,360 /yr 05-Jul-2016 2,356 cc 76,909 km MPV Available

1 Owner, 8 Seater, Fully Maintained By Agent, Low Mileage, 5 Years/Unlimited Mileage Warranty By Kah Motor, Excellent Condition Feels Like New, 100% Accident Free, Flexible Finance And Trade In Available.

Sng Auto Pte Ltd

Model: 24-Jun-2016 Tag: 2016 Honda Odyssey, 2016 Honda odyssey, Honda Odyssey, Honda odyssey, Honda, 2016 Honda odyssey, Honda odyssey, Used Honda



**Honda Odyssey 2.4A EX-S** \$95,800 \$12,470 /yr 21-Apr-2016 2,356 cc 57,000 km MPV Available

1 Owner, 8 Seater, Fully Maintained By Agent, Low Mileage, 5 Years/Unlimited Mileage Warranty By Kah Motor, Excellent Condition Feels Like New, 100% Accident Free. WhatsApp To View Now! By Appointment Only!

350 VR Cars

Model: 24-Jun-2016 Tag: 2016 Honda Odyssey, 2016 Honda odyssey, Honda Odyssey, Honda odyssey, Honda, 2016 Honda odyssey, Honda odyssey, Used Honda



**Honda Odyssey 2.4A EX-S** - N.A 21-Apr-2016 2,356 cc - MPV SOLD

Model: 20-Dec-2016 Tag: 2016 Honda Odyssey, 2016 Honda odyssey, Honda Odyssey, Honda odyssey, Honda, 2016 Honda odyssey, Honda odyssey, Used Honda



**Lee Sheng Auto Pte Ltd - Specialist for Honda Car repair, servicing & maintenance**

Lee Sheng Motor Works is a one-stop repair centre offering vehicle servicing, repairs, accident claims and spray painting.

[More info about this shop](#)



**Honda Odyssey 2.4A EX-S** \$88,000 \$11,870 /yr 02-Feb-2016 2,356 cc - MPV Available

Best Selling MPV In The Market! 5 Years Unlimited Mileage Warranty By Kah Motor! Fully Serviced & Maintained Agent Every 10,000km, Buy With A Ease Of Mind! 100% Accident Free, Spacious Interior With Polished Seat, Ample Leg Room, Comfortable To Drive, Very Well...

350 VR Cars

Model: 24-Jun-2016 Tag: 2016 Honda Odyssey, 2016 Honda odyssey, Honda Odyssey, Honda odyssey, Honda, 2016 Honda odyssey, Honda odyssey, Used Honda

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Oct 2019		30 Oct 2019 11:08 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>TRAVEL GSH PTE LTD</b> , Co. Reg. No.: 199205400K								
Vehicle Reg. No.:	<b>SKZ7356K</b>	Date of Loss:	21/10/2019 18:00 - :59 [44 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D205026C02</b>	Policy/Cover Note No.:	DMCVSN30323319011						
Vehicle Reg. No. (Insured):	<b>GBG1027G</b>	Policy No. (Claimant):	5112417558						
		Excess:	S\$500.00						
Repairer:	<b>Jd Motorsports Pte Ltd (HQ)</b> 25 KAKI BUKIT ROAD-4, #06-38 SYNERGY@KB, 417800 Kaki Bukit - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Muhammad Nazril Bin Abdullah</b> ] ... [Final Rpt due 08/11/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKZ7356K (SNM19D205026C02)  
 [GBG1027G]  
 TP  
 TRAVEL GSH PTE LTD  
 Oct 21 2019 6:00PM  
 [-]  
 Jd Motorsports Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
<b>Assessment Reports</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)					Thumbnail		Print		
1	25/10/19 11:12	<b>Accident Statement</b>						Load HTM			
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)					Thumbnail		Print		
1	25/10/19 11:11	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
2	25/10/19 11:11	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
3	25/10/19 11:11	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
4	25/10/19 11:11	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
5	25/10/19 11:11	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
6	25/10/19 11:11	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
7	25/10/19 11:11	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
8	25/10/19 11:11	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
9	25/10/19 11:11	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
10	25/10/19 11:11	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
11	25/10/19 11:11	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print		
1	05/11/19 09:12	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
2	05/11/19 09:12	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
3	05/11/19 09:12	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
4	05/11/19 09:12	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
5	05/11/19 09:12	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
6	05/11/19 09:12	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
7	05/11/19 09:12	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
8	05/11/19 09:12	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
9	05/11/19 09:12	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
10	05/11/19 09:12	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
11	05/11/19 09:12	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
12	05/11/19 09:12	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
13	05/11/19 09:12	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
14	05/11/19 09:12	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
15	05/11/19 09:12	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
16	05/11/19 09:12	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
17	05/11/19 09:12	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
18	05/11/19 09:12	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
19	05/11/19 09:12	<b>General View</b>						Load JPG	<input checked="" type="checkbox"/>		
<b>Documentation</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail		Print		
1	30/10/19 11:08	<b>PRS - SKZ7356K</b>						Load PDF			
No	Finalized On	National Assessment Centre Services (Ubi)					Thumbnail		Print		
1	25/10/19 11:11	<b>Accident Sketch Plan</b>						Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
		[Linked Accident Report Documents]		
2	25/10/19 11:11	<b>Individual Statement</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	25/10/19 11:11	<b>Accident Sketch Plan</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	25/10/19 11:12	<b>Accident Statement</b>	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	25/10/19 11:11	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
2	25/10/19 11:11	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
3	25/10/19 11:11	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
4	25/10/19 11:11	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
5	25/10/19 11:11	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
6	25/10/19 11:11	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
7	25/10/19 11:11	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
8	25/10/19 11:11	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
9	25/10/19 11:11	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
10	25/10/19 11:11	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
11	25/10/19 11:11	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	25/10/19 11:11	<b>Accident Sketch Plan</b>	 Load JPG	<input checked="" type="checkbox"/>
2	25/10/19 11:11	<b>Individual Statement</b>	 Load JPG	<input checked="" type="checkbox"/>
3	25/10/19 11:11	<b>Accident Sketch Plan</b>	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/CT119019145/NCF3E2

**Date:** 13/11/2019

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN30323319011	
Claimant Vehicle No: SKZ7356K	Insured Vehicle No: GBG1027G	
Date of Loss: 21/10/2019	Nature of Claim: TP	Claim No: SNM19D205026C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ7356K	Engine No:	K24W72010744
Make & Model:	HONDA ODYSSEY, 2.4 EXV-S CVT SR (A)	Chassis No:	JHMRC1880GC201694
Reg. Date:	01/02/2016 (Man. Year: 2015)	Odometer:	117482 km
Colour:	Purple		
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Continental 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	30/10/2019	
Date Inspected:	04/11/2019 Inspected At:	Jd Motorsports Pte Ltd (HQ) 25 KAKI BUKIT ROAD 4, #06-38 SYNERGY@KB Singapore 417800
Estimated Period of Repair:	3.0 days	

**Adjuster:** Muhammad Nazril Bin Abdullah

**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Nov 2019)
<b>Parts:</b> M1-SUV	HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKZ7356K)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >