SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Mobile Number

Fax Number
Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

atoresaid.	
	ACCIDENT STATEMENT
Date Of Report	30/10/2019 11:24
Date Of Accident	25/10/2019 09:30
Exact Location Of Accident	ALONG WARINGIN PARK BESIDE SFA EDUHEART INT SHOOL
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SJJ6341E
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD KHAIRI BIN MOHAMMAD KUSBARI
NRIC No	S9315318I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90685143
Alternative Phone No	OTHERS-90685143
Vehicle Particulars	
Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106447353
Cover Note Number	
Driver	
Name of Driver	MUHAMMAD KHAIRI BIN MOHAMMAD KUSBARI
NRIC No	S9315318I
Date Of Birth	09/05/1993
Occupation	INDOOR
Date Of Driving Pass	05/05/2015
Driving Experience	4 YEARS AND 5 MONTHS
Gender	MALE

(LOCAL) +65-90685143

OTHERS-90685143

NOEMAIL

BLK 37 BEDOK SOUTH AVE 2 Address

#02-461

Postcode 460037

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured **OWNER**

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

2

NO

NO

0

General Information of the Accident

COLLIDED INTO PARKED VEHICLE Type Of Accident

Weather Conditions **CLEAR** Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

YES Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name BEDOK SOUTH NEIGHBOURHOOD POLICE CENTRE

ROAD: 20 CHAI CHEE DRIVE, POSTCODE: 469045, COUNTRY: Police Station Address

SINGAPORE

Police Station Contact TEL NO: 1800-2448999 - FAX NO: 62446558

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLS REFER TO THE POLICE REPORT:G/20191026/2108

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP7647H

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

LAI ZENGDONG Name of Driver G3157249K NRIC/Passport Number **Contact Number** 88704236

Address

Postcode

Insurance Company Name

Page 2 of 18

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of ".
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

jun 30/00/19

Name:

NRIC/FIN No.:

Accident Sketch Plan

ian Waringin	Warings walt	
an waringin	Waringin Buk	Vehicle A: SJJ 6341E Vehicle B: YP7647H
DESCRIBE CIRCUMSTA	NCES OF THE ACCIDENT	
	Pefer to police report	
	- TO DOLLEY TOPON	
	Pro 111 Clean	0.000 / 0.000
	Report No: G/201	91026 / 2108
	Report No: G/201	91026 / 2108
	Report No: G/201	91026/2108
	Report No: G/201	91026 / 2108
	Report No: G/201	91026 / 2108
	Report No: G/201	91026 / 2108





1 of 3

Report No. G/20191026/2108

POLICE REPORT (NP299)

Police Station Of Origin Bedok South N.P.C

20 Chai Chee Drive SINGAPORE 469045 Tel No: 1800-2448999

Date/Time Report Made 26/10/2019 21:15	Vide Report No.			Station Diary No. 36
Name Of Informant	Address			
MUHAMMAD KHAIRI BIN MOHAMMAD	APT BLK 37 BEDOK SOUTH AVENUE 2 #02-461			JE 2 #02-461
KUSBARI	SINGAPORE 460037			
ID Type / ID No. NRIC NO / S9315318I	Contact No. Home/Office		Mobile 90685143	
Nationality SINGAPORE CITIZEN	Email Address muhdkhairi1036@gmail.com			
Occupation	Sex Age		Date of Birth	Race
CIVIL SERVANT	Male	26	09/05/1993	Malay
Institution/School Name	Language English			
Date/Time Of Incident 25/10/2019 09:30 - 25/10/2019 22:30	Location Of Incident WARINGIN PARK SINGAPORE			
	Along Waringin Park beside SFA Eduheart Inter		iheart International	

Brief details.

On 25/10/2019 at about 0930hrs, I had parked my car (SJJ 6341E, Honda Civic, Matte Black) along the side road of Waringin Park which was directly beside SFA Eduhearts International School. I secured and locked my car using the key button lock and left the said location to go to work. Everything was intact and nothing was amiss.

Signature Of Officer Recording The Report:

G / Sgt 3 SAM YEO WEN MING

Signature Of Interpreter: Not applicable

Officer In-Charge Of Case: G / Bedok Police Divisional Investigation Branch / Sgt 3 SOPHIA SIM SHI MEI Contact No.: 62447200

Classification Of Case:

26/10/2019 21:15

Date/Time:

Signature Of Informant:

Authentication Stamp



Individual Statement





2 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20191026/2108

On the same day at about 2230hrs, I went back to the place which I had parked my car. After unlocking the car, I noticed a white in colour note which was placed on my car windscreen. I went out of the car and took a look at the note and saw the following content "Please call this no: Mr Dong 88704236". The content was handwritten using a black ink pen. Before calling the said number that was written on the note, I made a visual check around my car and noticed that there was a damage to my front left bumper and also to my front head light. I also noticed that there was a dent and scratch marks seen on my left front bumper. After making a check, I contacted the given number.

A male Chinese subject did answer the call and he informed that he is Mr Dong. He admitted to me that earlier his lorry (YP7647H) had hit onto my car. He mentioned that he is the driver and he informed that while he was reversing, he had collided onto the front left side of my car. He also mentioned that he waited for 20 mins but was unable to get hold of the driver thus he was the one who wrote the note and left it on the windscreen of the car before leaving the said location.

I had already informed my car workshop with regards to the accident and also the damages on my car. As of now the cost of the repair to my car as informed by my workshop is still unknown as further checks are required on their end. My vehicle has an in car camera which is facing the front and rear however it is non-operational once my engine is turn off.

I am lodging this report for insurance claim against the said driver and also for my own record purpose.

Signature Of Officer Recording The Report:	Signature Of Informant:
G / Sgt 3 SAM YEO WEN MING	J.
Signature Of Interpreter: Not applicable	Date/Time: 26/10/2019 21:15
Officer In-Charge Of Case: G / Bedok Police Divisional Investigation Branch / Sgt 3 SOPHIA SIM SHI MEI Contact No.: 62447200	Classification Of Case:






















1 of 3

Report No. G/20191026/2108

POLICE REPORT (NP299)

Police Station Of Origin Bedok South N.P.C

20 Chai Chee Drive SINGAPORE 469045 Tel No: 1800-2448999

Date/Time Report Made 28/10/2019 21:15	Vide Report No.			Station Diary No. 36
Nama Of Informant MUHAMMAD KHAIRI BIN MOHAMMAD KUSBARI	Address APT BLK 37 BEDOK SOUTH AVENUE 2 #02-481 SINGAPORE 460037			
ID Type / ID No. NRIC NO / 89315318I			Mobile 90885143	
Nationality SINGAPORE CITIZEN	Email Address muhdkhairi1038@gmail.com			
Occupation	Sex	Age	Date of Birth	Race
CIVIL SERVANT	Male	28	09/05/1993	Malay
Institution/School Name	Language English			
Date/Time Of Incident 25/10/2019 09:30 - 25/10/2019 22:30	Location Of Incident WARINGIN PARK SINGAPORE Along Wartingin Park beside SFA Eduheart International School			

Brisf details.

On 25/10/2019 at about 0930hrs, I had parked my car (SJJ 6341E, Honda Civic, Matte Black) along the side road of Waringin Park which was directly beside SFA Eduhearts International School. I secured and locked my car using the key button lock and left the said location to go to work. Everything was intact and nothing was amiss.

Signature Of Officer Recording The Report: Signature Of Informant: G / Sgt 3 SAM YEO WEN MING Signature Of Interpreter: Date/Time: Not applicable 28/10/2019 21:15 Officer in-Charge Of Case: G / Bedok Police Divisional Investigation Branch / Sgt 3 SOPHIA SIM SHI MEI Classification Of Case: Contact No.: 62447200

Authentication Stamp







2 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20191026/2108

On the same day at about 2230hrs. I want back to the place which I had perked my car. After unlocking the car, I noticed a white in colour note which was placed on my car windscreen. I went out of the car and took a look at the note and saw the following content. Please call this no. Mr Dong 88704238". The content was handwritten using a black ink pen. Before calling the said number that was written on the note. I made a visual check around my car and noticed that there was a demage to my front left bumper and also to my front head light. I also noticed that there was a dent and scratch marks seen on my left front bumper. After making a check, I contacted the given number.

A male Chinese subject did answer the call and he informed that he is Mr Dong. He admitted to me that earlier his long (YP7647H) had hit onto my car. He mentioned that he is the driver and he informed that while he was reversing, he had collided onto the front left side of my car. He also mentioned that he waited for 20 mins but was unable to get hold of the driver thus he was the one who wrote the note and left it on the windscreen of the car before leaving the said location.

I had already informed my car workshop with regards to the accident and also the damages on my car. As of now the cost of the repair to my car as informed by my workshop is still unknown as further checks are required on their end. My vehicle has an in car camers which is facing the front and rear however it is non-operational once my engine is turn off.

I am lodging this report for insurance claim against the said driver and also for my own record outpose.

Signature Of Officer Recording The Report:	Signature Of Jeformant:
G / Sgt 3 SAM YEO WEN MING	y.
Signature Of interpreter: Not applicable	Date/Time: 26/10/2019 21:15
Officer In-Charge Of Case: G / Bedck Police Divisional Investigation Branch / Sgt 3 SOPHIA SIM SHI MEI Contact No.: 82447200	Classification Of Case:





191028/2108 3 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20191026/2108

Person Name	LAI ZENGDONG			
ID Type	FIN NO	ID No.	G3157249K	
Gender	Male	Age	32	
Nationality	CHINESE	Race	Chinese	
Language	English	Occupation	DELIVERY DRIVER	
Address Type	Apt Blk	Address	APT BLK 60 KIM KEAT ROAD #04-03 SINGAPORE 328827	
Mobile No	88704236		THE RESTRICTION OF THE PROPERTY OF THE PROPERT	

Signature Of Officer Recording The Report:

G / Sgt 3 SAM YEO WEN MING

Signature Of Interpreter: Not applicable

Officer In-Charge Of Case: G / Bedok Police Divisional Investigation Branch / Sgt 3 SOPHIA SIM SHI MEI Contact No.: 62447200

Authentication Stamp

SHEAPORE PORCE

SIGNATURE

Signature Of Informant:

Date/Time: 26/10/2019 21:15

Classification Of Case: