

22/07/2007

ASS. REC. BY:

REF:

CS/INC19C19151/EV6302

Special Instruction:

SUVA/OT

Steve

ASSIGNMENT (Office)

From (Person):

Theresa Vimala

of

INC

Date/Time 30 October 2019

Estimated Cost:

Bill to:

OD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMH 8329D

Insured:

YN 7602Y

at Workshop m/s

Pegasus Engineering & Trading Pte Ltd

Tel:

6513 7748

of

74 Kian Teck Road

Policy No:

Claim No:

MT 11068789-001

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

"wp"

D.O.A. 26/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

30/10/19 @ 11:45pm

Person Contacted:

yoyo

Vehicle IN / OUT

Date/Time

Action/Instruction (/) Estimate

YN 7602Y X

SMH 8329D X

Steve


REF:

ASSIGNMENT

am: _____ Date: _____
 Limited Cost: _____
 / TP / WS / TP RES / OD RES / EVA / INV / MV
 Inspect Vehicle No: _____
 Workshop m/s: _____
 Prod: _____
 cy No: _____
 ms No: _____
 Insured: _____ Excess: _____
 Client's Record: _____
 a of Veh: _____

Veh No: SMH83290 Yr Regn: 11/2/19
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hyundai OS Kona EV c.c. N/A (Electric car)
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 79414 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 Ci/No: KMHK28164KU024500
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/55R17
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or TRIANGLE



Policy Condition)
 Mark: The veh had commenced its repair at the time of inspection.

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.I. <u>30/10/19</u>
Survey held at <u>Pegasus</u>	<u>2:29pm</u>
Des. of Damages: <input checked="" type="checkbox"/> Frt / <input type="checkbox"/> Rear / <input type="checkbox"/> O/S / <input type="checkbox"/> N/S / <input type="checkbox"/> UIC / <input type="checkbox"/> Rooftop or	

or Market Value: _____
 Accident Report: _____ Consistent? : Yes or No
 / PR Seen: _____ Consistent? : Yes or No
 Repairs: _____ days Res.: Yes or No
 Sum: _____ % 3 Val.: Yes or No

1 REV / REP. / 24 HRS
 Vehicle: IN / OUT
 Person Contacted: _____

The UIC / Chassis frame / Body Structure affected due to collision.

o / Time	Action / Instruction
	MV- 155K 19/11/19 Finalize confir. \$ 3783.92, 3 days (Vivian) (Reol 12,818.31, 7790)

RECEIVED 20 NOV 2019

ma, File Pkss to? : Profl. Report
 : Final Report

Days Of Repair: 3
 Resurvey No. of Trip: 2

Survey Fee:	
Transportation:	
_____ \$ + RS. _____ \$	
_____ \$	
_____ \$	
TOTAL	<u>250</u>

ma, File Return to? 20/11 - typist
 ort Format : TP
 o Sum / I.B.I.: (\$ 3783.92)

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech Invs (\$)
 Weekend (\$)

Summer Lee (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Wednesday, 30 October, 2019 2:23 PM
To: Admin-D (LKKAuto); assignments
Cc: SUR
Subject: RE: TP CASES FARMED OUT TO LKK ON 30/10/2019

Here is the list of OIC details, etc... Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers



From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 30 October 2019 10:51 AM
To: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>; assignments <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 30/10/2019

Dear Theresa,

Thank you for the assignment.

Please be informed that vehicle SQ 85R is not in the workshop, repairer will arrange.

Celine Fong

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Theresa Vimala D/O Balagangadharan [mailto:thrsvim.bala@income.com.sg]
Sent: Wednesday, 30 October 2019 10:13 AM
To: assignments <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 30/10/2019

Dear LKK

Please assist to survey the following vehicles :

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	SWEE KENG	MT/1068827-001	30/10/2019	SHA213C	DING AUTOMOTIVE PTE LTD	31 CORPORATION ROAD SINGAPORE 649825	VADIVELAN MOHAN / 96891857		XE4850B	25/10	
2	AZHARI	MT/1068789-001	30/10/2019	5MH8329D	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	Yoyo / 65137748		YN7602Y	26/10	
3	ERIC TANG	MT/1068895-001	30/10/2019	5MN2898K	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	Chern / 65137748	14:00-16:00	SGRS107C	29/10	Owner waiting
4	FIONA	MT/1068926-001	30/10/2019	5KF4019J	VOLKSWAGEN GROUP SINGAPORE PTE LTD	17 TUAS AVENUE 9 SINGAPORE 639197	Tang Shu Shi / 9386-7833		YP7083J	25/10	
5	DAVID	MT/1065964-002	30/10/2019	XE3444Y	C L AUTO PTE LTD	48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586	Paul Antony Fernandez / 67956125	14:00-16:00	GRC628A	7/10	To call b4 survey
6	CHARLOTTE	MT/1054902-001	30/10/2019	SQ85R	MTM PERFORMANCE AUTO PTE LTD	48 TOH GUAN ROAD EAST #01-115 ENTERPRISE HUB SINGAPORE 608586	Erwin Ho / 92210404		SJS7108J	20/7	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg




At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Veron Chen (LKKAuto)

From: Steve Chen (LKK Auto)
Sent: Wednesday, 20 November 2019 9:11 AM
To: Vivian Tan
Cc: ar_claims@pegasusengrg.com.sg; Veron Chen (LKKAuto)
Subject: Finalise For SMH8329D (DOA 26/10/2019)

Dear Vivian,

Kindly inform that. Correct the finalize to \$3,783.92 (before GST).

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vivian Tan [mailto:vivian.pegasusengrg@gmail.com]
Sent: Tuesday, November 19, 2019 4:21 PM
To: Steve Chen (LKK Auto)
Cc: ar_claims@pegasusengrg.com.sg
Subject: Re: Finalise For SMH8329D (DOA 26/10/2019)

Without Prejudice,

Dear Steve,

We confirm the final COR @ P/P S\$3,783.91 (before GST) and 03 repair days.

Best Regards,

Vivian Tan

Pegasus Engineering & Trading Pte Ltd

74 Kian Teck Road S628800

Office: 65137748

Fax: 62513161

On Mon, 18 Nov 2019 at 17:42, Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Vivian,

Kindly refer our finalize \$3783.91 (P/P, before GST). 3 repair days.

Kindly confirm.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vivian Tan [mailto:vivian.pegasusengrg@gmail.com]

Sent: Friday, November 15, 2019 12:12 PM

To: Steve Chen (LKK Auto)

Cc: SUR; ar_claims@pegasusengrg.com.sg

Subject: RE: Finalise For SMH8329D (DOA 26/10/2019)

WITHOUT PREJUDICE

Dear Mr. Steve,

-

Finalise amount @ Part By Part \$6,890.86 @ 03 working days.

-

Parts - \$6,160.86

Labour - \$730.00

Total - \$6,890.86

-

Please check and confirm

-

Best Regards,

Vivian Tan

Pegasus Engineering & Trading Pte Ltd

74 Kian Teck Road S628800

Office: 65137748

Fax: 62513161

Steve Chen (LKK Auto)

From: Vivian Tan <vivian.pegasusengrg@gmail.com>
Sent: Tuesday, November 19, 2019 4:21 PM
To: Steve Chen (LKK Auto)
Cc: ar_claims@pegasusengrg.com.sg
Subject: Re: Finalise For SMH8329D (DOA 26/10/2019)

Without Prejudice,

Dear Steve,

We confirm the final COR @ P/P S\$3,783.91 (before GST) and 03 repair days.

Best Regards,

Vivian Tan

Pegasus Engineering & Trading Pte Ltd

74 Kian Teck Road S628800

Office: 65137748

Fax: 62513161

On Mon, 18 Nov 2019 at 17:42, Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Vivian,

-

Kindly refer our finalize \$3783.91 (P/P, before GST). 3 repair days.

-

Kindly confirm.

-

-

-

-

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	200G
Vehicle Details	
Vehicle No.:	SMH8329D
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	OS KONA EV
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	-
Chassis No.:	KMHK281GUKU024500
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$39,049.00
Original Registration Date:	11 Feb 2019
First Registration Date:	11 Feb 2019
Transfer Count:	0
Actual ARF Paid:	\$26,669.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Feb 2029
PARF Rebate Amount:	\$20,001.00
Intended COE Rebate Details	
COE Expiry Date:	10 Feb 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,302.00
COE Rebate Amount:	\$29,984.00
Total Rebate Amount:	\$49,985.00

The information contained herein is correct as at 30 Oct 2019

OK

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No:
SMH8329D

Make / Model:
HYUNDAI / DS KONA EV

Vehicle Type:
Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover

Vehicle Scheme:
Normal

Propellant:
Electric

Motor No.:
EM16JCW079BJ

Power Rating:
150.0 kW

Maximum Laden Weight:
2170 kg

Year Of Manufacture:
2019

Lifespan Expiry Date:
-

Quota Premium:
\$32,302.00

Road Tax Expiry Date:
10 Feb 2020

Inspection Due Date:
10 Feb 2022

CO2 Emission:
55.20 (g/km)

CO Emission:
-

NOx Emission:
-

Vehicle Attachment 1:
No Attachment

Chassis No.:
KMHK2B1GUKU024500

Engine No.:
-

Engine Capacity:
-

Maximum Power Output:
150.0 kW (201 bhp)

Unladen Weight:
1743 kg

Original Registration Date:
11 Feb 2019

CDE Category:
B - Car above 1600cc or 97kW (130bhp)

CDE Expiry Date:
10 Feb 2029

RARP Eligibility Expiry Date:
10 Feb 2029

Intended Transfer Date:
30 Oct 2019

CEV/VES Rebate Utilised Amount:
\$20,000.00

HC Emission:
-

PM Emission:
-

Fees To Be Paid For Transfer

Transfer Fees

\$25.00

Print

OK

Save as PDF

Copy as Text

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/10/2019 11:11
Date Of Accident	26/10/2019 09:35
Exact Location Of Accident	YISHUN AVE 4 BLK 662-666 MSCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH8329D
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-85688644
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	HYUNDAI
Model	KONA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	D29114745MKF
Cover Note Number	

Driver

Name of Driver	WONG WING CHIONG
NRIC No	S1528202I
Date Of Birth	07/02/1962
Occupation	OUTDOOR
Date Of Driving Pass	29/05/1984
Driving Experience	35 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85688644
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	50L FABER HEIGHTS #04-83
Postcode	129205
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 26 OCTOBER 2019 AT ABOUT 0936HRS, I WAS DRIVING MY VEHICLE AT BLK 665 YISHUN AVENUE 4 CARPARK. I DROVE MY VEHICLE TOWARDS EXIT OF BLK 665, SUDDENLY A VEHICLE YN7602Y IN FRONT OF MY VEHICLE REVERSED. I HONKED SO MANY TIMES, THAT TIME MY VEHICLE WAS STATIONARY, BUT THE VEHICLE STILL REVERSED AND COLLIDED ONTO MY FRONTAL PORTION. NOBODY WAS INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH GRAB
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN7602Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

2

Passenger 1

NAME: :

GENDER: :

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 26/10/16
1057h


Reporting Centre Person's Signature
Name: Channa Raj
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



BLK 665 YISHUN Ave 4 carpark

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26 October 2014 at about 0936hrs I was drove my vehicle at BLK 665 Yishun Avenue 4 carpark. I drove my vehicle towards exit of blk 665. suddenly a vehicle YN 7602Y in front of my vehicle was reversed. I saw him so many times. That time my vehicle was stationary. But the vehicle still reversed and collided onto my front portion. Nobody was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 26/10/14 - 1051R

Reporting Centre Personnel's Signature
Name: Khaw Kah
NRIC/FIN No.:



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : YOYO TIAN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
--	--

Quotation No. : QO19/10-1277	Quotation Date : 29/10/2019	Terms : 30 DAYS
Vehicle No. : SMH8329D	Chassis No. : KMHK281GUKU024500	Third Party Insurer : NTUC
Model : HYUNDAI KONA	Date of Accident : 26/10/2019	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	FRONT BUMPER / CR4	1	1,580.0000	494.70 / 1,580.00
2	FRONT BUMPER SIDE RETAINER ? X NAI	2	138.0000	276.00
3	FRONT BUMPER CLIPS / M	10	5.0000	30 / 50.00
4	FRONT BUMPER LOWER COVER X NAI	1	1,098.0000	1,098.00
5	FRONT BUMPER LOWER COVER CLIPS X NN	10	5.0000	50.00
6	FRONT BUMPER UPPER CENTER MOULDING (SILVER COLOUR) ? X NAI	1	398.0000	398.00
7	FRONT 'HYUNDAI' EMBLEM X NN	1	65.0000	65.00
8	FRONT EMBLEM BASE ? NN	1	95.0000	95.00
9	FRONT HEADLAMP ? / BR (CLH)	2	2,798.0000	1384.40 / 5,596.00
10	FRONT DAY RUNNING LIGHT ? / BR (CLH)	2	1,454.0000	722.10 / 2,908.00
11	FRONT REINFORCEMENT ? X NN	1	1,080.0000	1,080.00
12	FRONT SPONGE ? X NN	1	298.0000	298.00
13	FRONT SUPPORT PANEL ? X NN	1	1,708.2000	1,708.20
14	FRONT REINFORCEMENT BRACKET LOWER ? X NN	2	106.0000	212.00
15	FRONT REINFORCEMENT BRACKET UPPER ? X NN	2	106.0000	212.00
16	FRONT CHARGING PORT DOOR ? X NN	1		
17	FRONT CHARGING PORT ASSY ? / BR	1	1,466.6800	976.20 / 1,466.68
18	FRONT CHARGING PORT COVER CAP ? X NN	1		
19	FRONT SUPPORT PANEL BRACKET LHS ? / OT	1	372.4000	210 / 372.40
20	LESS 20%	1	-3,493.0600	-3,493.06
21	TO REMOVE & REFOCUS FRONT HEADLAMP	1	120.0000	30 / 120.00
22	TO REMOVE & RECONDUCT ELECTRIC VOLTAGE PER A REQUIREMENT FOR SAFETY PRECAUTIONS	1	250.0000	150 / 250.00

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : YOYO TIAN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
--	--

Quotation No. : QO19/10-1277	Quotation Date : 29/10/2019	Terms : 30 DAYS
Vehicle No. : SMH8329D	Chassis No. : KMHK281GUKU024500	Third Party Insurer : NTUC
Model : HYUNDAI KONA		Date of Accident : 26/10/2019
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
23	TO KNOCKING & PANEL BEATING	1 250	1,000.0000	1,000.00
24	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS	1 250	1,200.0000	1,200.00
25	TO DISCONNECT ELECTRIC POWER	1 50	60.0000	60.00

Handwritten signature and date: 30/10/19

*Steve (LKK)
8322 8813*

with Mr. 30/10/19, 2.30pm

3 day

*PIP
By Bel spy*

P-3053.92

L-750

3783.91

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sub Total 16,602.22
GST(7.00%) 1,162.16
Total (SGD) 17,764.38

Please conduct the survey at Pegasus Engineering @ 74 Kian Teck Road Singapore 628800



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19019151/Evf3n2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 25-11-2019



ATTN: AZHARI

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 7602Y	Veh. Inspected	SMH 8329D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1068789-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	30/10/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI OS KONA EV	c.c	0
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHK281GUKU024500	Colour	GREY
Odometer	79414 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	TRIANGLE	6 mm
L/H Front Tyre	215/55 R17	TRIANGLE	6 mm
R/H Rear Tyre	215/55 R17	TRIANGLE	6 mm
L/H Rear Tyre	215/55 R17	TRIANGLE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/10/2019	Inspect Date / Time	30/10/2019 (02:29 PM)
Survey held at	74 KIAN TECK ROAD		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 8329D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	CRUSHED	1,580.00	494.70
2	FRONT BUMPER SIDE RETAINER @\$138.00	NOT NECESSARY	276.00	-
10	FRONT BUMPER CLIPS @\$5.00	NECESSARY	50.00	30.00
1	FRONT BUMPER LOWER COVER	NOT NECESSARY	1,098.00	-
10	FRONT BUMPER LOWER COVER CLIPS @\$5.00	NOT NECESSARY	50.00	-
1	FRONT BUMPER UPPER CENTER MOULDING (SILVER COLOUR)	NOT NECESSARY	398.00	-
1	FRONT "HYUNDAI" EMBLEM	NOT NECESSARY	65.00	-
1	FRONT EMBLEM BASE	NOT NECESSARY	95.00	-
2	FRONT HEADLAMP @\$2798.00	N/S BROKEN	5,596.00	1,384.40
2	FRONT DAY RUNNING LIGHT @\$1454.00	N/S BROKEN	2,908.00	722.10
1	FRONT REINFORCEMENT	NOT NECESSARY	1,080.00	-
1	FRONT SPONGE	NOT NECESSARY	298.00	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	1,708.20	-
2	FRONT REINFORCEMENT BRACKET LOWER @\$106.00	NOT NECESSARY	212.00	-
2	FRONT REINFORCEMENT BRACKET UPPER @\$106.00	NOT NECESSARY	212.00	-
1	FRONT CHARGING PORT DOOR (NPA)	NOT NECESSARY	-	-
1	FRONT CHARGING PORT ASSY	BROKEN	1,466.68	976.20
1	FRONT CHARGING PORT COVER CAP (NPA)	NOT NECESSARY	-	-
1	FRONT SUPPORT PANEL BRACKET LHS	BENT	372.40	210.00
	LESS 20% DISCOUNT		-3,493.06	-763.48
			13,972.22	3,053.92
LABOUR				
	TO REMOVE & REFOCUS FRONT HEADLAMP.		120.00	30.00
	TO REMOVE & RECONDUCT ELECTRIC VOLTAGE PER A REQUIREMENT FOR SAFETY PRECAUTIONS.		250.00	150.00
	TO KNOCKING & PANEL BEATING.		1,000.00	250.00
	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.		1,200.00	250.00
	TO DISCONNECT ELECTRIC POWER.		60.00	50.00
			2,630.00	730.00
GRAND TOTAL			16,602.22	3,783.92

Report Ref No. CS/INC19019151/Evf3n2



RECOMMENDED COST OF REPAIRS (CONFIRMED)			3,783.92
---	--	--	----------

Report Ref No. CS/INC19019151/Evf3n2

CHEN TSUE YEE
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.