

22/03/2002

ASS. REC. BY:

REF:

CS/INC19019170/11y3

Special Instruction:

Surveyor

Taufik

ASSIGNMENT (Office)

From (Person): Theresa Vimala

of INC

Date/Time: 30 October 2019

Estimated Cost:

Bill to:

OD / / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XE 3444Y

Insured: GBC 628A

at Workshop m/s C L Auto Pte Ltd

Tel: 6795 6125

of 48 Toh Guan Road East #02-125

Policy No:

Claim No:

MT / 1065964-002

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

"wpi"

D.O.A. 07/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 30/10/2019 @ 11:52a.m

Person Contacted:

Paul

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBC 628A: X
	XE 3444Y: X

ASS. REC. BY:

Tang

REF:

INC

ASSIGNMENT

COE 2022 Nov

From: Date: 30/10

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XE3444Y.

at Workshop m/s CL Auto.

of H8 Poh Guan Rd East #02-125

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

2pm - 4pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: XE 3444Y Yr Regn: 2007, Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan CGR345 c.c. 13074

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 330909 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: CGR34CL500110.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 295/80R22.5

R: (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Roadwing.

Front

Rear

R/Bal. 8 mm R/Bal. 8/8 mm

L/Bal. 8 mm L/Bal. 8/8 mm

D.O.A. D.O.I. 30/10/19

Survey held at CL Auto.

Des. of Damages (Fr) Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/7 Submit Preli Report

Date/Time, File Pass to?

Preli. Report

Days Of Repair: 7

1)

Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2) 27/7/20 Typist

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Report Format:

Lump Sum / L.S.I. (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Summer Lee (LKK Auto)

From: Theresa Vimala.D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Wednesday, 30 October, 2019 2:23 PM
To: Admin-D (LKKAuto); assignments
Cc: SUR
Subject: RE: TP CASES FARMED OUT TO LKK ON 30/10/2019

Here is the list of OIC details, etc... Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers



From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 30 October 2019 10:51 AM
To: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>; assignments <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 30/10/2019

Dear Theresa,

Thank you for the assignment.

Please be informed that vehicle SQ 85R is not in the workshop, repairer will arrange.

Celine Fong

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Theresa Vimala D/O Balagangadharan [mailto:thrsvim.bala@income.com.sg]
Sent: Wednesday, 30 October 2019 10:13 AM
To: assignments <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 30/10/2019

Dear LKK

Please assist to survey the following vehicles .

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	SWEE KENG	MT/1068827-001	30/10/2019	SHA213C	DING AUTOMOTIVE PTE LTD	31 CORPORATION ROAD SINGAPORE 649825	VADIVELAN MOHAN / 96891857		XE4850B	25/10	
2	AZHARI	MT/1068789-001	30/10/2019	SMH8329D	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	Yoyo / 65137748		YN7602Y	26/10	
3	ERIC TANG	MT/1068895-001	30/10/2019	SMN2898K	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	Chern / 65137748	14:00-16:00	SGK5107C	29/10	Owner waiting
4	FIONA	MT/1068926-001	30/10/2019	SKF4019J	VOLKSWAGEN GROUP SINGAPORE PTE LTD	17 TUAS AVENUE 9 SINGAPORE 639197	Tang Shu Shi / 9386-7833		YP7083J	25/10	
5	DAVID	MT/1065964-002	30/10/2019	XE3444Y	C L AUTO PTE LTD	48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586	Paul Antony Fernandez / 67956125	14:00-16:00	GBC628A	7/10	To call b4 survey
6	CHARLOTTE	MT/1054902-001	30/10/2019	SQ85R	MTM PERFORMANCE AUTO PTE LTD	48 TOH GUAN ROAD EAST #01-116 ENTERPRISE HUB SINGAPORE 608586	Erwin Ho / 92210404		SJS7108J	20/7	

Please contact workshops.

Please revert to officer-in-charge after survey.


Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg




At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find-out more at income.com.sg/careers



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/10/2019 10:26
Date Of Accident	07/10/2019 06:55
Exact Location Of Accident	TUAS CRESCENT TOWARDS TUAS AVENUE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE3444Y
Insured/Policyholder	
Name Of Registered Owner	JIN CHOON CIVIL ENGINEERING PTE LTD
Co Reg No	198602272M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92320364
Alternative Phone No	OFFICE-92320364

Vehicle Particulars

Manufacturer	NISSAN
Model	CGB45CLSMNB-13.1 D (M)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	DMCG19001713
Cover Note Number	

Driver

Name of Driver	MEI JIANHUA
Passport No/FIN	G3063569N
Date Of Birth	04/08/1979
Occupation	INDOOR
Date Of Driving Pass	21/10/2014
Driving Experience	4 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92320364
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	12 TUAS SOUTH STREET 6
Postcode	636911
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC628A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident Vehicles: XE 3444Y (Client) & GBC 628A
 Date of Accident: 07/10/2019
 Time of Accident: At about 6.55am
 Location: Along Tuas Crescent towards Tuas Avenue 2

BRIEF FACTS OF ACCIDENT CASE

On 07/10/2019 at about 0655Hours, I was driving Company Lorry Reg No: XE 3444Y on the extreme right lane of this 2 lane traffic.

As I was approaching the traffic light junction, I slowed down. Suddenly another Vehicle Reg No: GBC 628A overtook my lorry from the left lane onto the right lane in which my lorry was slowing down.

Vehicle Reg No: GBC 628A after overtaking my lorry suddenly stopped abruptly, giving me no time at all to stop safely.

Due to the dangerous act by driver of GBC 628A switching lanes and stopping abruptly; I had no other choice but to collide onto the rear of GBC 628A.

No one was injured in this road traffic accident.

Due to the impact, as shown in the photographs taken after the road traffic accident, my lorry front windscreen hit GBC 628A canopy top right rear frame and broken; front left headlamp and front left signal light broken and the front lorry bumper damaged.

Photograph evidences proved that my lorry front left vehicle body was damaged because the driver of GBC 628A suddenly switched from left lane to right lane where I was driving my lorry XE 3444Y.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	272M
Vehicle Details	
Vehicle No.:	XE3444Y
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2020
Vehicle Make:	NISSAN
Vehicle Model:	CGB45CLSMNB
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	GE13334326B
Chassis No.:	CGB4CLS00110
Maximum Power Output:	-
Open Market Value:	\$126,780.00
Original Registration Date:	19 Dec 2007
First Registration Date:	19 Dec 2007
Transfer Count:	4
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,958.00
COE Rebate Amount:	\$13,264.00
Total Rebate Amount:	\$13,264.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 10 Jan 2020

OK

CL Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586
 TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg
 RCB NO:198800292M

264
 30/10/19
 97846868
 Sean

M/S : JIN CHOON CIVIL ENGINEERING PTE LTD,
 12 TUAS SOUTH STREET 6,
 SINGAPORE 636911

Estimate No: EST1900235
Date: 22 Oct 2019
Policy No: DMCG19001713
Veh Reg No: XE3444Y
Make/Model: NISSAN CGB45CLSMNB
Chassis No: CGB4CLS00110
Engine No: GE13334326B
Reg. Date: 19/12/2007

TEL: 6565 9511 **FAX:** 6565 9513
ATTN: MR.SEAN PAY BOON TAT
Your Ref No: XE3444Y
Claim Type: Third Party
Accident Date: 07/10/2019

Estimate Repair Cost to Vehicle No :XE3444Y

Description	Quantity	List Price	Amount
		S\$	S\$
Special Net:			
1 FRONT NUMBER PLATE	1 PC	45.00	30
		45.00	45.00
List Price:			
2 FRONT GLASS	1 PC	1,300.00	cur
3 FRONT GLASS INNER SEAL	1 PC	28.00	ng
4 FRONT GLASS GUM	3 TUBE	84.00	ner
5 FRONT GLASS TOP CENTER MOULDING	1 PC	80.00	ner
6 FRONT GLASS LOWER CENTER MOULDING	1 PC	80.00	ner
7 FRONT GLASS L/H MOULDING	1 PC	110.00	ner
8 FRONT GLASS R/H MOULDING	1 PC	110.00	ner
9 FRONT CENTER WIPER ARM	1 PC	130.00	bt
10 FRONT CENTER WIPER RUBBER	1 PC	26.00	out
11 FRONT L/H TOP HANDLE	1 PC	120.00	cur
12 FRONT BONNET	1 PC	800.00	okt
13 FRONT L/H BONNET HINGE	1 PC	120.00	?
14 FRONT L/H BONNET LOCK	1 PC	120.00	x
15 FRONT R/H BONNET LOCK	1 PC	120.00	x
16 FRONT BONNET TOP GRILL	1 PC	400.00	cur
17 FRONT TOP GRILL CLIP	1 SET	80.00	ner
18 FRONT LOWER GRILL	1 PC	300.00	cur
19 FRONT LOWER GRILL CLIP	1 SET	40.00	ner
20 FRONT BUMPER - CENTER ASSY	1 PC	800.00	bt
21 FRONT BUMPER R/H BRACKET	1 PC	240.00	?
22 FRONT BUMPER L/H BRACKET	1 PC	240.00	?
23 FRONT BUMPER TOP L/H STEP PAD	1 PC	90.00	bt
24 FRONT BUMPER TOP CENTER STEP PAD	1 PC	90.00	de
25 FRONT BUMPER R/H STEP PAD	1 PC	90.00	de
26 FRONT BUMPER R/H CENTER GRILL	1 PC	120.00	mis
27 FRONT BUMPER L/H CENTER GRILL	1 PC	120.00	mis
28 FRONT L/H BUMPER OUTER BUMPER SIDE	1 PC	60.00	x
29 FRONT L/H BUMPER GARNISH	1 PC	120.00	?
30 FRONT L/H HEAD LAMP ASSY	1 PC	450.00	cur
31 FRONT L/H HEAD LAMP PANEL	1 PC	280.00	?
32 FRONT L/H SIGNAL LAMP ASSY	1 PC	90.00	out
33 FRONT L/H SIGNAL LAMP BRACKET	1 PC	80.00	?
34 FRONT R/H HEAD LAMP ASSY	1 PC	450.00	cur
35 FRONT R/H HEAD LAMP PANEL	1 PC	280.00	?
36 FRONT R/H SIGNAL LAMP	1 PC	90.00	?

C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586
 TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg
 RCB NO:198800292M

M/S : JIN CHOON CIVIL ENGINEERING PTE LTD ,
 12 TUAS SOUTH STREET 6,
 SINGAPORE 636911

TEL: 6565 9511 FAX: 6565 9513
 ATTN: MR.SEAN PAY BOON TAT
 Your Ref No: XE3444Y
 Claim Type: Third Party
 Accident Date: 07/10/2019

Estimate No: EST1900235
Date: 22 Oct 2019
Policy No: DMCG19001713
Veh Reg No: XE3444Y
Make/Model: NISSAN CGB45CLSMNB
Chassis No: CGB4CLS00110
Engine No: GE13334326B
Reg. Date: 19/12/2007

Estimate Repair Cost to Vehicle No :XE3444Y

Description	Quantity	List Price	Amount
		S\$	S\$
37 FRONT R/H SIGNAL LAMP BRACKET	1 PC	80.00 ?	
38 FRONT R/H BUMPER SIDE GARNISH	1 PC	120.00 X	
39 FRONT BUMPER CENTER SUBFRAME ASSY	1 PC	650.00 ?	
		8,588.00	
	Less 30%	2,576.40	6,011.60
Others:			
40 FRONT WINDSCREEN SEAL	3 TUBE	75.00 <i>ae</i> ✓	
41 INNER SEAL	1 PC	30.00 <i>ae</i> ✓	
42 ERP BRACKET & FIXING	1 PC	15.00 <i>ae</i> ✓	
43 PRIMER AND CLEANER	1 SET	18.00 <i>ae</i> ✓	
		138.00	138.00
Labour Charges:			
44 TO REMOVE & FIXING FRONT WINDSCREEN GLASS & REPLACE WINDSCREEN GLASS	1 JOB	220.00 <i>180</i>	
45 REMOVE & FIXING FRONT METER & DESH BOX & AIR CON BLOWER FILTER	1 JOB	380.00 <i>200? photo</i>	
46 TO KNOCKING FIRE WALL & PANEL & BUMPER CROSS MEMBER & SUBFRAME & FRONT R/H & L/H HEAD LAMP & PANEL & WINDSCREEN GLASS & REPLACE BUMPER	1 JOB	1,100.00 <i>1000</i>	
47 TO RESPRAY PAINT PANEL & BONNET & BUMPER & LOWER SPOILER & GRILL	1 JOB	1,000.00 <i>900</i>	
		2,700.00	2,700.00
Total			S\$ 8,894.60

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND EIGHT HUNDRED NINETY FOUR AND CENTS SIXTY ONLY

*Tan Jiah 97495749 /
 67418434
 WP 30/10/19 @ 3:55pm
 Lumpsum
 Resurvey bkg after paint.
 7 days
 sw@clauto.com*

For C L Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: