

ASS. REC. BY: Sun Pih.

REF:

III

ASSIGNMENT

From:

Date:

11/11/19

Estimated Cost:

OD/TP WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

SMA 5461K

at Workshop m/s

Hua Hong

of

25D Sungai Madut street 1

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Vehicle In

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMA 5461K.

Yr Regn: 12/Jun/2018.

Type:

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Freed Hybrid.

c.c 1496

Colour

Grey.

A/C: Insured / Std / NI / NA

Sp. Reading

114553.

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GB71666576

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/60 R15

R: 195/60 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

25/10/2019.

D.O.I.

11/11/2019

Survey held at

Hua Hong

Des. of Damages: Frt /

Rear

O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV= 85,810

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.I. (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL