





**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHAS963M  
 MAKE : HYUNDAI  
 MODEL : IONIQ

DATE: 29. Oct. 2019

DOA: 26. Oct. 2019

**CHINA**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT DOOR - LH <i>x repair</i>			\$1,797.20
1	REAR DOOR - LH <i>x repair</i>			\$1,789.90
1	REAR WHEEL COVER - LH <i>x see</i>			\$346.60
	<i>for fender (LH) x repair</i>			
	<b>SUB TOTAL</b>			<b>\$3,933.70</b>
	<b>LESS 20%</b>			<b>\$786.74</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$3,146.96</b>
1	FRONT DOOR COMFORT LOGO <i>---</i>			\$75.00
1	REAR DOOR APP LOGO <i>---</i>			\$80.00
				<b>\$155.00</b>
	<b>Labour Charge</b>			<i>320</i>
1	Panel Beating			\$960.00
1	Spray Painting Charge			<i>600</i> \$250.00
1	Wiring Charge			<i>ms</i> x \$80.00
1	Tuff Kote			<i>an</i> x \$80.00
2	Transfer of Doors		\$120.00	<i>an</i> x \$240.00
	<b>TOTAL LABOUR</b>			<b>\$2,110.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$5,411.96</b>

Nett  
Nett



*Ka hui (1/1/19)*

*29/10/19 15:20L*  
*2 Pys*

*At the Repair p Loto*

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Our Job Ref No : 305344839

Date : 30. Oct. 2019

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHA5963M

Date of Accident: 26. Oct. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA SGP5716T

2. The finalized amount shall be:

(a) Spare Parts after List discount \$155.00

(b) Labour Charges \$920.00

**Total for Part-By-Part Repair Cost** \$1,075.00

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: \_\_\_\_\_

**Final Lumpsum Repair cost** \_\_\_\_\_

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Kalvin

Date : 31/10/19

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305344839  
 REGN NO : SHA5963M  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G2)  
 DATE OF REGN : 08.11.2018  
 DATE/TIME IN : 29.10.2019 09:50  
 ACCIDENT DATE : 26.10.2019

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	28-01-0103-0003-A	(140)FRT DOOR LOGO SONATA	1	75.00 0.00 75.00
0002	28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1	80.00 0.00 80.00

SUB-TOTAL : 155.00

## JOB NATURE

0000	PB	PANEL BEATING	320.00
0001	23-502	SPRAYPAINT ON AFFECTED AREA	600.00

SUB-TOTAL : 920.00

TOTAL : 1,075.00

MVA NAME & SIGNATURE  
 DATE :

AUTHORISED : YES / NO  
 SURVEYOR NAME & SIGNATURE  
 DATE :

A member of COMFORTDELGRO

Date/Time: 29.10.2019 14:26 Page : 1


Team: ARC Repair TP(CLSO)1      **JOB CARD**      Sales Order:      JC NO: 305344839

CUSTOMER MS CUSTOMER NO. ADDRESS (R) (P) ACCOUNT CARD NO.	COMFORT TRANSPORTATION PTE LTD <b>WARR</b> 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755	REGN NO: <b>SHA5963M</b>	MILEAGE
		MAKE: <b>HYUNDAI</b>	FUEL E. _____ 1/2. _____ F. _____
		MODEL <b>IONIQ(G2)</b>	DATE/TIME IN <b>29.10.2019 09:50</b>
		YR OF MANU. <b>08.11.2018</b>	TARGET DATE
		CHASSIS CODE <b>KMHC851CVKU115071</b>	COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 26.10.2019  
 NATURE: 3P 26.10.2019

S/NO	LABOR CODE	DESCRIPTION
		CHINA - Left Centre LKE/Kalni -



BOOKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR \_\_\_\_\_ CUSTOMER'S SIGNATURE \_\_\_\_\_

Exit Pass

Vehicle No.: **SHA5963M**

Service Advisor: **LARRY**

Signature/Date: \_\_\_\_\_

Returned to Service Reception upon collection

Exit Pass

Vehicle No.: **SHA5963M**

Name of Service Advisor: \_\_\_\_\_

Date: \_\_\_\_\_

To be kept by Security Guard



Your ref: To Be Advised  
Our ref: CC3/CTI19019187/K1eb3

Date: 30.10.2019

The Motor Claims Department  
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHA5963M**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 29.10.2019 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	5,411.96
Revised Estimate Amount	: S\$	1,075.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the  
N/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KALVIN ANG  
Licensed Appraiser





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI19019187/K1ea3q2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERSINGAPORE 079909

Date : 09-01-2020



Code : CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGP 5716T	Veh. Inspected	SHA 5963M
Policy No.	DMPCSN3071391805	Coverage (\$)	0.00
Claim No.	SNM19D205127	Excess (\$)	0.00
Assign From		Assign Date	29/10/2019

### 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KMHC851CVKU115071	Colour	BLUE
Odometer	107453	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DAVANTI	8 mm
L/H Front Tyre	195/65 R15	DAVANTI	8 mm
R/H Rear Tyre	195/65 R15	DAVANTI	8 mm
L/H Rear Tyre	195/65 R15	DAVANTI	8 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	26/10/2019	Inspection Date	29/10/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>2 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 5963M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT DOOR -LH	TO REPAIR SEE LABOUR	1,797.20	-
1	REAR DOOR -LH	TO REPAIR SEE LABOUR	1,789.90	-
1	REAR WHEEL COVER -LH	SERVICEABLE	346.60	-
1	REAR FENDER (LH) (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-786.74	-
			3,146.96	-
<b>SPECIAL NETT ITEMS</b>				
1	FRONT DOOR COMFORT LOGO (SN)	NECESSARY	75.00	75.00
1	REAR DOOR APP LOGO (SN)	NECESSARY	80.00	80.00
			155.00	155.00
<b>LABOUR</b>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT DOOR -LH,REAR DOOR -LH AND REAR FENDER (LH).		960.00	320.00
	SPRAY PAINTING CHARGE.		750.00	600.00
	WIRING CHARGE.	NOT NECESSARY	80.00	-
	TUFF KOTE.	NOT NECESSARY	80.00	-
	TRANSFER OF DOORS .	NOT NECESSARY	240.00	-
			2,110.00	920.00
<b>GRAND TOTAL</b>			<b>5,411.96</b>	<b>1,075.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,075.00</b>

Report Ref No. CC3/CTI19019187/K1ea3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.