

ASS. REC. BY:

REF: CS/SPF19019189 / Ev f3d2

Special Instruction:

Survivor: Steve

ASSIGNMENT (Office)

From (Person):

Harizul Rahman Rahmat

of

SPF

Date/Time:

30.10.19 3.54pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SSV 7008R

Insured:

Q x 295m

at Workshop m/s

Inchape Centre

Tel:

98476179

of

2 Pandan Crescent / Level 4

Policy No:

Claim No:

AEMD / 105 / 009 / 2019 / 106

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21.9.2019

CA / REV / REP. / REV 24 HRS

map

31.10.19

Date/Time:

30.10.19 4.07pm

Person Contacted:

Francis chur

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

SSV 7008R - NA / INC 10000000 / M DOP - 29/10/2010

Q x 295m - CS / SPF 17016096 / Sghe2 DSA

Do Not Finalise

20/11/19

@ 2.14pm Francis said vehicle has not send in for repair, pending liability

13/12/19

@ 2.25pm Francis said vehicle has not send in for repair, pending liability

ASSIGNMENT

om: Date:

Estimated Cost:

OT/TP/WS/TP RES/OD RES/EVA/INV/MV

Inspect Vehicle No:

Workshop m/s

ured

icy No.

ims No.

n Insured:

Excess:

Client's Record)

ce of Veh:

olicy Condition)

mark: The veh had commenced its repair at the time of inspection.

or Market Value:

Accident Report: Consistent? : Yes or No

/ PR. Seen: Consistent? : Yes or No

Repairs: days Res.: Yes or No

Sum: % 3 Val.: Yes or No

/ REV / REP. / 24 HRS

Person Contacted:

Vehicle: IN / OUT

N/S	O/S

Veh No: STN 7008R Yr Regn: 8/4/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis C.C. 1598

Colour: Silver A/C: Insured / Std / NI / NA

Sp.Reading: 10734 T/Radio: Insured / Std / NI / NA

Eng/No:

CiNo: MR 053 REH. 6045 96236

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16 R: 11

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO/YOKO or

Front		Rear
R/Bal. <u>5</u>	mm	R/Bal. <u>5</u> mm
L/Bal. <u>5</u>	mm	L/Bal. <u>5</u> mm
D.O.A. <u>21/9/19</u>		D.O.I. <u>31/10/19</u>

Survey held at Boonoo Motors

Des. of Damages: Frnt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

o / Time	Action / Instruction
	<u>MV-89K</u>

17/12/19 Submit preli report

RECEIVED 17 DEC 2019

me, File Pass to?

☒ : Proli. Report

☐ : Final Report

me, File Return to?

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

) S + RS, SI

) Priclos

) Others

)

TOTAL

270

270

17/12 - typist

ort Format :

o Sum / I.B.I: (\$)

## Summer Lee (LKK Auto)

---

**From:** Hafizul Farhan RAHMAT (SPF) <Hafizul\_Farhan\_RAHMAT@spf.gov.sg>  
**Sent:** Wednesday, 30 October, 2019 3:54 PM  
**To:** Admin-D (LKKAuto); SUR; assignments  
**Cc:** Frankie THAY (SPF); Cui Fen ENG (SPF)  
**Subject:** Pre-repair survey on SJN7008R (vs QX295M DOA 21/09/2019)  
**Attachments:** SJN7008R\_EST INV.pdf  
  
**Importance:** High

Our ref: AEMD/105/009/2019/106

Hi,

Kindly conduct pre-repair survey of **SJN7008R** (vs QX295M DOA 21/09/2019) at

**Inchcape Centre**  
**2 Pandan Crescent / Level 4** (currently vehicle **NOT** in workshop).  
**Contact: Francis Cher @ 9847 6179 / 6631 1863**

Thank you.

*Best Regards,*

*Hafizul Farhan Bin Rahmat*  
*Assistant Logistics Support Officer*  
*Logistics Support and Services Division*  
*Police Logistics Department | Singapore Police Force*  
*DID: (65) 6478 4840 | FAX: (65) 6478 4848*



**HOME TEAM**  
★ TRANSFORMATION 2025 ★  
One Home, One Team  
Building Our Future Together

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	847G
<b>Vehicle Details</b>	
Vehicle No.:	SJN7008R
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 STANDARD (AUTO)
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	1ZR0D41640
Chassis No.:	MR053REH604596236
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,741.00
Original Registration Date:	08 Apr 2019
First Registration Date:	08 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$19,741.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Apr 2029
PARF Rebate Amount:	\$14,805.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	07 Apr 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,170.00
COE Rebate Amount:	\$24,694.00
<b>Total Rebate Amount:</b>	<b>\$39,499.00</b>

The information contained herein is correct as at 31 Oct 2019

OK



<b>POLICY INFORMATION</b>		<b>Policy No. : VPA/P2270954</b>	
Source	:	(01) 14885 BMS-AXA TOYOTA NB	
Insured	:	NG TECK PIN	
Address	:	410D PASIR PANJANG ROAD SINGAPORE 118754	
Business/Profession	:	OTHER OCCUPATION Carrying on or engaged in the business or profession last declared and no other for the purpose of this insurance.	
Period of Insurance : From 08/04/2019 To 07/04/2021 (Both Dates Inclusive)			
Any subsequent period for which the Insured shall pay and the Company shall agree to accept a renewal premium.			
<b>PREMIUM</b>			
Premium After 50.00%	:	SGD 1,158.73	
NCD			
GST 7.00%	:	SGD 81.12	
Annual Premium	:	SGD 1,239.85	
Total Payable	:	SGD 2,479.68	
<b>RISK DETAILS THE MOTOR VEHICLE</b>			
Type Of Cover	:	Comprehensive	
Regn No.	:	SJN7008R	
Type Of Use	:	Private Car	
Make/Model	:	TOYOTA COROLLA ALTIS 1.6	
Year of Manufacture	:	2019	Seating Capacity (excl. Driver) : 04
Body Type	:	SALOON	Engine C.C. : 1598
Engine No.	:	1ZR0D41640	
Chassis No.	:	MR053REH604596236	
Insured's Estimated Market Value	:	Market Value At The Time Of Loss (including Accessories and Spare Parts)	
Limitations as to Use	:	As specified in Certificate of Insurance	
Hire Purchase	:	MAYBANK	
<u>Extra Coverage(Premium Breakdown)</u>		<u>Limits (SGD)</u>	<u>Premium (SGD)</u>
NCD Protector			
Basic Own Damage Excess		:	SGD 600.00
<u>Named Drivers</u>			
1 NG TECK PIN			
<b>MEMORANDA, CLAUSES, WARRANTIES &amp; ENDORSEMENTS</b>			
Subject to the Memoranda, Clauses, Warranties & Endorsements attached hereto:			
Sales Agent ID : BSTL027 -----			

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/09/2019 15:28
Date Of Accident	21/09/2019 18:10
Exact Location Of Accident	JUNC OF QUEENSWAY & COMMONWEALTH AVE TWD FARRER RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN7008R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG TECK PIN
NRIC No	S1620847G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93808802
Alternative Phone No	OFFICE-93808802

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P2270954
Cover Note Number	

### Driver

Name of Driver	NG TECK PIN
NRIC No	S1620847G
Date Of Birth	24/01/1963
Occupation	INDOOR
Date Of Driving Pass	20/10/1985
Driving Experience	33 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93808802
Fax Number	
Contact Number	OFFICE-93808802
EEmail Address	NOEMAIL

Address	410D PASIR PANJANG RD
Postcode	118754
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NG JIN
	GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	QUEENSTOWN N.P.C
Police Station Address	ROAD: 3 QUEENSWAY #01-03 , POSTCODE: 149073 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4719999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHED SKETCH PLAN AND STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX295M
Vehicle Make/Model/Colour	TOYOTA ALTIS 1.6 WHITE POLICE CAR
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	SSS HAZALI
NRIC/Passport Number	
Contact Number	
Address	

## MOTOR ACCIDENT REPORT

Date Of Report : 23/9/19 Time: 2.27 Date Of Accident : 21/09/2019 Time: 1810  
 Exact Location Of Accident : Junction of Queensway & Commonwealth ave towards Farrer Rd  
 Country/State of Loss: Singapore ☒ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ /

## OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number : SJN7008R Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No : S16208474  
 Name Of Registered Owner : NG TECK PIN  
 Mobile Number: 93808802 Alternative No: Email Address:

## Vehicle Particulars

Manufacturer : Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐ Model : ACTIS 1.6  
 Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):  
 Are you claiming under your own insurance policy for repair to your vehicle? Yes ☐ Reporting Only ☐ Third Party ☒  
 Vehicle Category : Private Car ☒ Commercial Vehicle ☐ Others ☐

## Insurance Company

Name of Insurance Company: AXA  
 Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐  
 Fleet Policy: Yes ☐ No ☒ Policy / Cover Note No: P2270954

## DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: NG TECK PIN NRIC/ Passport / FIN No : S16208474  
 Date Of Birth: 24/1/1963 Occupation: Indoor ☒ Outdoor ☐  
 Date Of Driving Pass: 20/10/1985 Gender: Male ☒ Female ☐  
 Mobile Number: 93808802 Fax No: - Alternative No: -  
 Address: 410D PASIR PANJANG ROAD Postal Code: 118754  
 Email Address:  
 Was driver an employee of the Insured's Company? Yes ☐ No ☐ State relationship of the driver with the insured:  
 Vehicle Registration Number of Driver's Own Vehicle (if applicable):  
 Insurance Company of Driver's Own Vehicle (if applicable):

## GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: Rear to front collision  
 Number of Passengers in the above vehicle (including Driver): 2 / If more than 2 Pax Please fill ANNEX B

## PASSENGER 1

Name: NG JIN Gender: Male ☒ Female ☐  
 Weather Conditions: Clear ☒ Raining ☐ Others ☐ (If others, please state condition):  
 Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):  
 Was any body injured in the Accident? No ☒ Yes ☐  
 Was any injured conveyed to hospital by ambulance? No ☒ Yes ☐  
 Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: Vehicle type:  
 Number of vehicles involved in the accident:  
 Was there any witness? No ☒ Yes ☐ If yes, please furnish witness details column below  
 Witness Name: | Contact No.: | Email:  
 Was there any other vehicle or property damaged? No ☐ Yes ☐  
 Was there any video captured by Car Camera? No ☐ Yes ☒ Are accident scene photos available for attachment? No ☐ Yes ☐  
 Was the accident reported to the police? No ☐ Yes ☒ (If yes, please state which Police Station): Queenstown NPC  
 Was notice of intended Prosecution given? No ☐ Yes ☐ (If yes, please state against whom):  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

## DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: QX295M Vehicle Make/Model/Colour: TOYOTA Altis 1.6 white  
 Details Of Properties Damage in Accident: Police Car  
 Vehicle Category:  
 Name of Driver: SSS Hazali  
 NRIC/Passport/FIN Number: Contact Number:  
 Address: Postal Code:  
 Insurance Company Name:  
 Nature Of Damage: No. Of Passenger (Including Driver):



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 23/9/19.  
2.35pm

Driver's Signature

(If driver is not the policyholder)  
Date & Time: 23/9/19.  
2.35pm.

Reporting Centre Personnel's Signature

Name:  
NRIC/FIN No.:

A hand-drawn diagram of a road intersection. A vertical road on the left has a 'Taxi!' sign pointing left and an 'Ambulance' sign pointing right. A horizontal road on the right has a '50N' speed limit sign pointing right and a 'No Right Turn' sign pointing left. A 'Yield' sign is also present at the intersection. Arrows indicate the flow of traffic: left for the vertical road, and right for the horizontal road.

Refer to Police Report .

T/W We declare the foregoing particulars are true in every respect.

7/We declare the foregoing

are true in every respect.

(If driver is not the policyholder)

Date & Time: 23/9/19/-2:35 pm



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



Police Station Of Origin:  
Queenstown N.P.C  
3 Queensway #01-03 SINGAPORE 149073  
Tel No: 1800-4719999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 22/09/2019 12:53	Vide Report No.: D/20190921/0106	Station Diary No.: 43
--	-------------------------------------	--------------------------

**Informant's Particulars**

Name of Informant: NG TECK PIN			Address: 410D PASIR PANJANG ROAD SINGAPORE 118754		
ID Type / ID No.: NRIC NO / S1620847G			Contact No.: Home/Office: Mobile: 93808802		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 56	Date of Birth: 24/01/1963	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Company director			Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Non-Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 21/09/2019 18:10	Type of Location: Straight Road
Location: Along Road 1 QUEENSWAY				
ALONG QUEENSWAY HEADING TOWARDS FARRER ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX295M	Car	TOYOTA	COROLLA ALTIS 1.6 AUTO	White	Slightly Damaged	1
SJN7008R	Car	TOYOTA	COROLLA ALTIS 1.6 STANDARD (AUTO)	Silver	Slightly Damaged	1

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



Police Station Of Origin:  
Queenstown N.P.C  
3 Queensway #01-03 SINGAPORE 149073  
Tel No: 1800-4719999

**CONTINUATION OF REPORT**

<b>Details of Vehicle Insurance</b>				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJN7008R	AXA INSURANCE SINGAPORE PTE LTD	P2270954	08/04/2019	07/04/2021

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	NG TECK PIN	ID No.	S1620847G
Related Vehicle	NIL	Contact No.	93808802
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 21/09/2019 at about 1810hrs. I was driving my vehicle (SJN7008R) along Queensway heading towards Farrer road. I noticed that the traffic light shows red and thus I come to a complete stop. I noticed that the police vehicle make a small reverse, however all of a sudden, the vehicle reversed fully and it hit onto the front of my vehicle. Subsequently both of us got out of our vehicle. He did admit that it is his fault and shortly after, traffic police also came to scene. Case card was given to me, Ref: D/20190921/0106. No one was injured throughout the incident.

I am lodging this report as instructed by the police.

Damages to my vehicle as follows: Front grill mis-aligned and front bumper dented with scratches.



Police Station Of Origin:  
Queenstown N.P.C  
3 Queensway #01-03 SINGAPORE 149073  
Tel No: 1800-4719999

3 of 3

Report No. T/20190922/2045

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

D /

Sgt 3 RYAN LIEW HUANG CHENG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

22/09/2019 12:53

Officer In Charge Of Case:

TP / DDGVT /

Sgt 3 MUHAMMAD FIRDAUS BIN SULEIMAN SN 50

Contact No.: 65476223

Classification Of Case:

Authentication Stamp

NP168

SIGNATURE



Borneo Motors (Singapore) Pte Ltd

Online Service Booking:  
www.toyota.com.sgCo Reg No : 196700086Z  
GST Reg No : MR-8500000-9

Francis

## ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account &amp; more!

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188  
Customer Detail

Account Detail	Account No	Mr Ng Teck Pin 410D Pasir Panjang Road  Singapore 118754 Mobile: 93808802
THIRD PARTY CLAIM	S1000020 / TPCLAIM	
	Document No	
	0	
	Document Date	
	23/09/2019	


LKK  
67418434  
summit

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	GEXGPZ C2	ZRE171R	08/04/2019	SJN7008R	0	48884	65DS/SJN7008R
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

MR053REH604596236	1ZROD41640	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00
-------------------	------------	----	------------------	------------	------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : T/P VEH. : QX295M ACC DATE : 21.09.19 BY :				80 100.00
2	L	BP-LPO SUPPLY REGN PLATE (PO# ) (FRT WITH CASING)				68.00/
3	B	BP-MECH2 RESET AND REPROGRAMME ECU.				180.00/
4	B	BP-MECH2 REMOVE AIR CON COMPONENTS TO REGAS AND REPLACE NEW PARTS.				? 360.00
5	B	BP-LAB2 REMOVE AND REFOCUS HEADLAMP.				180.00/
6	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, FRT SUPPORT PANEL AND AFFECTED PORTION OF CAR.				720 2160.00
7	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				885 1770.00
8	1	S52119-02982 COVER, FR BUMPER, L/ X R (To dismantle & check)	1.00	531.10		531.10
9	2	S52115-02380 SUPPORT, FR BUMPER S X	1.00	68.20		68.20
10	3	S52116-02370 SUPPORT, FR BUMPER S X	1.00	68.20		68.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	Amount Due
		Others	

PLEASE TEAR ALONG PERFORATED LINE

4044299

TO SECURITY GUARD

4044299

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE  
TIME 23/09/2019  
16:24

VEHICLE NO

SJN7008R

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors



Borneo Motors (Singapore) Pte Ltd

Online Service Booking:  
www.toyota.com.sgCo Reg No : 196700086Z  
GST Reg No : MR-8500000-9**ESTIMATE**Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ML account &amp; more!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	
	Document No	
	0	Mr Ng Teck Pin 410D Pasir Panjang Road
	Document Date	Singapore 118754
	23/09/2019	Mobile: 93808802

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	GEXGPZ	C2	ZRE171R	08/04/2019	SJN7008R	0	48884 65DS/SJN7008R
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR053REH604596236	1ZR0D41640	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	4	T90467-05170 CLIP ✓ MC 0	2.00	2.50		5.00
12	5	S52131-02190 REINFORCEMENT, FR	1.00	399.50		399.50
13	6	S53112-02300 GRILLE, RADIATOR, LW ?	1.00	169.60		169.60
14	7	S53208-02230 SUPPORT SUB-ASSY, HO ✓ BT	1.00	164.90		164.90
15	8	S88450-02350 A/C CONDENSER ASSY, ?	1.00	1801.70		1801.70
16	9	SPC593-1200F LED FOG LAMP (Lower only SP) ✓ CM	1.00	387.80		387.80
17	0	S53100-02B90 GRILLE ASSY, RADIATO ?	1.00	712.10		712.10

Steve (LKK)  
8322 8813  
stevechn@ikrands.com

W/L Mind 31/10/19, 12.00pm  
3 days  
PIP  
By Ref spy

LKK Auto Consultants hence notify the Repairer of the following:


- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of <b>Borneo Motors</b>	Customer's Signature	Change Summary	Total		
	Please acknowledge receipt of vehicle	Parts		9,126.10	
		Labour	4,308.10	GST 7.00%	638.83
		Materials	4,750.00	Less	0.00
		Lubrication/Fluid	68.00		
		Others	0.00		
			0.00	Amount Due	9,764.93

PLEASE TEAR ALONG PERFORATED LINE

4044300

4044300

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE  
TIME 23/09/2019  
16:24

VEHICLE NO

SJN7008R

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Inchcape

**Borneo Motors**



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING &amp; MGT DIVISION

Ref : CS/SPF19019189/Evf3e2

ACCIDENT CLAIM SECTION (SPORE POLICE  
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD  
POLICE ACADEMY SINGAPORE 298333

Date : 27-12-2019



ATTN : HAFIZUL FARHAN RAHMAT

Code : SPF

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	QX 295M	Veh. Inspected	SJN 7008R
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/106	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN RAHMAT	Assign Date	30/10/2019

**2. Vehicle Particulars & Condition**

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MR053REH604596236	Colour	SILVER
Odometer	10734	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	205/55 R16	DUNLOP	5 mm
L/H Front Tyre	205/55 R16	DUNLOP	5 mm
R/H Rear Tyre	205/55 R16	DUNLOP	5 mm
L/H Rear Tyre	205/55 R16	DUNLOP	5 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.
---

**5. General Information**

Accident Date	21/09/2019	Inspection Date	31/10/2019
Survey held at	2 PANDAN CRESCENT / LEVEL 4		
Repairer	BORNEO MOTORS (S) PTE LTD		

**5a. Remarks**

A) THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 7008R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	COVER, FR BUMPER, L (SN)	TO REPAIR SEE LABOUR	531.10	-
1	SUPPORT, FR BUMPER S (SN)	NOT NECESSARY	68.20	-
1	SUPPORT, FR BUMPER S (SN)	NOT NECESSARY	68.20	-
2	CLIP (SN)	NECESSARY	5.00	5.00
1	REINFORCEMENT, FR (SN)	* CHECK	399.50	-
1	GRILLE, RADIATOR, LW (SN)	* CHECK	169.60	-
1	SUPPORT SUB-ASSY, HO (SN)	BENT	164.90	164.90
1	A/C CONDENSER ASSY, (SN)	* CHECK	1,801.70	-
1	LED FOG LAMP (SN)	CUT	387.80	387.80
1	GRILLE ASSY, RADIATOR (SN)	* CHECK	712.10	-
			4,408.10	587.70
<b>LABOUR</b>				
	SUPPLY REGN PLATE (PO# ) (FRT WITH CASING).		68.00	68.00
	RESET AND REPROGRAMME ECU.		180.00	180.00
	REMOVE AIR CON COMPONENTS TO REGAS AND REPLACE NEW PARTS.	* CHECK	360.00	-
	REMOVE AND REFOCUS HEADLAMP.		180.00	180.00
	REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, FRT SUPPORT PANEL AND AFFECTED PORTION OF CAR. INCLUSIVE OF THE REPAIR OF COVER, FR BUMPER, L.		2,160.00	720.00
	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.		1,770.00	885.00
			-	-
			-	-
			4,718.00	2,033.00
<b>GRAND TOTAL</b>			<b>9,126.10</b>	<b>2,620.70</b>

Report Ref No. CS/SPF19019189/Evf3e2



RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$3,442.90 NETT)			2,620.70
---	--	--	----------

Report Ref No. CS/SPF19019189/Evf3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.