

ASS: REC. BY:

REF: CS / FWD No 197 / US f302

Special Instruction:

SUNVJOY

Mar/US

ASSIGNMENT (Office)

From (Person):

Eileen Bay

of

Fwd

Date/Time:

30.10.19 16.44pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 7325T

Insured:

at Workshop m/s

Progressive car

Tel:

67415336

of

Blk 5022A Ubi Road 1

Policy No:

PNCV2019-0000587

Claim No:

Sum Insured:

Excess:

\$ 1000.00

Make of Veh:

(Client's Record)

D.O.A.

26.10.2019

CA / REV

REP. / REV 24 HRS

Date/Time:

30.10.19 44pm

Person Contacted:

Pai Wen

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLF 7325T - N/A / NC 1910/27/24

DOA-26/10/19

31/10/19

@ 15:00 pm revised PA to Eileen Bay via memo

31/10/19

@ 15:00 pm mandate requested authorize repair to Eileen Bay via memo.

31/10/19

@ 15:13 pm mandate requested authorize repair to approval

ACC. REC. BY: marcus

REP:

FWD CS/FWD 190197/USF3

**ASSIGNMENT**

From: \_\_\_\_\_ Date: 31.10.2019

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLF 73257

at Workshop n/s Progressive Car

of BK 3022 A ubi road 1 #01-45/46

Insured:

Policy No.

Claims No.

Sum Insured: \_\_\_\_\_ Excess: \$1000

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: 63

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Loss Sum: 1.31 % 3 Mth: Yes or No

CA (REV) REP. / 24 HRS

4742

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLF 73257 Yr Regn: 12/17

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: KIA Cerato K3 C.C. 1591

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 72118 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KN AF2 411M J 575558/

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40 R 18  
R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front: 6 mm Rear: 6 mm

R/Bal: 6 mm L/Bal: 6 mm

D.O.A. 26/10/19 D.O.I. 31/10/19

Survey held at \_\_\_\_\_

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

H.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31/10/19 @ 16:00 pm informed CIA to Pei Wen (supervisor) via email.

15/11/19 @ 1:58 pm 3rd request to Eileen Bay via Wechat. (supplementary 283).

6/1/20 continue final by \$8944.00 with Ray.  
( \$ 3,190.00 Red - 26% )

Date/Time, File Pass to?

07/01/20

1) Type

Date/Time, File Return to?

2)

Rep. Form

Comp. Sum. \$ 8,944.00 pk

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 3

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

3 + RS. 01

Photos

Other

WILL

250

90

50+50+50

11

461

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

| Case | Notified                             | Est Submitted                        | Adj Assigned                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                               |
|------|--------------------------------------|--------------------------------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Main | 30 Oct 2019<br>14:31<br>Sendback Est | 30 Oct 2019<br>14:39<br>S\$10,321.00 | 30 Oct 2019<br>16:44<br>Assign |         |               |            | <b>New Assignment</b><br>Cancel Case |

| Main                             | Reference                                                                                     | Claim Details          | Documents                                                                    | Show All |         |             |              |            |       |
|----------------------------------|-----------------------------------------------------------------------------------------------|------------------------|------------------------------------------------------------------------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b>   |                                                                                               |                        |                                                                              |          |         |             |              |            |       |
| Insured:                         | TERRY LOH JUNRONG, ID: S8319474Z, Tel: +6593260316, Email: sakuraki2k@gmail.com               |                        |                                                                              |          |         |             |              |            |       |
| Vehicle Reg. No.:                | SLF7325T                                                                                      | Date of Loss:          | 26/10/2019 12:00 - :59<br>[22 Months and 11 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:                      | OD                                                                                            | Policy/Cover Note No.: | PNCV2019-00000387<br>(Comprehensive)                                         |          |         |             |              |            |       |
|                                  |                                                                                               | Excess:                | S\$1,000.00                                                                  |          |         |             |              |            |       |
| Repairer:                        | Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336 |                        |                                                                              |          |         |             |              |            |       |
| Handling Insurer:                | FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]                     |                        |                                                                              |          |         |             |              |            |       |
| Adjuster:                        | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/11/2019]             |                        |                                                                              |          |         |             |              |            |       |
| Driver/Custodian:                | TERRY LOH JUNRONG (36 / Male), NRIC: S8319474Z, Tel: +6593260316 Email: sakuraki2k@gmail.com  |                        |                                                                              |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b>  |                                                                                               |                        |                                                                              |          |         |             |              |            |       |
| There are no mail for this case. |                                                                                               |                        |                                                                              |          |         |             |              |            |       |
| View All Compose Case Mail       |                                                                                               |                        |                                                                              |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b>      |                                                                                               |                        |                                                                              |          |         |             |              |            |       |
| Due Date                         | Priority                                                                                      | Type                   | Task Group                                                                   | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                      |                                                                                               |                        |                                                                              |          |         |             |              |            |       |

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                                      |
|-------------------------------------|--------------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                      |
| Owner ID Type:                      | Singapore NRIC                       |
| Owner ID:                           | 474Z                                 |
| <b>Vehicle Details</b>              |                                      |
| Vehicle No.:                        | SLF7325T                             |
| Vehicle to be Exported:             | No                                   |
| Intended Deregistration Date:       | 31 Oct 2019                          |
| Vehicle Make:                       | KIA                                  |
| Vehicle Model:                      | CERATO K3 1.6A SUNROOF               |
| Primary Colour:                     | Black                                |
| Manufacturing Year:                 | 2017                                 |
| Engine No.:                         | G4FGHH687860                         |
| Chassis No.:                        | KNAFZ411MJ5755581                    |
| Maximum Power Output:               | 95.3 kW (127 bhp)                    |
| Open Market Value:                  | \$15,649.00                          |
| Original Registration Date:         | 15 Dec 2017                          |
| First Registration Date:            | 15 Dec 2017                          |
| Transfer Count:                     | 0                                    |
| Actual ARF Paid:                    | \$15,649.00 7804                     |
| <b>Intended PARF Rebate Details</b> |                                      |
| PARF Eligibility:                   | Yes                                  |
| PARF Eligibility Expiry Date:       | 14 Dec 2027                          |
| PARF Rebate Amount:                 | \$11,736.00                          |
| <b>Intended COE Rebate Details</b>  |                                      |
| COE Expiry Date:                    | 14 Dec 2027                          |
| COE Category:                       | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):                  | 10                                   |
| QP Paid:                            | \$46,791.00                          |
| COE Rebate Amount:                  | \$37,998.00                          |
| <b>Total Rebate Amount:</b>         | <b>\$49,734.00</b>                   |

The information contained herein is correct as at 31 Oct 2019

OK



**ALL-NEW**  
Mercedes-Benz GLE450 AMG  
Premium Plus

**TEST DRIVE TODAY!**

📞 6250 6696 / 9637 5329

F1 F







Home » Used Cars » Pure Motors Pte Ltd » Kia Cerato K3 1.6A EX

## Kia Cerato K3 1.6A EX

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)


PURE MOTORS PTE LTD



|                        |                                                               |                      |                                       |
|------------------------|---------------------------------------------------------------|----------------------|---------------------------------------|
| <b>Price</b>           | \$65,800                                                      |                      |                                       |
| <b>Depreciation</b>    | \$7,390 /yr<br><a href="#">View models with similar depre</a> | <b>Reg Date</b>      | 17-Nov-2017<br>(8yrs 16days COE left) |
| <b>Mileage</b>         | 8,500 km (4.4k /yr)                                           | <b>Manufactured</b>  | 2017                                  |
| <b>Road Tax</b>        | \$738 /yr                                                     | <b>Transmission</b>  | Auto                                  |
| <b>Dereg Value</b>     | \$43,021 as of today (change)                                 | <b>OMV</b>           | \$12,696                              |
| <b>COE</b>             | \$41,617                                                      | <b>ARF</b>           | \$12,696                              |
| <b>Engine Cap</b>      | 1,591 cc                                                      | <b>Power</b>         | 95.3 kW (127 bhp)                     |
| <b>Curb Weight</b>     | 1,295 kg                                                      | <b>No. of Owners</b> | 1                                     |
| <b>Type of Vehicle</b> | Mid-Sized Sedan                                               |                      |                                       |

### Features

Responsive And Fuel Efficient! 1.6L 4 Cylinders Inline DOHC Dual CVVT Engine, 6 Speed Auto Transmission, ABS/SRS Airbags. [View specs of the Kia Cerato K3 \(2013-2018\)](#)

### Accessories

Sports Rims, Factory Audio With Steering Controls, Reverse Sensors, Auto Retractable Side Mirrors, Fog Lights, Rear Aircon.

### Description

1 Owner Only. Agent Service And 5 Years/Unlimited Mileage C&C Warranty. Spacious And Comfortable Ride. Trade In Welcome. Bank/In House Loan Available. Please Visit Us Now For Further Details.

### Category

PARF Car, Low Mileage Car


Star

Avi [Compare](#)



Location Map

Price Chart



[Click on the point to view the vehicle](#)

[Shortlist](#)
[Compare](#)
[Report Error](#)
[More Actions](#)



Kia Cerato K3 1.6A \$62,888 \$7,250 /yr 16-Aug-2017 1,591 cc 26,562 km Sedan

1 Owner, Full Agent Service Record And Still Under Warranty, Super Low Mileage, Full Loan Available, Come View Now!

Posted: 25-Oct-2019 Tags: 2017 Kia Cerato, 2017 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Kia Cerato K3 1.6A \$59,800 \$7,200 /yr 17-Apr-2017 1,591 cc 40,875 km Sedan

In House Financing Available! 1 Owner, Car Under Agent Warranty! Bank Loan Interest At Only 2.28%! Extremely Well Maintained, Ideal Car For Your Family, Trade In Available, Call Now For Viewing!

Posted: 25-Oct-2019 Tags: 2017 Kia Cerato, 2017 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Kia Cerato K3 1.6A EX \$65,800 \$7,390 /yr 17-Nov-2017 1,591 cc 8,500 km Sedan

1 Owner Only, Agent Service And 5 Years/Unlimited Mileage C&C Warranty. Spacious And Comfortable Ride. Trade In Welcome. Bank/In House Loan Available. Please Visit Us Now For Further Details.

Pure Motors Pte Ltd

Posted: 24-Oct-2019 Tags: 2017 Kia Cerato, 2017 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Kia Cerato K3 1.6A Sunroof \$69,000 \$7,570 /yr 28-Nov-2017 1,591 cc 56,000 km Sedan

High Specs Model Comes With Sunroof, Electric Seats. Vinyl Roof And Body. Look No Further! Warranty Till Nov 2022! Best Value For Your Money. Selling Due To Upgrading To New Car. Low Fuel Consumption, Low Maintenance. Original Paintwork Condition And Well Taken C...

Monster Motors Pte Ltd

Posted: 23-Oct-2019 Tags: 2017 Kia Cerato, 2017 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Kia Cerato K3 1.6A SX Sunroof \$66,800 \$7,790 /yr 06-Apr-2017 1,591 cc 35,762 km Sedan

1 Owner. Highest Spec SX Model! Low Mileage As It's An OPC Converted Unit! Popular And Reliable K3. Fully Agent Service Unit With Warranty! Spacious Interior With Sporty Outlook! View Today!

Posted: 23-Oct-2019 Tags: 2017 Kia Cerato, 2017 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Save on petrol with UOB One card!

Enjoy huge petrol savings of up to 24%, attractive cashback on your monthly spend, and 1-year annual fee waiver. Apply now and start enjoying today.

Find out more!



Kia Cerato K3 1.6A Sunroof \$67,800 \$7,870 /yr 02-Jun-2017 1,591 cc 34,058 km Sedan

Monthly \$695 Only! 1 Careful Owner! Smell Like A New Car! Low Deprecation! Bank And In House Full Loan At Low Interest Rate! Fully Agent (C&C) Servicing Records Since Days 1. Still Under Agent Warranty! High Trade In Are Welcome! Original Stock Condition! 100% A...

Starise Automobile

Posted: 22-Oct-2019 Tags: 2017 Kia Cerato, 2017 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Kia Cerato K3 1.6A SX Sunroof \$69,800 \$7,710 /yr 09-Nov-2017 1,591 cc 29,000 km Sedan

Graded A by STP

Low Monthly From \$6xx Only! Highest Specs SX Model! New Arrival! Full Agent Servicing By C&C! Agent Warranty C&C Till Nov 2022! One And Only Owner! Come With Nice Car Plate Number! Well Maintained By Owner! 100% Accident Free! No Repair Needed! Vehicle In Exc...

Posted: 20-Oct-2019 Tags: 2017 Kia Cerato, 2017 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Kia Cerato K3 1.6A \$65,555 \$7,640 /yr 24-Jul-2017 1,591 cc - Sedan

Posted: 19-Oct-2019 Tags: 2017 Kia Cerato, 2017 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Kia Cerato K3 1.6A EX \$64,500 \$7,190 /yr 28-Nov-2017 1,591 cc 39,000 km Sedan

1 Owner, Pristine Condition. Fully Stock. 5 Years Warranty With Kia! Full Servicing Records Available. Don't Miss! Trade In/ Flexible Loan Available, Please Call Now For A Viewing! Viewing By Appointment Only. STA Inspection Welcome!

360 VR Cars

ad: 18-Oct-2019 Tags: 2017 Kia Cerato, 2017 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

Compare

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto)  
**Sent:** Thursday, 31 October 2019 4:00 pm  
**To:** Peiwen  
**Cc:** 'Lily'; Wendy; 'Wayne'  
**Subject:** SLF 7325T OD (FWD) DOA - 26/10/2019

Dear Pei Wen,

As instructed by our client, please proceed to repair the insured vehicle **SLF 7325T (Excess \$ 1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315  
Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## View Received Message

This mail is associated with :

**SLF7325T (1201900032377)**

OD

Oct 26 2019 12:00PM

[TERRY LOH JUNRONG]

Progressive Car Care Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** FWD Singapore Pte. Ltd. (HQ) (FWD\_SG), sent on 06/01/2020 15:33 PM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$8944.00) - SLF7325T - Claim Handler: Eileen Bay

Approved:8944.00.

### DOCUMENTS SUMMARY

There are no documents.

## View Received Message

This mail is associated with :

**SLF7325T (1201900032377)**

OD

Oct 26 2019 12:00PM

[TERRY LOH JUNRONG]

Progressive Car Care Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** FWD Singapore Pte. Ltd. (HQ) (FWD\_SG), sent on 16/11/2019 09:26 AM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$10241.00) - SLF7325T - Claim Handler: Eileen Bay

Approved:10241.00.

### DOCUMENTS SUMMARY

There are no documents.

## View Received Message

This mail is associated with :

**SLF7325T (1201900032377)**

OD

Oct 26 2019 12:00PM

[TERRY LOH JUNRONG]

Progressive Car Care Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** FWD Singapore Pte. Ltd. (HQ) (FWD\_SG), sent on 07/11/2019 11:53 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$9495.00) - SLF7325T - Claim Handler: Eileen Bay

Approved:9495.00:Please reseek mandate after check items being verified, Thanks.

### DOCUMENTS SUMMARY

There are no documents.

## View Received Message

This mail is associated with :

**SLF7325T (1201900032377)**

OD

Oct 26 2019 12:00PM

[TERRY LOH JUNRONG]

Progressive Car Care Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** FWD Singapore Pte. Ltd. (HQ) (FWD\_SG), sent on **31/10/2019 15:13 PM**.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$7500.00) - SLF7325T - Claim Handler: Eileen Bay

Approved:7500.00:Please reseek mandate after check items being verified. Thanks.

### DOCUMENTS SUMMARY

There are no documents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Eileen Bay

Date: 06 Jan 2020

**Preliminary Advice**

|                    |                                                                                            |                         |                     |
|--------------------|--------------------------------------------------------------------------------------------|-------------------------|---------------------|
| Vehicle No         | : SLF7325T                                                                                 | Accident Date           | : 26/10/2019        |
| Make               | : KIA CERATO K3                                                                            | Policy No.              | : PNCV2019-00000387 |
| Assignment Date    | : 30/10/2019                                                                               | Excess                  | : S\$1,000.00       |
| Date of Inspection | : 31/10/2019                                                                               | Est. Duration of Repair | : 6.00              |
| Inspection At      | : PROGRESSIVE CAR CARE PTE LTD (HQ)<br>BLK 3022A UBI ROAD 1, #01-45/46<br>SINGAPORE 408716 |                         |                     |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

|                             |      |                                                |
|-----------------------------|------|------------------------------------------------|
| Repairer's Estimate (Gross) | :S\$ | 12,134.00 (inclusive supp 1 \$ 1,053.00 + supp |
| Revised Amount              | :S\$ | 8,944.00 (inclusive supp)                      |
| Check Items (Estimated)     | :S\$ | 0.00                                           |
| Total                       | :S\$ | 8,944.00                                       |
| Lump Sum Repair             | :S\$ |                                                |

**Total Loss Consideration**

|                    |      |           |
|--------------------|------|-----------|
| New for Old Value  | :S\$ |           |
| Pre-Accident Value | :S\$ | 63,000.00 |
| COE / PARF Rebate  | :S\$ | 49,374.00 |
| Salvage Value      | :S\$ |           |
| Margin for Repair  | :S\$ | 13,266.00 |

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Eileen Bay

Date: 15 Nov 2019

**Preliminary Advice**

|                    |                                                                                            |                         |                     |
|--------------------|--------------------------------------------------------------------------------------------|-------------------------|---------------------|
| Vehicle No         | : SLF7325T                                                                                 | Accident Date           | : 26/10/2019        |
| Make               | : KIA CERATO K3                                                                            | Policy No.              | : PNCV2019-00000387 |
| Assignment Date    | : 30/10/2019                                                                               | Excess                  | : S\$1,000.00       |
| Date of Inspection | : 31/10/2019                                                                               | Est. Duration of Repair | : 6.00              |
| Inspection At      | : PROGRESSIVE CAR CARE PTE LTD (HQ)<br>BLK 3022A UBI ROAD 1, #01-45/46<br>SINGAPORE 408716 |                         |                     |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

|                             |      |           |                                                                  |
|-----------------------------|------|-----------|------------------------------------------------------------------|
| Repairer's Estimate (Gross) | :S\$ | 12,134.00 | (ESTIMATE \$11,374.00 +<br>SUPP 2 \$280.00 + SUPP 3<br>\$480.00) |
| Revised Amount              | :S\$ | 9,385.00  | (INCLUSIVE OF<br>SUPPLEMENTARY)                                  |
| Check Items (Estimated)     | :S\$ | 856.00    |                                                                  |
| Total                       | :S\$ | 10,241.00 |                                                                  |
| Lump Sum Repair             | :S\$ |           |                                                                  |

**Total Loss Consideration**

|                    |      |           |
|--------------------|------|-----------|
| New for Old Value  | :S\$ |           |
| Pre-Accident Value | :S\$ | 63,000.00 |
| COE / PARF Rebate  | :S\$ | 49,734.00 |
| Salvage Value      | :S\$ |           |
| Margin for Repair  | :S\$ | 13,266.00 |

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Eileen Bay

Date: 07 Nov 2019

## Preliminary Advice

|                    |                                                                                            |                         |                     |
|--------------------|--------------------------------------------------------------------------------------------|-------------------------|---------------------|
| Vehicle No         | : SLF7325T                                                                                 | Accident Date           | : 26/10/2019        |
| Make               | : KIA CERATO K3                                                                            | Policy No.              | : PNCV2019-00000387 |
| Assignment Date    | : 30/10/2019                                                                               | Excess                  | : S\$1,000.00       |
| Date of Inspection | : 31/10/2019                                                                               | Est. Duration of Repair | : 6 days            |
| Inspection At      | : Progressive Car Care Pte Ltd (HQ)<br>Blk 3022A Ubi Road 1, #01-45/46<br>Singapore 408716 |                         |                     |

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

|                             |      |                            |
|-----------------------------|------|----------------------------|
| Repairer's Estimate (Gross) | :S\$ | 11,374.00 (inclusive supp) |
| Revised Amount              | :S\$ | 7,202.00 (inclusive supp)  |
| Check Items (Estimated)     | :S\$ | 2,293.00                   |
| Total                       | :S\$ | 9,495.00                   |

|                 |      |  |
|-----------------|------|--|
| Lump Sum Repair | :S\$ |  |
|-----------------|------|--|

### Total Loss Consideration

|                    |      |           |
|--------------------|------|-----------|
| New for Old Value  | :S\$ |           |
| Pre-Accident Value | :S\$ | 63,000.00 |
| COE / PARF Rebate  | :S\$ | 49,734.00 |
| Salvage Value      | :S\$ |           |
| Margin for Repair  | :S\$ | 13,266.00 |

### Remarks

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Supplementary amount is \$ 708.00

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Eileen Bay

Date: 31 Oct 2019

**Preliminary Advice**

|                    |                                                                                            |                         |                     |
|--------------------|--------------------------------------------------------------------------------------------|-------------------------|---------------------|
| Vehicle No         | : SLF7325T                                                                                 | Accident Date           | : 26/10/2019        |
| Make               | : KIA CERATO K3                                                                            | Policy No.              | : PNCV2019-00000387 |
| Assignment Date    | : 30/10/2019                                                                               | Excess                  | : S\$1,000.00       |
| Date of Inspection | : 31/10/2019                                                                               | Est. Duration of Repair | : 6 days            |
| Inspection At      | : Progressive Car Care Pte Ltd (HQ)<br>Blk 3022A Ubi Road 1, #01-45/46<br>Singapore 408716 |                         |                     |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 10,321.00 |
| Revised Amount              | :S\$ | 6,494.00  |
| Check Items (Estimated)     | :S\$ | 2,293.00  |
| Total                       | :S\$ | 8,787.00  |

|                 |      |  |
|-----------------|------|--|
| Lump Sum Repair | :S\$ |  |
|-----------------|------|--|

**Total Loss Consideration**

|                    |      |           |
|--------------------|------|-----------|
| New for Old Value  | :S\$ |           |
| Pre-Accident Value | :S\$ | 63,000.00 |
| COE / PARF Rebate  | :S\$ | 49,734.00 |
| Salvage Value      | :S\$ |           |
| Margin for Repair  | :S\$ | 13,266.00 |

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                  |
|----------------------------|------------------|
| Date Of Report             | 26/10/2019 16:01 |
| Date Of Accident           | 26/10/2019 12:40 |
| Exact Location Of Accident | CTE TO CITY      |
| Country/State of Loss      | SINGAPORE        |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SLF7325T             |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | TERRY LOH JUNRONG    |
| NRIC No                     | S8319474Z            |
| Email Address               | SAKURAKI2K@GMAIL.COM |
| Mobile Phone No             | (LOCAL) +65-93260316 |
| Alternative Phone No        | OTHERS-93260316      |

### Vehicle Particulars

|              |                   |
|--------------|-------------------|
| Manufacturer | KIA               |
| Model        | CERATO K3-1.6 (A) |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

|                  |              |
|------------------|--------------|
| Vehicle Category | PRIVATE HIRE |
|------------------|--------------|

### Insurance Company

|                           |                         |
|---------------------------|-------------------------|
| Name of Insurance Company | FWD SINGAPORE PTE. LTD. |
| Type Of Coverage          | COMPREHENSIVE           |
| Fleet Policy              | NO                      |
| Policy Number             | PNCV2019-00000387       |
| Cover Note Number         |                         |

### Driver

|                      |                        |
|----------------------|------------------------|
| Name of Driver       | TERRY LOH JUNRONG      |
| NRIC No              | S8319474Z              |
| Date Of Birth        | 25/06/1983             |
| Occupation           | INDOOR                 |
| Date Of Driving Pass | 10/12/2003             |
| Driving Experience   | 15 YEARS AND 10 MONTHS |
| Gender               | MALE                   |
| Mobile Number        | (LOCAL) +65-93260316   |
| Fax Number           |                        |
| Contact Number       | OTHERS-93260316        |
| Email Address        | SAKURAKI2K@GMAIL.COM   |

|                                                     |                                |
|-----------------------------------------------------|--------------------------------|
| Address                                             | BLK 676A PUNGGOL DRIVE #05-708 |
| Postcode                                            | 821676                         |
| Was driver an employee of the Insured's Company     | NO                             |
| If No, Relationship of the Driver with the Insured  | OWNER                          |
| Vehicle Registration Number of Driver's Own Vehicle | -                              |
|                                                     | -                              |
|                                                     | -                              |
| Insurance Company of Driver's Own Vehicle           | -                              |
|                                                     | -                              |
|                                                     | -                              |

#### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR                    |
| Road Surface       | DRY                      |

#### Other Information

|                                                                                             |     |
|---------------------------------------------------------------------------------------------|-----|
| Was any foreign vehicle involved in this accident?                                          | NO  |
| Number of vehicles (including own vehicle) involved in the accident                         | 2   |
| Was any body injured in the Accident?                                                       | NO  |
| Was any injured conveyed to hospital by ambulance?                                          | NO  |
| Was any other material or property damaged?                                                 | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)                                                     | 1   |

#### Details of Police Action

|                                           |    |
|-------------------------------------------|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORD BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

#### Attachment(s)

|                                               |     |
|-----------------------------------------------|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | YES |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |             |
|-------------------------------------|-------------|
| Vehicle Registration Number         | SKU162A     |
| Vehicle Make/Model/Colour           |             |
| Details Of Properties               |             |
| Vehicle Category                    | PRIVATE CAR |
| Name of Driver                      |             |
| NRIC/Passport Number                |             |
| Contact Number                      |             |
| Address                             |             |
| Postcode                            |             |
| Insurance Company Name              |             |
| Nature Of Damage                    |             |
| No. Of Passenger (Including Driver) |             |

## Sketch Plan


### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### Sketch Plan #2

### SKETCH PLAN

Vehicle  
A - SLF732ST  
B - SKW162A

WHILE CLOSING GAP  
I WAS CHECKING RIGHT  
BLIND SPOT TO AFTER  
NAGEN FRONT CAR STOP.

Legend

|                                                                                     |                                                                                     |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|  |  |
| Vehicle                                                                             | Motorcycle                                                                          |

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

I WAS DRIVING ALONG CTE TO 1ST EXIT BALESTIER (TO CITY). AS I WAS CHECKING MY BLIND SPOT TO FILTER RIGHT FRONT CAR STOPPED AND I WASN'T ABLE TO STOP AND BAM RIGHT ON. THE OTHER DRIVER MENTIONED NO ONE INJURED AND THEY MIGHT SEND THEIR GIRL TO A CLINIC JUST TO HAVE A CHECK. THEY ARE SENDING THEIR CAR TO CBC AS WELL. AFTER TAKING PHOTOS AND HP NUMBER I DROVE TO 120 BALESTIER ED TO WAIT FOR TOW. THE OTHER DRIVER REPORTED TO IDAC.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

26/10/19

Policyholder's Signature \_\_\_\_\_

**Date & Time:**

26/10/19.

Driver's Signature \_\_\_\_\_

(If driver is not the policyholder)

**Date & Time:**

Reporting Centre Personnel's Signature

Names: \_\_\_\_\_  
NRIC/EPN No.: \_\_\_\_\_



**PROGRESSIVE**  
CAR CARE PTE LTD

**Progressive Car Care Pte Ltd**

(Co. Reg. No. 201006949C)

Blk 3022A Ubi Road 1 #01-45/ 46 S408716

T: +65 5741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

INSURER: **FWD Singapore Pte. Ltd. (HQ)**

#### PARTICULARS OF CLAIM

|                     |                   |                       |              |
|---------------------|-------------------|-----------------------|--------------|
| Claim Type:         | OD (OWN DAMAGE)   | Ref. No:              | OD 1019-7224 |
| Policy No:          | PNCV2019-00000387 | Date of Loss:         | 26/10/2019   |
| Vehicle Reg. No.:   | <b>SLF7325T</b>   | Driveable?            |              |
| Driver Age/Info:    | 36 / MALE         | Party At Fault:       | UNKNOWN      |
| TP Injury Involved? | NO                | Third Party Involved? | YES          |
| Insured/Claimant:   | TERRY LOH JUNRONG | Contact No:           | +6593260316  |
| Driver:             | TERRY LOH JUNRONG |                       |              |

|                 |                        |                    |                   |
|-----------------|------------------------|--------------------|-------------------|
| Make/Model:     | KIA CERATO K3, 1.6 (A) | Vehicle Reg. Date: | 15/12/2017        |
| Vehicle Colour: | BLACK                  |                    |                   |
| Engine No:      | G4FGHH687860           | Chassis No:        | KNAFZ411MJ5755581 |
| Odometer:       | 72118 KM               |                    |                   |

|                               |           |
|-------------------------------|-----------|
| Paint Type:                   |           |
| Total Loss?                   | <b>NO</b> |
| Est. Duration of Repair (day) | <b>8</b>  |

Description of Accident/Loss: REFER TO ATTACHED STATEMENT RECORD BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

Remarks: VEHICLE IS IN WORKSHOP

Present Location: PROGRESSIVE CAR CARE PTE LTD (HQ)

#### COST OF CLAIMS

|                     | Amount   |
|---------------------|----------|
| Parts               | 7,896.00 |
| Miscellaneous Items | 85.00    |
| Labour              | 1,240.00 |
| Paintwork Labour    | 1,100.00 |
| Towing              | 0.00     |

Gross Total (S\$) **10,321.00**

+ GST 7.00% (S\$) **722.47**

Nett Amount (S\$) **11,043.47**

This claim is handled by: LILY LIM

Generated using Merimen e-Claims Interest Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized  
LKK  
31/10/19  
To be resurveyed  
6 day.  
EXCESS \$1000

## REPAIR DETAILS

## Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 30 Oct 2019)

Parts: 143

KIA CERATO K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Progressive Car Care Pte Ltd/SLF7325T/30/10/2019 14:39

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*

## Estimates on Parts

| No. | Qty | Part No. | Particulars                          | %Disc | %Depr | Amount             |
|-----|-----|----------|--------------------------------------|-------|-------|--------------------|
| 1   | 1   | NA       | *FRONT BUMPER                        | -0.00 | 0.00  | D/S *310.00 F      |
| 2   | 10  | NA       | *FRONT BUMPER CLIPS                  | 0.00  | 0.00  | 11 *30.00 F X      |
| 3   | 1   | NA       | *FRONT BUMPER SIDE HOLDER - LH       | -0.00 | 0.00  | 51 *7.00 F         |
| 4   | 1   | NA       | *FRONT BUMPER SIDE HOLDER - RH       | -0.00 | 0.00  | 51 *7.00 F         |
| 5   | 1   | NA       | *FRONT BUMPER FOAM                   | -0.00 | 0.00  | 30.3 *45.00 F      |
| 6   | 1   | NA       | *FRONT BUMPER REINFORCEMENT W/BACKET | -0.00 | 0.00  | 5.5 *220.00 F      |
| 7   | 6   | NA       | *FRONT BUMPER SENSOR                 | 0.00  | 0.00  | SUC *510.00 F X    |
| 8   | 1   | NA       | *FRONT BUMPER UPPER GRILLE           | -0.00 | 0.00  | 20 *165.00 F       |
| 9   | 10  | NA       | *FRONT BUMPER UPPER GRILLE CLIPS     | -0.00 | 0.00  | 11 *30.00 F        |
| 10  | 1   | NA       | *FRONT BUMPER LOWER GRILLE           | -0.00 | 0.00  | 11 *35.00 F        |
| 11  | 10  | NA       | *FRONT BUMPER LOWER GRILLE CLIPS     | 0.00  | 0.00  | 11 *30.00 F X      |
| 12  | 1   | NA       | *FRONT BUMPER LOWER SPOILER          | 0.00  | 0.00  | 11 *35.00 F X      |
| 13  | 1   | NA       | *FRONT BUMPER LOGO                   | 0.00  | 0.00  | NS *F X            |
| 14  | 1   | NA       | *FRONT BUMPER TOW COVER              | 0.00  | 0.00  | c/w bumper *6.00 F |
| 15  | 1   | NA       | *BONNET                              | -0.00 | 0.00  | SUC *430.00 F      |
| 16  | 1   | NA       | *BONNET INSULATOR                    | -0.00 | 0.00  | 20 *60.00 F        |
| 17  | 8   | NA       | *BONNET INSULATOR CLIPS              | -0.00 | 0.00  | 20 *24.00 F        |
| 18  | 1   | NA       | *BONNET HINGE - RH                   | -0.00 | 0.00  | 51 *25.00 F        |
| 19  | 1   | NA       | *BONNET HINGE - LH                   | -0.00 | 0.00  | 51 *25.00 F        |
| 20  | 1   | NA       | *BONNET LOCK                         | -0.00 | 0.00  | 11 *40.00 F        |
| 21  | 1   | NA       | *BONNET CATCH                        | 0.00  | 0.00  | NS *28.00 F X      |
| 22  | 4   | NA       | *BONNET RUBBER STOPPER               | 0.00  | 0.00  | 11 *24.00 F X      |
| 23  | 1   | NA       | *FRONT FOGLAMP - RH                  | 220   | 0.00  | CNE *490.80 F      |
| 24  | 1   | NA       | *FRONT FOGLAMP - LH                  | 0.00  | 0.00  | SUC *190.00 F X    |
| 25  | 1   | NA       | *FRONT FOGLAMP COVER - RH            | 0.00  | 0.00  | 11 *20.00 F        |
| 26  | 1   | NA       | *FRONT FOGLAMP COVER - LH            | 0.00  | 0.00  | 11 *20.00 F        |
| 27  | 1   | NA       | *FRONT FOGLAMP OUTER CHROME - RH     | 0.00  | 0.00  | NS *F X            |
| 28  | 1   | NA       | *FRONT FOGLAMP OUTER CHROME - LH     | 0.00  | 0.00  | NS *F X            |
| 29  | 1   | NA       | *HEADLAMP UNIT - RH                  | -0.00 | 0.00  | CNE *1,150.00 F    |
| 30  | 1   | NA       | *HEADLAMP UNIT - LH                  | -0.00 | 0.00  | CNE *1,150.00 F    |
| 31  | 1   | NA       | *HEADLAMP LOWER RETAINER - RH        | 0.00  | 0.00  | 11 *28.00 F        |
| 32  | 1   | NA       | *HEADLAMP LOWER RETAINER - LH        | 0.00  | 0.00  | 11 *28.00 F        |
| 33  | 1   | NA       | *WIPER TANK                          | 0.00  | 0.00  | 11 *65.00 F        |
| 34  | 1   | NA       | *RADIATOR                            | -0.00 | 0.00  | D/S *250.00 F      |
| 35  | 1   | NA       | *RADIATOR TOP HOSE                   | 0.00  | 0.00  | 51 *16.00 F X      |
| 36  | 1   | NA       | *RADIATOR LOWER HOSE                 | -0.00 | 0.00  | 51 *18.00 F        |
| 37  | 1   | NA       | *RADIATOR SPARE TANK                 | 0.00  | 0.00  | 51 *70.00 F        |
| 38  | 1   | NA       | *AIR CLEANER BOX                     | 0.00  | 0.00  | 11 *70.00 F        |
| 39  | 1   | NA       | *AIRDUCT                             | 0.00  | 0.00  | 11 *50.00 F        |
| 40  | 1   | NA       | *ENGINE INTAKE MANIFOLD              | -0.00 | 0.00  | fra *450.00 F      |
| 41  | 1   | NA       | *ENGINE ALTERNATOR                   | 0.00  | 0.00  | 11 *550.00 F       |
| 42  | 1   | NA       | *ENGINE THROTTLE BODY                | 0.00  | 0.00  | 51 *380.00 F       |
| 43  | 1   | NA       | *AIRCON SUCTION PIPE                 | -0.00 | 0.00  | 51 *280.00 F       |
| 44  | 1   | NA       | *AIRCON DISCHARGE PIPE               | 0.00  | 0.00  | SUC *280.00 F      |
| 45  | 1   | NA       | *AIRCON CONDENSER                    | 0.00  | 0.00  | D/S *770.00 F      |

F=Franchise part.

Total Parts (\$S)

7,896.00

Progressive Car Care Pte Ltd/SLF7325T/30/10/2019 14:39. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

5283

## Estimates on Miscellaneous Items

| No                         | Qty | Particulars                    | Amount |
|----------------------------|-----|--------------------------------|--------|
| <u>Miscellaneous Items</u> |     |                                |        |
| 1                          | 1   | COOLANT                        | 50.00  |
| 2                          | 1   | FRONT NUMBER PLATE WITH CASING | 35.00  |
| Sub Total (\$\$)           |     |                                | 85.00  |

## Estimates on Labour

| No                       | Particulars                                                                    | Lab.Type | Amount   |
|--------------------------|--------------------------------------------------------------------------------|----------|----------|
| <u>Paintwork Labour</u>  |                                                                                |          |          |
| 1                        | TO RESPRAY PAINT ON ACCIDENT PORTIONS                                          | New 980  | 1,100.00 |
| <u>Labour Items</u>      |                                                                                |          |          |
| 2                        | TO REMOVE; REALIGN; REPAIR; CUT/WELD; KNOCK OUT DENTS & REPLACE ACCIDENT PARTS | New 880  | 1,000.00 |
| 3                        | TO CHECK WIRING                                                                | New ✓    | 20.00    |
| 4                        | TO REMOVE; REPLACE CONDENSER AND REFILL GAS                                    | New ✓    | 100.00   |
| 5                        | TO REMOVE; REPLACE FRONT BUMPER SENSOR                                         | New 40   | 120.00   |
| Gross Labour Cost (\$\$) |                                                                                |          | 2,340.00 |

Progressive Car Care Pte Ltd/SLF7325T/30/10/2019 14:39. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

2020

Our equipment include the latest and reliable CAR-OLIBER MARK II repair bench, crow aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

P-670P  
S.N-65  
L-2020  
SL-150  
8944



**PROGRESSIVE**  
CAR CARE PTE LTD

**Progressive Car Care P**  
(Co. Reg. No. 20100)  
Blk 3022A Ubi Road 1 #01-45/46 S  
T: +65 6741 5336 | F: +65 674  
E: claims@procarcare.  
W: www.procarcare.

(SUPPLEMENTARY)

INSURER: FWD Singapore Pte. Ltd. (HQ)

| PARTICULARS OF CLAIM          |                                                                                    |                       |                   |
|-------------------------------|------------------------------------------------------------------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (OWN DAMAGE)                                                                    | Ref. No:              | OD 1019-7224      |
| Policy No:                    | PNCV2019-00000387                                                                  | Date of Loss:         | 26/10/2019        |
| Vehicle Reg. No.:             | SLF7325T                                                                           | Driveable?            |                   |
| Driver Age/Info:              | 36 / MALE                                                                          | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | NO                                                                                 | Third Party Involved? | YES               |
| Insured/Claimant:             | TERRY LOH JUNRONG                                                                  | Contact No:           | +6593260316       |
| Driver:                       | TERRY LOH JUNRONG                                                                  |                       |                   |
| Make/Model:                   | KIA CERATO K3, 1.6 (A)                                                             | Vehicle Reg. Date:    | 15/12/2017        |
| Vehicle Colour:               | BLACK                                                                              |                       |                   |
| Engine No:                    | G4FGHH687860                                                                       | Chassis No:           | KNAFZ411MJ5755581 |
| Odometer:                     | 72118 KM                                                                           |                       |                   |
| Paint Type:                   |                                                                                    |                       |                   |
| Total Loss?                   | NO                                                                                 |                       |                   |
| Est. Duration of Repair (day) | 8                                                                                  |                       |                   |
| Description of Accident/Loss  | REFER TO ATTACHED STATEMENT RECORD BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336 |                       |                   |
| Present Location:             | PROGRESSIVE CAR CARE PTE LTD (HQ)                                                  |                       |                   |

| COST OF CLAIMS              |  | Amount    |
|-----------------------------|--|-----------|
| Parts                       |  | 1,053.00  |
| Miscellaneous Items         |  | 0.00      |
| Labour                      |  | 0.00      |
| Paintwork Labour            |  | 0.00      |
| Towing                      |  | 0.00      |
| Gross Total (\$\$)          |  | 1,053.00  |
| + GST 7.00% (\$\$)          |  | 73.71     |
| Nett Amount (\$\$)          |  | 1,126.71  |
| + Previous Estimates (\$\$) |  | 11,043.47 |
| Claim Total (\$\$)          |  | 12,170.18 |

Generated using Merimen e-Claims Internet Estimation & Adjusting System

# REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Nov 2019)  
 Parts: 143 KIA CERATO K3 1.6 (A) (Catalogue: Marimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: (Unsubmitted, no print-code for SLF7325T)  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further info: Items/values not in reference catalogue are prefixed with an asterisk \*

## Estimates on Parts

| No.               | Qty | Part No. | Particulars                             | %Disc | %Depr | Amount      |
|-------------------|-----|----------|-----------------------------------------|-------|-------|-------------|
| 1                 | 1   |          | *SUPPORT PANEL <i>D.S.</i>              | 0.00  | 0.00  | *300.00 F ✓ |
| 2                 | 1   |          | *CONDENSER SIDE GARNISH - L <i>21.1</i> | 0.00  | 0.00  | *15.00 F ✓  |
| 3                 | 1   |          | *CONDENSER SIDE GARNISH - R <i>10.1</i> | 0.00  | 0.00  | *15.00 F ✓  |
| 4                 | 1   |          | *FRT BUMPER LOWER GARNISH <i>71.1</i>   | 0.00  | 0.00  | *65.00 F ✓  |
| 5                 | 1   |          | *GRILLE INNER GARNISH <i>D.S.</i>       | 0.00  | 0.00  | *55.00 F ✓  |
| 6                 | 1   |          | *GRILLE TOP GARNISH <i>D.S.</i>         | 0.00  | 0.00  | *28.00 F ✓  |
| 7                 | 1   |          | *FRT NUMBER PLATE GARNISH <i>D.S.</i>   | 0.00  | 0.00  | *15.00 F ✓  |
| 8                 | 1   |          | *RHF FENDER <i>31.1</i>                 | 0.00  | 0.00  | *180.00 F ✓ |
| 9                 | 1   |          | *AIRCON FUSE <i>51.1</i>                | 0.00  | 0.00  | *55.00 F ✓  |
| 10                | 1   |          | *AIRCON DISCHARGE PIPE (B) <i>11.1</i>  | 0.00  | 0.00  | *125.00 F ✓ |
| 11                | 1   |          | *FOGLAMP ASSY - R <i>11.1</i>           | 0.00  | 0.00  | *220.00 F ✓ |
| Total Parts (S\$) |     |          |                                         |       |       | 1,053.00    |

F=Franchise part.

Report was unsubmitted during this print-out.  
 Generated using Marimen e-Claims IEAS

*supp 1/276*

*816*



**PROGRESSIVE**  
CAR CARE PTE LTD

**Progressive Car Care Pte Ltd**

(Co. Reg. No. 201006949C)

Blk 3022A Ubi Road 1 #01-45/46 S408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

**(SUPPLEMENTARY)**

INSURER: FWD Singapore Pte. Ltd. (HQ)

**PARTICULARS OF CLAIM**

|                               |                                                                                    |                       |                   |
|-------------------------------|------------------------------------------------------------------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (OWN DAMAGE)                                                                    | Ref. No:              | OD 1019-7224      |
| Policy No:                    | PNCV2019-00000387                                                                  | Date of Loss:         | 26/10/2019        |
| Vehicle Reg. No.:             | SLF7325T                                                                           | Driveable?            |                   |
| Driver Age/Info:              | 36 / MALE                                                                          | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | NO                                                                                 | Third Party Involved? | YES               |
| Insured/Claimant:             | TERRY LOH JUNRONG                                                                  | Contact No:           | +6593260316       |
| Driver:                       | TERRY LOH JUNRONG                                                                  |                       |                   |
| Make/Model:                   | KIA CERATO K3, 1.6 (A)                                                             | Vehicle Reg. Date:    | 15/12/2017        |
| Vehicle Colour:               | BLACK                                                                              | Chassis No:           | KNAFZ411MJ5755581 |
| Engine No:                    | G4FGHH687860                                                                       |                       |                   |
| Odometer:                     | 72118 KM                                                                           |                       |                   |
| Paint Type:                   |                                                                                    |                       |                   |
| Total Loss?                   | NO                                                                                 |                       |                   |
| Est. Duration of Repair (day) | 8                                                                                  |                       |                   |
| Description of Accident/Loss  | REFER TO ATTACHED STATEMENT RECORD BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336 |                       |                   |
| Present Location:             | PROGRESSIVE CAR CARE PTE LTD (HQ)                                                  |                       |                   |

**COST OF CLAIMS**

|                                   | Amount           |
|-----------------------------------|------------------|
| Parts                             | 280.00           |
| Miscellaneous Items               | 0.00             |
| Labour                            | 0.00             |
| Paintwork Labour                  | 0.00             |
| Towing                            | 0.00             |
| <b>Gross Total (S\$)</b>          | <b>280.00</b>    |
| <b>+ GST 7.00% (S\$)</b>          | <b>19.60</b>     |
| <b>Nett Amount (S\$)</b>          | <b>299.60</b>    |
| <b>+ Previous Estimates (S\$)</b> | <b>12,170.18</b> |
| <b>Claim Total (S\$)</b>          | <b>12,469.78</b> |

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Nov 2019)

Parts: 143 KIA CERATO K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Progressive Car Care Pte Ltd/SLF7325T/08/11/2019 17:05

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No.               | Qty | Part No. | Particulars            | %Disc | %Depr | Amount          |
|-------------------|-----|----------|------------------------|-------|-------|-----------------|
| 1                 | 1   |          | *AIRCON FAN MOTOR ASSY | 0.00  | 0.00  | CRA *280.00 F ✓ |
| Total Parts (S\$) |     |          |                        |       |       | 280.00          |

F=Franchise part.

Progressive Car Care Pte Ltd/SLF7325T/08/11/2019 17:05. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS



**PROGRESSIVE**  
CAR CARE PTE LTD

**Progressive Car Care Pte Ltd**

(Co. Reg. No. 201006949C)

Blk 3022A Ubi Road 1 #01-45/ 46 S408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

**(SUPPLEMENTARY)**

INSURER:

FWD Singapore Pte. Ltd. (HQ)

**PARTICULARS OF CLAIM**

|                               |                                                                                    |                       |                   |
|-------------------------------|------------------------------------------------------------------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (OWN DAMAGE)                                                                    | Ref. No:              | OD 1019-7224      |
| Policy No:                    | PNCV2019-00000387                                                                  | Date of Loss:         | 26/10/2019        |
| Vehicle Reg. No.:             | SLF7325T                                                                           | Driveable?            |                   |
| Driver Age/Info:              | 36 / MALE                                                                          | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | NO                                                                                 | Third Party Involved? | YES               |
| Insured/Claimant:             | TERRY LOH JUNRONG                                                                  | Contact No:           | +6593260316       |
| Driver:                       | TERRY LOH JUNRONG                                                                  |                       |                   |
| Make/Model:                   | KIA CERATO K3, 1.6 (A)                                                             | Vehicle Reg. Date:    | 15/12/2017        |
| Vehicle Colour:               | BLACK                                                                              | Chassis No:           | KNAFZ411MJ5755581 |
| Engine No:                    | G4FGHH687860                                                                       |                       |                   |
| Odometer:                     | 72118 KM                                                                           |                       |                   |
| Paint Type:                   |                                                                                    |                       |                   |
| Total Loss?                   | NO                                                                                 |                       |                   |
| Est. Duration of Repair (day) | 8                                                                                  |                       |                   |
| Description of Accident/Loss  | REFER TO ATTACHED STATEMENT RECORD BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336 |                       |                   |
| Present Location:             | PROGRESSIVE CAR CARE PTE LTD (HQ)                                                  |                       |                   |

**COST OF CLAIMS**

|                                   | Amount           |
|-----------------------------------|------------------|
| Parts                             | 330.00           |
| Miscellaneous Items               | 0.00             |
| Labour                            | 150.00           |
| Paintwork Labour                  | 0.00             |
| Towing                            | 0.00             |
| <b>Gross Total (S\$)</b>          | <b>480.00</b>    |
| <b>+ GST 7.00% (S\$)</b>          | <b>33.60</b>     |
| <b>Nett Amount (S\$)</b>          | <b>513.60</b>    |
| <b>+ Previous Estimates (S\$)</b> | <b>12,469.78</b> |
| <b>Claim Total (S\$)</b>          | <b>12,983.38</b> |

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS****Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Nov 2019)

Parts: 143 KIA CERATO K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Progressive Car Care Pte Ltd/SLF7325T/15/11/2019 12:12

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

| No.               | Qty | Part No. | Particulars         | %Disc | %Depr  | Amount         |
|-------------------|-----|----------|---------------------|-------|--------|----------------|
| 1                 | 1   |          | *FRONT BUMPER LOWER | 0.00  | ✓ 0.00 | TN *330.00 F ✓ |
| Total Parts (S\$) |     |          |                     |       |        | 330.00         |

F=Franchise part.

Progressive Car Care Pte Ltd/SLF7325T/15/11/2019 12:12. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

| No                       | Particulars                          | Lab.Type | Amount |
|--------------------------|--------------------------------------|----------|--------|
| <u>Labour Items</u>      |                                      |          |        |
| 1                        | TO RESPRAY PAINT ON FRT BUMPER LOWER | New      | 150.00 |
| Gross Labour Cost (\$\$) |                                      |          | 150.00 |

Progressive Car Care Pte Ltd/SLF7325T/15/11/2019 12:12. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

Our equipment include the latest and reliable CAR-O-LINER MARK 1 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.



# 特立機器貿易

## MEGA POWER ENGINEERING & TRADING

Automobile Air Conditioning System Is Our Business

Head Office: 39 Genting Road Singapore 349485 Tel: 6842 3388 Fax: 6842 3373  
Email: mega1989@shgnet.com.sg Business Reg. No. 40569100W

### TAX INVOICE

GST Reg# : M8-8002898-3  
Invoice No. : INV 10228844  
Invoice Date : 8-Nov-2019  
Terms : 30 DAYS  
PO No :  
Vehicle No : SLF7325T  
Chassis No :  
Staff : YOU FU

Bill To: PRO002

PROGRESSIVE CAR CARE PTE LTD  
BLK 3022A UBI ROAD 1  
#01-45/46  
SINGAPORE 408716  
Attn: Account Dept

Ship To: KG1

PROGRESSIVE CAR CARE PTE LTD  
BLK 3022A UBI ROAD 1  
#01-45/46  
Attn: WENDY  
Tel: 82585595

Remarks:

# MUST KEY IN ORDER PERSON'S  
NAME & VEHICLE NO.

0077224

| S/NC       | DESCRIPTION                                  | MOQ        | BIN     | WH | QTY | PRICE  | SP  | TOTAL (SGD) |
|------------|----------------------------------------------|------------|---------|----|-----|--------|-----|-------------|
| PO Number: |                                              | DO Number: |         |    |     |        |     |             |
| 1 HS       | KIA CERATO K3 SUCTION & LIQUID PIPE ORIGINAL |            |         | KB | 1   | 280.00 | 43  | 280.00 ✓    |
| 2 HD       | KIA CERATO K3 DISCHARGE PIPE                 |            |         | KB | 1   | 125.00 | 510 | 125.00 ✓    |
| 3 RM-00096 | KIA CERATO Y13 RAD FAN W/RES                 |            | KB1-D10 | KB | 1   | 280.00 | 51  | 280.00 ✓    |
| 4 CD-00288 | KIA FORTE K3 <15 DW COND W/DESI              |            | KB2-C04 | KB | 1   | 345.00 | 45  | 345.00 ✓    |
| 5 *TAKEN*  | *****TAKEN*****                              |            |         | KB | 1   | -      |     | -           |

Rate: 1 SGD: 1.000000 SGD

Note: Goods sold are not returnable.

All Brand New compressor sold are without warranty.  
Late payment is subject to 2% interest per month.

SUB-TOTAL 1,030.00 SGD  
DISC 0.00% (-) SGD  
GST 7% 72.10 SGD  
AMOUNT 1,102.10 SGD

This is a computer-generated document.  
No signature is required.  
Printed on: 08/11/2019 18:35:01

CUSTOMER COPY

Customer Signature & Stamp



Blk 5025, Ang Mo Kio Ind Park 2 #01-55/57 S(569538) Tel: 6482 3388 Fax: 6481 1187

No. 13 Kallang Rd #01-27 Bartley Bldg Centre S(417007) Tel: 6303 3388 Fax: 6303 3329

No. 5 Soon Lee St #01-26 Pioneer Point S(617607) Tel: 6252 3388 Fax: 6275 3388

No. 21 Toh Guan Rd East #01-32 Toh Guan Centre S(608600) Tel: 6700 3388 Fax: 6316 2464





# 日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:  
48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg  
GST REG. NO.: M2-0118201-3 CO. REG. NO.: 109307741M



Wiper blade: NWB (Nippon Wiper blade), Sliper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

## PROGRESSIVE CAR CARE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WENDY

TAX INVOICE : AR201911-00068

DATE : 01/11/2019

CUSTOMER ID : PRO005

VEH REG. NO. : SLF73251

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 3

CURR. : SGD

| SQ | STOCKID                  | DESCRIPTION               | Stk Loc    | QTY | U/PRICE | AMOUNT |
|----|--------------------------|---------------------------|------------|-----|---------|--------|
| 1  | KS86511A7810             | FRT BUMPER                | CC         | 1   | 310.00  | 310.00 |
|    | K3 16-                   |                           | CC7-N-070  |     |         |        |
| 2  | HY14206-08250B           | RAD GRILLE UPR COVER CLIP | CC         | 6   | 3.00    | 18.00  |
|    |                          | X4 (ELANTRA 16-18)        |            |     |         |        |
|    | IONIQ TAXI 16-/B30 2018- |                           | CC7-A-08BK |     |         |        |
| 3  | KS1420608250B            | CLIP                      | CC         | 3   | 3.00    | 9.00   |
|    | K3 16-18-                |                           | CC7-B-12AD |     |         |        |
| 4  | KS86514A7000             | FRT BUMPER RETAINER RH    | CC         | 1   | 7.00    | 7.00   |
|    | K3 13-16-                |                           | CC7-A-09AO |     |         |        |
| 5  | KS86513A7000             | FRT BUMPER RETAINER LH    | CC         | 1   | 7.00    | 7.00   |
|    | K3 13-16-                |                           | CC7-A-07AB |     |         |        |
| 6  | KS86520A7800             | FRT BUMPER FOAM           | CC         | 1   | 45.00   | 45.00  |
|    | K3 16-                   |                           | CC7-D-09B  |     |         |        |
| 7  | KS86530A7600             | REINFORCEMENT             | CC         | 1   | 220.00  | 220.00 |
|    | K3 16-                   |                           | CC7-J-070  |     |         |        |

CONTINUE NEXT PAGE

[P] 01/11/2019 09:21:46

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 01/11/2019 6:07:42PM

6709



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729572  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS  
Dept Direct: 9417 8381 / 8749 9838



Dept Direct: 9417 9734

Dept Direct: 9417 9735

Dept Direct: 9417 9736

Dept Direct: 9417 9737

Wiper blade: NWB (Nippon Wiper blade), Bilper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WENDY

TAX INVOICE : AR201911-00068

DATE : 01/11/2019

CUSTOMER ID : PRO005

VEH REG. NO. : SLF73251

TERMS : 30 days

PO NO. :

PAGE NO. : Page 3 of 3

CURR. : SGD

00 7224

| STOCK ID     | DESCRIPTION    | Stk Loc   | QTY | U/PRICE | AMOUNT |
|--------------|----------------|-----------|-----|---------|--------|
| HY25350-3X50 | RADIAN COWLING | CC7-B-04E | 1   | 70.00   | 70.00  |
| ELANTRA 2014 |                |           |     |         |        |

SUB-TOTAL : 2,186.00  
ADD GST 7.00 % 153.02

H. & O.E

TOTAL AMOUNT SGD : 2,339.02

[P] 01/11/2019 09:21:46

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 01/11/2019 07:42PM

JAE Auto Pte. Ltd.

Sales Executive: KOW



This is computer generated document.  
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature/ Co Stamp/ Date



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Bldg 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450816 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE

SINGAPORE 737889 TEL: 63625228 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 100307741M

PROGRESSIVE CAR CARE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WENDY

WIPERBLADE BLANK  
Dept Direct: 6417 8781 / 8743 8639



Dept Direct: 6417 8781

Dept Direct: 6417 8786

Dept Direct: 6417 8786

Dept Direct: 6417 8786

Wiper blades: NWB (Nippon Wiper blade), Silper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201911-09356

DATE : 19/11/2019

CUSTOMER ID : PRO005

VEH REG. NO. : SLF7325T

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

45 007224

| SQ STOCKID                       | DESCRIPTION         | StkLoc         | QTY | U/PRICE | AMOUNT |
|----------------------------------|---------------------|----------------|-----|---------|--------|
| 1. KSUK-L1-900K3 16-<br>K3 16-18 | F.BUMP AIRDAM SKIRT | UI<br>SUPPLIER | 1   | 330.00  | 330.00 |

Sum

SUB-TOTAL : 330.00  
ADD GST 7.00 % 23.10

E. & O.E TOTAL AMOUNT SGD : 353.10

[P] 19/11/2019 1:44:26PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[B] 19/11/2019 1:43:34PM

JAE Auto Pte. Ltd.

Sales Executive: KOW

This is computer generated document.

No signature is required.



\* AR201911-09356 \*

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450618 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE  
SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0118201-3 CO. REG. NO.: 199307741M

NISSAN  
Dept Direct: 6417 8701 / 6743 0809

Dept Direct: 6206 9810

Dept Direct: 6417 8704

Dept Direct: 6417 8705

Dept Direct: 6417 8706

Dept Direct: 6417 8707

Dept Direct: 6417 8708

Dept Direct: 6417 8709

Dept Direct: 6417 8710

Dept Direct: 6417 8711

Dept Direct: 6417 8712

Dept Direct: 6417 8713

Wiper blade: NWB (Nippon Wiper Blade), Siliper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD  
BLOCK 3022A #01-45/46  
UBI ROAD 1  
BUTTON 92712711  
SINGAPORE 408716  
TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY  
ATTN: WENDY

TAX INVOICE : AR201911-00449  
DATE : 01/11/2019  
CUSTOMER ID : PRO005  
VEH REG. NO. : SLF7325T  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR. : SGD

| SQ STOCKID             | DESCRIPTION                       | Stk Loc              | QTY | U/PRICE | AMOUNT |
|------------------------|-----------------------------------|----------------------|-----|---------|--------|
| KS64101A7600<br>K3 16- | SUPPORT PANEL                     | U1<br>BM-B3          | 151 | 300.00  | 300.00 |
| KS29134A7500<br>K3 16- | GUARD-AIR,RH                      | U1<br>U1L2-A3-02CC-B | 152 | 15.00   | 15.00  |
| KS29136A7500<br>K3 16- | GUARD AIR LH                      | U1<br>U1L2-A3-02CC-B | 153 | 15.00   | 15.00  |
| KS86571A7800<br>K3 16- | STIFFENER - FRONT BUMPER<br>LOWER | U1<br>U1L1-D3-03A-SD | 154 | 65.00   | 65.00  |
| KS253103X600<br>K3 16- | RADIATOR ASSY                     | U1<br>U1L1-C3-01B    | 134 | 250.00  | 250.00 |
| KS254123X001<br>K3 12- | HOSE LOWER                        | U1<br>U1L2-D3-02B-H  | 136 | 18.00   | 18.00  |

SUB-TOTAL : 663.00  
ADD GST 7.00 % 46.41

E. & O.E TOTAL AMOUNT SGD : 709.41

[P] 01/11/2019 2:21:10PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 01/11/2019 2:13:27PM

Goods Received in Good Order

JAE Auto Pte. Ltd.

Sales Executive : KOW

This is computer generated document.

No signature is required.



\* AR201911-00449 \*

ORIGINAL

Signature / Co Stamp / Date



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450816 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE  
SINGAPORE 737889 TEL: 63825226 FAX: 63826877

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS  
Dept Direct: 6417 8761 / 6743 9638



Dept Direct: 6417 8764

Dept Direct: 6417 8766

Dept Direct: 6417 8768

Dept Direct: 6417 8769

Wiper blade: NWB (Nippon Wiper blade), Silpar (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: BUTTON

00 7224

TAX INVOICE : AR201911-02310

DATE : 05/11/2019

CUSTOMER ID : PRO005

VEH REG. NO. : SLF7325T

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

| SQ STOCKID                | DESCRIPTION           | StkLoc              | QTY | U/PRICE | AMOUNT |
|---------------------------|-----------------------|---------------------|-----|---------|--------|
| 888KS86357A7800<br>K3 16- | STRIP-FR BUMPER UPPER | U1<br>UIL2-D2-02B-H | 158 | 18.00   | 18.00  |

SUB-TOTAL : 18.00

ADD GST 7.00 % 1.26

E. & O.E.

TOTAL AMOUNT SGD : 19.26

[P] 05/11/2019 4:01:33PM

[E] 05/11/2019 4:01:11PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : KOW

This is computer generated document.

No signature is required.



\* AR201911-02310 \*

ORIGINAL

Goods Received in Good Order

*C. M. S.*  
Signature / Co Stamp / Date



# 日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

## WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0118201-3 CO. REG. NO.: 199307741M



Dept Direct: 6417 8704

Dept Direct: 6417 8705

Dept Direct: 6417 8706

Dept Direct: 6417 8707

Wiper blade: NWB (Nippon Wiper blade), Sliper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

## PROGRESSIVE CAR CARE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY

AFTN : BUTTON

TAX INVOICE : AR201911-01191

DATE : 04/11/2019

CUSTOMER ID : PRO005

VEH REG. NO. : SLK7325T

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

007224

| SO STOCK ID  | DESCRIPTION             | Slk.co     | QTY | U/PRICE | AMOUNT |
|--------------|-------------------------|------------|-----|---------|--------|
| KS86356A7800 | GARNISH ASSY-RAD GRILLE | CC7-C-06B  | 156 | 28.00   | 28.00  |
| K3 16-       | UPR                     |            |     |         |        |
| KS86519A7800 | HOLDER LICHNSB          | CC7-D-10AE | 157 | 15.00   | 15.00  |
| K3 16-       |                         |            |     |         |        |
| KS66321A7000 | FENDER RH               | CC7-G-02B  | 158 | 180.00  | 180.00 |
| K3 13-       |                         |            |     |         |        |

SUB-TOTAL : 223.00  
ADJ GST 7.00 % 15.61

E & OE

TOTAL AMOUNT SGD: 238.61

[P] 04/11/2019 11:16:03

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[P] 04/11/2019 11:12:16AM

JAE Auto Pte. Ltd.

Sales Executive: KOW

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE

SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0118201-3 CO. REG. NO.: 199307741M

PROGRESSIVE CAR CARE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: CHINA LAU TAT

007224

WINDSHIELD GLASS  
Dept Direct 8417 8701 / 8743 8928



Dept Direct 8308 8418

Dept Direct 8305 8018

Dept Direct 8417 8702



Dept Direct 8417 8194

Dept Direct 8417 8702

Dept Direct 8417 8708

Dept Direct 8417 8702

Wiper blades: NWB (Nippon Wiper blade), Silpar (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201911-01809

DATE : 05/11/2019

CUSTOMER ID : PRO005

VEH REG. NO. : SLF7325T

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

| SO STOCKID      | DESCRIPTION | StkLoc   | QTY | U/PRICE | AMOUNT |
|-----------------|-------------|----------|-----|---------|--------|
| 1. KS1879001316 | MULTI FUSE  | UI       | 51  | 55.00   | 55.00  |
| FORTE K3 16     |             | SUPPLIER |     |         |        |

SUB-TOTAL : 55.00

ADD GST 7.00 % 3.85

E. & O.E

TOTAL AMOUNT SGD : 58.85

[P] 05/11/2019 9:56:14AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[B] 05/11/2019 9:55:55AM

JAE Auto Pte. Ltd.

Sales Executive : KOW

This is computer generated document.

No signature is required.



\* AR201911-01809 \*

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



# 日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450816 (Account)

WAREHOUSE:  
48A SUNGEI KADUT AVE SINGAPORE 729572  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg  
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS  
Dept Direct: 6417 8793 / 6745 6229



Wiper blade: NWB (Nippon Wiper blade), Süper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD  
BLOCK 3022A #01-45/46  
UBI ROAD 1  
BUITION 92712711  
SINGAPORE 408716  
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY  
ATTN : WENDY

00 7224

TAX INVOICE : AR201911-02396  
DATE : 05/11/2019  
CUSTOMER ID : PRO005  
VEH REG. NO. : SLK7325T  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR. : SGD

| SO STOCK ID            | DESCRIPTION        | Slk, Loc | QTY | U/PRICE | AMOUNT |
|------------------------|--------------------|----------|-----|---------|--------|
| KS92202A7500<br>K3 16- | FRONT LAMP ASSY RH | SUPPLIER | 23  | 220.00  | 220.00 |

SUB-TOTAL : 220.00  
ADD GST 7.00 % 15.40

E. & O.E. TOTAL AMOUNT SGD: 235.40

[P] 05/11/2019 17:51:34

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 05/11/2019 3:50:35PM

JAE Auto Pte. Ltd.

Sales Executive: KOW

This is computer generated document.  
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



# 日美汽車私人有限公司 JAE AUTO PTE LTD


Blk 301B UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

## WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Wiper blade: NWB (Nippon Wiper blade), Sllper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

## PROGRESSIVE CAR CARE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WENDY

00 7224

TAX INVOICE : AR201911-00068  
DATE : 01/11/2019  
CUSTOMER ID : PRO005  
VEH REG. NO. : SLK73251  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 2 of 3  
CURR. : SGD

| SQ | STOCK ID           | DESCRIPTION                      | Stk Loc          | QTY  | U/PRICE | AMOUNT     |
|----|--------------------|----------------------------------|------------------|------|---------|------------|
| 8. | KS86350A7810       | GRILLE ASSY-RADIATOR<br>W/CHROME | CC<br>CC7-A-09D  | 1 8  | 165.00  | 165.00 ✓   |
|    | K3 16-             |                                  |                  |      |         |            |
|    | KS86522A7800       | MESH-FR BUMPER CTR               | CC<br>CC7-C-01A  | 1 10 | 35.00   | 35.00 ✓    |
|    | K3 16-             |                                  |                  |      |         |            |
|    | KS81125A7000       | INSULATOR BONNET                 | CC<br>CC7-D-10D  | 1 16 | 60.00   | 60.00 ✓    |
|    | K3 13-             |                                  |                  |      |         |            |
|    | KS79120A7600/A7000 | HINGE BONNET RH                  | CC<br>CC7-A-09H  | 1 18 | 25.00   | 25.00 ✓    |
|    | K3 16-             |                                  |                  |      |         |            |
|    | KS79110A7600/A7000 | HINGE BONNET LH                  | CC<br>CC7-A-07G  | 1 19 | 25.00   | 25.00 ✓    |
|    | K3 16-             |                                  |                  |      |         |            |
|    | KS81130A7810       | LOCK BONNET                      | CC<br>CC7-E-03AC | 1 20 | 40.00   | 40.00 ✓    |
|    | K3 16-             |                                  |                  |      |         |            |
|    | KS92102A7610       | HEAD LAMP RH                     | CC<br>CC7-B-01B  | 1 29 | 1150.00 | 1,150.00 ✓ |
|    | K3 16-             |                                  |                  |      |         |            |

CONTINUE NEXT PAGE

[P] 01/11/2019 09:21:46

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% permonth will be imposed on OverDue Account(s).

ORIGINAL

[E] 01/11/2019 6:07:42PM



# 日美汽車私人有限公司 JAE AUTO PTE LTD

80/3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

## WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE  
SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@paciflo.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Wiper blade: NYB (Nippon Wiper Blade), Silper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

## PROGRESSIVE CAR CARE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WENDY

TAX INVOICE : AR201911-00069

DATE : 01/11/2019

CUSTOMER ID : PRO005

VEH REG. NO. : SLF7325T

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

| SQ STOCKID                | DESCRIPTION              | Std Loc           | QTY | U/PRICE | AMOUNT     |
|---------------------------|--------------------------|-------------------|-----|---------|------------|
| KS66400A7600<br>K3 16-    | BONNET                   | U1<br>HL1-B9      | 1   | 430.00  | 430.00 ✓   |
| KS8112637010<br>ALL MODEL | CLIP-HOOD INSULATOR (12) | U1<br>U1L1-A2-F9  | 8   | 3.00    | 24.00 ✓    |
| KS92101A7610<br>K3 16-    | HEAD LAMP LH             | U1<br>U1L1-D2-02A | 1   | 1150.00 | 1,150.00 ✓ |

SUB-TOTAL : 1,604.00

ADD GST 7.00 % 112.28

E. & O.E

TOTAL AMOUNT SGD 1,716.28

[P] 01/11/2019 6:25:44PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 01/11/2019 6:23:58PM

JAE Auto Pte. Ltd.

Sales Executive: KOW

This is computer generated document.

No signature is required.



\* AR201911-00069 \*

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



# 日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

## WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE  
SINGAPORE 737869 TEL: 63625228 FAX: 63626977

Email: jaeauto@pacific.net.sg

OST REG. NO.: M2-0110201-3 CO. REG. NO.: 109307741M



Dept Direct: 6417 8701 / 8745 9020

Dept Direct: 6417 8701

Dept Direct: 6417 8701

Dept Direct: 6417 8701

Dept Direct: 6417 8701

Wiper blade: NWB (Nippon Wiper blade), Sliper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD  
BLOCK 3022A #01-45/46  
UBI ROAD 1  
BUTTON 92712711  
SINGAPORE 408716  
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY  
ATTN : CHINA LAU TAT

007224

TAX INVOICE : AR201911-00629  
DATE : 01/11/2019  
CUSTOMER ID : PRO005  
VEH REG. NO. : SLF7325T  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR. : SGD

| SQ STOCKID   | DESCRIPTION                  | StkLoc      | QTY | U/PRICE | AMOUNT |
|--------------|------------------------------|-------------|-----|---------|--------|
| KS283102B830 | INLET MANIFOLD (WITH GASKET) | U1          | 1   | 450.00  | 450.00 |
| K3 16-       |                              | UIL2-D2-01B |     |         |        |

SUB-TOTAL : 450.00  
ADD GST 7.00 % 31.50

E. & O.E. TOTAL AMOUNT SGD : 481.50

[P] 01/11/2019 4:56:22PM

[B] 01/11/2019 4:55:53PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : KOW

This is computer generated document.  
No signature is required.



\* AR201911-00629 \*

ORIGINAL

Goods Received in Good Order

↓

Signature / Co Stamp / Date

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |                                                   |                                                                          |                                                     |                                                |                                                |            |                                                                 |
|--------------------------|---------------------------------------------------|--------------------------------------------------------------------------|-----------------------------------------------------|------------------------------------------------|------------------------------------------------|------------|-----------------------------------------------------------------|
| Case                     | Notified                                          | Est Submitted                                                            | Adj Assigned                                        | Adj Rpt                                        | Adj Submitted                                  | Ins Auth'd | Status                                                          |
| Main                     | 30 Oct 2019 14:31<br><a href="#">Sendback Est</a> | 30 Oct 2019 14:39<br><b>\$510,321.00</b><br><a href="#">Edit Adj Rpt</a> | 30 Oct 2019 16:44<br><a href="#">Edit Estimates</a> | <b>\$58,944.00</b><br><a href="#">View Rpt</a> | <b>\$58,944.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |
| Supp #1                  | 01 Nov 2019 12:29                                 | 07 Nov 2019 10:03<br><b>\$51,053.00</b>                                  | 07 Nov 2019 10:03                                   |                                                |                                                | (Combined) | <b>Combined with Main</b><br><a href="#">Uncombine Suppl.</a>   |
| Supp #2                  | 08 Nov 2019 10:14                                 | 08 Nov 2019 17:05<br><b>\$5280.00</b>                                    | 08 Nov 2019 17:05                                   |                                                |                                                | (Combined) | <b>Combined with Main</b><br><a href="#">Uncombine Suppl.</a>   |
| Supp #3                  | 15 Nov 2019 12:11                                 | 15 Nov 2019 12:12<br><b>\$5480.00</b>                                    | 15 Nov 2019 12:12                                   |                                                |                                                | (Combined) | <b>Combined with Main</b><br><a href="#">Uncombine Suppl.</a>   |

|             |                  |                      |                  |                          |
|-------------|------------------|----------------------|------------------|--------------------------|
| <b>Main</b> | <b>Reference</b> | <b>Claim Details</b> | <b>Documents</b> | <a href="#">Show All</a> |
|-------------|------------------|----------------------|------------------|--------------------------|

**CLAIM SUBFOLDER DETAILS**

Insured: **TERRY LOH JUNRONG**, ID: S8319474Z, Tel: +6593260316, Email: sakuraki2k@gmail.com

Vehicle Reg. No.: **SLF7325T** Date of Loss: 26/10/2019 12:00 - :59  
[22 Months and 11 Days From LTA Reg Date (Man Yr)]

Claim Type: **OD / 1201900032377** Policy/Cover Note No.: PNCV2019-00000387 (Comprehensive)  
Coverage: 05/04/2019 - 04/04/2020

Excess: \$51,000.00

Repairer: **Progressive Car Care Pte Ltd (HQ)** Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336

Handling Insurer: **FWD Singapore Pte. Ltd. (HQ)** - Tel: 6727 5700 ... [Handled by **Eileen Bay**]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **MARCUS CHUA**] ... [Final Rpt due 08/11/2019]

Driver/Custodian: **TERRY LOH JUNRONG (36 / Male)**, NRIC: S8319474Z, Tel: +6593260316 Email: sakuraki2k@gmail.com

**ASSOCIATED MAIL RECEIVED**
[View All](#)
[Compose Case Mail](#)

- FWD\_SG (06/01/2020): Alert - Adj Mandate Approved (\$58944.00) - SLF7325T - Claim Handler: Eileen Bay
- FWD\_SG (06/01/2020): MANDATE REQUEST DIFFERS FROM ADJUSTER REPORT
- FWD\_SG (16/11/2019): Alert - Adj Mandate Approved (\$510241.00) - SLF7325T - Claim Handler: Eileen Bay
- FWD\_SG (15/11/2019): amount don't tally
- FWD\_SG (15/11/2019): Alert - Adj Mandate Maintained - SLF7325T - Claim Handler: Eileen Bay
- FWD\_SG (07/11/2019): Alert - Adj Mandate Approved (\$59495.00) - SLF7325T - Claim Handler: Eileen Bay
- FWD\_SG (31/10/2019): Alert - Adj Mandate Approved (\$57500.00) - SLF7325T - Claim Handler: Eileen Bay

**ALL ASSOCIATED TASKS**
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## Claim Documents

SLF7325T (1201900032377)

OD

Oct 26 2019 12:00PM

[TERRY LOH JUNRONG]

Progressive Car Care Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Video

1 per page

| No | Finalized On   | Progressive Car Care Pte Ltd (HQ)                      |  | Thumbnail | Print |
|----|----------------|--------------------------------------------------------|--|-----------|-------|
| 1  | 29/10/19 09:58 | Video - Accident<br>[Linked Accident Report Documents] |  | Load MP4  |       |
| 2  | 29/10/19 09:58 | Video - Accident<br>[Linked Accident Report Documents] |  | Load MP4  |       |
| 3  | 29/10/19 10:02 | Video - Accident<br>[Linked Accident Report Documents] |  | Load MP4  |       |
| 4  | 29/10/19 10:03 | Video - Accident<br>[Linked Accident Report Documents] |  | Load MP4  |       |

Assessment Reports

1 per page

| No | Finalized On   | Progressive Car Care Pte Ltd (HQ) |  | Thumbnail | Print |
|----|----------------|-----------------------------------|--|-----------|-------|
| 1  | 30/10/19 14:39 | Repairer Estimates                |  | Load HTM  |       |
| 2  | 07/11/19 10:03 | Repairer Estimates Suppl. #1      |  | Load HTM  |       |
| 3  | 08/11/19 17:05 | Repairer Estimates Suppl. #2      |  | Load HTM  |       |
| 4  | 15/11/19 12:12 | Repairer Estimates Suppl. #3      |  | Load HTM  |       |

| No | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) |  | Thumbnail | Print |
|----|----------------|-----------------------------------|--|-----------|-------|
| 1  | 31/10/19 15:00 | Adjuster Immediate Advice         |  | Load HTM  |       |
| 2  | 07/11/19 10:14 | Adjuster Immediate Advice         |  | Load HTM  |       |
| 3  | 15/11/19 13:57 | Adjuster Immediate Advice         |  | Load HTM  |       |
| 4  | 06/01/20 11:07 | Adjuster Immediate Advice         |  | Load HTM  |       |

Photos/Images

3 per page

| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |  | Thumbnail | Print |
|----|-----------------|-----------------------------------|--|-----------|-------|
| 1  | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 2  | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 3  | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 4  | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 5  | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 6  | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 7  | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 8  | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 9  | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 10 | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 11 | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 12 | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 13 | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 14 | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 15 | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 16 | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 17 | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 18 | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 19 | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 20 | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 21 | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 22 | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 23 | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 24 | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 25 | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 26 | 07/11/19 10:15  | General View                      |  | Load JPG  |       |
| 27 | 07/11/19 10:15  | General View                      |  | Load JPG  |       |

| Video |                |                                   | 1 per page                                                                            | <input checked="" type="checkbox"/> |
|-------|----------------|-----------------------------------|---------------------------------------------------------------------------------------|-------------------------------------|
| No    | Finalized On   | Progressive Car Care Pte Ltd (HQ) | Thumbnail                                                                             | Print                               |
|       |                |                                   |                                                                                       | <input checked="" type="checkbox"/> |
| 28    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 29    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 30    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 31    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 32    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 33    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 34    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 35    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 36    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 37    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 38    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 39    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 40    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 41    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 42    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 43    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 44    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 45    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 46    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 47    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 48    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 49    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 50    | 07/11/19 10:15 | General View                      |    | <input checked="" type="checkbox"/> |
| 51    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 52    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 53    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 54    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 55    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 56    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 57    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 58    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 59    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 60    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 61    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 62    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 63    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 64    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 65    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 66    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 67    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 68    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 69    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 70    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 71    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 72    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 73    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 74    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 75    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 76    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 77    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 78    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 79    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 80    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 81    | 07/11/19 10:15 | General View                      |  | <input checked="" type="checkbox"/> |
| 82    | 07/11/19 10:16 | Reinspection Photo                |  | <input checked="" type="checkbox"/> |

| Video |                |                                   | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|-------|----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No    | Finalized On   | Progressive Car Care Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 83    | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 84    | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 85    | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 86    | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 87    | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 88    | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 89    | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 90    | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 91    | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 92    | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 93    | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 94    | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 95    | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 96    | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 97    | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 98    | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 99    | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 100   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 101   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 102   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 103   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 104   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG  | <input checked="" type="checkbox"/> |
| 105   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 106   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 107   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 108   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 109   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 110   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 111   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 112   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 113   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 114   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 115   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 116   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 117   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 118   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 119   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 120   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 121   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 122   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 123   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 124   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 125   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 126   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 127   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 128   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 129   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 130   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 131   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 132   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 133   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 134   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 135   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 136   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 137   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 138   | 07/11/19 10:16 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |

| Video         |                 |                                    | 1 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|------------------------------------|------------|-------------------------------------|
| No            | Finalized On    | Progressive Car Care Pte Ltd (HQ)  | Thumbnail  | Print                               |
| 139           | 07/11/19 10:16  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 140           | 07/11/19 10:16  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 141           | 07/11/19 10:16  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 142           | 07/11/19 10:16  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 143           | 07/11/19 10:16  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 144           | 07/11/19 10:16  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 145           | 07/11/19 10:16  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 146           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 147           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 148           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 149           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 150           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 151           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 152           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 153           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 154           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 155           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 156           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 157           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 158           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 159           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 160           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 161           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 162           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 163           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 164           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 165           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 166           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 167           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 168           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 169           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 170           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 171           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 172           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 173           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 174           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 175           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 176           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 177           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 178           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 179           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 180           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 181           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 182           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| 183           | 06/01/20 11:00  | Reinspection Photo                 |            | <input checked="" type="checkbox"/> |
| Documentation |                 |                                    | 1 per page | <input checked="" type="checkbox"/> |
| No            | Finalized On    | Progressive Car Care Pte Ltd (HQ)  | Thumbnail  | Print                               |
| 1             | 30/10/19 14:39  | Claimant's NRIC & LIC              |            | <input checked="" type="checkbox"/> |
| 2             | 30/10/19 14:39  | Certificate of Insurance           |            | <input checked="" type="checkbox"/> |
| 3             | 30/10/19 14:39  | E-filed GIA report                 |            | <input checked="" type="checkbox"/> |
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)  | Thumbnail  | Print                               |
| 1             | 31/10/19 15:01  | ESTIMATE.pdf                       |            | <input checked="" type="checkbox"/> |
| 2             | 07/11/19 10:15  | SUPP.pdf                           |            | <input checked="" type="checkbox"/> |
| 3             | 15/11/19 13:40  | SUPPLEMENTARY 2 & 3                |            | <input checked="" type="checkbox"/> |
| 4             | 06/01/20 11:00  | ESTIMATE, SUPP 1, 2 & 3 MARKED.pdf |            | <input checked="" type="checkbox"/> |
| 5             | 06/01/20 15:24  | Parts Invoice                      |            | <input checked="" type="checkbox"/> |

## Linked Accident Report Documents

| View <span>View in Browser</span> |                |                                   |                                                                                                |
|-----------------------------------|----------------|-----------------------------------|------------------------------------------------------------------------------------------------|
| Video                             |                |                                   |                                                                                                |
| No                                | Finalized On   | Progressive Car Care Pte Ltd (HQ) | Thumbnail Print                                                                                |
| 1                                 | 29/10/19 09:58 | Video - Accident                  |  Load MP4   |
| 2                                 | 29/10/19 09:58 | Video - Accident                  |  Load MP4   |
| 3                                 | 29/10/19 10:02 | Video - Accident                  |  Load MP4   |
| 4                                 | 29/10/19 10:03 | Video - Accident                  |  Load MP4   |
| Assessment Reports                |                |                                   |                                                                                                |
| No                                | Finalized On   | Progressive Car Care Pte Ltd (HQ) | Thumbnail Print                                                                                |
| 1                                 | 29/10/19 10:06 | Addendum Sheet                    |  Load JPG   |
| 2                                 | 06/12/19 18:56 | Accident Statement                |  Load HTM   |
| 3                                 | 06/12/19 18:57 | Accident Statement                |  Load HTM   |
| 4                                 | 06/12/19 18:59 | Accident Statement                |  Load HTM   |
| 5                                 | 06/12/19 18:59 | Accident Statement                |  Load HTM   |
| 6                                 | 06/12/19 19:07 | Accident Statement                |  Load HTM   |
| 7                                 | 06/12/19 19:07 | Accident Statement                |  Load HTM   |
| 8                                 | 06/12/19 19:08 | Accident Statement                |  Load HTM   |
| 9                                 | 06/12/19 19:11 | Accident Statement                |  Load HTM   |
| Photos/Images                     |                |                                   |                                                                                                |
| No                                | Finalized On   | Progressive Car Care Pte Ltd (HQ) | Thumbnail Print                                                                                |
| 1                                 | 26/10/19 16:18 | Accident Photo                    |  Load JPG   |
| 2                                 | 26/10/19 16:18 | Accident Photo                    |  Load JPG   |
| 3                                 | 26/10/19 16:18 | Accident Photo                    |  Load JPG   |
| 4                                 | 26/10/19 16:18 | Accident Photo                    |  Load JPG   |
| 5                                 | 26/10/19 16:18 | Accident Photo                    |  Load JPG   |
| 6                                 | 26/10/19 16:18 | Accident Photo                    |  Load JPG  |
| 7                                 | 26/10/19 16:18 | Accident Photo                    |  Load JPG |
| 8                                 | 26/10/19 16:18 | Accident Photo                    |  Load JPG |
| Documentation                     |                |                                   |                                                                                                |
| No                                | Finalized On   | Progressive Car Care Pte Ltd (HQ) | Thumbnail Print                                                                                |
| 1                                 | 26/10/19 16:05 | Sketch Plan                       |  Load JPG |
| 2                                 | 26/10/19 16:05 | Sketch Plan #2                    |  Load JPG |

## Documents Checklist

| DOCUMENTS CHECKLIST                                                                                                                                                                  | Reset | Save | Print |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|------|-------|
| There are no document checklists configured.                                                                                                                                         |       |      |       |
| <div style="border: 1px solid black; height: 40px; margin-top: 10px;"></div>                                                                                                         |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>                                                                                                                     |       |      |       |
| <div style="border: 1px solid black; height: 100px; margin-top: 10px;"></div>                                                                                                        |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower 4  
Singapore 038986

Our File No: CS/FWD19019197/USF3E2

Date: 07/01/2020

### REFERENCE

Insured/Claimant: TERRY LOH JUNRONG Policy No: PNCV2019-00000387  
Date of Loss: 26/10/2019 Nature of Claim: OD Claim No: 1201900032377

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLF7325T  
Make & Model: KIA CERATO K3, 1.6 (A)  
Reg. Date: 15/12/2017 (Man. Year: 2017)  
Colour: Black  
Engine Capacity: 1591 cc  
Market Value/New Car Price: S\$63,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: G4FGHH687860  
Chassis No: KNAFZ411MJ5755581  
Odometer: 72118 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18  
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm  
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                      | Repairer's       | Adjuster's      | Difference       | Diff %       |
|-------------------------------------|------------------|-----------------|------------------|--------------|
| Parts                               | 9,559.00         | 6,709.00        | 2,850.00         | 29.81        |
| Miscellaneous Items                 | 85.00            | 65.00           | 20.00            | 23.53        |
| Labour                              | 1,390.00         | 1,190.00        | 200.00           | 14.39        |
| Paintwork Labour                    | 1,100.00         | 980.00          | 120.00           | 10.91        |
| Towing                              | 0.00             | 0.00            | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b> | <b>12,134.00</b> | <b>8,944.00</b> | <b>3,190.00</b>  | <b>26.29</b> |
| <b>- Excess (S\$)</b>               | <b>0.00</b>      | <b>1,000.00</b> | <b>-1,000.00</b> |              |
| <b>(S\$)</b>                        | <b>12,134.00</b> | <b>7,944.00</b> | <b>4,190.00</b>  | <b>34.53</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>       | <b>849.38</b>    | <b>556.08</b>   | <b>293.30</b>    | <b>34.53</b> |
| <b>Nett Amount (S\$)</b>            | <b>12,983.38</b> | <b>8,500.08</b> | <b>4,483.30</b>  | <b>34.53</b> |

### INSPECTION

Date of Assignment: 30/10/2019 Present Location: Progressive Car Care Pte Ltd (HQ)  
Date Inspected: 31/10/2019 Inspected At: Progressive Car Care Pte Ltd (HQ)  
Blk 3022A Ubi Road 1, #01-45/46  
Singapore 408716

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

|                      |                                                                                                                                                                              |                                                         |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 06 Jan 2020)           |
| <b>Parts:</b>        | 143                                                                                                                                                                          | KIA CERATO K3 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                       |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLF7325T)                                                                                                                                    |                                                         |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                         |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                         |

## Recommended Parts

| No. | Qty | Part No. | Particulars                              | Condition             | Repairer's | Amount      |
|-----|-----|----------|------------------------------------------|-----------------------|------------|-------------|
| 1   | 1   | NA       | *FRONT BUMPER                            | Distorted             | 310.00 F   | *310.00 F   |
| 2   | 10  | NA       | *FRONT BUMPER CLIPS                      | Not Necessary         | 30.00 F    | *- F        |
| 3   | 1   | NA       | *FRONT BUMPER SIDE HOLDER - LH           | Bent                  | 7.00 F     | *7.00 F     |
| 4   | 1   | NA       | *FRONT BUMPER SIDE HOLDER - RH           | Bent                  | 7.00 F     | *7.00 F     |
| 5   | 1   | NA       | *FRONT BUMPER FOAM                       | Torn                  | 45.00 F    | *45.00 F    |
| 6   | 1   | NA       | *FRONT BUMPER REINFORCEMENT W/BACKET     | Distorted             | 220.00 F   | *220.00 F   |
| 7   | 6   | NA       | *FRONT BUMPER SENSOR                     | Serviceable           | 510.00 F   | *- F        |
| 8   | 1   | NA       | *FRONT BUMPER UPPER GRILLE               | Deformed              | 165.00 F   | *165.00 F   |
| 9   | 1   | NA       | *FRONT BUMPER UPPER GRILLE CLIPS (10PCS) | Necessary (9Pcs Only) | 30.00 F    | *27.00 F    |
| 10  | 1   | NA       | *FRONT BUMPER LOWER GRILLE               | Twisted               | 35.00 F    | *35.00 F    |
| 11  | 10  | NA       | *FRONT BUMPER LOWER GRILLE CLIPS         | Not Necessary         | 30.00 F    | *- F        |
| 12  | 1   | NA       | *FRONT BUMPER LOWER SPOILER              | Not Necessary         | 35.00 F    | *- F        |
| 13  | 1   | NA       | *FRONT BUMPER LOGO (NPA)                 | No such part          | 0.00 F     | *- F        |
| 14  | 1   | NA       | *FRONT BUMPER TOW COVER                  |                       | 6.00 F     | *- F        |
| 15  | 1   | NA       | *BONNET                                  | Buckled               | 430.00 F   | *430.00 F   |
| 16  | 1   | NA       | *BONNET INSULATOR                        | Deformed              | 60.00 F    | *60.00 F    |
| 17  | 8   | NA       | *BONNET INSULATOR CLIPS                  | Necessary             | 24.00 F    | *24.00 F    |
| 18  | 1   | NA       | *BONNET HINGE - RH                       | Bent                  | 25.00 F    | *25.00 F    |
| 19  | 1   | NA       | *BONNET HINGE - LH                       | Bent                  | 25.00 F    | *25.00 F    |
| 20  | 1   | NA       | *BONNET LOCK                             | Twisted               | 40.00 F    | *40.00 F    |
| 21  | 1   | NA       | *BONNET CATCH                            | Not Such Part         | 28.00 F    | *- F        |
| 22  | 4   | NA       | *BONNET RUBBER STOPPER                   | Not Necessary         | 24.00 F    | *- F        |
| 23  | 1   | NA       | *FRONT FOGLAMP - RH                      | Cracked               | 190.00 F   | *220.00 F   |
| 24  | 1   | NA       | *FRONT FOGLAMP - LH                      | Serviceable           | 190.00 F   | *- F        |
| 25  | 1   | NA       | *FRONT FOGLAMP COVER - RH                | Not Necessary         | 20.00 F    | *- F        |
| 26  | 1   | NA       | *FRONT FOGLAMP COVER - LH                | Not Necessary         | 20.00 F    | *- F        |
| 27  | 1   | NA       | *FRONT FOGLAMP OUTER CHROME - RH (NPA)   | Not fitted            | 0.00 F     | *- F        |
| 28  | 1   | NA       | *FRONT FOGLAMP OUTER CHROME - LH (NPA)   | Not fitted            | 0.00 F     | *- F        |
| 29  | 1   | NA       | *HEADLAMP UNIT - RH                      | Cracked               | 1,150.00 F | *1,150.00 F |
| 30  | 1   | NA       | *HEADLAMP UNIT - LH                      | Holder Cracked        | 1,150.00 F | *1,150.00 F |
| 31  | 1   | NA       | *HEADLAMP LOWER RETAINER - RH            | Not Necessary         | 28.00 F    | *- F        |
| 32  | 1   | NA       | *HEADLAMP LOWER RETAINER - LH            | Not Necessary         | 28.00 F    | *- F        |
| 33  | 1   | NA       | *WIPER TANK                              | Not Necessary         | 65.00 F    | *- F        |
| 34  | 1   | NA       | *RADIATOR                                | Distorted             | 250.00 F   | *250.00 F   |
| 35  | 1   | NA       | *RADIATOR TOP HOSE                       | Serviceable           | 16.00 F    | *- F        |
| 36  | 1   | NA       | *RADIATOR LOWER HOSE                     | Torn                  | 18.00 F    | *18.00 F    |
| 37  | 1   | NA       | *RADIATOR SPARE TANK                     | Serviceable           | 70.00 F    | *- F        |

Report was unsubmitted during this print-out.

| No.                       | Qty | Part No. | Particulars                  | Condition     | Repairer's      | Amount          |
|---------------------------|-----|----------|------------------------------|---------------|-----------------|-----------------|
| 38                        | 1   | NA       | *AIR CLEANER BOX             | Not Necessary | 70.00 F         | *- F            |
| 39                        | 1   | NA       | *AIRDUCT                     | Not Necessary | 50.00 F         | *- F            |
| 40                        | 1   | NA       | *ENGINE INTAKE MANIFOLD      | Cracked       | 450.00 F        | *450.00 F       |
| 41                        | 1   | NA       | *ENGINE ALTERNATOR           | Not Necessary | 550.00 F        | *- F            |
| 42                        | 1   | NA       | *ENGINE THROTTLE BODY        | Serviceable   | 380.00 F        | *- F            |
| 43                        | 1   | NA       | *AIRCON SUCTION PIPE         | Bent          | 280.00 F        | *280.00 F       |
| 44                        | 1   | NA       | *AIRCON DISCHARGE PIPE       | Serviceable   | 65.00 F         | *- F            |
| 45                        | 1   | NA       | *AIRCON CONDENSER            | Distorted     | 770.00 F        | *345.00 F       |
| <b>Supplementary #1</b>   |     |          |                              |               |                 |                 |
| 46                        | 1   |          | *SUPPORT PANEL               | Distorted     | 300.00 F        | *300.00 F       |
| 47                        | 1   |          | *CONDENSER SIDE GARNISH - L  | Torn          | 15.00 F         | *15.00 F        |
| 48                        | 1   |          | *CONDENSER SIDE GARNISH - R  | Torn          | 15.00 F         | *15.00 F        |
| 49                        | 1   |          | *FRT BUMPER LOWER GARNISH    | Torn          | 65.00 F         | *65.00 F        |
| 50                        | 1   |          | *GRILLE INNER GARNISH        | Distorted     | 35.00 F         | *18.00 F        |
| 51                        | 1   |          | *GRILLE TOP GARNISH          | Distorted     | 28.00 F         | *28.00 F        |
| 52                        | 1   |          | *FRT NUMBER PLATE GARNISH    | Distorted     | 15.00 F         | *15.00 F        |
| 53                        | 1   |          | *RHF FENDER                  | Buckled       | 180.00 F        | *180.00 F       |
| 54                        | 1   |          | *AIRCON FUSE                 | Shorted       | 55.00 F         | *55.00 F        |
| 55                        | 1   |          | *AIRCON DISCHARGE PIPE ( B ) | Bent          | 125.00 F        | *125.00 F       |
| 56                        | 1   |          | *FOGLAMP ASSY - R            | Repeated      | 220.00 F        | *- F            |
| <b>Supplementary #2</b>   |     |          |                              |               |                 |                 |
| 57                        | 1   |          | *AIRCON FAN MOTOR ASSY       | Cracked       | 280.00 F        | *280.00 F       |
| <b>Supplementary #3</b>   |     |          |                              |               |                 |                 |
| 58                        | 1   |          | *FRONT BUMPER LOWER          | Torn          | 330.00 F        | *330.00 F       |
| F=Franchise part.         |     |          |                              |               |                 |                 |
| <b>Total Parts (\$\$)</b> |     |          |                              |               | <b>9,559.00</b> | <b>6,709.00</b> |

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

## Recommended Miscellaneous Items

| No                         | Qty | Particulars                                 | Repairer's | Amount |
|----------------------------|-----|---------------------------------------------|------------|--------|
| <u>Miscellaneous Items</u> |     |                                             |            |        |
| 1                          | 1   | COOLANT<br>(NECESSARY)                      | 50.00      | 30.00  |
| 2                          | 1   | FRONT NUMBER PLATE WITH CASING<br>(CRACKED) | 35.00      | 35.00  |
| Sub Total (S\$)            |     |                                             | 85.00      | 65.00  |

## Recommended Labour

| No                      | Particulars                                                                    | Lab.Type | Repairer's | Amount   |
|-------------------------|--------------------------------------------------------------------------------|----------|------------|----------|
| <u>Paintwork Labour</u> |                                                                                |          |            |          |
| 1                       | TO RESPRAY PAINT ON ACCIDENT PORTIONS                                          | New      | 1,100.00   | 980.00   |
| <u>Labour Items</u>     |                                                                                |          |            |          |
| 2                       | TO REMOVE; REALIGN; REPAIR; CUT/WELD; KNOCK OUT DENTS & REPLACE ACCIDENT PARTS | New      | 1,000.00   | 880.00   |
| 3                       | TO CHECK WIRING                                                                | New      | 20.00      | 20.00    |
| 4                       | TO REMOVE; REPLACE CONDENSER AND REFILL GAS                                    | New      | 100.00     | 100.00   |
| 5                       | TO REMOVE; REPLACE FRONT BUMPER SENSOR                                         | New      | 120.00     | 40.00    |
| <u>Supplementary #3</u> |                                                                                |          |            |          |
| <u>Labour Items</u>     |                                                                                |          |            |          |
| 6                       | TO RESPRAY PAINT ON FRT BUMPER LOWER                                           | New      | 150.00     | 150.00   |
| Gross Labour Cost (S\$) |                                                                                |          | 2,490.00   | 2,170.00 |

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

&lt; END OF ESTIMATES &gt;