



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION (TP)		Ref:	CS/SPF19019242/R1f3e2
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date:	06/12/2019
ATTN : FRANKIE THAY		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 234P	Veh. Inspected	SLN 820J
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/108	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	31/10/2019
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 3 1.5 AT	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0151144	Colour	BROWN
Odometer	37310 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/50 R16	FALKEN	6 mm
L/H Front Tyre	205/50 R16	FALKEN	6 mm
R/H Rear Tyre	205/50 R16	FALKEN	6 mm
L/H Rear Tyre	205/50 R16	FALKEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/10/2019	Inspection Date	31/10/2019
Survey held at	TRANS EUROKARS PTE LTD 27A TANJONG PENJURU SINGAPORE 609042		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		27 Working Days	