

Auto Dynamac Service Trading

Blk 3019A Ubi Road 1

#01-28

Singapore 408713

Phone Number: 6745 9702

Fax Number: 6748 9764

Customer:	Date:	31/10/2019 1:27 PM
Company:	VIN	
License NO:	Technician:	
Odometer:	Order NO:	

VEHICLE ALIGNMENT REPORT

NISSAN, SYLPHY (C11), 06-18 (Customized)

Primary Angles

		Initial	Specifications		Final
			Min.	Max.	
Front	Caster	---	4°00'	5°30'	---
			4°00'	5°30'	---
	Camber	-0°24'	-0°55'	0°35'	-0°24'
			-0°06'	0°35'	0°00'
	Toe	-0°29'	0°00'	0°05'	-0°29'
Rear		-2°52'	0°00'	0°05'	-2°52'
		-3°21'	0°00'	0°11'	-3°21'
	Camber	-1°24'	-2°01'	-1°01'	-1°24'
		-1°30'	-2°01'	-1°01'	-1°30'
	Toe	0°13'	-0°02'	0°17'	0°14'
Max Thrust Angle		0°14'	-0°02'	0°17'	0°16'
		0°27'	-0°05'	0°34'	0°30'
		0°00'	---	---	0°01'

Secondary Angles

	Initial	Specifications		Final
		Min.	Max.	
SAI	---	9°10'	10°40'	---
	---	9°10'	10°40'	---
Included Angle	---	---	---	---

