

22/02/2019

ASS. REC. BY:

REF:

CS/AGI19019277/Q&amp;P302

Special Instruction:

glynn@jxc.com.sg

Surveyor: Sun Pin

ASSIGNMENT (Office)

From (Person): Ivy Ratilla

of

AGI

Date/Time: 31/10/2019.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XD 8493C

Insured:

SIS 5334L

at Workshop m/s

JXC

Tel:

83832726

of

58 Sungai Kadut Loop

Policy No:

Claim No:

C10004447/LA

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

31/10

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction

13/11/2019 ( )

XD 8493C-X

SIS 5334L-X

ASS. REC. BY: Sun Pin

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: XD 8493C Yr Regn: 10/03/2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer orMake: ISUZU FXZ77M c.c. 9839Colour: White A/C: Insured / Std / NI / NASp. Reading: 432564 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JAIFXZZ77ME7000018Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or Steel RimTyre Size: F: 315/80 R22R: 315/80 R22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Delun.

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 30/10/2019D.O.I. 31/10/2019

Survey held at

JXCDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV:

RECEIVED 02 JAN 2020

Confirm with Glynn

Finalize \$1,400 @ 2 days (L/S). (\$2,365.40 red - 67%)

Date/Time, File Pass to?

02/01/20☐ : Prell. ReportDays Of Repair: 21) Typ 24☒ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

Survey Fee: 290

2)

Add Fee:

☐ : Site Insp (\$

Transportation:

☐ : Interview (\$

Photos

☐ : Tech. Invs (\$

Others

☐ : Weekend (\$

TOTAL

Rep. Forms:

Lump Sum / L.E.I. / \$1,400/- c/s290

## Nivitha (LKK Auto)

---

**From:** Ivy Ratilla <ivy.r@budgetdirect.com.sg>  
**Sent:** Thursday, 31 October 2019 11:26 AM  
**To:** Admin-D (LKKAuto)  
**Cc:** SUR; Loganathan Agoram  
**Subject:** FW: TPPD Survey: Claim ref:C10004447/LA || OI- SLS5334L (White) TP-XD8493C ||  
Est:0.00 || JXC

Hi Team,

We would like to arrange TP survey for XD8493C.

Workshop information:

JXC PTE LTD | Jia Xiu Contractors | Aquatemp PTE LTD

Mobile. +65 8383 2726

Phone. +65 6785 2726

Email. [glynn@jxc.com.sg](mailto:glynn@jxc.com.sg)

Website. [www.jxc.com.sg](http://www.jxc.com.sg) | [www.aquatemp.com](http://www.aquatemp.com)

Office Add. 61 Tuas Crescent S638737

Mailing Add. 123 Simei Street 1 #01-374 S520123

Thank you.

Regards,

**Ivy Ratilla**  
**Executive, Claims Admin**

T +65 6540 2185

F +65 6725 0853

E [ivy.r@budgetdirect.com.sg](mailto:ivy.r@budgetdirect.com.sg)



**Customer Care** +65 6221 2111

**Claims** +65 6221 2199

**Claims (Int.)** +65 6540 2199

190 Clemenceau Avenue, #03-01

Singapore Shopping Centre

Singapore

239924

[budgetdirect.com.sg](http://budgetdirect.com.sg)

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

**From:** Glynn Neo <[glynn@jxc.com.sg](mailto:glynn@jxc.com.sg)>

**Sent:** Wednesday, 30 October 2019 4:03 PM

**To:** Claims <[claims@budgetdirect.com.sg](mailto:claims@budgetdirect.com.sg)>


**Subject:** Requesting for surveyor for accident between SL55334L and XD8493C (VERY URGENT)

On the 30 October 2019, one of your client vehicle SL55334L had an accident with our truck XD8493C. We would like to request for a surveyor from your side so that we could proceed with a third party claim. We have done our insurance report.

Kindly assist us.

Thank you.

**Best Regards,**



Our Solution is Your Achievement



**GLYNN**

*Purchasing Director*

JXC PTE LTD | Jia Xiu Contractors | Aquatemp  
PTE LTD

**Mobile.** +65 8383 2726

**Phone.** +65 6785 2726

**Email.** [glynn@jxc.com.sg](mailto:glynn@jxc.com.sg)

**Website.** [www.jxc.com.sg](http://www.jxc.com.sg) |  
[www.aquatemp.com](http://www.aquatemp.com)

**Office Add.** 61 Tuas Crescent  
S638737

**Mailing Add.** 123 Simei Street 1  
#01-374 S520123

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the

stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Business  
Owner ID: 853X

### Vehicle Details

Vehicle No.: XD8493C  
Vehicle to be Exported: No  
Intended Deregistration Date: 11 Dec 2019  
Vehicle Make: ISUZU  
Vehicle Model: FXZ77M  
Primary Colour: White  
Manufacturing Year: 2013  
Engine No.: 6UZ1482010  
Chassis No.: JALFXZ77ME7000018

Maximum Power Output: -  
Open Market Value: \$80,640.00  
Original Registration Date: 10 Mar 2014  
First Registration Date: 10 Mar 2014  
Transfer Count: 2  
Actual ARF Paid: \$4,032.00

### Intended PARF Rebate Details

PARF Eligibility: No  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 09 Mar 2024  
COE Category: C - Goods Vehicle & Bus  
COE Period(Years): 10  
QP Paid: \$52,890.00  
COE Rebate Amount: \$22,439.00  
Total Rebate Amount: \$22,439.00

The information contained herein is correct as at 11 Dec 2019

OK

## Oi Sun Pin (LKK Auto)

---

**From:** Glynn Neo <glynn@jxc.com.sg>  
**Sent:** Thursday, 19 December, 2019 12:07 AM  
**To:** Oi Sun Pin (LKK Auto)  
**Subject:** Re: Finalize XD 8493C

Agree.

Regards,

Glynn Neo

+65 8383 2726

JXC Pte Ltd  
Jia Xiu Contractors  
Aquatemp Pte Ltd

[www.jxc.com.sg](http://www.jxc.com.sg)

On 18 Dec 2019, at 18:07, Oi Sun Pin (LKK Auto) <[sunpin@lkkauto.com](mailto:sunpin@lkkauto.com)> wrote:

Dear Glynn,

Kindly refer the finalize amount \$1,400. Repair day 2 days, (L/S Repair, before gst).  
Please reply if agree.

Thank you.

Best Regards,

**Oi Sun Pin** | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: [Sunpin@lkkauto.com](mailto:Sunpin@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<XD 8493C FINAL.pdf>

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	31/10/2019 12:22
Date Of Accident	30/10/2019 09:05
Exact Location Of Accident	PAYA LEBAR RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD8493C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	JIA XIU CONTRACTORS
Co Reg No	53311853X
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82608425
Alternative Phone No	OFFICE-82608425

### Vehicle Particulars

Manufacturer	ISUZU
Model	LORRY
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5087372517-02
Cover Note Number	

### Driver

Name of Driver	MUTHUVEL VELMURUGAN
Passport No/FIN	G7314159T
Date Of Birth	18/07/1975
Occupation	OUTDOOR
Date Of Driving Pass	13/03/2009
Driving Experience	10 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82608425
Fax Number	
Contact Number	
Email Address	NOEMAIL



Address —  
 Postcode  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 Vehicle -  
 Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLS5334L  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

IDAC BUKIT BATOK (VAC)

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 30/10/2019, when I was driving on Paya Lebar Road. I was moving very slowly at 2nd lane. Suddenly, I feel my vehicle right side was hit by the vehicle beside me. I immediately stop my vehicle and get down from my vehicle to check. I saw vehicle [SLS5334L] hit my lorry right side.

DECLARATION  
I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time: 11

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

IDAĆ BUKIT BATOK (NAC)  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



佳  
秀

# JIA XIU CONTRACTOR!

Simei St 1, BLOCK 123, #01-374  
TEL: 67852726 H/P: 83832726  
EMAIL: GLYNN@JXC.COM.SG

Date: 31 October 2019

M/S: LKK Auto Pte Ltd  
Blk 51, Ubi avenue 1, #01-25, Paya Ubi industrial Park  
Singapore 408933  
Email: sunpin@lkkauto.com

L/S = \$ 1,400

ITEMS	Quantity	Price
New Safe Guard Set / BT	1	\$2,865
Labour fee	1	\$500.00
Painting	1	\$400.00
Welding	1	\$500.00
Total		\$4265.40

1,200 N = 1,200  
350 L = 550  
200  
x  
1,750  
- 20%  
1,400

TOTAL AMOUNT PAYABLE TO JIA XIU CONTRACTORS

\$4,265.40

Above is the quotation for XD8493C parts and repair fees for your attention.  
For any questions, feel free to contact me @ 83832726.

Repair day - 2 days

L/S Repair.

After paint photo

Sun Pin (LKK)

TP without prejudice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

TORS

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO &amp; GENERAL INSURANCE (S) PL

Ref : CS/AGI19019277/Qsf3e2

(BUDGET DIRECT INSURANCE)  
190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRESINGAPORE  
239924

Date : 15-01-2020



Code : AGI

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SLS 5334L	Veh. Inspected	XD 8493C
Policy No.		Coverage (\$)	0.00
Claim No.	C10004447/LA	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	31/10/2019

**2. Vehicle Particulars & Condition**

Make & Model	ISUZU FXZ77M	c.c	9839
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JALFXZ77ME7000018	Colour	WHITE
Odometer	432564	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	315/80 R22	DELUN	5 mm
L/H Front Tyre	315/80 R22	DELUN	5 mm
R/H Rear Tyre	315/80 R22	DELUN	5 mm
L/H Rear Tyre	315/80 R22	DELUN	5 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

**5. General Information**

Accident Date	30/10/2019	Inspection Date	31/10/2019
Survey held at	58 SUNGEI KADUT LOOP		
Repairer	JXC PTE LTD		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 8493C**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<b><u>REPLACEMENT OF PARTS</u></b>	BENT		
	SET NEW SAFE GUARD (SN)		2,865.00	1,200.00
			2,865.00	1,200.00
	<b><u>LABOUR</u></b>	NOT NECESSARY		
	LABOUR FEE.		500.00	350.00
	PAINTING.		400.00	200.00
	WELDING.		500.00	-
			1,400.00	550.00
<b>GRAND TOTAL</b>			<b>4,265.00</b>	<b>1,750.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,400.00</b>

Report Ref No. CS/AGI19019277/Qsf3e2

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.