

ASS. REC. BY:

REF: CS3/SM019019282/Eqf3²

Special Instruction:

SURVEYOR: Steve

ASSIGNMENT (Office)

From (Person): Ruth chun hok Tiang of SMO Date/Time: 31.10.19 15.50p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YL 8312M Insured: GBC 2799B

at Workshop m/s Willy Motor Tel: 9276 7180

of 27A Jurong Port Road #01-32

Policy No: D19MTDCV6003243 Claim No: CM17405050

Sum Insured: Excess:

Make of Veh: D.O.A. 24.10.19
(Client's Record) 1.11.2019

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 31.10.19 4.46p.m Person Contacted: Ms Khoo Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	YL 8312M - X
	GBC 2799B - X
12/11/19	submit PRS.

Wuriman

APP. REC. BY: Steve REP: SMO

ASSIGNMENT

Mdn. Koo 92767180
From: Date: 1.11.2019

Veh No: YL 8312 M Yr Regn: 29/10/04

Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

To Inspect Vehicle No: YL 8312 m

Make: ISUZU NAR 70P C.C. 4751

at Workshop m/s Willy Motor of 27 A Jurong Post Road #01-32

Colour: Blue Sp. Reading: 506673 A/C: Insured / Std / NI / NA T/Radio: Insured / Std / NI / NA

Insured: Policy No. Claims No.

Eng/No: C/No: JAANIR 70P47101153

Sum Insured: Excess: (Client's Record)

Gen. Cond: Good / Fair / Poor / Burnt

Make of Veh: (Policy Condition)

Steering: In order / Jammed / Leaked / Burnt or

Remark: The veh had commenced its repair at the time of inspection.

Brake: In order / Jammed / Leaked / Burnt or

Bal. or Market Value: IDAC Accident Rpt: Consistent? : Yes or No

Modi: Nil / S/Rim / STD / Rim or

GIA / PR Seen: Consistent? : Yes or No

Tyre Size: F: 7.50R16 R: "

Est. Repairs: days Res.: Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or OHTSU

Lum Sum: % 3 Val.: Yes or No

Front Rear R/Bal. 4 mm R/Bal. 4 mm L/Bal. 4 mm L/Bal. 4 mm

CA / REV / REP. / 24 HRS mp¹

D.O.A. 24/10/19 D.O.I. 1/11/19

Date: Person Contacted: Vehicle: IN / OUT

Survey held at Willy Motor

The UIC / Chassis frame / Body Structure affected due to collision.

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Date / Time Action / Instruction

Repair work - (SK - GK) 7 days

Signature: 5/11/2019

RECEIVED 12 NOV 2019

Date/Time, File Pass to? : Preli. Report : Final Report

Days Of Repair: Resurvey No. of Trip:

Table with columns for Survey Fee, Transportation, Photos, Other, TOTAL

Date/Time, File Return to? 1) Willy Motor 2) Report Format: PPS. Lump Sum / EEJ: C

Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend C

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Oct 2019		31 Oct 2019 15:50 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	PDS INTERNATIONAL PTE LTD , Co. Reg. No.: 199302758Z			
Main Claimant:	ANG POH WEE , ID: S7137853E			
Vehicle Reg. No.:	YL8312M	Date of Loss:	24/10/2019 15:00 - :59	
Claim Type:	TP / CMTD1905050	Policy/Cover Note No.:	D19MTPCVE003243 (Comprehensive)	
Vehicle Reg. No. (Insured):	GBC2799B	Policy No. (Claimant):		
		Excess:		
Repairer:	Willy Motor Company (HQ) 27A JURONG PORT ROAD, #01-32, 619101 Jurong Island - Tel:			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/11/2019]			
Driver/Custodian (Insured):	HU WEISAI (), NRIC: G3460424Q, Tel: +6593152314 Email: -			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/10/2019 09:46
Date Of Accident	24/10/2019 15:25
Exact Location Of Accident	JUNCTION OF NEW BRIDGE RD & EU TONG SEN ST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YL8312M
Insured/Policyholder	
Name Of Registered Owner	JJ-SINGAPORE SALES & MARKETING PTE LTD
Co Reg No	199900178G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68977469

Vehicle Particulars

Manufacturer	ISUZU
Model	NQR70P-4.8 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	SD18V11231
Cover Note Number	

Driver

Name of Driver	ANG POH WEE
NRIC No	S7137853E
Date Of Birth	20/10/1971
Occupation	OUTDOOR
Date Of Driving Pass	21/08/1995
Driving Experience	24 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97436570
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 451A BUKIT BATOK WEST AVE 6 #20-711
Postcode	651451
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ONG LYE TUA GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 24/10/2019 AT ABOUT 1525 HRS. WHILE I WAS TRAVELLING STRAIGHT ALONG KAMPONG BHARU RD . TRAFFIC LIGHT IS ON MY FAVOR GOING STRAIGHT TOWARDS EU TONG SEN ST. WHEN I PASS THE JUNCTION , VEHICLE B FROM NEW BRIDGE RD TURNING TO HOSPITAL DR DIDNT GIVE WAY TO MY VEHICLE . MY VEHICLE HAD COLLIDED WITH VEHICLE B . NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC2799B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	HU WEISAI
NRIC/Passport Number	G3460424Q
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A **14 DAYS TIMEFRAME** FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	178G
Vehicle Details	
Vehicle No.:	YL8312M
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Nov 2019
Vehicle Make:	ISUZU
Vehicle Model:	NQR70P
Primary Colour:	Blue
Manufacturing Year:	2004
Engine No.:	4HE1106494
Chassis No.:	JAAN1R70P47101153
Maximum Power Output:	-
Open Market Value:	\$38,279.00
Original Registration Date:	29 Oct 2004
First Registration Date:	29 Oct 2004
Transfer Count:	0
Actual ARF Paid:	\$1,914.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$42,932.00
COE Rebate Amount:	\$20,738.00
Total Rebate Amount:	\$20,738.00

The information contained herein is correct as at 01 Nov 2019

OK

Google Pixel 4

Meet the new Pixel 4, built around the helpful Google software you k

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

MINI John Cooper Works 3 Door 2.0A,



Rare And Well Maintained JCW With JCW Pro Body Kit, Call To Arrange For A Drive. Direct Owner - StarAd

Think One Automobile

NEW & USED COMMERCIAL VEHICLES

Browse by Category ▾

Sort by Date Posted ▾ 20 results/page ▾

2 vehicles

ISUZU NQR

Advanced Search 🔍

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	ISUZU NQR	Any	Any	Any	Any	Any	Any	Available
	Isuzu NQR75U Fuel Type: Diesel Isuzu NQR75 17ft With Hood 07/2017 Selling Cheap! \$56800 Only! 100% In House Loan Available Call Now To Get This Opportunity Should Not Be Missed!	\$56,800	\$7,420 /yr	04-Jul-2017	5,193 cc	-	Truck	Available
Think One Automobile & Trading Posted: 30-Oct-2019 Tags: 2017 Isuzu NQR75U, 2017 isuzu nqr75u, Isuzu NQR75U, isuzu nqr75u, Isuzu, NQR75U, nqr75u, Used Isuzu								
	Isuzu NQR75U Fuel Type: Diesel New Arrive 08/11 ISUZU NQR75 Box With Tailgate, Can Carry 5 Ton, New Paintwork, All Wear & Tear Replace, TipTop Condition, Well Maintained By Previous Owner, Best Recommend For Mover Or Logistic, High Loan & High Trade In Available! Come And View It!	\$31,800	\$17,690 /yr	25-Aug-2011	5,193 cc	-	Truck	Available
ABWIN (1994) Pte Ltd Posted: 13-Sep-2019 Tags: 2011 Isuzu NQR75U, 2011 isuzu nqr75u, Isuzu NQR75U, isuzu nqr75u, Isuzu, NQR75U, nqr75u, Used Isuzu								

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view [Expired ads](#)

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used ISUZU NQR, ISUZU NQR Singapore, used ISUZU NQR Singapore, used ISUZU NQR, used vehicles Singapore or even buy used ISUZU NQR Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement
©2004-2019 sgCarMart. All rights reserved.

Compare

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Oct 2019		31 Oct 2019 15:50 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	PDS INTERNATIONAL PTE LTD, Co. Reg. No.: 199302758Z		
Main Claimant:	ANG POH WEE, ID: S7137853E		
Vehicle Reg. No.:	YL8312M	Date of Loss:	24/10/2019 15:00 - :59 [179 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1905050	Policy/Cover Note No.:	D19MTPCVE003243 (Comprehensive)
Vehicle Reg. No. (Insured):	GBC2799B	Policy No. (Claimant):	
		Excess:	
Repairer:	Willy Motor Company (HQ) 27A JURONG PORT ROAD, #01-32, 619101 Jurong Island - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 11/11/2019]		
Driver/Custodian (Insured):	HU WEISAI (), NRIC: G3460424Q, Tel: +6593152314 Email:		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***YL8312M (CMTD1905050)**
[GBC2799B]
TP
ANG POH WEE
Oct 24 2019 3:00PM
[PDS INTERNATIONAL PTE LTD]
Willy Motor Company

View

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
2	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
3	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
4	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
5	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
6	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
7	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
8	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
9	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
10	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
11	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
12	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
13	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
14	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
15	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
16	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
17	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
18	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
19	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
20	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
21	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
22	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
23	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
24	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
25	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
26	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
27	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
28	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
29	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
30	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
31	06/11/19 18:26	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	30/10/19 12:37	TP - YL8312M (TP/LIBERTY) Accident Report	Load PDF	
2	31/10/19 13:38	Letter from TP	Load PDF	
3	31/10/19 13:39	PRI - ACK	Load HTM	
4	31/10/19 15:44	2nd Letter from Law Firm (No consensus)	Load PDF	
5	31/10/19 15:50	PRI - LKK	Load HTM	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19019282/EQF3S2
Date: 18/11/2019

REFERENCE

Handling Insurer: Sompoo Insurance Singapore Pte. Ltd. Policy No: D19MTPCVE003243
Claimant Vehicle No : YL8312M **Insured Vehicle No :** GBC2799B
 Date of Loss: 24/10/2019 Nature of Claim: TP Claim No: CMTD1905050

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YL8312M**
 Make & Model: ISUZU NQR70P, 4.8 D (M) Engine No: 4HE1106494
 Reg. Date: 29/10/2004 (Man. Year: 2004) Chassis No: JAAN1R70P47101153
 Colour: White Odometer: 506673 km
 Engine Capacity: 4751 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 7.50 R16 Rear Tyre Size: 7.50 R16
 Front Left Side: OHTSU 4 mm Rear Left Side: OHTSU 4 mm
 Front Right Side: OHTSU 4 mm Rear Right Side: OHTSU 4 mm

The above values represent the remaining tyre treads depth

<u>COST OF CLAIMS</u>	<u>Repairer's</u>	<u>Adjuster's</u>	<u>Difference</u>	<u>Diff %</u>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 31/10/2019
 Date Inspected: 01/11/2019 Inspected At: Willy Motor Company (HQ)
 27A JURONG PORT ROAD, #01-32
 Singapore 619101
 Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Nov 2019)	
Parts:	N/A	ISUZU NQR70P 4.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YL8312M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >