

ASS. REC. BY:

REF: CS/CT119019284/Hcf302

Special Instruction:

Surveyor: Hock AnnASSIGNMENT (Office)From (Person): Chong Boon Sen of CT1 Date/Time: 31/10/19

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMG 9280H Insured: STU 5208Gat Workshop m/s Teamwork Garage Tel: 6844 2475of 53 Ubi Ave 1 #01-24Policy No: DMPCEN301F311901 Claim No: SNM19D 205102

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 29/10/19  
(Client's Record)CA / REV / REP. / REV 24 HRS Wp1

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>Johnnie (X)</u>
	<u>SMG 9280H X</u>
	<u>STU 5208G X</u>
	<u>Disassemble: 1/11/2019</u>
	<u>After repair: 5/11/2019</u>

ASS. REC. BY:

H-ANN

REF:

CT2

## ASSIGNMENT

From:

Date:

31.10.2019

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMG 92804

at Workshop m/s Teamwork Garage

of Blk 536bi Ave 1 # 01-24

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

my

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SMG 9280H

Yr Regn:

4/01/19

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia CERATO 1.6 (A)

C.C

1591

Colour:

B/K

A/C:

Insured / Std / NI / NA

Sp. Reading:

99281

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KNAF1416MK 5021850

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65/R15

R:

195/65/R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8 - NEXEN mm

Rear

R/Bal.

8 - NEXEN mm

L/Bal.

8 mm

L/Bal.

8 mm

D.O.A.

29/10/19

D.O.I.

31/10/19

Survey held at

Teamwork

Des. of Damages: Frt / ☒ Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Page 5-7/K

MV - 70000

PV - 30020

NV - 39000

\* SMG 9280H

4 workshop Exchng → (PRS) case

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

150

Transportation:

S + RS. \$

Photos

Others

TOTAL

150

Rep. Format: PRS.

Lump Sum / U/C /

## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Thursday, 31 October 2019 3:32 PM  
**To:** Jeffrey Tay; claims@teamworkgarage.com  
**Cc:** assignments  
**Subject:** RE: OUR REF: SNM19D205102-SJU5208G-CBS-: YOUR REF : 1910-42 // OUR REF : SJU5208G ACCIDENT INVOLVING SJU5208G AND SMG9280H

### WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

### Chong Boon Sen

Claims Executive  
Department

#### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Claims Dept of CTI  
**Sent:** Wednesday, October 30, 2019 5:11 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>; claims@teamworkgarage.com  
**Subject:** OUR REF: SNM19D205102-SJU5208G-CBS-: YOUR REF : 1910-42 // OUR REF : SJU5208G ACCIDENT INVOLVING SJU5208G AND SMG9280H

Dear Boon Sen,

Please conduct PRS for SMG9280H.

Note : officer in charge – Boon Sen 63896171.

Regards,

Claims Department

#### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Nov 2019		23 Dec 2019 10:39 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	<b>THRIVENI D/O CHNDRAGASAN, ID: S8315467E</b>
Vehicle Reg. No.:	<b>SMG9280H</b>
Date of Loss:	29/10/2019 05:00 - :59
Claim Type:	<b>TP / SNM19D205102-SJU5208G-CBS</b>
Policy/Cover Note No.:	DMPCSN3017311901 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>SJU5208G</b>
Policy No. (Claimant):	1900000294
Excess:	S\$0.00
Repairer:	<b>Teamwork Garage Pte Ltd (HQ)</b> 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]
Claimant's Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> - Tel: 65-6419-3000
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>LEE HOCK ANN</b> ] ... <b>[Final Rpt due 03/01/2020]</b>

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

T: (65) 63896116 | F: (65) 62247175

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](http://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** TEAMWORK [<mailto:claims@teamworkgarage.com>]

**Sent:** Wednesday, 30 October, 2019 4:26 PM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Cc:** TEAMWORK <[claims@teamworkgarage.com](mailto:claims@teamworkgarage.com)>

**Subject:** OUR REF : 1910-42 // YOUR REF : SJU5208G ACCIDENT INVOLVING SJU5208G AND SMG9280H

WITHOUT PREJUDICE

OUR REF : 1910-42

YOUR REF : SJU5208G

Dear Sir / Madam,  
PRE-REPAIR INSPECTION FOR SMG9280H  
ACCIDENT INVOLVING SJU5208G AND SMG9280H ON 29.10.2019.

We refer to the above matter and enclosed herewith our client's GIA report and notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction-Amendment No. 1 of 2016 of Pre-repair Inspection for your attention.

Thank you and have a nice day.

Regards,

*Shu Shan*

Teamwork Garage Pte Ltd  
Blk 53 Ubi Avenue 1  
#01-24  
Paya Ubi Industrial Park  
Singapore 408934  
Tel: 6844 2475  
Fax: 6844 2474

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	467E
Vehicle Details	
Vehicle No.:	SMG9280H
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Oct 2019
Vehicle Make:	KIA
Vehicle Model:	CERATO 1.6(A) LX
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	G4FGJH711673
Chassis No.:	KNAF1416MK5021850
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$11,196.00
Original Registration Date:	04 Jan 2019
First Registration Date:	04 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$11,196.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Jan 2029
PARF Rebate Amount:	\$8,397.00
Intended COE Rebate Details	
COE Expiry Date:	03 Jan 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$23,568.00
COE Rebate Amount:	\$21,623.00
<b>Total Rebate Amount:</b>	<b>\$30,020.00</b>

The information contained herein is correct as at 31 Oct 2019

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Re



Kia Min Price to No Max Depreciation Vehicle Type Category

Home » New Cars » New Car Brands » Kia » Kia Cerato

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Featured Merchants



## Related Articles



Kia organises the largest car collection event



Kia launches Cerato K3 Sports and new Carens



How does VES affect your car-buying decision?



Compare

## Kia Cerato

Overview

Pricing

Photos

Research

Reviews

Specs

Features

Similar

Accessories

Prom

Add to Shortlist

Submit a Review

Report Error

Share



USER RATINGS: (22 reviews)

## Details

Distributor Cycle & Carriage Kia

Hotline 66648111 / 67455000

Built in Korea (launched 2018)

Predecessor Kia Cerato K3 (2013-2018)

Pricelist 26-Oct Pricelist Select Another Date

Promotion From \$77,999. Enjoy \$7,000 COE cash subsidy.

» View all other promotions

Download Brochure

Add to Shortlist

Submodel	Price	Depreciation	Fuel Economy	Power	Transmission	Detailed
1.6 EX (A)	\$82,999 ▼	\$7,600 /yr	15.1km/L	126bhp	6-speed (A)	Specs   Fe
1.6 L (A)	\$82,999 ▲	\$7,700 /yr	15.1km/L	126bhp	6-speed (A)	Specs   Fe
1.6 GT Line (A)	\$96,999 ▲	-	15.1km/L	126bhp	6-speed (A)	Specs   Fe

Price updated 26-Oct-2019

## Photos &amp; Review



+ View All 13 Kia Cerato P

## Car Review - Kia Cerato 1.6 SX (A)

31 Aug 2018 | Kia Reviews

Well-equipped, spacious and practical, the third generation Kia Cerato is an appealing and affordable compact family sedan that is sure to attract car buyers.

## Comparison Tests:

Kia Cerato 1.6 GT Line vs Seat Toledo 1.4 TSI DSG Style

## CONSUMER REVIEWS

## Kia Cerato GT line

Test drove the car recently. The looks of the car interior and exterior as well as the features was better than expected!

Read More »



## PROS

- Eye-catching looks
- Generous equipment in the cabin
- Large 502-litre boot
- Cabin is quite spacious
- Good value for your money



## CONS

- Engine lacks power
- Not particularly interesting to drive



VS



## Excellent value for money for a normal d...

Finally collected my GT Line model after a 6-month wait. To me it was alright and in fact perfectly great timing as I started looking new replacement car to my Honda Accord since Feb 2019. Placed order in end March and the car arrived end Sep just nice when I

Read More »

Submit a review

Receive 3 MCF points when you submit a review

+ View All 22 Consumer Revi

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/10/2019 15:43
Date Of Accident	29/10/2019 05:30
Exact Location Of Accident	BUKIT BATOK BLK 442 MSCP
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMG9280H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	THRIVENI D/O CHNDRAGASAN
NRIC No	S8315467E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90618251
Alternative Phone No	OTHERS-91011049

### Vehicle Particulars

Manufacturer	KIA
Model	K3
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900000294
Cover Note Number	

### Driver

Name of Driver	MAGENTHIRAN RAJENI S/O SUNDAM
NRIC No	S7903782F
Date Of Birth	17/01/1979
Occupation	INDOOR
Date Of Driving Pass	29/08/2005
Driving Experience	14 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91011049
Fax Number	
Contact Number	
EEmail Address	NOEMAIL



Address	BLK 442B BUKIT BATOK WEST AVENUE 8 #11-849
Postcode	652442
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORD BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REQUEST FROM OWNER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJU5208G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE:

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

30/10/19.

## Sketch Plan #2

### SKETCH PLAN



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was parked along Bukit batok blk 442 Multi-Story carpark, when I got back to my car I saw a note stating that Vehicle B had collide onto my car and ask me to claim his insurance. Therefore I check my vehicle for the damaged portion and saw that my front right and my rear was damaged during the accident.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.  
Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

30/10/19.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

#### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Nov 2019		23 Dec 2019 10:39 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

#### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	THRIVENI D/O CHNDRAGASAN, ID: S8315467E		
Vehicle Reg. No.:	SMG9280H	Date of Loss:	29/10/2019 05:00 - :59 [9 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D205102-SJU5208G-CBS	Policy/Cover Note No.:	DMPCSN3017311901 (Comprehensive)
Vehicle Reg. No. (Insured):	SJU5208G	Policy No. (Claimant):	1900000294
		Excess:	S\$0.00
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 03/01/2020]		

#### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS





































[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)























































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

























































## Claim Documents

**\*SMG9280H (SNM19D205102-SJU5208G-CBS)**  
**[SJU5208G]**
















































**TP**  
**THRIVENI D/O CHNDRAGASAN**  
**Oct 29 2019 5:00AM**  
**[-]**  
**Teamwork Garage Pte Ltd**

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/>	
<b>Photos/Images</b>				3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print
1	30/10/19 15:49	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	30/10/19 15:49	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	30/10/19 15:49	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	30/10/19 15:49	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	30/10/19 15:49	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	30/10/19 15:49	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
2	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
3	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
4	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
5	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
6	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
7	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
8	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
9	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
10	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
11	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
12	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
13	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
14	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
15	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
16	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
17	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
18	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
19	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
20	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
21	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
22	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
23	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
24	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
25	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
26	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
27	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
28	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
29	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
30	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
31	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
32	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
33	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
34	24/12/19 13:13	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
35	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
36	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
37	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
38	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
39	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
40	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
41	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
42	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
43	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
44	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
45	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
46	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
47	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
48	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
49	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
50	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
51	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
52	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
53	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
54	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
55	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
56	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
57	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
58	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
59	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
60	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
61	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
62	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
63	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
64	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
65	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
66	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
67	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
68	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
69	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
70	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
71	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
72	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
73	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
74	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
75	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
76	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
77	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
78	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
79	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
80	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
81	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
82	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
83	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
84	24/12/19 13:13	General View	 Load JPG	<input checked="" type="checkbox"/>
85	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	24/12/19 13:15	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
90	24/12/19 13:15	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
91	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
130	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
131	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
132	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
133	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
134	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
135	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
136	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
137	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
138	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
139	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
140	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
141	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
142	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
143	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
144	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
145	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
146	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
147	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
148	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
149	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
150	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
151	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
152	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
153	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
154	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
155	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
156	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
157	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
158	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
159	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
160	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
161	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
162	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
163	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
164	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
165	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
166	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
167	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
168	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
169	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
170	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
171	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
172	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
173	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
174	24/12/19 13:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
175	24/12/19 15:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
176	24/12/19 15:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
177	24/12/19 15:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
178	24/12/19 15:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
179	24/12/19 15:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
180	24/12/19 15:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
181	24/12/19 15:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
182	24/12/19 15:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
183	24/12/19 15:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
184	24/12/19 15:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
185	24/12/19 15:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
186	24/12/19 15:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
187	24/12/19 15:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
188	24/12/19 15:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
189	24/12/19 15:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
190	24/12/19 15:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
191	24/12/19 15:32	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	30/10/19 15:51	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	30/10/19 15:51	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

View



Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print
1	06/12/19 19:10	Accident Statement		Load HTM	
2	06/12/19 19:12	Accident Statement		Load HTM	
3	06/12/19 19:12	Accident Statement		Load HTM	
4	06/12/19 19:16	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print
1	30/10/19 15:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	30/10/19 15:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	30/10/19 15:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	30/10/19 15:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	30/10/19 15:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	30/10/19 15:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print
1	30/10/19 15:51	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	30/10/19 15:51	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19019284/HCF3E2

Date: 26/12/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3017311901		
Claimant Vehicle No :	SMG9280H	Insured Vehicle No :	SJU5208G		
Date of Loss:	29/10/2019	Nature of Claim:	TP	Claim No:	SNM19D205102-SJU5208G-CBS

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SMG9280H		Engine No:	G4FGJH711673	
Make & Model:	KIA CERATO, 1.6 LX (A)		Chassis No:	KNAF1416MK5021850	
Reg. Date:	04/01/2019 (Man. Year: 2018)		Odometer:	9928 km	
Colour:	Black				
Engine Capacity:	1591 cc				
Market Value/New Car Price:	N/A				
Sum Insured (S\$):	Market Value/New Car Price				

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 8 mm	Rear Left Side:	Nexen 8 mm
Front Right Side:	Nexen 8 mm	Rear Right Side:	Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	23/12/2019	
Date Inspected:	31/10/2019 Inspected At:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	6.0 days	

Adjuster: LEE HOCK ANN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$7,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 26 Dec 2019)
<b>Parts:</b>	143	KIA CERATO 1.6 LX (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMG9280H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >