

(08/11/15)

Surveyor: Kalvin

REF:

NS/IN(19019305/E19f302

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Insp'd Vehicle No: _____

at Workshop m/s _____

of _____

Insured: FBC 1622JPolicy No. 5086493606-02 (03/12/2018-02/12/2019)Claims No. MT/1069249-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 8302R Yr Regn: 6 Aug 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 2.0 C.C. 1.685Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 518524 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLD414M.44075666

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wentik

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 29/10/19 D.O.I. 31/10/19Survey held at C DHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear/s

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|--|
| 1/11/19 | <u>Chd 4/5 \$1200 / 2 Rys. (Rep \$3073.52, 75%)</u> <u>Inc</u> |
| | <u>SHC 8302R - NS/IN(10014078/DG1)</u> <u>D.O.A - 15/07/2010</u> <u>4.</u> |
| | <u>PBC 1622J - x</u> |
| | |
| | |
| | |
| | |
| | |
| | |

RECEIVED 05 NOV 2019

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 21) 05/11/19 Inc☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee: 160

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

Transportation: _____

☐ : Interview (\$ _____)

S + RS _____ SI

Photos _____

Report Format

TOTAL

160

TP Claims against NTUC Income: Follow-Through Survey

Date : 04/11/2019

| S/No | Income Reference | Claimant (Owner / Taxi Company) | Claimant Vehicle No. | Income Vehicle No. | Date of Accident | Time of Accident | Estimate |
|------|-----------------------|-----------------------------------|----------------------|--------------------|------------------|------------------|-------------|
| 1 | MT/1069342-002 | COMFORTDELGRO ENGINEERING PTE LTD | SHD 7007U | SJX 6988R | 30/10/2019 | 19:25 | \$ 3,665.28 |
| 2 | MT/1069249-002 | COMFORTDELGRO ENGINEERING PTE LTD | SHC 8302R | FBC 1622J | 29/10/2019 | 19:10 | \$ 4,223.52 |

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

| | | | |
|---------------------------------------|---------------------------------------|--------------------|---|
| Policy No. | <input type="text"/> | Date of Accident | <input type="text" value="29/11/2019 09:10"/> |
| Vehicle No.(For Motor) | <input type="text" value="FBC1622J"/> | Certificate Number | <input type="text"/> |
| <input type="button" value="Search"/> | | | |

| Select | Policy No. | Certificate Number | Policyholder Name | Policyholder NRIC | Product | Cover Type | Vehicle No. | Insured Object | Commence Date | Expiry Date |
|----------------------------------|---------------|--------------------|-------------------|-------------------|---------|-------------|-------------|----------------|---------------|-------------|
| <input checked="" type="radio"/> | 5086493606-02 | | LIM ZHEE WEI | S9006329D | GMC | Third Party | FBC1622J | FBC1622J | 03/12/2018 | 02/12/2019 |

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|---|
| Date Of Report | 30/10/2019 16:24 |
| Date Of Accident | 29/10/2019 19:10 |
| Exact Location Of Accident | ALONG PIE TOWARDS CHANGI AFTER EXIT 9 JLN EUNOS |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|--------------------------------|
| Vehicle Registration Number | SHC8302R |
| Insured/Policyholder | |
| Name Of Registered Owner | COMFORT TRANSPORTATION PTE LTD |
| Co Reg No | 199303821R |
| Email Address | FLEETSAFETY@CDGTAXI.COM.SG |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-65508768 |

Vehicle Particulars

| | |
|--|-------------|
| Manufacturer | HYUNDAI |
| Model | I40 |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | TAXI |

Insurance Company

| | |
|---------------------------|---------------------------------------|
| Name of Insurance Company | INDIA INTERNATIONAL INSURANCE PTE LTD |
| Type Of Coverage | THIRD PARTY FIRE AND/OR THEFT |
| Fleet Policy | YES |
| Policy Number | MCOM0015 |
| Cover Note Number | |

Driver

| | |
|----------------------|------------------------|
| Name of Driver | TAN TUAN POH |
| NRIC No | S1314913E |
| Date Of Birth | 18/09/1958 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 08/04/1980 |
| Driving Experience | 39 YEARS AND 6 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-96288220 |
| Fax Number | |
| Contact Number | |
| EMAIL Address | TUANPOH@SINGNET.COM.SG |

| | |
|---|---------------------------------------|
| Address | BLK 724 BEDOK RESERVOIR ROAD #10-5222 |
| Postcode | 470724 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OTHER - TAXI DRIVER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|------------|
| Type Of Accident | SIDE SWIPE |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----------------------------|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | YES |
| Was any injured conveyed to hospital by ambulance? | YES |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 2 |
| Passenger 1 | NAME: : - GENDER: : MALE |

Details of Police Action

| | |
|---|-------------------|
| Was the accident reported to the police? | YES |
| If Yes, Please state which Police Station | |
| POLICE STATION NAME [OTHER] | BEDOK NORTH N.P.C |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

PLS REFER TO ATTACHED / POLICE REPORT : T/20191029/2164

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|--|
| Vehicle Registration Number | FBC1622J |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | MOTORCYCLE |
| Name of Driver | LIM ZHI WEI |
| NRIC/Passport Number | 0053326 |
| Contact Number | 90053326 |
| Address | |
| Postcode | |
| Insurance Company Name | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Nature Of Damage | RIGHT FRT |

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

| | |
|---|-------------|
| Name | LIM ZHI WEI |
| Approximate Age | |
| Injuries Sustain | NOT SURE |
| Injured person in which vehicle? | FBC1622J |
| Were seat belts worn? | |
| Was this injured conveyed to hospital by ambulance? | YES |
| Address | |
| Postcode | |

DETAILS OF INJURED PERSON 2

| | |
|---|----------|
| Name | PILLION |
| Approximate Age | |
| Injuries Sustain | NOT SURE |
| Injured person in which vehicle? | FBC1622J |
| Were seat belts worn? | |
| Was this injured conveyed to hospital by ambulance? | YES |
| Address | |
| Postcode | |

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
1475, 1476, 1477, 1478, 1479, 1480, 1481, 1482, 1483, 1484, 1485, 1486, 1487, 1488, 1489, 1490, 1491, 1492, 1493, 1494, 1495, 1496, 1497, 1498, 1499, 1500, 1501, 1502, 1503, 1504, 1505, 1506, 1507, 1508, 1509, 1510, 1511, 1512, 1513, 1514, 1515, 1516, 1517, 1518, 1519, 1520, 1521, 1522, 1523, 1524, 1525, 1526, 1527, 1528, 1529, 1530, 1531, 1532, 1533, 1534, 1535, 1536, 1537, 1538, 1539, 1540, 1541, 1542, 1543, 1544, 1545, 1546, 1547, 1548, 1549, 1550, 1551, 1552, 1553, 1554, 1555, 1556, 1557, 1558, 1559, 1560, 1561, 1562, 1563, 1564, 1565, 1566, 1567, 1568, 1569, 1570, 1571, 1572, 1573, 1574, 1575, 1576, 1577, 1578, 1579, 1580, 1581, 1582, 1583, 1584, 1585, 1586, 1587, 1588, 1589, 1590, 1591, 1592, 1593, 1594, 1595, 1596, 1597, 1598, 1599, 1600, 1601, 1602, 1603, 1604, 1605, 1606, 1607, 1608, 1609, 1610, 1611, 1612, 1613, 1614, 1615, 1616, 1617, 1618, 1619, 1620, 1621, 1622, 1623, 1624, 1625, 1626, 1627, 1628, 1629, 1630, 1631, 1632, 1633, 1634, 1635, 1636, 1637, 1638, 1639, 1640, 1641, 1642, 1643, 1644, 1645, 1646, 1647, 1648, 1649, 1650, 1651, 1652, 1653, 1654, 1655, 1656, 1657, 1658, 1659, 1660, 1661, 1662, 1663, 1664, 1665, 1666, 1667, 1668, 1669, 1670, 1671, 1672, 1673, 1674, 1675, 1676, 1677, 1678, 1679, 1680, 1681, 1682, 1683, 1684, 1685, 1686, 1687, 1688, 1689, 1690, 1691, 1692, 1693, 1694, 1695, 1696, 1697, 1698, 1699, 1700, 1701, 1702, 1703, 1704, 1705, 1706, 1707, 1708, 1709, 1710, 1711, 1712, 1713, 1714, 1715, 1716, 1717, 1718, 1719, 1720, 1721, 1722, 1723, 1724, 1725, 1726, 1727, 1728, 1729, 1730, 1731, 1732, 1733, 1734, 1735, 1736, 1737, 1738, 1739, 1740, 1741, 1742, 1743, 1744, 1745, 1746, 1747, 1748, 1749, 1750, 1751, 1752, 1753, 1754, 1755, 1756, 1757, 1758, 1759, 1760, 1761, 1762, 1763, 1764, 1765, 1766, 1767, 1768, 1769, 1770, 1771, 1772, 1773, 1774, 1775, 1776, 1777, 1778, 1779, 1780, 1781, 1782, 1783, 1784, 1785, 1786, 1787, 1788, 1789, 1790, 1791, 1792, 1793, 1794, 1795, 1796, 1797, 1798, 1799, 1800, 1801, 1802, 1803, 1804, 1805, 1806, 1807, 1808, 1809, 1810, 1811, 1812, 1813, 1814, 1815, 1816, 1817, 1818, 1819, 1820, 1821, 1822, 1823, 1824, 1825, 1826, 1827, 1828, 1829, 1830, 1831, 1832, 1833, 1834, 1835, 1836, 1837, 1838, 1839, 1840, 1841, 1842, 1843, 1844, 1845, 1846, 1847, 1848, 1849, 1850, 1851, 1852, 1853, 1854, 1855, 1856, 1857, 1858, 1859, 1860, 1861, 1862, 1863, 1864, 1865, 1866, 1867, 1868, 1869, 1870, 1871, 1872, 1873, 1874, 1875, 1876, 1877, 1878, 1879, 1880, 1881, 1882, 1883, 1884, 1885, 1886, 1887, 1888, 1889, 1890, 1891, 1892, 1893, 1894, 1895, 1896, 1897, 1898, 1899, 1900, 1901, 1902, 1903, 1904, 1905, 1906, 1907, 1908, 1909, 1910, 1911, 1912, 1913, 1914, 1915, 1916, 1917, 1918, 1919, 1920, 1921, 1922, 1923, 1924, 1925, 1926, 1927, 1928, 1929, 1930, 1931, 1932, 1933, 1934, 1935, 1936, 1937, 1938, 1939, 1940, 1941, 1942, 1943, 1944, 1945, 1946, 1947, 1948, 1949, 1950, 1951, 1952, 1953, 1954, 1955, 1956, 1957, 1958, 1959, 1960, 1961, 1962, 1963, 1964, 1965, 1966, 1967, 1968, 1969, 1970, 1971, 1972, 1973, 1974, 1975, 1976, 1977, 1978, 1979, 1980, 1981, 1982, 1983, 1984, 1985, 1986, 1987, 1988, 1989, 1990, 1991, 1992, 1993, 1994, 1995, 1996, 1997, 1998, 1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173, 2174, 2175, 2176, 2177, 2178, 2179, 2180, 2181, 2182, 2183, 2184, 2185, 2186, 2187, 2188, 2189, 2190, 2191, 2192, 2193, 2194, 2195, 2196, 2197, 2198, 2199, 2200, 2201, 2202, 2203, 2204, 2205, 2206, 2207, 2208, 2209, 2210, 2211, 2212, 2213, 2214, 2215, 2216, 2217, 2218, 2219, 2220, 2221, 2222, 2223, 2224, 2225, 2226, 2227, 2228, 2229, 2230, 2231, 2232, 2233, 2234, 2235, 2236, 2237, 2238, 2239, 2240, 2241, 2242, 2243, 2244, 2245, 2246, 2247, 2248, 2249, 2250, 2251, 2252, 2253, 2254, 2255, 2256, 2257, 2258, 2259, 2260, 2261, 2262, 2263, 2264, 2265, 2266, 2267, 2268, 2269, 2270, 2271, 2272, 2273, 2274, 2275, 2276, 2277, 2278, 2279, 2280, 2281, 2282, 2283, 2284, 2285, 2286, 2287, 2288, 2289, 2290, 2291, 2292, 2293, 2294, 2295, 2296, 2297, 2298, 2299, 2300, 2301, 2302, 2303, 2304, 2305, 2306, 2307, 2308, 2309, 2310, 2311, 2312, 2313, 2314, 2315, 2316, 2317, 2318, 2319, 2320, 2321, 2322, 2323, 2324, 2325, 2326, 2327, 2328, 2329, 2330, 2331, 2332, 2333, 2334, 2335, 2336, 2337, 2338, 2339, 2340, 2341, 2342, 2343, 2344, 2345, 2346, 2347, 2348, 2349, 2350, 2351, 2352, 2353, 2354, 2355, 2356, 2357, 2358, 2359, 2360, 2361, 2362, 2363, 2364, 2365, 2366, 2367, 2368, 2369, 2370, 2371, 2372, 2373, 2374, 2375, 2376, 2377, 2378, 2379, 2380, 2381, 2382, 2383, 2384, 2385, 2386, 2387, 2388, 2389, 2390, 2391, 2392, 2393, 2394, 2395, 2396, 2397, 2398, 2399, 2400, 2401, 2402, 2403, 2404, 2405, 2406, 2407, 2408, 2409, 2410, 2411, 2412, 2413, 2414, 2415, 2416, 2417, 2418, 2419, 2420, 2421, 2422, 2423, 2424, 2425, 2426, 2427, 2428, 2429, 2430, 2431, 2432, 2433, 2434, 2435, 2436, 2437, 2438, 2439, 2440, 2441, 2442, 2443, 2444, 2445, 2446, 2447, 2448, 2449, 2450, 2451, 2452, 2453, 2454, 2455, 2456, 2457, 2458, 2459, 2460, 2461, 2462, 2463, 2464, 2465, 2466, 2467, 2468, 2469, 2470, 2471, 2472, 2473, 2474, 2475, 2476, 2477, 2478, 2479, 2480, 2481, 2482, 2483, 2484, 2485, 2486, 2487, 2488, 2489, 2490, 2491, 2492, 2493, 2494, 2495, 2496, 2497, 2498, 2499, 2500, 2501, 2502, 2503, 2504, 2505, 2506, 2507, 2508, 2509, 2510, 2511, 2512, 2513, 2514, 2515, 2516, 2517, 2518, 2519, 2520, 2521, 2522, 2523, 2524, 2525, 2526, 2527, 2528, 2529, 2530, 2531, 2532, 2533, 2534, 2535, 2536, 2537, 2538, 2539, 2540, 2541, 2542, 2543, 2544, 2545, 2546, 2547, 2548, 2549, 2550, 2551, 2552, 2553, 2554, 2555, 2556, 2557, 2558, 2559, 2560, 2561, 2562, 2563, 2564, 2565, 2566, 2567, 2568, 2569, 2570, 2571, 2572, 2573, 2574, 2575, 2576, 2577, 2578, 2579, 2580, 2581, 2582, 2583, 2584, 2585, 2586, 2587, 2588, 2589, 2590, 2591, 2592, 2593, 2594, 2595, 2596, 2597, 2598, 2599, 2600, 2601, 2602, 2603, 2604, 2605, 2606, 2607, 2608, 2609, 2610, 2611, 2612, 2613, 2614, 2615, 2616, 2617, 2618, 2619, 2620, 2621, 2622, 2623, 2624, 2625, 2626, 2627, 2628, 2629, 2630, 2631, 2632, 2633, 2634, 2635, 2636, 2637, 2638, 2639, 2640, 2641, 2642, 2643, 2644, 2645, 2646, 2647, 2648, 2649, 2650, 2651, 2652, 2653, 2654, 2655, 2656, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, 2668, 2669, 2670, 2671, 2672, 2673, 2674, 2675, 2676, 2677, 2678, 2679, 2680, 2681, 2682, 2683, 2684, 2685, 2686, 2687, 2688, 2689, 2690, 2691, 2692, 2693, 2694, 2695, 2696, 2697, 2698, 2699, 2700, 2701, 2702, 2703, 2704, 2705, 2706, 2707, 2708, 2709, 2710, 2711, 2712, 2713, 2714, 2715, 2716, 2717, 2718, 2719, 2720, 2721, 2722, 2723, 2724, 2725, 2726, 2727, 2728, 2729, 2730, 2731, 2732, 2733, 2734, 2735, 2736, 2737, 2738, 2739, 2740, 2741, 2742, 2743, 2744, 2745, 2746, 2747, 2748, 2749, 2750, 2751, 2752, 2753, 2754, 2755, 2756, 2757, 2758, 2759, 2760, 2761, 2762, 2763, 2764, 2765, 2766, 2767, 2768, 2769, 2770, 2771, 2772, 2773, 2774, 2775, 2776, 2777, 2778, 2779, 2780, 2781, 2782, 2783, 2784, 2785, 2786, 2787, 2788, 2789, 2790, 2791, 2792, 2793, 2794, 2795, 2796, 2797, 2798, 2799, 2800, 2801, 2802, 2803, 2804, 2805, 2806, 2807, 2808, 2809, 2810, 2811, 2812, 2813, 2814, 2815, 2816, 2817, 2818, 2819, 2820, 2821, 2822, 2823, 2824, 2825, 2826, 2827, 2828, 2829, 2830, 2831, 2832, 2833, 2834, 2835, 2836, 2837, 2838, 2839, 2840, 2841, 2842, 2843, 2844, 2845, 2846, 2847, 2848, 2849, 2850, 2851, 2852, 2853, 2854, 2855, 2856, 2857, 2858, 2859, 2860, 2861, 2862, 2863, 2864, 2865, 2866, 2867, 2868, 2869, 2870, 2871, 2872, 2873, 2874, 2875, 2876, 2877, 2878, 2879, 2880, 2881, 2882, 2883, 2884, 2885, 2886, 2887, 2888, 2889, 2890, 2891, 2892, 2893, 2894, 2895, 2896, 2897, 2898, 2899, 2900, 2901, 2902, 2903, 2904, 2905, 2906, 2907, 2908, 2909, 2910, 2911, 2912, 2913, 2914, 2915, 2916, 2917, 2918, 2919, 2920, 2921, 2922, 2923, 2924, 2925, 2926, 2927, 2928, 2929, 2930, 2931, 2932, 2933, 2934, 2935, 2936, 2937, 2938, 2939, 2940, 2941, 2942, 2943, 2944, 2945, 2946, 2947, 2948, 2949, 2950, 2951, 2952, 2953, 2954, 2955, 2956, 2957, 2958, 2959, 2960, 2961, 2962, 2963, 2964, 2965, 2966, 2967, 2968, 2969, 2970, 2971, 2972, 2973, 2974, 2975, 2976, 2977, 2978, 2979, 2980, 2981, 2982, 2983, 2984, 2985, 2986, 2987, 2988, 2989, 2990, 2991, 2992, 2993, 2994, 2995, 2996, 2997, 2998, 2999, 3000, 3001, 3002, 3003, 3004, 3005, 3006, 3007, 3008, 3009, 3010, 3011, 3012, 3013, 3014, 3015, 3016, 3017, 3018, 3019, 3020, 3021, 3022, 3023, 3024, 3025, 3026, 3027, 3028, 3029, 3030, 3031, 3032, 3033, 3034, 3035, 3036, 3037, 3038, 3039, 3040, 3041, 3042, 3043, 3044, 3045, 3046, 3047, 3048, 3049, 3050, 3051, 3052, 3053, 3054, 3055, 3056, 3057, 3058, 3059, 3060, 3061, 3062, 3063, 3064, 3065, 3066, 3067, 3068, 3069, 3070, 3071, 3072, 3073, 3074, 3075, 3076, 3077, 3078, 3079, 3080, 3081, 3082, 3083, 3084, 3085, 3086, 3087, 3088, 3089, 3090, 3091, 3092, 3093, 3094, 3095, 3096, 3097, 3098, 3099, 3100, 3101, 3102, 3103, 3104, 3105, 3106, 3107, 3108, 3109, 3110, 3111, 3112, 3113, 3114, 3115, 3116, 3117, 3118, 3119, 3120, 3121, 3122, 3123, 3124, 3125, 3126, 3127, 3128, 3129, 3130, 3131, 3132, 3133, 3134, 3135, 3136, 3137, 3138, 3139, 3140, 3141, 3142, 3143, 3144, 3145, 3146, 3147, 3148, 3149, 3150, 3151, 3152, 3153, 3154, 3155, 3156, 3157, 3158, 3159, 3160, 3161, 3162, 3163, 3164, 3165, 3166, 3167, 3168, 3169, 3170, 3171, 3172, 3173, 3174, 3175, 3176, 3177, 3178, 3179, 3180, 3181, 3182, 3183, 3184, 3185, 3186, 3187, 3188, 3189, 3190, 3191, 3192, 3193, 3194, 3195, 3196, 3197, 3198, 3199, 3200, 3201, 3202, 3203, 3204, 3205, 3206, 3207, 3208, 3209, 3210, 3211, 3212, 3213, 3214, 3215, 3216, 3217, 3218, 3219, 3220, 3221, 3222, 3223, 3224, 3225, 3226, 3227, 3228, 3229, 3230, 3231, 3232, 3233, 3234, 3235, 3236, 3237, 3238, 3239, 3240, 3241, 3242, 3243, 3244, 3245, 3246, 3247, 3248, 3249, 3250, 3251, 3252, 3253, 3254, 3255, 3256, 3257, 3258, 3259, 3260, 3261, 3262, 3263, 3264, 3265, 3266, 3267, 3268, 3269, 3270, 3271, 3272, 3273, 3274, 3275, 3276, 3277, 3278, 3279, 3280, 3281, 3282, 3283, 3284, 3285, 3286, 3287, 3288, 3289, 3290, 3291, 3292, 3293, 3294, 3295, 3296, 3297, 3298, 3299, 3300, 3301, 3302, 3303, 3304, 3305, 3306, 3307, 3308, 3309, 3310, 3311, 3312, 3313, 3314, 3315, 3316, 3317, 3318, 3319, 3320, 3321, 3322, 3323, 3324, 3325, 3326, 3327, 3328, 3329, 3330, 3331, 3332, 3333, 3334, 3335, 3336, 3337, 3338, 3339, 3340, 3341, 3342, 3343, 3344, 3345, 3346, 3347

Sketch Plan Pg. 2

SKETCH PLAN

A = SHC 8302R

B = FBC 16223
(MOTORCYCLE) → perched

EXIT 9
JLN 201103

Edwards
VET -
CHC

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Statement as per Police Report (5)

T/2019 1029/2164

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMEDOL TRANSPORTATION LTD
100, 1000, 1000, 1000, 1000

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Olivia Kennedy

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

COMEDOL Transportation Ltd

30 OCT 2019

30 OCT 2019



**SINGAPORE
POLICE FORCE**



T/20191029/2164

1 of 3

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999

Report No. T/20191029/2164

REPORT OF A TRAFFIC ACCIDENT

| | | |
|--|-------------------------------------|---------------------------|
| Date/Time Report Made: 29/10/2019 21:46 | Vide Report No.: G/20191029/0146 | Station Diary No.: 137 |
|--|-------------------------------------|---------------------------|

Informant's Particulars

| | | | | | |
|--|------------|------------------------------|---|--|----------------------------|
| Name of Informant: TAN TUAN POH | | | Address: APT BLK 724 BEDOK RESERVOIR ROAD #10-5222 SINGAPORE 470724 | | |
| ID Type / ID No.: NRIC NO / S1314913E | | | Contact No.: Home/Office: Mobile: 96288220 | | |
| Nationality: SINGAPORE CITIZEN | | | Email: | | |
| Sex: Male | Age: 61 | Date of Birth: 18/09/1958 | Type of Informant: Driver | | |
| Race: Chinese | | | Language: English | | Institution / School Name: |
| Occupation: Taxi driver | | | Driving Licence Information: Class: 3 | | |
| | | | Date of Expiry: | | |

General Information of the Accident

| | | | | |
|---|------------------------------|------------------------------------|--|-------------------------------------|
| General Information of the Accident | | | | |
| Type of Accident: | Injury Attended by Police | Drink Drive: No | Date/Time of Accident: 29/10/2019 19:10 | Type of Location: Straight Road |
| Location: Along Road 1 PAN ISLAND EXPRESSWAY heading towards Changi at 9.8km mark, L/P 434 | | | | |
| Weather: Clear | | Road Surface: Dry | | Road Speed Limit: 90 Km/h |
| Traffic Flow: Dual Carriage Way | | Traffic Control: Not Controlled | | Traffic Volume: Heavy |
| Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction | | | | Anyone conveyed by ambulance: No |

Details of Vehicle Involved

| Vehicle No. | Type | Make | Model | Color | Condition | No of Passenger |
|-------------|------------|---------|-------|-------|---------------------|-----------------|
| FBC1622J | Motorcycle | YAMAHA | T135 | Red | Slightly Damaged | 1 |
| SHC8302R | Car | HYUNDAI | I40 | Blue | Slightly Damaged | 1 |

Details of Person Involved

| | |
|---------------------------------|--------------------------------|
| Any Pedestrian Involved: No | |
| No. of Pedestrians Injured: NIL | Use of Pedestrian Crossing: NA |



**SINGAPORE
POLICE FORCE**



T/20191029/2164

2 of 3

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999

Report No. T/20191029/2164

CONTINUATION OF REPORT

| | | | |
|-----------------------------------|-----------------------|--|-----------------------------------|
| Rider | | | |
| Name | Lim Zhi Wei | ID No. | NIL |
| Related Vehicle | FBC1622J (Motorcycle) | Contact No. | 90053326 |
| Hospital/Clinic | NIL | Class of Driving Licence & Expiry Date | Class: NIL Date of Expiry: NIL |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | Serious |
| Driver | | | |
| Name | TAN TUAN POH | ID No. | S1314913E |
| Related Vehicle | SHC8302R (Car) | Contact No. | 96288220 |
| Hospital/Clinic | NIL | Class of Driving Licence & Expiry Date | Class: 3 Date of Expiry: NIL |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | NIL |

Brief Details.

On the 29/10/2019 at around 7.10pm, I was driving my car bearing registration number SHC8302R Hyundai I40 Comfort taxi along PIE heading towards Changi. I was driving on the 2nd lane from the right and the traffic volume was heavy. After Eunos exit, the car in front of mine suddenly jammed brake. I also jammed brake as to avoid collision. Then a motorcycle suddenly side swipe on the left side of my taxi and fell on the road. Both rider and pillion fell in front on the road. I came out to check and saw that the motorcycle registration is FBC1622J. I called for the police and a few minutes later the traffic police came with ambulance. The rider and pillion both conveyed to hospital. There is CCTV in my taxi and it was taken by the traffic police.



**SINGAPORE
POLICE FORCE**



T/20191029/2164

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999

3 of 3



Report No. T/20191029/2164

CONTINUATION OF REPORT


Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

| | |
|--|---|
| Signature Of Officer Recording The Report: G / Sr Staff Sgt ANWAR BIN ZAINAL  | Signature Of Informant:  |
| Signature Of Interpreter: Not applicable | Date/Time: 29/10/2019 21:46 |
| Officer In Charge Of Case: TP / GIT / Sr Staff Sgt SHAHRUL NIZAM BIN SAMARRI Contact No.: 65476904 | Classification Of Case: |

Authentication Stamp
NP168



A member of COMFORTDELGRO

Date/Time: 31.10.2019 09:26 Page : 1

| | | | | |
|----------------|--------------------------------|------------------------|-----------------------|-------------------|
| Team: | ARC Repair TP(CLSO)1 | JOB CARD | Sales Order: | JC NO.: 305345373 |
| TOMER | COMFORT TRANSPORTATION PTE LTD | REGN NO.: SHC8302R | MILEAGE | |
| MS | 7010045 | MAKE : HYUNDAI | FUEL | E.....1/2.....F |
| TOMER NO. | 383 SIN MING DRIVE | MODEL I-40 | DATE/TIME IN | 30.10.2019 14:05 |
| RESS | Singapore SINGAPORE 575717 | YR OF MANU. 06.08.2015 | TARGET DATE | |
| (R) | 65508755 | CHASSIS CODE | COMPLETION DATE/TIME: | |
| (P) | | KMHLB41UMGU075666 | | |
| COUNT CARD NO. | | | | |

JOB DESCRIPTION

Accident Date: 29.10.2019
NATURE: 3P 31.10.2019

| S/NO | LABOR CODE | DESCRIPTION |
|------|------------------|-------------|
| | NTUC - Left Rear | |
| | LCC/Kahni - | |



| | | | |
|---|-------|------------------------------|--|
| CKED & PASSED OUT BY: | | | |
| SERVICE ADVISOR | | CUSTOMER'S SIGNATURE | |
| Acknowledgement Slip | | Exit Pass | |
| No.: SHC8302R | LARRY | Vehicle No.: SHC8302R | |
| Signature/Date | | Date | |
| Returned to Service Reception upon collection | | To be kept by Security Guard | |

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC8302R

DATE: 31. Oct. 2019

MAKE : HYUNDAI

MODEL : i40

DOA: 29. Oct. 2019

NTUC

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|---|---|------|------------|-------------------|
| 1 | Rear Bumper / on 50% | | | \$553.00 |
| 10 | Rear Bumper Clips / ne | | \$2.20 | \$22.00 |
| 1 | Rear Bumper Side Bracket - LH X sn | | | \$49.00 |
| 1 | Rear Fender - LH X sn | | | \$2,020.10 |
| | Tail lamp (LH) / ra | | \$ 697.80 | |
| | SUB TOTAL | | | \$2,644.10 |
| | LESS 20% | | | \$528.82 |
| | DISCOUNTED TOTAL | | | \$2,115.28 |
| 1 | Advertisement - Rear Bumper / ne | | | \$50.00 |
| 2 | Advertisement - Rear Fenders LH/RH / ne | | \$100.00 | \$200.00 |
| | | | | \$250.00 |
| | Labour Charge | | | |
| 1 | Panel Beating | | | 280 \$600.00 |
| 1 | Spray Painting Charge | | | 200 \$500.00 |
| 1 | Remove/refix Reverse Sensor | | | 30 \$100.00 |
| 1 | Tuff Kote | | | X \$100.00 |
| | TOTAL LABOUR | | | \$1,300.00 |
| | ESTIMATE TOTAL | | | \$3,665.28 |
| <p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p> | | | | |

21650

Nett

Nett

TOTAL LABOUR

ESTIMATE TOTAL

Larry Ng

Kalin (UCC)

31/10/19 1045h

2 Pys

45 All Repair photos

Signature:
Date:

4073.52

Our Job Ref No : 305345373

Date : 31. Oct. 2019

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHC8302R

Date of Accident: 29. Oct. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC FBC1622J

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

\$1200.00
~~\$2000.00~~

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Kalvin

Date : 1/11/19

For Official Use Only

| Item | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|--|--------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day | | YES | | |
| 2. Loss of Income Paid | | | | |
| 3. Survey Fees | | | | |
| 4. LTA Search Fee | \$7.49 | | | |
| 5. Medical Fees (on behalf of driver, if applicable) | | | | |
| 6. Overrun | | | | |

Remarks:



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19019305/K1qf3e2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556

Date: 06-11-2019



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|----------------|----------------|------------|
| Insured Veh. | FBC 1622J | Veh. Inspected | SHC 8302R |
| Policy No. | 5086493606-02 | Coverage (\$) | 0.00 |
| Claim No. | MT/1069249-002 | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 31/10/2019 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|--------------------|
| Make & Model | HYUNDAI I40 | c.c | 1685 |
| Engine No. | HIDDEN | Year of Reg. | 2015 |
| Chassis No. | KMHLB41UMGU075666 | Colour | BLUE |
| Odometer | 518524 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | FAIR | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|-----------|---------|
| R/H Front Tyre | 205/60 R16 | WEST LAKE | 7 mm |
| L/H Front Tyre | 205/60 R16 | WEST LAKE | 7 mm |
| R/H Rear Tyre | 205/60 R16 | WEST LAKE | 7 mm |
| L/H Rear Tyre | 205/60 R16 | WEST LAKE | 7 mm |

4. Description of Damages

| |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS. |
|--|

5. General Information

| | | | |
|----------------|--|-----------------|------------|
| Accident Date | 29/10/2019 | Inspection Date | 31/10/2019 |
| Survey held at | COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 2 Working Days |
|-------------------------------------|----------------|

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8302R

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|---|---------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | REAR BUMPER (50%) | CRACKED | 553.00 | 276.50 |
| 10 | REAR BUMPER CLIPS @\$2.20 | NECESSARY | 22.00 | 22.00 |
| 1 | REAR BUMPER SIDE BRACKET-LH | SERVICEABLE | 49.00 | - |
| 1 | REAR FENDER-LH | SERVICEABLE | 2,020.10 | - |
| 1 | TAIL LAMP (LH) | CRACKED | 697.80 | 697.80 |
| | LESS 20% DISCOUNT | | -668.38 | -199.26 |
| | | | 2,673.52 | 797.04 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | ADVERTISEMENT-REAR BUMPER (SN) | NECESSARY | 50.00 | 50.00 |
| 2 | ADVERTISEMENT-REAR FENDERS LH/RH @\$100.00 (SN) | NECESSARY | 200.00 | 200.00 |
| | | | 250.00 | 250.00 |
| <u>LABOUR</u> | | | | |
| | PANEL BEATING. | | 600.00 | 280.00 |
| | SPRAY PAINTING CHARGE. | | 500.00 | 200.00 |
| | REMOVE/REFIX REVERSE SENSOR. | | 100.00 | 30.00 |
| | TUFF KOTE. | NOT NECESSARY | 100.00 | - |
| | | | 1,300.00 | 510.00 |
| GRAND TOTAL | | | 4,223.52 | 1,557.04 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) | | | | 1,200.00 |

Report Ref No. NS/INC19019305/K1qf3e2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.