

2000/02

ASS. REC. BY:

REF:

CS/CT190 19306/Gsf3 n2

Special Instruction:

Surveyor

GQ

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

1.11.19 9.30 a.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKF 5603R

Insured:

GY 450 U

at Workshop m/s

Allswell Motor

Tel:

66791146

of

15 Dohi Law 9

Policy No:

Claim No:

SNM19170504202

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27.10.2019

CA / REV / REP. / REV 24 HRS

mp

Survey 1.11.19 2pm

H.O.D. Endorsement:

Date/Time:

1.11.19 10.30 a.m.

Person Contacted:

Cai Yee

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKF 5603R - X

GY 450 U - X

ASS. REC. BY:

666

REF:

C11

ASSIGNMENT

From:

Date: 1.11.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKF 5603R

at Workshop m/s: AHS W211

of 25 Defn Lnw 9

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh: 2pm Owner waiting.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKF 5603R

Yr Regn: 14 Jun 2012

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Altis 1.6 cc 1598

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading:

236686

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR 053 REG 104/38560

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kapsen

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 01-11-19

Survey held at

W/S

2pm

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

01/11 Initial \$ 600 with Ben.
 (\$ 800/- Red- 57%)

8/11/2019

RECEIVED 8 NOV 2019

Date/Time, File Pass to?

08/11/19

1) Typ: 4

Date/Time, File Return to?

2)

Rep. Estimate:

Lump Sum / M.B.: 600/- 4/5

☐ : Prel. Report☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : Wheel end (\$

Survey Fee:

Transportation

S + RS \$

Photos

CASH

TOTAL

220

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Company
Owner ID:	541Z
Vehicle No.:	SKF5603R
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2012
Engine No.:	1ZRX199665
Chassis No.:	MRO53REE104138560
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$15,101.00
Original Registration Date:	14 Jun 2012
First Registration Date:	14 Jun 2012
Transfer Count:	2
Actual ARF Paid:	\$15,101.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jun 2022
PARF Rebate Amount:	\$9,060.00
COE Expiry Date:	13 Jun 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$64,201.00
COE Rebate Amount:	\$16,745.00
Total Rebate Amount:	\$25,805.00

The information contained herein is correct as at 04 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/10/2019 18:06
Date Of Accident	27/10/2019 22:30
Exact Location Of Accident	TEBIN LANE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKF5603R
Insured/Policyholder	
Name Of Registered Owner	ALLSWELL LEASING & LIMOUSINE PTE LTD
Co Reg No	201432541Z
Email Address	ACCOUNT5@ALLSWELLMOTOR.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-66791146

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999994370
Cover Note Number	

Driver

Name of Driver	LIM CHONG JIN
NRIC No	S1795068A
Date Of Birth	04/12/1967
Occupation	OUTDOOR
Date Of Driving Pass	07/01/1988
Driving Experience	31 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88083951
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 304A ANCHORVALE LINK #15-136
Postcode	541304
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER & LEASEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : PASSENGER GENDER: : MALE
Passenger 2	NAME: : PASSENGER GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER WITH ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GY450U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any **false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claim;
 - (iii) carrying out and/or dealing with my instructions or responding to my enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (b) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
PNC/CRN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON THE 27 OCT 2019 at about 10-00pm I was travelling towards Tebin Lane as I was about to enter into the car park. Lorry (B) QY4504 came from behind me and hit my bumper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
Ref/C/TIN No.:

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146

email: ben@allswellmotor.com.sg

(3rd party claim against CTI insured GY450U

DOA 27.10.2019

Estimate repair

Vehicle No. : SFF 5603 R
 Make & Model : Toyota Auris 1.6A
 Chassis No. : _____

Submitted by : Ben
 COE expiry : 13-06-2022
 Engine No. : _____

Date of survey : _____

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	Rear bumper / RE.	01	\$1,200.00	482	
02				25%:	361.5
01	Special net Chips / Rebar studs #20 / MCL	01	\$20.00		
	Labour Description				
01	Dismantle / Assembly of rear bumper	01	\$180.00	150.	
02	Make sensor holes & reinstall sensor	01	\$580.00	40.	
02	Spray painting includes wash & polish	01	\$220.00	200	
	2 Days.			1700/-	
	11amp sum repair.				771.5
	After repair.				20% 600
	Caro Rep.				
	01/11/19.				

Note: If any of the quoted parts are recommended to be repaired, then on additional labour cost, they will be charged accordingly under supplementary.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

1700

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19019308/GSF3N2

Date: 11/11/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN31141918022	
Claimant Vehicle No :	SKF5603R	Insured Vehicle No :	GY450U	
Date of Loss:	27/10/2019	Nature of Claim:	TP	Claim No: SNM19D205092C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF5603R	Engine No:	1ZR199665
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REE104138560
Reg. Date:	14/06/2012 (Man. Year: 2012)	Odometer:	236686 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,220.00	381.50	838.50	68.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	480.00	390.00	90.00	18.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,700.00	771.50	928.50	54.62
Approved Total (Overridden) (S\$)		600.00		
(S\$)	1,700.00	600.00	1,100.00	64.71
+ GST 7.00/7.00% (S\$)	119.00	42.00	77.00	64.71
Nett Amount (S\$)	1,819.00	642.00	1,177.00	64.71

INSPECTION

Date of Assignment:	01/11/2019	Inspected At:	Allswell Motor Traders (HQ)
Date Inspected:	01/11/2019		25 Defu Lane 9
			Singapore 539266
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Nov 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF5603R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,200.00 F	*482.00 FL
2	1		*CLIPS/RETAINER STUDS	Necessary	20.00 FS	*20.00 FS
					Sub Total (S\$)	502.00
					- List Item Discount on L Items 0.00/25.00% (S\$)	120.50
					Total Parts (S\$)	381.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DISMANTLE/ASSEMBLY OF REAR BUMPER	New	180.00	150.00
2	MAKE SENSOR HOLES & REINSTALL SENSORS	New	80.00	40.00
3	SPRAY PAINTING INCLUDES WASH & POLISH	New	220.00	200.00
Gross Labour Cost (\$\$)			480.00	390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >