

ASS. REC. BY:

REF: CS/CT19019313 / R2y f30k Special Instruction:

Surveyor: Rosul ASSIGNMENT (Office)

From (Person): Juan Tony Hui Ping of CT1 Date/Time: 1.11.19 10.25 a.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMB 3044P Insured: GBJ 822H

at Workshop m/s Tower Trans Tel: 81688950

of 21 Bulim Drive

Policy No: DMCV SA19327019006 Claim No: SVM 1902513602

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 30.10.2019

(Client's Record) imp 4.11.2019

CA / REV / REP. / REV 24 HRS _____ H.O.D. Endorsement: _____

Date/Time: 1.11.19 11.25am Person Contacted: Lynn Vehicle-IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SMB 3044P - x
	GBJ 822H - x


Minima

ASSIGNMENT

417K

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SMB 3044P
 at Workshop no: TOWER TRANSIT
 of: BULIM DRIVE
 Insured: CTI
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? Yes or No
 GIA / PR Seen: _____ Consistent? Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle IN / OUT

Veh No: SMB 3044P Yr Regn: 2013 / APR
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: MAN NL320F (A22) CC: 10518
 Colour: GREEN A/C: Insured / Std / NI / NA
 Sp Reading: 404058 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WMAA2222567001785
 Gen. Cond: Good / Poor / Burnt
 Steering: Jammed / Leaked / Burnt or
 Brake: Jammed / Leaked / Burnt or
 Modi: S/Rim / STD A/Rim or
 Tyre Size: F: 275/70R22-5
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 8 mm R/Bal: 8/8 mm
 L/Bal: 8 mm L/Bal: 8/8 mm
 D.O.A: 30/10/19 D.O.I: 04/11/19
 Survey held at: TOWER TRANSIT
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
o/s Frt
 The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time	Action / Instruction
7/2	PIP \$5250-90 (Red \$2213-31, 29%)
RECEIVED 08 FEB 2020	

Date/Time: File Pass to? : Prel. Report : Final Report
 Days Of Repair: 2
 Resurvey No. of Trip: 2
 Date/Time: File Return to? 7/2/20 Typist
 Add Fee: Site Insp: \$5 _____
 Interview: \$5 _____
 Tech Work: \$5 _____
 Other: \$5 _____
 Survey Fee: 270
 Transport: _____
 Other: _____
 PIP: 270
 PIP \$5250-90

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins. Auth'ed	Status
Main	31 Oct 2019		01 Nov 2019 10:25 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:									
Main Claimant:	TOWER TRANSIT SINGAPORE PTE LTD, Co. Reg. No.: 201419417K								
Vehicle Reg. No.:	SMB3044P	Date of Loss: 30/10/2019 10:00 - :59							
Claim Type:	TP / SNM19D205136CD2	Policy/Cover Note No.: DMCV5N19367019000							
Vehicle Reg. No. (Insured):	GBJ8727H	Policy No. (Claimant): D-18092210MFBP							
		Excess: S\$350.00							
Repairer:	Tower Transit Singapore Pte Ltd (HQ) 21 Bulim Drive, Bulim Bus Depot, 648170 Jurong West - Tel: 81688950								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hul Ping - 638986192]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/11/2019]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Friday, 1 November 2019 10:20 AM
To: Wu Tzu Ying; Bazlin Ahmad; assignments
Cc: Irene Tay
Subject: RE: OUR REF: SNM19S205136-GBJ8727H-THP- PRS FOR ACCIDENT INVOLVING SMB3044P & GBJ8727H ON 30/10/2019 AT 10:35HRS ALONG BUKIT BATOK EAST AVE 3 - BS 42311

WITHOUT PREJUDICE

Dear Tzu Ying,

We refer to your email dated 31.10.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Wu Tzu Ying [mailto:Wu.Zy@towertransit.sg]
Sent: Friday, November 1, 2019 10:07 AM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Bazlin Ahmad <Bazlin.Ahmad@towertransit.sg>
Cc: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19S205136-GBJ8727H-THP- PRS FOR ACCIDENT INVOLVING SMB3044P & GBJ8727H ON 30/10/2019 AT 10:35HRS ALONG BUKIT BATOK EAST AVE 3 - BS 42311

Hi Kah Leong,

We would like to choose Marcus Chua from LKK to conduct the survey on Monday, 4th November, between 1pm to 4pm.

Thank you.

Best regards,

Tzu Ying
Senior Finance Manager

Mobile +65 9754 6590
Office +65 6817 1757
Email wu.zy@towertransit.sg



Tower Transit Singapore Pte Ltd
21 Bulim Drive, Bulim Bus Depot, Singapore 648170
Registration number 201419417K
www.towertransit.sg



Disclaimer: This email and any attached files may be coincidental, privileged and intended solely for the addressee. It may not be reviewed, acted upon, filed or communicated to or by any other person. If you have received this email by error, please delete it and notify the sender immediately. The views expressed in this email are not necessarily the views of Tower Transit.

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Friday, 1 November, 2019 9:36 AM
To: Bazlin Ahmad <Bazlin.Ahmad@towertransit.sg>; Wu Tzu Ying <Wu.Zy@towertransit.sg>
Cc: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19S205136-GBJ8727H-THP- PRS FOR ACCIDENT INVOLVING SMB3044P & GBJ8727H ON 30/10/2019 AT 10:35HRS ALONG BUKIT BATOK EAST AVE 3 - BS 42311

THIS EMAIL IS FROM AN EXTERNAL SOURCE – Do not click links or open attachments unless you recognise the sender/email.
If in doubt, please check with IT Support!

Without Prejudice

Dear Ms Wu,

Please refer to our email dated 01.11.2019.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Tan Kah Leong
Sent: Friday, November 1, 2019 8:58 AM
To: Bazlin.Ahmad@towertransit.sg
Cc: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19S205136-GBJ8727H-THP- PRS FOR ACCIDENT INVOLVING SMB3044P & GBJ8727H ON 30/10/2019 AT 10:35HRS ALONG BUKIT BATOK EAST AVE 3 - BS 42311

Without Prejudice

Dear Lynn,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Thursday, October 31, 2019 5:59 PM
To: Bazlin.Ahmad@towertransit.sg; Irene Tay <irene.tay@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: OUR REF: SNM19S205136-GBJ8727H-THP- PRS FOR ACCIDENT INVOLVING SMB3044P & GBJ8727H ON 30/10/2019 AT 10:35HRS ALONG BUKIT BATOK EAST AVE 3 - BS 42311

Dear Kah Leong,

Please assist to conduct PRS for SMB3044P.

Note: officer in charge – Irene Tay 63896192.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平辦城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Bazlin Ahmad [<mailto:Bazlin.Ahmad@towertransit.sg>]
Sent: Thursday, October 31, 2019 4:04 PM
To: Claims Dept of CTI; Elaine Cheong
Cc: Wu Tzu Ying
Subject: PRS FOR ACCIDENT INVOLVING SMB3044P & GBJ8727H ON 30/10/2019 AT 10:35HRS ALONG BUKIT BATOK EAST AVE 3 - BS 42311

WITHOUT PREJUDICE

Dear Sir / Mdm,

We would like to notify you of a road accident on **30/10/2019** at about **10:35hrs** along **Bukit Batok East Ave 3** involving our bus, **SMB3044P** & your insured vehicle **GBJ8727H**.

As a result of this accident, our bus has been damaged. Before we proceed to repair the damaged bus, please let us know **within the next 48 hours** if you wish to conduct a pre-repair survey of our bus. If we do not receive any reply from you within the stipulated timeline, we shall proceed to repair the bus without any further reference to you.

Please arrange survey appointment on Monday 04th Nov 2019 between 2pm – 4pm.

**Survey Location : Tower Transit Singapore Pte Ltd
21 Bulim Drive, Bulim Bus Depot, Singapore 648170**

Contact Person : Lynn @ +65 9199 0025

Thank You

Best Regards

Lynn Ahmad (Ms)

Senior Executive, Claims

Office +65 6248 0987

Mobile +65 9199 0025

Email bazlin.ahmad@towertransit.sg

Tower Transit Singapore Pte Ltd

21 Bulim Drive, Bulim Bus Depot, Singapore 648170

Registration number 201419417K

www.towertransit.sg

DISCLAIMER: This email and any attached files may be confidential, privileged and intended solely for the addressee. It may not be reviewed, acted upon, filed or communicated to or by any other person. If you have received this email in error please delete it and notify the sender immediately. If you do not wish to receive general email communications, or you wish to change/update your email details, please email grey@towertransit.co.uk to tell us. The views expressed in this email are not necessarily the views of Tower Transit

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

DISCLAIMER: This email and any attached files may be confidential, privileged and intended solely for the addressee. It may not be reviewed, acted upon, filed or communicated to or by any other person. If you have received this email in error please delete it and notify the sender immediately. If you do not wish to receive general email communications, or you wish to change/update your email details, please email grey@towertransit.co.uk to tell us. The views expressed in this email are not necessarily the views of Tower Transit

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/10/2019 16:41
Date Of Accident	30/10/2019 10:35
Exact Location Of Accident	BUKIT BATOK EAST AVE 3 - BS 42311
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB3044P
Insured/Policyholder	
Name Of Registered Owner	TOWER TRANSIT SINGAPORE PTE LTD
Co Reg No	201419417K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62480987

Vehicle Particulars

Manufacturer	MAN
Model	NL320F (A22)-10.5 D ABS TURBO (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken.	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	D-18092210MFBP
Cover Note Number	

Driver

Name of Driver	SAW ENG HENG
NRIC No	S7480735F
Date Of Birth	23/04/1974
Occupation	OUTDOOR
Date Of Driving Pass	21/04/2016
Driving Experience	3 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98888888
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address 21 BULIM DRIVE SINGAPORE 648170

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 10

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

please refer attached

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBJ8727H

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver KAY TANG YI, BERNARD

NRIC/Passport Number S9424081F

Contact Number

Address

Postcode

Insurance Company Name CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & time:

Reporting Centre Personnel's Signature
Name:
NIC/PIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

After BR B/S 42311 at Bukit Batok East Ave 3 a
 my bus at left lane. Out of sudden before I reach turn
 to Bukit Batok St 25 and my bus sideswapped by PTE
 lorry and hit my right side mirror. My side head plastic
 cracked, small cracked at side windscreen corner. I informed
 BCC and we exchange particulars. The lorry from
 2nd lane to left lane.

My bus SM3044P
 Tel: 97773009 - Pte lorry contact.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/IN No.:

ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	10:35hrs
ACCIDENT DATE	30-Oct-19
BUS CAPTAIN NAME	
THIRD PARTY CLAIM AGAINST	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

BUS REGISTRATION NUMBER	SMB3044P
BUS TYPE (SD/DD)	SD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	O/S/F VIEW MIRROR <i>CA /</i>	1	\$751.90
2	FRONT WINDSCREEN GLASS <i>CA /</i>	1	\$3,500.00
3	IU BRACKET <i>CA /</i>	1	\$20.00
4	SIKAFLEX BLACK <i>CA /</i>	4	\$64.00
5	MIRROR REFLECTOR STICKER <i>CA /</i>	2	\$40.00
6			
7			
8			
		7% GST	\$306.31
		PARTS TOTAL COST	\$4,682.21

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE DAMAGED BODY PARTS	<i>325</i> \$1,980.00
TO REMOVE AND INSTALL FRONT WINDSCREEN	<i>550</i> \$650.00
	7% GST
	\$182.00
	LABOUR TOTAL COST
	\$2,782.00

SPRAY PAINTING \$640 PER PANEL
LABOUR CHARGES \$650 PER DAY

6979.90

ESTIMATED ACCIDENT REPAIR COST



SECTION 3: REPAIRS TO BUS ADVERTISEMENT VINYL/PANELS (ADVERTISEMENT COST)

TOTAL ADVERTISEMENT REPAIR COST	
---------------------------------	--

SECTION 4: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	
-------------------	--

SECTION 5: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

BUS TYPE (SD / DD)		Date In For Repairs	4/11/2019
		Date Out From Repairs	
		Number of Days Bus in Workshop	
LOSS OF USE COST			\$1,500.00

SUMMARY	
SECTION NO.	COST
1	\$4,682.21
2	\$2,782.00
3	-
4	-
5	\$1,500.00
GRAND TOTAL	\$8,964.21

[Handwritten signature]
4/11/19

Rasul
Hp 900/0068
2 days
04/11/19 @ 1500
Resy after repair

Lock/Info Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Any illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Approved by Repairer
Signature
Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Oct 2019		01 Nov 2019 10:25 Edit Adj Rpt	S\$5,250.90 Edit Estimates	S\$5,250.90 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	TOWER TRANSIT SINGAPORE PTE LTD , Co. Reg. No.: 201419417K								
Vehicle Reg. No.:	SMB3044P	Date of Loss:	30/10/2019 10:00 - :59 [78 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D205136C02	Policy/Cover Note No.:	DMCVSN19367019000						
Vehicle Reg. No. (Insured):	GBJ8727H	Policy No. (Claimant):	D-18092210MFBP						
		Excess:	S\$350.00						
Repairer:	Tower Transit Singapore Pte Ltd (HQ) 21 Bulim Drive, Bulim Bus Depot, 648170 Jurong West - Tel: 81688950								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 12/11/2019]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMB3044P (SNM19D205136C02)
[GBJ8727H]
TP
TOWER TRANSIT SINGAPORE PTE LTD
Oct 30 2019 10:00AM
[-]
Tower Transit Singapore Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)	Thumbnail	Print
1	31/10/19 15:53	Video - Accident [Linked Accident Report Documents]	Load MP4	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
2	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
3	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
4	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
5	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
6	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
7	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
8	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
9	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
10	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
11	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
12	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
13	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
14	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
15	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
16	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
17	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
18	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
19	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
20	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
21	07/02/20 17:02	General View	Load JPG	<input checked="" type="checkbox"/>
22	07/02/20 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
23	07/02/20 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
24	07/02/20 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
25	07/02/20 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
26	07/02/20 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)	Thumbnail	Print
1	31/10/19 15:53	Video - Accident	Load MP4	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)	Thumbnail	Print
Assessment Reports				
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)	Thumbnail	Print
1	31/10/19 15:55	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>
2	06/12/19 19:10	Accident Statement	 Load HTM	
3	06/12/19 19:14	Accident Statement	 Load HTM	
4	06/12/19 19:14	Accident Statement	 Load HTM	
5	06/12/19 19:16	Accident Statement	 Load HTM	
6	06/12/19 19:16	Accident Statement	 Load HTM	
7	06/12/19 19:16	Accident Statement	 Load HTM	
8	06/12/19 19:16	Accident Statement	 Load HTM	
9	06/12/19 19:20	Accident Statement	 Load HTM	
Photos/Images				
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)	Thumbnail	Print
1	30/10/19 16:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	30/10/19 16:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	30/10/19 16:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	30/10/19 16:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	31/10/19 15:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	31/10/19 15:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	31/10/19 15:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	31/10/19 15:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	31/10/19 15:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	31/10/19 15:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	31/10/19 15:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	31/10/19 15:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	31/10/19 15:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	31/10/19 15:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	31/10/19 15:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	31/10/19 15:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation				
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)	Thumbnail	Print
1	30/10/19 16:52	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	30/10/19 16:52	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	31/10/19 15:55	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
4	31/10/19 15:55	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19019313/R1YF3E2

Date: 07/02/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN19367019000
 Claimant Vehicle No: SMB3044P Insured Vehicle No: GBJ8727H
 Date of Loss: 30/10/2019 Nature of Claim: TP Claim No: SNM19D205136C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMB3044P Engine No: 50333662273356
 Make & Model: MAN NL320F (A22), 10.5 D ABS TURBO (A) Chassis No: WMAA2ZZZ5D7001785
 Reg. Date: 02/04/2013 (Man. Year: 2012) Odometer: 404058 km
 Colour: Green Engine Capacity: 10518 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
 Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8/8 mm
 Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,375.90	4,375.90	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	875.00	1,725.00	66.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,975.90	5,250.90	1,725.00	24.73
+ GST 7.00/7.00% (S\$)	488.31	367.56	120.75	24.73
Nett Amount (S\$)	7,464.21	5,618.46	1,845.75	24.73

INSPECTION

Date of Assignment: 01/11/2019
 Date Inspected: 04/11/2019 Inspected At: Tower Transit Singapore Pte Ltd (HQ)
 21 Bulim Drive, Bulim Bus Depot
 Singapore 648170
 Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 07 Feb 2020)
Parts:	N/A MAN NL320F (A22) 10.5 D ABS TURBO (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMB3044P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S/F VIEW MIRROR	Cracked	751.90 FS	*751.90 FS
2	1		*FRONT WINDSCREEN GLASS	Cracked	3,500.00 FS	*3,500.00 FS
3	1		*IU BRACKET	Necessary	20.00 FS	*20.00 FS
4	4		*SIKAFLEX BLACK	Necessary	64.00 FS	*64.00 FS
5	2		*MIRROR REFLECTOR STICKER	Necessary	40.00 FS	*40.00 FS
Total Parts (S\$)					4,375.90	4,375.90

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED BODY PARTS	New	1,950.00	325.00
2	TO REMOVE AND INSTALL FRONT WINDSCREEN	New	650.00	550.00
Gross Labour Cost (\$\$)			2,600.00	875.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >