

ASS. REC. BY:

REF: CS3/ FCI K019316/Gcf3⁵²

Special Instruction:

Surveyor

GA

ASSIGNMENT (Office)

From (Person):

Muhim Chin San San

of

FCI

Date/Time: 1.11.2019 11.40 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBM 8534G

Insured:

SHC 7504G

at Workshop m/s

Trickster 1

Tel:

8363 3059

of

1 Kaki Bukit Ave C # 02-35

Policy No:

Claim No:

D19006929MPSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14.10.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

1.11.19 11.53 p.m

Person Contacted:

Wilson

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	Spelton: #02-35
	FBM 8534G - X	
	SHC 7504G - CS3/ FCI 1501935/Gcf3 ⁵²	P.O.A - 17/11/2015
	Disassemble: 4/11/2019	

ASS. REC. BY:

REF:

PC1

PRS

ASSIGNMENT

From:

Date:

1-11-2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: FBM 85346

at Workshop m/s Tri Kristal

of 1 Kaki Bukit bvd 6 # 02-35

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: 8363 3059 Wilson

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$8000

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

np**

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBM 85346

Yr Regn:

25 Apr 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

FS150F

C.C

149

Colour:

orange

A/C: Insured / Std / NI / NA

Sp. Reading:

48407

T/Radio: Insured / Std / NI / NA

Eng/No:

PMK KC 27A 0JB 109229

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

90/80-17

R:

120/70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

06-11-19

Survey held at

w/s

3:30pm

Des. of Damages (Frt / Rear / O/S / N/S / UIC / Rooftop or

and

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Rep. Formel:

PRS

Lump Sum / EP. J. C.

Days Of Repair:

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

MOTOR SURVEY ASSIGNMENT

Date	31-10-2019	Our Ref No. D19006929MFSH
Accident Date	14-10-2019	Claim Type. Third Party
Insured Vehicle	SHC7504G	Third Party Vehicle. FBM8534G
Survey Location	1 KAKI BUKIT AVENUE 6 #02-36 AUTOBAY @KAKIBUKIT	
Contact Person.	WILSON	
Contact No.	98615303/ 98615303	Fax No. 65098726
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRIKRISTAL AEROSPACE PTE. LTD.	Attention. NIL
Cc : TP Solicitor	CHIA S ARUL LLC	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN201330709H

ARULCHELVAN S • A. RAVIDASS • DON TAN

Our ref: FBM 8534 G (iz)

Your ref: SHC 7504 G

11 March 2019

India International Insurance Pte Ltd
Singapore

Dear Sirs,

**NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2
WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL
FOR NIMA CASE
ACCIDENT INVOLVING MOTOR VEHICLES FBM 8534 G AND SHC 7504 G ALONG
YUAN CHING ROAD ON 14 OCTOBER 2019**

We act for Muhammad Hafiz Bin Muhammad Abdul Halim, owner of motor cycle FBM 8534 G who has appointed us to act on his behalf to claim against your insured's vehicle no. SHC 7504 G in regards to the road traffic accident on 14 October 2019.

Please be informed that the said motor vehicle can be inspected at:-

**TRISTIKAL AEROSPACE PTE LTD
1 KAKI BUKIT AVENUE 6
#02-35 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883**

Kindly contact Mr Wilson at 9861 5303 to make the necessary arrangements.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

MR ARULCHELVAN S

151 CHIN SWEE ROAD • #03-09
MANHATTAN HOUSE • SINGAPORE 169876
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)
EMAIL : info@chiaarul.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/10/2019 15:27
Date Of Accident	14/10/2019 07:45
Exact Location Of Accident	YUAN CHING ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBM8534G
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD HAFIZ BIN MUHAMMAD ABDUL HALIM
NRIC No	S8946247I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83882930
Alternative Phone No	OTHERS-83882930

Vehicle Particulars

Manufacturer	HONDA
Model	FS150F
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MSD/VMS/19-500298-WTT
Cover Note Number	

Driver

Name of Driver	MUHAMMAD HAFIZ BIN MUHAMMAD ABDUL HALIM
NRIC No	S8946247I
Date Of Birth	28/12/1989
Occupation	INDOOR
Date Of Driving Pass	23/06/2011
Driving Experience	8 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83882930
Fax Number	
Contact Number	OTHERS-83882930
Email Address	NOEMAIL

Address	BLK 545 JURONG WEST ST 42 #04-83
Postcode	S640545
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	SUNNY
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NUR HAZIRAH BINTE MUHAMMAD ABDUL HALIM GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT : T/20191018/7017

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC7504G
Vehicle Make/Model/Colour	TOYOTA / YELLOW
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


DETAILS OF INJURED PERSON 1

Name	MUHAMMAD HAFIZ BIN MUHAMMAD ABDUL HALIM
Approximate Age	29
Injuries Sustain	SERIOUS INJURY
Injured person in which vehicle?	FBM8534G
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 545 JURONG WEST ST 42 #04-83
Postcode	S640545

DETAILS OF INJURED PERSON 2

Name	NUR HAZIRAH BINTE MUHAMMAD ABDUL HALIM
Approximate Age	
Injuries Sustain	SERIOUS INJURY
Injured person in which vehicle?	FBM8534G
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to the police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20191018/7017

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20191018/7017

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/10/2019 16:22		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: MUHAMMAD HAFIZ BIN MUHAMMAD ABDUL HALIM			Address: APT BLK 545 JURONG WEST STREET 42 #04-83 SINGAPORE 640545		
ID Type / ID No.: NRIC NO / S89462471			Contact No.: Home/Office:		Mobile: 83882930
Nationality: SINGAPORE CITIZEN			Email: mdfiz@hotmail.com		
Sex: Male	Age: 29	Date of Birth: 28/12/1989	Type of Informant: Rider		
Race: Boyanese			Language: English		Institution / School Name:
Occupation: Warehouse coordinator			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 14/10/2019 07:45	Type of Location: Straight Road
Location: YUAN CHING ROAD				
Weather: Sunny		Road Surface: Dry		Road Speed Limit: 50 Km/h
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBM8534G	Motorcycle	HONDA	RS150R	Orange		0
SHC 7504 G	Motor taxi	TOYOTA		Yellow		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBM8534G	MSIG INSURANCE (SINGAPORE) PTE. LTD.	MSDSMT19500298	26/04/2019	25/04/2020



**SINGAPORE
POLICE FORCE**



T/20191018/7017

3 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20191018/7017

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
TAN CHIN YONG
Contact No.: 65476178

Authentication Stamp

NP168

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:
18/10/2019 16:22

Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	247I
Vehicle Details	
Vehicle No.:	FBM8534G
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	FS150F
Primary Colour:	Orange
Manufacturing Year:	2018
Engine No.:	KC27E2121372
Chassis No.:	PMKKC27A0JB109229
Maximum Power Output:	-
Open Market Value:	\$2,373.00
Original Registration Date:	25 Apr 2018
First Registration Date:	25 Apr 2018
Transfer Count:	1
Actual ARF Paid:	\$356.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Apr 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$7,115.00
COE Rebate Amount:	\$6,020.00
Total Rebate Amount:	\$6,020.00

The information contained herein is correct as at 08 Nov 2019

OK

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT

MS FIRST CAPITAL INSURANCE LTD

Ref: CS3/FCI19019316/Gcf3s2

36 ROBINSON ROAD

Date: 22-11-2019

#16-01 CITY HOUSESINGAPORE 068877



Code: FCI2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHC 7504G	Veh. Inspected	FBM 8534G
Policy No.		Coverage (\$)	0.00
Claim No.	D19006929MFSH	Excess (\$)	0.00
Assign From	MERINE CHIA SAN SAN	Assign Date	01/11/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA FS150F	c.c	149
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	PMKKC27A0JB109229	Colour	ORANGE
Odometer	48407 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	90/80-17	MAXXIS	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	120/70-17	MAXXIS	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.

**5. General Information**

Accident Date	14/10/2019	Inspect Date / Time	01/11/2019 (03:30 PM)
Survey held at	TRIKRISTAL AEROSPACE PTE LTD 1 KAKI BUKIT AVE 6 #02-35 AUTOBAY@KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
 THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
 D) MARKET VALUE: \$8,000.00

Report Ref No. CS3/FCI19019316/Gcf3s2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.