

MSME19137996 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 17/10/2019 17:56
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/10/2019 17:56
Date Of Accident	17/10/2019 08:10
Exact Location Of Accident	BEDOK RESERVOIR RD (TAMPINES)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ6591B
Insured/Policyholder	
Name Of Registered Owner	CARS 88 HIRE PTE LTD
Co Reg No	201820615D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96931407

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	TOURAN

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102235080
Cover Note Number	

Driver

Name of Driver	ERYANTO BIN PUNGOT
NRIC No	S7806854Z
Date Of Birth	14/03/1978
Occupation	OUTDOOR
Date Of Driving Pass	24/09/1997
Driving Experience	22 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94596235
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 4 BEDOK SOUTH AVE 1 #02-815
Postcode	460004
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	AIRPORT POLICE DIVISION
Police Station Address	ROAD: 35 AIRPORT BOULEVARD , POSTCODE: 819645 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65460000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: T/20191017/2058.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF4108S
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

VEHICLE B PASSENGER

Approximate Age

Injuries Sustain

Injured person in which vehicle?

GBF4108S

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode



Sketch Plan Pg. 1

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my Instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

CAS KIRKAL

Sketch Plan #2 Pg. 1

Bedok Reservoir Rd (Tampine)

A - SPK 6591B

B - GBF 4108S




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to police report 7/2019, 017/2018

DISCLAIMATION

I/we declare the foregoing particulars are known in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #3 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20191017/2058

AIRPORT POLICE POST
AIRPORT POLICE DIVISION

1 of 3

Report No. T/20191017/2058

Police Station Of Origin:
Airport Police, Airport Police Post
35 Airport Boulevard SINGAPORE 819645
Tel No: 1800-5460000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/10/2019 12:28		Vide Report No.: G/20191017/0051		Station Diary No.: 48	
Informant's Particulars					
Name of Informant: ERYANTO BIN PUNGOT			Address: APT BLK 4 BEDOK SOUTH AVENUE 1 #02-815 SINGAPORE 460004		
ID Type / ID No.: NRIC NO / S7806854Z			Contact No.: Home/Office: Mobile: 94596235		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 41	Date of Birth: 14/03/1978	Type of Informant: Driver		
Race: Javanese			Language: English		Institution / School Name:
Occupation: PRIVATE HIRE DRIVER			Driving Licence Information: Class: 2B,2A,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 17/10/2019 08:10	Type of Location: Straight Road
Location: Along Road 1 BEDOK RESERVOIR ROAD				
Towards Tampines near Blk 725 and 724.				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF4108S	Lorry				Seriously Damaged	6
SKQ6591B	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			

Sketch Plan #4 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20191017/2058

2 of 3

Police Station Of Origin:
Airport Police, Airport Police Post
35 Airport Boulevard SINGAPORE 819645
Tel No: 1800-5460000

Report No: T/20191017/2058

CONTINUATION OF REPORT

Driver			
Name	ERYANTO BIN PUNGOT		ID No. S7806854Z
Related Vehicle	SKQ6591B (Car)		Contact No. 94596235
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL

Brief Details.

On 17/10/2019 at about 0810hrs, I was driving the vehicle, SKQ6591B, on lane 1 along Bedok Reservoir Road towards Tampines. Subsequently, a lorry with vehicle registration number, GBF4108S, went into my lane abruptly from lane 2 and hit onto my vehicle's left rear passenger door area. The lorry then skidded and overturned at lane 2. I then stopped and assisted the passengers of the lorry.

The traffic police attended to the case and TP IO Isa was at scene. TP IO Isa told me to lodge a Traffic Accident report. That is all.

Sketch Plan #5 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20191017/2058

2 of 3

Report No. T/20191017/2058

Police Station Of Origin:
Airport Police, Airport Police Post
35 Airport Boulevard SINGAPORE 819645
Tel No: 1800-5460000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
APD /
Sr Staff Sgt MOHAMMED FADLY BIN ROSLI

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
17/10/2019 12:28

Officer In Charge Of Case:
TP / GIT /
SI ONG CHEE HIEN
Contact No: 65476437

Classification Of Case:

Authentication Stamp
NP188

