



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19019342/T1pa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 08-05-2020



ATTN:RICHARD ANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 6065T	Veh. Inspected	XE 3828Z
Policy No.	VFX/P2214992	Coverage (\$)	0.00
Claim No.	S9M024X6	Excess (\$)	0.00
Assign From		Assign Date	01/11/2019

2. Vehicle Particulars & Condition

Make & Model	SCANIA P400L	c.c	12742
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	YS2P4X20005485835	Colour	BLUE
Odometer	70374	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	315/80 R22.5	BRIDGESTONE	8 mm
L/H Front Tyre	315/80 R22.5	BRIDGESTONE	8 mm
R/H Rear Tyre	315/80 R22.5 (D)	BRIDGESTONE	8/8 mm
L/H Rear Tyre	315/80 R22.5 (D)	BRIDGESTONE	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S AND REAR O/S PORTION. DAMAGES SEE DETAILS

5. General Information

Accident Date	24/10/2019	Inspection Date	01/11/2019
Survey held at	ASM AUTOMOTIVE SERVICES PTE LTD 13 PIONEER SECTOR 1 SINGAPORE 628424		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------