

ASSIGNMENT

Surveyor: RASUL DOI: 29.10.2019 Date / Time: 25.10.2019

Registered in Merimen: _____

Pre-assign / CCU / FTE

Insured Vehicle No. : YN 2069U

Claim No. : _____

Name of Insured : California Laundry Pte Ltd

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II :SS

D.O.A : 22/10/2019 08:00Place of Accident : LOADING/UNLOADING BAY @ HOLIDAY INNIs driver the owner? (YES / NO)

Nature of Accident : _____

If NO, Driver Name / Age : _____

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No. : _____

(V/L: YES / NO)Insured Liability : % Final ? Yes / No

GBF 9340D

INSRS:
WSP: SIN SHENG

Tel : _____

Liability : _____

RMKS: _____

INSRS:
WSP: _____

Tel : _____

Liability : _____

RMKS: _____

INSRS:
WSP: _____

Tel : _____

Liability : _____

RMKS: _____

INSRS:
WSP: _____

Tel : _____

Liability : _____

RMKS: _____

Date/ Time			STAGE	DATE / PIC	
	GBF9340D - X	YN 2069U - X	Non-Reporting ltr (1st):		
			Non-Reporting ltr (2nd):		
05.12.19	EMAIL WSP LIABILITY CLEAR.		Non-Reporting ltr (Final):		
			Notification ltr (if non-pickup):		
			Call OI:		
19.12.19	FIVE DAYS TO TRANS TO REPAIRER REPORT.		After call ltr to OI:		
			Documentation Check List:	Handler Typist	
			Notification ltr (if non-pickup)	<input type="checkbox"/>	<input type="checkbox"/>
			After call ltr to OI:	<input type="checkbox"/>	<input type="checkbox"/>
			Authorisation To Act:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
			Release Voucher:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
			Final Repair Bill:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
			Car Rental Invoice:	<input type="checkbox"/>	<input type="checkbox"/>
			Towing Invoice:	<input type="checkbox"/>	<input type="checkbox"/>
			LTA / GIA :	<input checked="" type="checkbox"/>	<input type="checkbox"/>
			Medical Bill:	<input type="checkbox"/>	<input type="checkbox"/>
			PIR:	<input type="checkbox"/>	<input type="checkbox"/>
			Mandate/Reject Instruction:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
			LOD	<input checked="" type="checkbox"/>	<input type="checkbox"/>
			Payment Breakdown Form:	<input type="checkbox"/>	<input type="checkbox"/>
PRELIMINARY ADVICE Date/Time:			Post-Repair Photos:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
			Others:	<input type="checkbox"/>	<input type="checkbox"/>
Sent By:					

PRELIMINARY ADVICE	Date/Time: _____	Sent By: _____	Confirm by: <u>WLS</u>
FINALIZATION	Date/Time: _____	Confirm with: _____	Confirm by: <u>WLS</u>
Repair Cost:	<u>TP SS 3,274.98</u>	(<u>4</u> days) Reduction: <u>41</u> %	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: <u>05.03.20</u>	Confirm with: <u>PB</u>	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	<u>% 100</u>	(Agreed / Assessed) BOLA S/N No. : <u>ML</u>	If NO or B 28, Ass. Lia : _____
Repair Cost:	<u>WLS SS 3,504.23</u>	<u>DID REVERSED AND WLS TP.</u>	
Loss of Rental (LOR):	SS - (_____ days)		
Loss of Use (LOU):	SS <u>120.00</u> (<u>1500</u> x <u>6</u> days)		
Loss of Income (LOI):	SS - (\$ x _____ days)		
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]			
GIA/LTA Search	SS <u>2.00</u>		
Medical:	SS -		
Disbursement:	SS - (e.g. Tow/ Independent)		
Legal Cost	SS -		
Total:	SS <u>4,226.23</u>	Global Sum SS:	
FINAL PAYMENT	Date/Time: <u>05.03.20</u>	Confirm with: <u>PB</u>	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS <u>4,226.23</u>	Name 1: <u>SIN SHENG ENGINEERING SERVICES.</u>	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC4/LPC19019375/R1ea3

Date: 05/11/2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBF 9340D

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 29/10/2019 at the premises of M/s Sin Sheng Engineering Services and have the following to report:-

Workshop Estimate Amount	: S\$	6,231.34
Revised Estimate Amount	: S\$	2,725.69
"Check" Items Amount	: S\$	2,805.65
Total (Including Check Items)	: S\$	5,531.34
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

196N

Vehicle Details

Vehicle No.:

GBF9340D

Vehicle to be Exported:

Yes

Intended Deregistration Date:

31 Dec 2019

Vehicle Make:

mitsubishi

Vehicle Model:

CANTER FEA01BR2SDEB (CBU)

Primary Colour:

White

Manufacturing Year:

2016

Engine No.:

4P10C48632

Chassis No.:

FEA01BA20565

Maximum Power Output:

-

Open Market Value:

\$26,857.00

Original Registration Date:

17 Apr 2017

First Registration Date:

17 Apr 2017

Transfer Count:

0

Actual ARF Paid:

\$1,343.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

16 Apr 2027

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

PQP Paid:

\$46,249.00

COE Rebate Amount:

\$33,736.00

Total Rebate Amount:

\$33,736.00

The information contained herein is correct as at 23 Oct 2019

OK

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002992

Date : 29/10/2019
Vehicle Num. : GBF9340D
Make/Model : MITSUBISHI FEA 01
Chassis/Eng# : FEA01BA20565
Accident Date : 22/10/2019
Claim No. :
Reference : YN2069U
Policy No. : 29131844

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT PANEL		2,092.63
2.	1	FUSO EMBLEM		154.96
3.	1	FRONT GRILLE		423.70
4.	1	HEATER ASSY		2,584.78
5.	1	BLOWER ASSY		599.05
List TotalS\$:				5,855.12
25.00% Discount S\$:				1,463.78
				4,391.34
LABOUR :				
		TO DISMANTLE/REPAIR DASHBOARD (photo)	150	280.00
		TO DISMANTLE/REPLACE HEATER	100?	180.00
		TO TOP-UP GAS		
		TO PANEL BEAT AND REPAIR FRONT BODY	550	750.00
		TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS		
		TO SPRAY PAINTING	300	550.00
		TO APPLY TUFF KODE	40	80.00

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002992


Date : 29/10/2019
Vehicle Num. : GBF9340D
Make/Model : MITSUBISHI FEA 01
Chassis/Eng# : FEA01BA20565
Accident Date : 22/10/2019
Claim No. :
Reference : YN2069U
Policy No. : 29131844

S/N	Quantity	Particular	Unit Price	Amount SS
-----	----------	------------	------------	-----------

LOSS OF USE : 5 DAYS @ SS120/DAY

Labour Total SS :

1,840.00



Resue
Hp 90010568
4 days
P/P
29/10/19 @ 1715
Ready before paint

Total SS : 6,231.34

SIN SHENG ENGINEERING SERVICES

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002992

Date : 29/10/2019
Vehicle Num. : GBF9340D
Make/Model : MITSUBISHI FEA 01
Chassis/Eng# : FEA01BA20565
Accident Date : 22/10/2019
Claim No. :
Reference : YN2069U
Policy No. : 29131844

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	FRONT PANEL <i>bl</i>		2,092.63
3.	1	FUSO EMBLEM <i>ne</i>		154.96
4.	1	FRONT GRILLE <i>? X 1 on</i>		423.70
5.	1	HEATER ASSY <i>? X 1 on</i>		2,584.78
5.	1	BLOWER ASSY <i>? ca</i>		599.05

List Total S\$:
25.00% Discount S\$:

2846.64
25%
2134.98
5,855.12
1,463.78
4,391.34

LABOUR :
TO DISMANTLE/REPAIR DASHBOARD *(photo)*
TO DISMANTLE/REPLACE HEATER *blower*
TO TOP-UP GAS
TO PANEL BEAT AND REPAIR FRONT BODY
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS
TO SPRAY PAINTING
TO APPLY TUFF KOTE

1140
150 ~~280.00~~
100? ~~180.00~~
550 ~~750.00~~
300 ~~550.00~~
40 ~~80.00~~

CONTINUE / ...

2134.98
1140.00
3274.98
4 days

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002992

Date : 29/10/2019
Vehicle Num. : GBF9340D
Make/Model : MITSUBISHI FEA 01
Chassis/Eng# : FEA01BA20565
Accident Date : 22/10/2019
Claim No. :
Reference : YN2069U
Policy No. : 29131844

S/N	Quantity	Particular	Unit Price	Amount SS
-----	----------	------------	------------	-----------

LOSS OF USE : 5 DAYS @ SS120/DAY

Labour Total SS :

1,840.00

L&K Auto Consultants hence notify
the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-confirmed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

Resid
Hp 90010018
4 days
p/p
29/10/19 @ 1715
Repay before paint

Total SS : 6,231.34


SIN SHENG ENGINEERING SERVICES

Nivitha (LKK Auto)

From: KENNY LIM CHING GHEE <kennylim@lonpac.com>
Sent: Friday, 25 October 2019 5:01 PM
To: 'sinsheng engineering services'; 'admin-a@lkkauto.com'; 'admin-d@lkkauto.com'
Cc: MT_Claim_SG
Subject: RE: Accident Involving GBF9340D with YN2069U on 22/10/2019 [External Confidential]
Attachments: SAS GBF9340D.PDF; GBF9340D_TP Search.pdf; GBF9340D_PRI.pdf

Lonpac External - Confidential

Dear Pei Jin

Noted and we will arrange accordingly.

Aside to Nivitha, please arrange for PRI – Surveyor: Mohd Rasul. FYI, our Insured has yet to report the accident. We are following up with them.

Best Regards

Kenny Lim
Asst. Claims Manager | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
DID: 6279 9256 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: sinsheng engineering services <sinsheng1981@gmail.com>
Sent: Friday, 25 October 2019 4:55 pm
To: KENNY LIM CHING GHEE <kennylim@lonpac.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: Re: Accident Involving GBF9340D with YN2069U on 22/10/2019 [External Confidential]

Hi Kenny,

We are selected Mohd Rasul. Thanks

Veh In. - Rasul

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You
Regards

Pei Jin

Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892
(Level 3_Office)
(Level 5_Workshop)
Tel: 6863 9595
Fax: 6863 6477

On Fri, 25 Oct 2019 at 16:51, KENNY LIM CHING GHEE <kennylim@lonpac.com> wrote:

Lonpac External - Confidential

Dear Pei Jin

Please refer to the attached email where we replied you yesterday.

Best Regards

Kenny Lim

Asst. Claims Manager | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

DID: 6279 9256 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: sinsheng engineering services <sinsheng1981@gmail.com>

Sent: Friday, 25 October 2019 4:39 pm

To: GERALD POH WEE BIN <geraldpoh@lonpac.com>; MT_Claim_SG <mt_claim@lonpac.com>

Subject: Fwd: Accident Involving GBF9340D with YN2069U on 22/10/2019

Dear Officer In charge,

We are repairer of motor vehicle GBF9340D. Enclosed Accident Statement and LTA search fee for your attention please. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two (2) workings days upon received this email.

Kindly let us have your list of 10 nominated surveyors to conduct the Single-Joint Inspection.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You

Regards

Pei Jin

Sin Sheng Engineering Services
No 8 Tuas Ave 18

Singapore 638892

(Level 3_Office)

(Level 5_Workshop)

Tel: 6863 9595

Fax: 6863 6477

----- Forwarded message -----

From: **sinsheng engineerservices** <sinsheng1981@gmail.com>

Date: Wed, 23 Oct 2019 at 17:02

Subject: Accident Involving GBF9340D with YN2069U on 22/10/2019

To: MT_Claim_SG <mt_claim@lonpac.com>

Dear Officer In charge,

We are repairer of motor vehicle GBF9340D. Enclosed Accident Statement and LTA search fee for your attention please. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two (2) workings days upon received this email.

Kindly let us have your list of 10 nominated surveyors to conduct the Single-Joint Inspection.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You
Regards

Pei Jin
Sin Sheng Engineering Services
No 8 Tuas Ave 18

Singapore 638892

(Level 3_Office)

(Level 5_Workshop)

Tel: 6863 9595
Fax: 6863 6477

Your Insured's vehicle : YN2069U
Our customer's vehicle : GBF9340D
Date : 23-Oct-19

LONPAC INSURANCE BHD

Dear Sirs,

DATE OF ACCIDENT : 22-Oct-19

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION/SURVEY & SEEK ATTENTION

We have been appointed by Goldbell Leasing Pte Ltd repair their vehicle no. GBF9340D.
Please be informed that the said vehicle can be inspected at :

Workshop : Sin Sheng Engineering Services
Address : No 8 Tuas Ave 18 (Level 5), Singapore 638892
Contact : Ms Susan
Tel / Fax : 6863 9595 / 6863 6477

Pursuant to ePractice Direction No 2 of 2011, we hereby give you notice to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday failing which we will commence repairs thereafter without any further notice or reference to you. Kindly acknowledge upon inspection in the acknowledgement box below. Alternatively kindly inform us in writing if you are waiving your rights to an inspection of our customer's vehicle.

NB. Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damage only and shall not preclude client's driver/passenger from claiming injury-related damage arising from this accident.

Your sincerely,

Lei Jin

TS

Acknowledgement

This is to confirm that I \[Full Name of Surveyor]
of \[Surveyor's Company]
have completed the pre-repair inspection on \[Date if Inspection]
at \[Time of Inspection]

Lei Jin

.....
Signature of Appointed Surveyor
Company Stamp

.....
Witnessed By:
Date

Waiver

We waive our rights to an inspection/survey of the above vehicle.

Signature
Name :
Date :

Mei Kwan (LKKAUTO)

From: KENNY LIM CHING GHEE <kennylim@lonpac.com>
Sent: Monday, 25 November, 2019 11:35 AM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG; Asher Sng (LKKAUTO); Admin A
Subject: RE: Accident Involving GBF9340D with YN2069U on 22/10/2019 [External Confidential]
Attachments: MRM49218747.PDF
Categories: HMK

Lonpac External - Confidential


Dear Mei Kwan

Please see attachment for a copy of our Insured's report and to proceed with direct settlement.

Thanks.

Best Regards

Kenny Lim
Asst. Claims Manager | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
DID: 6279 9256 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>
Sent: Tuesday, 19 November 2019 9:27 am
To: KENNY LIM CHING GHEE <kennylim@lonpac.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Accident Involving GBF9340D with YN2069U on 22/10/2019 [External Confidential]

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)
Sent: Tuesday, 5 November, 2019 10:22 AM
To: KENNY LIM CHING GHEE
Cc: MT_Claim_SG ; Asher Sng (LKKAuto) ; Admin A
Subject: RE: Accident Involving GBF9340D with YN2069U on 22/10/2019 [External Confidential]

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

LPC ref: TBA
LKK REF: CC4/LPC19019375/R1ea3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: GBF 9340D

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Please take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: KENNY LIM CHING GHEE <kennylim@lonpac.com>
Sent: Friday, 25 October, 2019 5:01 PM
To: 'sinsheng engineering services' <sinsheng1981@gmail.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: Accident Involving GBF9340D with YN2069U on 22/10/2019 [External Confidential]

Lonpac External - Confidential

Dear Pei Jin

Noted and we will arrange accordingly.

Aside to Nivitha, please arrange for PRI – Surveyor; Mohd Rasul. FYI, our Insured has yet to report the accident. We are following up with them.

Best Regards

Kenny Lim

Asst. Claims Manager | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

DID: 6279 9256 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: sinsheng engineering services <sinsheng1981@gmail.com>

Sent: Friday, 25 October 2019 4:55 pm

To: KENNY LIM CHING GHEE <kennylim@lonpac.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: Re: Accident Involving GBF9340D with YN2069U on 22/10/2019 [External Confidential]

Hi Kenny,

We are selected Mohd Rasul. Thanks

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You

Regards

Pei Jin

Sin Sheng Engineering Services

No 8 Tuas Ave 18

Singapore 638892

(Level 3_Office)

(Level 5_Workshop)

Tel: 6863 9595

Fax: 6863 6477

On Fri, 25 Oct 2019 at 16:51, KENNY LIM CHING GHEE <kennylim@lonpac.com> wrote:

Lonpac External - Confidential

Dear Pei Jin

Please refer to the attached email where we replied you yesterday.


Best Regards

Kenny Lim

Asst. Claims Manager | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

DID: 6279 9256 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: sinsheng engineerservices <sinsheng1981@gmail.com>

Sent: Friday, 25 October 2019 4:39 pm

To: GERALD POH WEE BIN <geraldpoh@lonpac.com>; MT_Claim_SG <mt_claim@lonpac.com>

Subject: Fwd: Accident Involving GBF9340D with YN2069U on 22/10/2019

Dear Officer In charge,

We are repairer of motor vehicle GBF9340D. Enclosed Accident Statement and LTA search fee for your attention please. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two (2) workings days upon received this email.

Kindly let us have your list of 10 nominated surveyors to conduct the Single-Joint Inspection.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You
Regards

Pei Jin
Sin Sheng Engineering Services
No 8 Tuas Ave 18

Singapore 638892

(Level 3_Office)

(Level 5_Workshop)

Tel: 6863 9595
Fax: 6863 6477

----- Forwarded message -----

From: **sinsheng engineerservices** <sinsheng1981@gmail.com>
Date: Wed, 23 Oct 2019 at 17:02
Subject: Accident Involving GBF9340D with YN2069U on 22/10/2019
To: MT_Claim_SG <mt_claim@lonpac.com>

Dear Officer In charge,

We are repairer of motor vehicle GBF9340D. Enclosed Accident Statement and LTA search fee for your attention please. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two (2) workings days upon received this email.

Kindly let us have your list of 10 nominated surveyors to conduct the Single-Joint Inspection.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You
Regards

Pei Jin

Sin Sheng Engineering Services
No 8 Tuas Ave 18

Singapore 638892

(Level 3_Office)

(Level 5_Workshop)

Tel: 6863 9595

Fax: 6863 6477

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Thursday, 5 December 2019 3:09 PM
To: sinsheng engineering services
Subject: RE: Accident Involving GBF9340D with YN2069U on 22/10/2019 [External Confidential]

'WITHOUT PREJUDICE' SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

88k 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 3(408933)



From: KENNY LIM CHING GHEE <kennylim@lonpac.com>

Sent: Friday, 25 October, 2019 5:01 PM

To: 'sinsheng engineeringservices' <sinsheng1981@gmail.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: RE: Accident Involving GBF9340D with YN2069U on 22/10/2019 [External Confidential]

Lonpac External - Confidential

Dear Pei Jin

Noted and we will arrange accordingly.

Aside to Nivitha, please arrange for PRI – Surveyor: Mohd Rasul. FYI, our Insured has yet to report the accident. We are following up with them.


Best Regards

Kenny Lim

Asst. Claims Manager | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

DID: 6279 9256 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: sinsheng engineeringservices <sinsheng1981@gmail.com>

Sent: Friday, 25 October 2019 4:55 pm

To: KENNY LIM CHING GHEE <kennylim@lonpac.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: Re: Accident Involving GBF9340D with YN2069U on 22/10/2019 [External Confidential]

Hi Kenny,

We are selected Mohd Rasul. Thanks

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You

Regards

Pei Jin

Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892
(Level 3_Office)
(Level 5_Workshop)
Tel: 6863 9595
Fax: 6863 6477

On Fri, 25 Oct 2019 at 16:51, KENNY LIM CHING GHEE <kennylim@lonpac.com> wrote:

Lonpac External - Confidential

Dear Pei Jin

Please refer to the attached email where we replied you yesterday.


Best Regards

Kenny Lim

Asst. Claims Manager | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

DID: 6279 9256 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: sinsheng engineeringservices <sinsheng1981@gmail.com>

Sent: Friday, 25 October 2019 4:39 pm

To: GERALD POH WEE BIN <geraldpoh@lonpac.com>; MT_Claim_SG <mt_claim@lonpac.com>
Subject: Fwd: Accident Involving GBF9340D with YN2069U on 22/10/2019

Dear Officer In charge,

We are repairer of motor vehicle GBF9340D. Enclosed Accident Statement and LTA search fee for your attention please. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two (2) workings days upon received this email.

Kindly let us have your list of 10 nominated surveyors to conduct the Single-Joint Inspection.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

*Thank You
Regards*

Pei Jin
*Sin Sheng Engineering Services
No 8 Tuas Ave 18*

Singapore 638892

(Level 3_Office)

(Level 5_Workshop)

*Tel: 6863 9595
Fax: 6863 6477*

----- Forwarded message -----

From: sinsheng engineeringservices <sinsheng1981@gmail.com>
Date: Wed, 23 Oct 2019 at 17:02
Subject: Accident Involving GBF9340D with YN2069U on 22/10/2019
To: MT_Claim_SG <mt_claim@lonpac.com>

Dear Officer In charge,

We are repairer of motor vehicle GBF9340D. Enclosed Accident Statement and LTA search fee for your attention please. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two (2) workings days upon received this email.

Kindly let us have your list of 10 nominated surveyors to conduct the Single-Joint Inspection.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

*Thank You
Regards*

Pei Jin
*Sin Sheng Engineering Services
No 8 Tuas Ave 18*

Singapore 638892

(Level 3_Office)

(Level 5_Workshop)

*Tel: 6863 9595
Fax: 6863 6477*




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC19019375/R1ea3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 17-03-2020	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 2069U	Veh. Inspected	GBF 9340D
Policy No.	Z/18/VC00/102913	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	KENNY	Assign Date	25/10/2019
2. Vehicle Particulars & Condition			
Make & Model	mitsubishi canter fea01	c.c	2998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	FEA01BA20565	Colour	RED
Odometer	89820	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	AUSTONE	7 mm
L/H Front Tyre	195 R15C	AUSTONE	7 mm
R/H Rear Tyre	195 R15C (D)	AUSTONE	7/7 mm
L/H Rear Tyre	195 R15C (D)	AUSTONE	7/7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/10/2019	Inspection Date	29/10/2019
Survey held at	NO 8 TUAS AVE 18		
Repairer	SIN SHENG ENGINEERING SERVICES		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 9340D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT PANEL	BENT	2,092.63	2,092.63
1	FUSO EMBLEM	NECESSARY	154.96	154.96
1	FRONT GRILLE	NOT NECESSARY	423.70	-
1	HEATER ASSY	NOT NECESSARY	2,584.78	-
1	BLOWER ASSY	CRACKED	599.05	599.05
	LESS 25% DISCOUNT		-1,463.78	-711.66
			4,391.34	2,134.98
LABOUR				
	TO DISMANTLE/REPAIR DASHBOARD.		280.00	150.00
	TO DISMANTLE/REPLACE BLOWER TO TOP-UP GAS.		180.00	100.00
	TO PANEL BEAT AND REPAIR FRONT BODY TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS.		750.00	550.00
	TO SPRAY PAINTING.		550.00	300.00
	TO APPLY TUFF KOTE.		80.00	40.00
			1,840.00	1,140.00
GRAND TOTAL			6,231.34	3,274.98
RECOMMENDED COST OF REPAIRS				3,274.98

Report Ref No. CC4/LPC19019375/R1ea3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.