

Veron Chen (LKKAUTO)

From: MTCL@income.com.sg
Sent: Friday, 8 November 2019 12:38 PM
To: Veron Chen (LKKAUTO)
Subject: FW: REQUEST FOR CLAIM NUMBER

Hi

All claim created

With Regards

Azlin Rani
Senior Administrator, Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Friday, 8 November 2019 8:33 AM
To: MTCL@income.com.sg
Subject: REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Kindly provides us claim number.

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle
1	MT/1069374-002	COMFORT TRANSPORTATION PTE LTD	SHA 6949Z	GBE 7396I

D.O.A	Time of Accident	Estimate	Tentative repair cost
31/10/19	11:45	\$9105.04	\$4405.12

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

eBaoTech

General Claim

Hello, NAC_PAYA_US1_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="31/10/2019 08:47"/>							
Vehicle No.(For Motor)	<input type="text" value="GBE7396L"/>	Certificate Number	<input type="text"/>							
<input type="button" value="Search"/>										
Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5088445993-02		SIM LIAN CONSTRUCTION CO. (PTE.) LTD.	197903750Z	GCV	Preferred Workshop Plan	GBE7396L	GBE7396L	16/03/2019	15/03/2020

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/10/2019 14:29
Date Of Accident	31/10/2019 11:45
Exact Location Of Accident	BANGKIT ROAD OPENSOURCE CARPARK CKB15 & CKB22
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA6949Z
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	IONIQ HYBRID
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	CHUA BOON LEONG
NRIC No	S1423942A
Date Of Birth	10/12/1960
Occupation	OUTDOOR
Date Of Driving Pass	11/12/1984
Driving Experience	34 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91081485
Fax Number	
Contact Number	
Email Address	WILLIAM4790@YAHOO.COM.SG

Address	BLK 508 JELAPANG ROAD #08-98
Postcode	670508
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE7396L
Vehicle Make/Model/Colour	NISSAN LORRY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RAMA SAMY KOLANJI NATHAN
NRIC/Passport Number	
Contact Number	91412374
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	LH CENTRE
No. Of Passenger (Including Driver)	

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CLARENCE INTERNATIONAL PTE LTD
600, HILL STREET, SINGAPORE

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

REPORTING CENTRE PERSONNEL'S SIGNATURE



SKETCH PLAN

A: SHIA 69492

B: GBE 7396L



CKBJ15A CKBJ22
Bonght Road Open Space Corporate

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 31/10/19 at about 11:45 hrs, my taxi
 van A was parked at above said location
 and I went to buy something. When I come
 back to collect taxi, I saw my taxi front
 right sustained badly damage and a note with
 contact number
 leave on windscreen. I called the person, he
 approached and admit his lorry hit onto my
 taxi when he try to avoid contact with
 other vehicle. Scene photo and exchange particulars
 No injury reported in this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

31/10/19

Enquire Transaction History



Transaction History Details

Log Date/Time:	03 Oct 2019 / 13:15:50		
Asset Type:	Vehicle	Transaction Amount:	\$7.49
Asset ID:	SLJ1646K		
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)	Channel:	External Agency
User ID:	ECENGCC0 - GOH CHENG CHUAN ANDREW CORNELIUS	Business Transaction Reference No.:	20191003131550545066
Search Date / Time:	01 Oct 2019 16:30:00		
Insurance Company:	LIBERTY INS P L		

Information displayed is correct as at the log date and time.

[Enquire Related Logs](#)

[Back to List](#)





Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305345600

OMER
S COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)


REGN NO.: SHA6949Z	MILEAGE
MAKE: HYUNDAI	FUEL E 1/2 F
MODEL: IONIQ(G2)	DATE/TIME IN 31.10.2019 13:25
YR OF MANU. 30.04.2019	TARGET DATE
CHASSIS CODE KMH851CVKU146258	COMPLETION DATE/TIME

UNIT CARD NO.

JOB DESCRIPTION

Accident Date: 31.10.2019
NATURE: 3P 31.10.19

S/NO LABOR CODE DESCRIPTION



LED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Idgement Slip

Exit Pass

SHA6949Z

JU NTUC LKK

Vehicle No.:

SHA6949Z

Service Advisor

Signature/Date

Name of Service Advisor

Date

ined to Service Reception upon collection

To be kept by Security Guard

REPAIR ESTIMATE*

VEHICLE NO : SHA 6949Z

DATE 31/10/2019 15:53

MAKE :

MODEL : HYUNDAI IONIQ

NTUC-JU.

PIP

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet X Repair			\$ 2,253.80
	Bonnet Lock X su			\$ 127.30
	Radiator Grille / cr			\$ 1,409.10
	Front Bumper Cover / cr			\$ 418.30
	Front Bumper Grille (RH) X / cr			\$ 186.90
	Front Bumper Centre Moulding / cr			\$ 188.00
	Front Bumper Moulding X su		\$ 93.60	\$ 187.20
	Front Bumper Lower Stiffener X su			\$ 85.10
	Front Bumper Lip X su			\$ 35.10
	Front Bumper Bracket Top (LH/RH) LH X su RH / cr		\$ 35.00	\$ 70.00
	Front Bumper Bracket (LH/RH) LH X su RH / cr		\$ 28.00	\$ 56.00
	Front Bumper Clips 10 pcs + m			\$ 22.00
	Headlamp Support Panel Assy X su			\$ 949.30
	Headlamp (LH/RH) LH X su RH / cr		\$ 1,198.80	\$ 2,397.60
	Front Fender (RH) - Bubbled			\$ 490.70
	Front Fender Retainer X su			\$ 41.40
	Emblem-Blue Drive (RH) - ne			\$ 26.60
	Wiper Container X su			\$ 61.90
	Wiper Container Motor X su			\$ 75.00
	SUB TOTAL			\$ 9,081.30
	LESS 20%			\$ 1,816.26
	DISCOUNTED TOTAL			\$ 7,265.04
	Front Fender Advertisement Logo (RH) ne			\$ 100.00
	Labour Charge			
	Panel Beating			\$ 700.00
	Spray Painting Charge			\$ 700.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Towing Charge			\$ 90.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	TOTAL LABOUR			\$ 1,740.00
	ESTIMATE TOTAL			\$ 9,105.04

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 07.11.2019
Time: 14:42:38
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305345600
REGN NO : SHA6949Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 30.04.2019
DATE/TIME IN : 31.10.2019 13:25
ACCIDENT DATE : 31.10.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2534-G	IONIQV2&3 COVER-FR BUMPER	1	418.30	20.00	334.64
0002 04-01-0104-2164-G	IONIQV1-3 GRILLE ASSY-RAD	1	1,409.10	20.00	1,127.28
0003 04-01-0104-3813-G	IONIQ EMBLEM-BLUE DRIVE L	1	26.60	20.00	21.28
0004 04-01-0104-0573-G	IONIQVC PANEL-FENDER RH#	1	490.70	20.00	392.56
0005 04-01-0104-3918-G	IONIQ BRACKET-FR BUMPER S	1	28.00	20.00	22.40
0006 04-01-0104-2915-G	IONIQV1-3 LAMP ASSY-HEAD	1	1,198.80	20.00	959.04
0007 04-01-0104-2361-G	IONIQV1-3 MOULDING-FRONT	1	188.00	20.00	150.40
0008 04-01-0104-2971-G	IONIQ BRACKET-FR BUMPER S	1	35.00	20.00	28.00
0009 04-01-0104-0634-G	IONIQ GRILLE-FRONT BUMPER	1	186.90	20.00	149.52

SUB-TOTAL : 3,185.12

JOB NATURE

0000 PB	PANEL BEATING	480.00
0001 SP	SPRAYPAINT CHARGE	600.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 07.11.2019

Time: 14:42:38

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305345600
REGN NO : SHA6949Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 30.04.2019
DATE/TIME IN : 31.10.2019 13:25
ACCIDENT DATE : 31.10.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0002 17-01	CHECK ALL LIGHTING	20.00		
0003 20-00	TUFF COAT ON AFFECTED PARTS.	20.00		
0004 20-05	RENEW ADVERTISMENT STICKER-	100.00		
		SUB-TOTAL	:	1,220.00
		TOTAL	:	4,405.12

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

Our Job Ref No 305345600

Date : 06/11/19

ComfortDelGro Engineering Pte Ltd
59 Luyang Drive Singapore 508969
Fax: 6548 8156

FINALIZATION FORM

To : LKK
Attn : KALVIN
: SHA6949Z

Fax :

31/10/2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- QBE7396L
###
2. The finalized amount shall be:


(a) Spare Parts after List discount		3185.12
(b) Labour Charges	###	1220.00
Total for Part-By-Part Repair Cost		4405.12
		###
- (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost


3. Estimated normal period for repairs: 3 working days

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature : 
Name : Kalvin
Date : 7/11/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19019382/K1vf3n2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 13-11-2019	
		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBE 7396L	Veh. Inspected	SHA 6949Z
Policy No.	5088445993-02	Coverage (\$)	0.00
Claim No.	MT/1069374-002	Excess (\$)	0.00
Assign From		Assign Date	01/11/2019
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHC851CVKU146258	Colour	BLUE
Odometer	82973	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	DAVANTI	9 mm
L/H Front Tyre	195/65 R15	DAVANTI	9 mm
R/H Rear Tyre	195/65 R15	DAVANTI	9 mm
L/H Rear Tyre	195/65 R15	DAVANTI	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	31/10/2019	Inspection Date	01/11/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 6949Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET	TO REPAIR SEE LABOUR	2,253.80	-
1	BONNET LOCK	SERVICEABLE	127.30	-
1	RADIATOR GRILLE	CRACKED	1,409.10	1,409.10
1	FRONT BUMPER COVER	CRACKED	418.30	418.30
1	FRONT BUMPER GRILLE (RH)	CRACKED	186.90	186.90
1	FRONT BUMPER CENTRE MOULDING	CRACKED	188.00	188.00
2	FRONT BUMPER MOULDING @\$93.60	SERVICEABLE	187.20	-
1	FRONT BUMPER LOWER STIFFNER	SERVICEABLE	85.10	-
1	FRONT BUMPER LIP	SERVICEABLE	35.10	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$35.00	O/S CRACKED / N/S SERVICEABLE	70.00	35.00
2	FRONT BUMPER BRACKET (LH/RH) @\$28.00	O/S CRACKED / N/S SERVICEABLE	56.00	28.00
10	FRONT BUMPER CLIPS	NOT NECESSARY	22.00	-
1	HEADLAMP SUPPORT PANEL ASSY	SERVICEABLE	949.30	-
2	HEADLAMP (LH/RH) @\$1198.80	O/S CRACKED / N/S SERVICEABLE	2,397.60	1,198.80
1	FRONT FENDER (RH)	BUCKLED	490.70	490.70
1	FRONT FENDER RETAINER	SERVICEABLE	41.40	-
1	EMBLEM-BLUE DRIVE (RH)	NECESSARY	26.60	26.60
1	WIPER CONTAINER	SERVICEABLE	61.90	-
1	WIPER CONTAINER MOTOR	SERVICEABLE	75.00	-
	LESS 20% DISCOUNT		-1,816.26	-796.28
			7,265.04	3,185.12
<u>SPECIAL NETT ITEMS</u>				
1	FRONT FENDER ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
			100.00	100.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BONNET.		700.00	480.00

Report Ref No. NS/INC19019382/K1vf3n2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING CHARGE.		700.00	600.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.		50.00	20.00
	TOWING CHARGE.		90.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	150.00	-
			1,740.00	1,120.00
GRAND TOTAL			9,105.04	4,405.12

RECOMMENDED COST OF REPAIRS (CONFIRMED)				4,405.12
---	--	--	--	----------

Report Ref No. NS/INC19019382/K1vf3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.