

22482002

ASS. REC. BY:

REF:

C/TE019019394/PV

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Kamalish Kamis

of

SPF

Date/Time: 3/11/2019

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY/CS

To Inspect Vehicle No: XE 15313

Insured:

at Workshop m/s

Tel:

of

Policy No: MHASPF06000038124/1

Claim No:

TP/IP/67665/2019

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 2/11/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction Estimate ( )

New case

Sherwin.

Thank you.

V15 for lot

## Sherwin Beh (LKK Auto)

**From:** Kamaliah KAMIS (SPF) <Kamaliah\_KAMIS@spf.gov.sg>  
**Sent:** Sunday, 3 November, 2019 10:40 PM  
**To:** Sherwin Beh (LKK Auto); Naz (LKKAuto)  
**Cc:** Bryan Ang (LKKAuto)  
**Subject:** Mechanical Inspection Report Request [URGENT]

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the following **1 vehicle** on an urgent basis as the vehicle below are required to be returned to the owner ASAP:

a) **Case IAFP-IB-20191102 - Mechanical Inspection of Motor Lorry, XE1531S (TP/IP/67665/2019)**

On 2 November 2019 (Saturday) at about 8.18 a.m., the Deceased on his motorcycle was travelling along the exit of Woodlands Avenue 2 from SLE (CTE), directly behind the Involved Party's motor lorry. The Deceased had swerved to his right side and was believed to be trying to overtake the Involved Party's motor lorry from the right side. As the Deceased was approaching the right rear side of the Involved Party's motor lorry, the left side of the Deceased's motorcycle side-swiped the right rear side of the motor lorry. Due to the impact, the Deceased skidded together with his motorcycle and landed behind the motor lorry. The Witness was unsure if the Deceased was run over by the Involved Party's motor lorry but confirmed that the Involved Party was within his lane and did not veer left or right before the collision occurred. As a result of the accident, the Deceased sustained multiple injuries and was pronounced dead at the scene by the attending Paramedic Nur Azhar at 8.30 a.m.

**Vehicle to be inspected:** XE1531S - Driver (Involved Party)

IO In-Charge: SIO Kamaliah

2. Thank you Sirs.

cc: Bryan, fyip

Best regards,

Kamaliah Kamis (Miss)  
Senior Investigation Officer | Fatal Accident Investigation Team  
Traffic Police Department | Singapore Police Force  
DID: (65) 6547 6435 | FAX: (65) 6547 6352



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."