

ASS. REC. BY:

REF:

CS/AGI19019415/KV2312

Special Instruction:

Surveyor: KmshASSIGNMENT (Office)From (Person): Julieat AGIDate/Time: 1/11/2019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 8LV1049XInsured: 868 65818at Workshop m/c Lim Tan MotorTel: 64520893of Blk 176 Sin Ming Drive #03-09

Policy No: _____

Claim No: C10004435

Sum Insured: _____

Excess: _____

Make of Veh:

(Client's Record)

D.O.A. 26/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endowment: _____

Date/Time: 4/11Person Contacted: NandyVehicle IN/OUT OUT

Date/Time

Action/Instruction Estimate (✓)8LV1049X - X86865818 - X25/11 11 Lp 8200d Confirm (Red 2137.85, 570)

ASSIGNMENT

From: Date: 10.2.2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLV 1049X

at Workshop m/s Lim Tan motor

of BK 176 sin my drive #103-09

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: After 11.00.00

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLV 1049X yr Regn: 05 15

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Beetle c.c. 1197

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 59352 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WUV 228162FM 620565

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: R: 235/45 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 26/10/2019

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 25 MAR 2020

Date/Time, File Pass 1/2

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return 1/2

2) 25/3 - typist

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Insp (\$

☐ Misc. and (\$

Survey Fee:

Transportation:

3 = PS. \$

Phone:

Other:

TOTAL

250

Report Form:

TP

Lump Sum / Fee: 2000/-

Nivitha (LKK Auto)

From: Claims <claims@budgetdirect.com.sg>
Sent: Friday, 1 November 2019 5:43 PM
To: Nivitha (LKK Auto); SUR
Subject: FW: Survey Request - Our Client : SLV1049X Your Insured : SGS6581S D.O.A : 26/10/2019 || C10004435

On behalf of Logan

Hi Team

We would like to appoint LKK to survey third party client on a without prejudice basis.
TP workshop would like to choose Kenneth Kong as their surveyor.

Thank you,
-Julie

From: Mandy <mandy@ltm.sg>
Sent: Friday, 1 November, 2019 3:28 PM
To: Ivy Ratilla <ivy.r@budgetdirect.com.sg>; Claims <claims@budgetdirect.com.sg>
Cc: venus@ltm.sg; Loganathan Agoram <loganathan.a@budgetdirect.com.sg>
Subject: RE: Survey Request - Our Client : SLV1049X Your Insured : SGS6581S D.O.A : 26/10/2019 || C10004435

WITHOUT PREJUDICE

Dear Ivy,

We will choose **Kenneth Kong LKK Auto Consultants Pte Ltd** to conduct the pre-repair survey.

Pls give your assignment to LKK and we will arrange the appointment with LKK accordingly.

Pls revert this case is a direct settlement and kindly let us have your officer-in-charge's contact.

Thank you and regards,

Mandy Lim

Lim Tan Motor Pte Ltd

[www. LTM.sg](http://www.LTM.sg)
+65 6452 0893 (Office)
+65 6458 9127 (Facsimile)

Like us in Facebook!!

www.facebook.com/LTMsg
www.facebook.com/LTM.Performance.Singapore

Vehi Out



LIM TAN MOTOR PTE LTD 林陈摩哆私人有限公司

COMPANY REGISTRATION NO: 199307277D GST REGISTRATION NO: M2-0119086-0

MAIN OFFICE / WORKSHOP

BLK 176 SIN MING DRIVE
SIN MING AUTOCARE #03-09/10/06
SINGAPORE 575721

TEL: +65 6452 0893 FAX: +65 6458 9127

BRANCH

BLK 9 SECTOR C #01-38/40/42
SIN MING INDUSTRIAL ESTATE
SINGAPORE 575644

TEL: +65 6452 2135 FAX: +65 6452 2159

EMAIL: SALES@LTM.SG

Operating Hours: Mon – Fri 9am – 6 pm

Sat 9am – 5pm



24hrs Helpline: +65 64520893

WWW.LTM.SG

IMPORTANT NOTICE

This email, including all attachments may contain confidential or legally privileged information.

The sending of this email to any person other than the intended recipient is not a waiver of confidentiality or privilege of the information. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of the company.

From: Ivy Ratilla [<mailto:ivy.r@budgetdirect.com.sg>]

Sent: Thursday, 31 October, 2019 3:46 PM

To: Mandy <mandy@ltm.sg>; Claims <claims@budgetdirect.com.sg>

Cc: venus@ltm.sg; Loganathan Agoram <loganathan.a@budgetdirect.com.sg>

Subject: RE: Survey Request - Our Client : SLV1049X Your Insured : SGS6581S D.O.A : 26/10/2019 || C10004435

WITHOUT PREJUDICE

Dear Sir/Ma'am

With regards to your email below,

Please find the list of your surveyors to choose from.

1. Philip Phoong A-PAC Adjusters & Surveyors Pte Ltd
2. Siew Meng Hui A-PAC Adjusters & Surveyors Pte Ltd
3. Muammar Gaddafi Bin Marzuki A-PAC Adjusters & Surveyors Pte Ltd
4. Xing Guo Qiang LKK Auto Consultant Pte Ltd
5. Mohammed Rasul LKK Auto Consultants Pte Ltd
6. Mohamad Taufihk LKK Auto Consultants Pte Ltd
7. Adrian Ling LKK Auto Consultants Pte Ltd
8. Marcus Chua LKK Auto Consultants Pte Ltd
9. Kenneth Kong LKK Auto Consultants Pte Ltd
10. Pang Kiah Keen (Frankie) FormTeam Adjusters Pte Ltd
11. Chua Soo Teck (Benjamin) FormTeam Adjusters Pte Ltd

12. Lim Say Koon FormTeam Adjusters Pte Ltd
13. Ng You Han FormTeam Adjusters Pte Ltd
14. Soon HanXin (Gary) FormTeam Adjusters Pte Ltd
15. Chow Bo Xiong FormTeam Adjusters Pte Ltd
16. Derrick Quok – in house surveyor

Kindly let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Mandy <mandy@ltm.sg>
Sent: Thursday, 31 October 2019 3:11 PM
To: Claims <claims@budgetdirect.com.sg>

Cc: venus@ltn.sg

Subject: RE: Survey Request - Our Client : SLV1049X Your Insured : SGS6581S D.O.A : 26/10/2019

WITHOUT PREJUDICE

Good Afternoon Sir / Madam,

We are assisting our mutual client the vehicle owner of **SLV 1049 X** to submit a claim against your insured, **SGS 6581 S** which we understand that you are insurer at the material time of the accident.

We now enclosed the following documents for your easy reference :

- Our client's GIA report
- Repair Estimate
- LTA Search result

Please let us have a list of your external surveyor for us to choose.

Thank you and regards,

Mandy Lim

Lim Tan Motor Pte Ltd

[www. LTM.sg](http://www.LTM.sg)

+65 6452 0893 (Office)

+65 6458 9127 (Facsimile)

Like us in Facebook!!

www.facebook.com/LTMsg

www.facebook.com/LTM.Performance.Singapore



LIM TAN MOTOR PTE LTD 林陈摩哆私人有限公司

COMPANY REGISTRATION NO: 199307277D GST REGISTRATION NO: M2-0119086-0

MAIN OFFICE / WORKSHOP

BLK 176 SIN MING DRIVE
SIN MING AUTOCARE #03-09/10/06
SINGAPORE 575721

TEL: +65 6452 0893 FAX: +65 6458 9127

BRANCH

BLK 9 SECTOR C #01-38/40/42
SIN MING INDUSTRIAL ESTATE
SINGAPORE 575644

TEL: +65 6452 2135 FAX: +65 6452 2159

EMAIL: SALES@LTM.SG

Operating Hours: Mon – Fri 9am – 6 pm

Sat 9am – 5pm



24hrs Helpline: +65 64520893

WWW.LTM.SG

IMPORTANT NOTICE

This email, including all attachments may contain confidential or legally privileged information.

The sending of this email to any person other than the intended recipient is not a waiver of confidentiality or privilege of the information. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of the company.



Virus-free. www.avg.com

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised. This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

Veron Chen (LKKAUTO)

From: motor claims Dept <motorclaims@lrm.sg>
Sent: Thursday, 19 March 2020 12:43 PM
To: Kenneth Kong (LKKAUTO); Veron Chen (LKKAUTO)
Cc: 'Mandy'; 'venus'
Subject: Finalisation - SLV 1049 X
Attachments: DSCN2332.jpg; DSCN2333.jpg; DSCN2334.jpg; DSCN2335.jpg; DSCN2336.jpg; 1371_001 (002).tif

WITHOUT PREJUDICE

Dear Mr Kenneth,

The above survey refers.

Please confirm finalisation at **LS \$2,000.00** with a repair period of **2-working days**.

Please revert.

Thank you and regards,

Tina

Motor Claim Department

www.LTM.sg

+65 6452 0893 (Office)

+65 6458 9127 (Facsimile)

+65 8484 5418 (Mobile)

Like us in Facebook!!

www.facebook.com/LTMsg

www.facebook.com/LTM.Performance.Singapore



LIM TAN MOTOR PTE LTD 林陈厚珍私人有限公司

COMPANY REGISTRATION NO: 199807277D GST REGISTRATION NO: S42-0113086-0

MAIN OFFICE / WORKSHOP

BLK 179 SIN MANG DRIVE
SIN MANG AUTOCARE #01-08/10/06
SINGAPORE 575721

TEL: +65 6452 0893 FAX: +65 6458 9127

EMAIL: SLV@LTM.SG

Operating Hours: Mon - Fri 9am - 6 pm

Sat 9am - 5pm

24hrs Helpline: +65 64520893

WWW.LTM.SG

BRANCH

BLK 9 SECTOR C #01-08/40/42
SIN MANG INDUSTRIAL ESTATE
SINGAPORE 575644

TEL: +65 6452 2135 FAX: +65 6452 2139



IMPORTANT NOTICE

This email, including all attachments may contain confidential or legally privileged information.

The sending of this email to any person other than the intended recipient is not a waiver of confidentiality or privilege of the information. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of the company.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	992J

Vehicle Details

Vehicle No.:	SLV1049X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Oct 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	BEETLE 1.2 TSI AT 5C13D5
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	CBZH40297
Chassis No.:	WVWZZZ16ZFM620565
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$19,514.00
Original Registration Date:	29 May 2015
First Registration Date:	29 May 2015
Transfer Count:	1
Actual ARF Paid:	\$9,514.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 May 2025
PARF Rebate Amount:	\$7,135.00

Intended COE Rebate Details

COE Expiry Date:	28 May 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,590.00
COE Rebate Amount:	\$37,144.00
Total Rebate Amount:	\$44,279.00

The information contained herein is correct as at 29 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/10/2019 16:58
Date Of Accident	28/10/2019 10:55
Exact Location Of Accident	UPPER PAYA LEBAR ROAD TOWARDS EUNOS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV1049X
Insured/Policyholder	
Name Of Registered Owner	R SOBAHNA
NRIC No	S1657992J
Email Address	SHOBANA_6@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96848991
Alternative Phone No	OFFICE-96848991
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	BEETLE-1.2 TSI (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5109767316
Cover Note Number	
Driver	
Name of Driver	R SOBAHNA
NRIC No	S1657992J
Date Of Birth	06/06/1964
Occupation	INDOOR
Date Of Driving Pass	04/10/1991
Driving Experience	28 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96848991
Fax Number	
Contact Number	OFFICE-96848991
Email Address	SHOBANA_6@HOTMAIL.COM

Address:	APT BLK 211 SERANGOON AVENUE 4, SINGAPORE
Postcode:	550211
Was driver an employee of the Insured's Company?	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident:	CHAIN COLLISION
Weather Conditions:	CLEAR
Road Surface:	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NEVER NOTE DOWN
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I, Veh A was travelling along Upper Paya Lebar Road on the most right lane when the vehicle in front stopped. I braked in time and Veh B also braked in time. However, Veh C could not stop in time and hit into Veh B. Veh B was being pushed forward and hit my car rear. Nobody was injured. There's roadworks in process.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGS6581S
Vehicle Make/Model/Colour	TOYOTA WISH
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHEW YEW TECH
NRIC/Passport Number	S8103604G
Contact Number	91169184
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SDZ8359D
Vehicle Make/Model/Colour	VOLVO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JERRY
NRIC/Passport Number	S6826848F
Contact Number	96785959
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date
& Time

Driver's Signature
(If driver is not the policyholder) Date
& Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN

Date & Time of Accident: 26/10/2019, 10:58 AM Location: UPPER DAYA LEBAR ROAD TOWARDS
 Veh A: SLV 1049X Veh B: SGS 65B/S Veh C/Others: SDZ 0359D

500
44
100



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I, VEH A WAS TRAVELLING ALONG UPPER DAYA LEBAR ROAD ON THE MOST RIGHT LANE WHEN THE VEHICLE IN FRONT, STOPPED. I BRAKED IN TIME AND VEH B ALSO BRAKED IN TIME. HOWEVER, VEH C COULD NOT STOP IN TIME AND HIT INTO VEH B. VEH B WAS BEING PUSHED FORWARD AND HIT MY CAR REAR. NOBODY WAS INJURED THERE'S ROAD WORK IN PROGRESS. PROCESS.

☐ Own Damage Claim at Lim Tan Motor ☒ TP Claim at Lim Tan Motor
☐ Own Damage Claim at Other Workshop ☐ TP Claim at Other Workshop ☐ Reporting Only

I/We hereby authorised Lim Tan Motor Pte Ltd to forward my/our filed GIA accident report to:-

My/Our workshop via email: _____

My/Our email: _____


DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature Date
 & Time

Driver's Signature
 (If driver is not the policyholder) Date
 & Time:




 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

ESTIMATE TO REPAIR

VEHICLE NO. : SLV 1049 X
 MAKE : VOLKSWAGON
 MODEL : BEETLE-1.2 TSI (A)
 YEAR : 2014
 CHASSIS NO : WVVZZZ16ZFM620565

SURVEYOR NAME : *Kenneth (LKK)*
 DATE OF SURVEY : *10.02.2020*
 TIME OF SURVEY :

DATE : 31-Oct-19
 DATE OF ACCIDENT: 26-Oct-19
 THIRD PARTY REF : SGS6581S / AUTO & GENERAL

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 PC	REAR BUMPER			<i>Be R</i> \$ 2,055.35	✓
1 PC	REAR BUMPER REINFORCEMENT			\$ <i>Net</i> 685.15	X
1 PC	REAR BUMPER LOWER SPOILER			\$ <i>Net</i> 217.05	✓
2 PC	REAR BUMPER RETAINER		\$ 155.15	\$ <i>Be</i> 310.30	X
1 PC	REAR BUMPER SENSOR	S.Nett		\$ <i>Be</i> 280.00	X
1 PC	REAR BUMPER PLATE	S.Nett		\$ <i>Net</i> 40.00	✓
	TO PUTTY & SPRAY PAINT.			\$ 300.00	22cl
	LABOUR CHARGES.			\$ 250.00	20cl
TG/ML	TOTAL				\$ 4,137.85
<p><i>Not Notified</i> <i>Returning After Paying</i> <i>2 days</i></p> <div> <p>LKK Auto Consultants hereby notify the Reparer of the following:</p> <ul style="list-style-type: none"> • To return to the Reparer the survey report • To display damaged parts to the surveyor • Parts prices are subject to confirmation • Third party survey is on a "Joint Practical" basis • No illegal modification is allowed • Supplementary items must be surveyed and is subject to final approval from Insurance Company <p>Acknowledged by Reparer Signature: Date:</p> </div>					

ESTIMATE TO REPAIR

VEHICLE NO. : SLV 1049 X
 MAKE : VOLKSWAGON
 MODEL : BEETLE-1.2 TSI (A)
 YEAR : 2014
 CHASSIS NO : WVWZZZ16ZFM620565

SURVEYOR NAME : Kenneth (LKK)
 DATE OF SURVEY : 10.02.2020
 TIME OF SURVEY :

DATE : 31-Oct-19
 DATE OF ACCIDENT : 26-Oct-19
 THIRD PARTY REF : SGS6581S / AUTO & GENERAL

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 PC	REAR BUMPER			<i>Be</i>	\$ 2,055.35
1 PC	REAR BUMPER REINFORCEMENT				\$ 885.15
1 PC	REAR BUMPER LOWER SPOILER				\$ 217.05
2 PC	REAR BUMPER RETAINER		\$ 155.15		\$ 310.30
1 PC	REAR BUMPER SENSOR	S.Nett			\$ 280.00
1 PC	REAR BUMPER PLATE	S.Nett			\$ 40.00
	TO PUTTY & SPRAY PAINT.				\$ 300.00
	LABOUR CHARGES.				\$ 250.00
TG/ML	TOTAL				\$ 4,137.85
<i>Not Notified</i> <i>Returning After Paying</i> <i>2 days</i>					<i>2272.80</i> <i>-10% 227.28</i> <i>2045.16</i> <i>SN 40.00</i> <i>420.00</i> <i>2505.16</i> <i>Insur \$ 2000</i> <i>12/1/20</i> <i>APPROVED</i>

Lim Tan Motor Pte Ltd
 Blk 175 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel: 65-64520893 Fax: 65-64589127 Email: edmund@lmtm.sg
 Co. Reg No. 199307277D GST Reg No. M2-0019006-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI19019415/Kvf3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRES SINGAPORE

239924

Date : 27-03-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGS 6581S	Veh. Inspected	SLV 1049X
Policy No.		Coverage (\$)	0.00
Claim No.	C10004435	Excess (\$)	0.00
Assign From	JULIE	Assign Date	01/11/2019

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN BEETLE (A)	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WWZZZ16ZFM620565	Colour	RED
Odometer	59352	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/45 R18	DUNLOP	6 mm
L/H Front Tyre	235/45 R18	DUNLOP	6 mm
R/H Rear Tyre	235/45 R18	DUNLOP	5 mm
L/H Rear Tyre	235/45 R18	DUNLOP	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	26/10/2019	Inspection Date	10/02/2020
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 1049X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BUCKLED	2,055.35	2,055.35
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	685.15	-
1	REAR BUMPER LOWER SPOILER	DENTED	217.05	217.05
2	REAR BUMPER RETAINER @\$155.15	SERVICEABLE	310.30	-
	LESS 10% DISCOUNT		-	-227.24
			3,267.85	2,045.16
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER SENSOR (SN)	SERVICEABLE	280.00	-
1	REAR BUMPER PLATE (SN)	DENTED	40.00	40.00
			320.00	40.00
<u>LABOUR</u>				
	TO PUTTY & SPRAY PAINT.		300.00	220.00
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT.		250.00	200.00
			550.00	420.00
GRAND TOTAL			4,137.85	2,505.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CS/AGI19019415/Kvf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.