

22/07/2002

ASS. REC. BY:

REF: CS/MSG1909430/Evf3n2

Special Instruction:

Surveyor: Said

ASSIGNMENT (Office)

From (Person): Mund Asit B Madiof MSLGDate/Time: 4.11.19 12.59 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SKZ 8128x

Insured:

GBA 7609U

at Workshop m/s

Auto Insure

Tel:

3157 2626 | 3157 2628of 6 Marsling LanePolicy No: 29082432Claim No: 609830

Sum Insured:

Excess:

Make of Veh:

D.O.A. 26.10.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 4.11.19 2.20 p.m

Person Contacted:

Sam Goh

H.O.D. Endorsement:

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SKZ 8128x - X</u>
	<u>GBA 7609U - X</u>
<u>5/11/19</u>	<u>Send preli revised via merimen</u>

Surveyor

Steve

REF:

MSG

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SKZ 8128 X Yr Regn: 16/12/15
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trallor or
 Make: Honda Vezel C.C. 1496
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 139226 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RU 11107313
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: NII / S/Rim / STD A/Rim or
 Tyre Size: F: 215 / 60R16
 R: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kunho

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

Front: _____ Rear: _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 26/10/19 D.O.I. 4/11/19

CA / REV / REP. / 24 HRS

Survey held at Auto Insure

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV- S9K

STEVE

2/12/19 Final Rpt (\$3950), 5 days (Perm) (Red 7519.52, 669)

RECEIVED 2 DEC 2019

Date/Time, File Pass to?

☐

: Proll. Report

Days Of Repair: 5

1)

☐

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2) 2/12 - typist

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Insp (\$

☐

: Weekend (\$

Report Format :

menimen

Lump Sum / I.B.I. (\$

3950/2

Survey Fee:

Transportation:

: \$ - RS. - SI

: Pledge

: Others

TOTAL

300

11

211

LKK Auto Consultants Pte Ltd (Co.Reg.No:198607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
---	--

Attn: Muhd Ashik B Madi

Date: 05 Nov 2019

Preliminary Advice

Insured Vehicle No	: GBA7609U	Accident Date	: 26/10/2019
TP Vehicle No	: SKZ8128X	Assignment Date	: 04/11/2019
Make	: HONDA VEZEL	Est. Duration of Repair	: 5.00
Date of Inspection	: 04/11/2019		
Inspection At	: AUTO INSURE PTE LTD (HQ) 6 MARSILING LANE SINGAPORE 739145		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,469.52
Revised Amount	:S\$	6,377.60
Check Items (Estimated)	:S\$	576.00
Total	:S\$	6,953.60

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Oct 2019		04 Nov 2019 13:59 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SAMWOH PREMIX PTE LTD, Co. Reg. No.: 199703387Z								
Main Claimant:	HONG BOON PUN, ID: S7574014Z								
Vehicle Reg. No.:	SKZ8128X	Date of Loss:	26/10/2019 15:00 - :59 [46 Months and 10 Days From LTA Reg Date (Mon Yr)]						
Claim Type:	TP / 609830	Policy/Cover Note No.:	29082433 (Third Party Only) Coverage: 17/06/2019 - 16/06/2020						
Vehicle Reg. No. (Insured):	GBA7609U	Policy No. (Claimant):							
		Excess:							
Repairer:	Auto Insure Pte Ltd (HQ) 6 Marsiling Lane, 739145 Woodlands - Tel: 3157 2626								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/11/2019]								
Driver/Custodian (Insured):	ASHWANI KUMAR (), NRIC: G8237553N, Tel: +6582601082 Email:								
Adj Asg. Remarks:	on WP. Please arrange survey ASAP. OI:Samwoh. Lieb: clear. Agree on SJE. Contact: Sam Goh @ 9743 6363 / 3157 2624 / 3157 2628.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Steve Chen (LKK Auto)

From: AutoInsure (Claims) <claims01@autoinsure.com.sg>
Sent: Saturday, November 30, 2019 1:27 PM
To: Steve Chen (LKK Auto)
Cc: Veron Chen (LKKAuto)
Subject: Re: SKZ8128X Finalize

WITHOUT PREJUDICE

Dear Steve,

We refer to the above matter and email below.

We confirm finalization amount at \$3950.00

Thank You.

Regards

Sam Goh
did: (65) 3157 2624 / 3157 2628
mobile: (65) 9743 6363
e: claims01@autoinsure.com.sg

Auto Insure Pte. Ltd.
201437380M
6 Marsiling Lane S739145

t: (65) 3157 2626
f: (65) 6368 0081
w: www.autoinsure.com.sg
g.e: claims@autoinsure.com.sg

-- Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail.--

Data Privacy Policy Notice: Auto Insure Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

On Wed, Nov 27, 2019 at 8:46 AM Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Sir,

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	014Z
Vehicle Details	
Vehicle No.:	SKZ8128X
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	L15B4027316
Chassis No.:	RU11107313
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,193.00
Original Registration Date:	16 Dec 2015
First Registration Date:	16 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$9,193.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Dec 2025
PARF Rebate Amount:	\$6,894.00
Intended COE Rebate Details	
COE Expiry Date:	15 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,989.00
COE Rebate Amount:	\$34,836.00
Total Rebate Amount:	\$41,730.00

The information contained herein is correct as at 04 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/10/2019 10:38
Date Of Accident	26/10/2019 13:30
Exact Location Of Accident	BLK 346 TAMPINES ST 34 CARPARK EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ8128X
Insured/Policyholder	
Name Of Registered Owner	HONG BOON PUN
NRIC No	S7574014Z
Email Address	FERDINAND.HONG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98312011
Alternative Phone No	OFFICE-88232626

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 X (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00433676/01
Cover Note Number	

Driver

Name of Driver	NGIO SOI CHING
NRIC No	S7972229D
Date Of Birth	04/02/1979
Occupation	INDOOR
Date Of Driving Pass	27/09/2003
Driving Experience	16 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97711619
Fax Number	
Contact Number	OFFICE-88232626
Email Address	FERDINAND.HONG@GMAIL.COM

Address	BLK 323 TAMPINES ST 33 #05-156
Postcode	520323
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : MALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WHILE I WAS WAITING FOR MY TURN TO EXIT THE CARPARK, VEHICLE B SUDDENLY REVERSE AND HIT ONTO MY VEHICLE FRONT PORTION. MY VEHICLE SUFFER DAMAGES FROM THIS ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA7609U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ASHWANI KUMAR
NRIC/Passport Number	G8237553N

- Contact Number
- Address
- Postcode
- Insurance Company Name
- Nature Of Damage
- No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

26 Oct 2019
1505 hrs


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: MAM Siew Hwa
NRIC/FIN No.:

S8208780E

Sketch Plan #2

SKETCH PLAN



VEH A
- SKZ 8128X

VEH B
- GBA 7609U

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While I was waiting for my turn to exit the carpark, Vehicle B suddenly reverse and hit onto my vehicle front portion. My vehicle suffer damages from this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 26 Oct 2019
1506 hrs.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: MAH SIEW HSIUNG
NRIC/FIN No.: S8208788E



Auto Insure Pte. Ltd.
6 Marsiling Lane
Singapore (739145)
E: claims01@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 3157 2626 F: 6368 0081
GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: **SKZ8128X**

Your Ref: **GBA7609U**

Date: **29-Oct-19**

BY EMAIL ONLY
(claims01@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

Email: claims@sg.msig-asia.com

MSIG INSURANCE

4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Assessed Vehicle No : **SKZ8128X**
Car Make and Model : **HONDA VEZEL-1.5 S (A)**
Date of Accident : **26-Oct-19**
Date of Assessment : **29-Oct-19**

We have carried out a physical assessment of SKZ8128X at our workshop Auto Insure Pte Ltd sustained damages to the FRONT LH portion of the vehicle.


4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the FRONT LH portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : L/S
Adjusted Amount : \$ **12,272.39**
Est. Repair Days : 10



Pursuant to your instruction, we have **NOT AUTHORIZED** repair.
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatever shall be held by
AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: SKZ8128X

Your Ref: GBA7609U

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
PARTS REPLACEMENT - LIST ITEMS				
1	1	FRONT BUMPER / OR		\$ 801.70 / 1,355.00
2	1	FRONT BUMPER SIDE RETAINER LH / OR		\$ 59.00 /
3	1	FRONT BUMPER SIDE RETAINER RH / OR		\$ 59.00 /
4	1	FRONT BUMPER LOWER SKIRT X NAI		\$ 559.00
5	1	BONNET ASSY / DO		\$ 1020 / 1,200.00
6	1	BONNET HINGE LH / DT		\$ 50 / 105.00
7	1	BONNET HINGE RH / DT		\$ 50 / 105.00
8	1	RADIATOR GRILL ASSY / OR		\$ 850.00 /
9	1	RADIATOR GRILL HONDA LOGO / MC		\$ 45 / 110.00
10	1	RADIATOR GRILL TOP GARNISH X NAI		\$ 250.00
11	1	FRONT REINFORCEMENT BAR X NAI		\$ 720.00
12	1	RADIATOR ASSY X NAI		\$ 1,300.00
13	1	AIR CON CONDENSOR ASSY X NAI		\$ 900.00
14	1	FRONT FENDER LH X R		\$ 735.00
15	1	FRONT FENDER INNER SHIELD LH X NAI		\$ 265.90
16	1	FRONT FENDER WHEEL ARCH LH X NAI		\$ 235.00
17	1	FRONT WHEEL HOUSING LH X NAI		REPAIR
18	1	HEADLAMP LH / OR		\$ 1759.10 / 2,354.00
19	1	FRONT DOOR LH X NAI		REPAIR
			SUB TOTAL	\$ 11,161.90
			LESS 20%	\$ 2,232.38
			TOTAL AMOUNT	\$ 8,929.52

4693.80
- 25%
3520.35

Our Ref: SKZ8128X

Your Ref: GBA7609U

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	FRONT NUMBER PLATE WITH HOLDER	✓	\$ 80.00
2	1	FRONT BUMPER CLIPS	✓	\$ 80.00
3	2	RADIATOR COOLANT	✓	\$ 60.00
4	1	AIR CON GAS	✓	\$ 90.00
			SUB TOTAL	\$ 310.00
			TOTAL PARTS COST	\$ 9,239.52

Our Ref: SKZ8128X

Your Ref: GBA7609U

S/NO	DESCRIPTION	EST. BY WORKSHOP
LABOUR & PAINTWORK		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 1,000.00
2	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	\$ 250.00
3	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 100.00
4	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 800.00
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ 80.00
TOTAL BEFORE GST		\$ 11,469.52
GST 7%		\$ 802.87
TOTAL (PARTS & LABOUR):		\$ 12,272.39

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$ 12,272.39 for LUMP SUM with the third party insurance.

Yours Faithfully,

Jason Heng
Claims Director

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1360
P-3520.35
M-60
L-1360
4940.35
L/S-3952.28
= 3950

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19019430/EVF3N2

Date: 03/12/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29082433
Claimant Vehicle No :	SKZ8128X	Insured Vehicle No :	GBA7609U
Date of Loss:	26/10/2019	Nature of Claim:	TP
		Claim No:	609830

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ8128X	Engine No:	L15B4027316
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU11107313
Reg. Date:	16/12/2015 (Man. Year: 2015)	Odometer:	139226 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,239.52	3,580.35	5,659.17	61.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,230.00	1,360.00	870.00	39.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,469.52	4,940.35	6,529.17	56.93
Approved Total (Overridden) (\$\$)		3,950.00		
(\$\$)	11,469.52	3,950.00	7,519.52	65.56
+ GST 7.00/7.00% (\$\$)	802.87	276.50	526.37	65.56
Nett Amount (\$\$)	12,272.39	4,226.50	8,045.89	65.56

INSPECTION

Date of Assignment:	04/11/2019		
Date Inspected:	04/11/2019	Inspected At:	Auto Insure Pte Ltd (HQ) 6 Marsiling Lane Singapore 739145
Estimated Period of Repair:	5.0 days		

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Dec 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ8128X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,355.00 FL	*801.70 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Broken	59.00 FL	*59.00 FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Broken	59.00 FL	*59.00 FL
4	1		*FRONT BUMPER LOWER SKIRT	Not Necessary	559.00 FL	*- FL
5	1		*BONNET ASSY	Dented	1,200.00 FL	*1,020.00 FL
6	1		*BONNET HINGE LH	Bent	105.00 FL	*50.00 FL
7	1		*BONNET HINGE RH	Bent	105.00 FL	*50.00 FL
8	1		*RADIATOR GRILL ASSY	Broken	850.00 FL	*850.00 FL
9	1		*RADIATOR GRILL HONDA LOGO	Necessary	110.00 FL	*45.00 FL
10	1		*RADIATOR GRILL TOP GARNISH	Not Necessary	250.00 FL	*- FL
11	1		*FRONT REINFORCEMENT BAR	Not Necessary	720.00 FL	*- FL
12	1		*RADIATOR ASSY	Not Necessary	1,300.00 FL	*- FL
13	1		*AIRCON CONDENSOR ASSY	Not Necessary	900.00 FL	*- FL
14	1		*FRONT FENDER LH	Repair	735.00 FL	*- FL
15	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	265.90 FL	*- FL
16	1		*FRONT FENDER WHEEL ARCH LH	Not Necessary	235.00 FL	*- FL
17	1		*FRONT WHEEL HOUSING LH (NPA)	Not Necessary	0.00 FL	*- FL
18	1		*HEADLAMP LH	Broken	2,354.00 FL	*1,759.10 FL
19	1		*FRONT DOOR LH (NPA)	Not Necessary	0.00 FL	*- FL
20	1		*FRONT NUMBER PLATE WITH HOLDER	Cut	80.00 FS	*30.00 FS
21	1		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
22	2		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
23	1		*AIR CON GAS	Not Necessary	90.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	11,471.90	4,753.80
- List Item Discount on L Items 20.00/25.00% (\$\$)	2,232.38	1,173.45
Total Parts (\$\$)	9,239.52	3,580.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	New	1,000.00	600.00
2	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	New	250.00	30.00
3	TO REMOVE/REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	New	100.00	0.00
4	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	New	800.00	700.00
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	80.00	30.00
Gross Labour Cost (\$\$)			2,230.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >