

ASS. REC. BY:

REF:

CS/CTI19019454/12y^{SV}

Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person): Chang Hoon San

of

CTI

Date/Time: 04/11/19 @ 242pm.

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SLA3477R

Insured:

G2 476SE

at Workshop m/s

Trans Eurokars

Tel:

63310680

of

MTA Tanjung Pagar

Policy No:

DMCVEN30811218011

Claim No:

SMM19020513902

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/10/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

(WP)

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>Estimate ()</u>
	<u>SLA3477R X</u>
	<u>G2 476SE X</u>

ASS. REC. BY:

REF: C12

ASSIGNMENT

From:

Date: 5.11.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLA 347R

at Workshop m/s Trans Eurokars

of 27A Tanjung Rujum

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh: 10am - 11.00am own way

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLA 347R Yr Regn: 206 Feb.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 2.

c.c. 1496

Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 45952

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MM6DL2S417GW176683

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

05/11/19

Survey held at Trans Eurokars

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/1/20

\$9717.48, 9 days email to Jessica - (Red \$4027-45, 29%)

RECEIVED 22 JAN 2020

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

22/1/20 Typist

Rep. Format:

Lump Sum / F.B. / C.

PIP \$9717-48

Days Of Repair: 9

Resurvey No. of Trip: 3

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Nov 2019		04 Nov 2019 15:58 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:			
Main Claimant:	CHONG JIA LI, ID: S8711051F		
Vehicle Reg. No.:	SLA3477R	Date of Loss:	25/10/2019 19:00 - :59
Claim Type:	TP / SNM19D205139C02	Policy/Cover Note No.:	DMCVSN30811218011
Vehicle Reg. No. (Insured):	GZ4765E	Policy No. (Claimant):	PNPV2017-00001703-02
		Excess:	S\$0.00
Repairer:	Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ) 27A Tanjong Penjuru, 609042 West Coast - Tel: 6331 0680		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/11/2019]		
		View All	Compose Case Mail
ASSOCIATED MAIL RECEIVED			
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All	Search Tasks Create New Task Complete
Due Date	Priority	Type	Task Group
Subject			
Handler			
Assigned By			
Completed On			
Created On			
Done?			
No results.			

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 4 November 2019 2:42 PM
To: samuel.ng@eurokars.com.sg
Cc: catherinechua@eurokars.com.sg; jess.francis@eurokars.com.sg; jobithomas@eurokars.com.sg; eva.kok@eurokars.com.sg; assignments
Subject: RE: OUR REF: SNM19D205139-GZ4765E-CML- YOUR REF: GZ4765E / OUR REF: SLA3477R THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s lkk AUTO CONSULTANTS to survey your client's vehicle.

Aside to lkk AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Chong Boon Sen

Sent: Monday, November 4, 2019 2:42 PM

To: 'samuel.ng@eurokars.com.sg' <samuel.ng@eurokars.com.sg>

Cc: catherinechua@eurokars.com.sg; jess.francis@eurokars.com.sg; jobithomas@eurokars.com.sg; eva.kok@eurokars.com.sg; assignments <assignments@lkkauto.com>

Subject: RE: OUR REF: SNM19D205139-GZ4765E-CML- YOUR REF: GZ4765E / OUR REF: SLA3477R THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LBS AUTO CONSULTANTS to survey your client's vehicle.

Aside to LBS AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: samuel.ng@eurokars.com.sg [mailto:samuel.ng@eurokars.com.sg]

Sent: Monday, November 4, 2019 2:39 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Cc: catherinechua@eurokars.com.sg; jess.francis@eurokars.com.sg; jobithomas@eurokars.com.sg; eva.kok@eurokars.com.sg

Subject: RE: OUR REF: SNM19D205139-GZ4765E-CML- YOUR REF: GZ4765E / OUR REF: SLA3477R THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Dear Chong,

Sorry for overlook, kindly arrange LKK for survey.

Best Regards,

Samuel Ng

Insurance Claims Officer
Trans Eurokars Pte Ltd

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent: 04 November 2019 2:27 PM

To: Samuel Ng <samuel.ng@eurokars.com.sg>

Cc: Catherine Chua <catherinechua@eurokars.com.sg>; Jess Francis Amurao Carlos <jess.francis@eurokars.com.sg>; Jobi Thomas <jobithomas@eurokars.com.sg>; Eva Kok <eva.kok@eurokars.com.sg>

Subject: RE: OUR REF: SNM19D205139-GZ4765E-CML- YOUR REF: GZ4765E / OUR REF: SLA3477R THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

You chose the surveyor? Please find list.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: samuel.ng@eurokars.com.sg [mailto:samuel.ng@eurokars.com.sg]

Sent: Monday, November 4, 2019 2:23 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Cc: catherinechua@eurokars.com.sg; jess.francis@eurokars.com.sg; jobithomas@eurokars.com.sg; eva.kok@eurokars.com.sg; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D205139-GZ4765E-CML- YOUR REF: GZ4765E / OUR REF: SLA3477R THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Dear Sir/Madam,

Any update regarding the timing of survey?

Best Regards,
Samuel Ng
Insurance Claims Officer
Trans Eurokars Pte Ltd

From: Samuel Ng
Sent: 04 November 2019 8:35 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; 'Elaine Cheong' <elaine.cheong@sg.cntaiping.com>
Cc: Catherine Chua <catherinechua@eurokars.com.sg>; Jess Francis Amurao Carlos <jess.francis@eurokars.com.sg>; Jobi Thomas <jobithomas@eurokars.com.sg>; Eva Kok <eva.kok@eurokars.com.sg>; 'Claims Dept of CTI' <claimsdept@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D205139-GZ4765E-CML- YOUR REF: GZ4765E / OUR REF: SLA3477R THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Dear Sir/Madam,

Kindly confirm PRS as soon as possible, owner waiting our conformation to arrange her schedule.

Best Regards,
Samuel Ng
Insurance Claims Officer
Trans Eurokars Pte Ltd

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: 01 November 2019 5:02 PM
To: Samuel Ng <samuel.ng@eurokars.com.sg>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: Catherine Chua <catherinechua@eurokars.com.sg>; Jess Francis Amurao Carlos <jess.francis@eurokars.com.sg>; Jobi Thomas <jobithomas@eurokars.com.sg>; Eva Kok <eva.kok@eurokars.com.sg>
Subject: OUR REF: SNM19D205139-GZ4765E-CML- YOUR REF: GZ4765E / OUR REF: SLA3477R THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Dear Boon Sen,

Please assist to conduct PRS for SLA3477R.

Note : officer in charge – Elaine Cheong.

Regards,
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: samuel.ng@eurokars.com.sg [mailto:samuel.ng@eurokars.com.sg]
Sent: Friday, 1 November, 2019 4:58 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: catherinechua@eurokars.com.sg; jess.francis@eurokars.com.sg; jobithomas@eurokars.com.sg; eva.kok@eurokars.com.sg
Subject: RE: YOUR REF: GZ4765E / OUR REF: SLA3477R THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Dear Sir/Madam,

Any update regarding the timing of survey?

Best Regards,
Samuel Ng
Insurance Claims Officer
Trans Eurokars Pte Ltd

From: Samuel Ng
Sent: 01 November 2019 9:16 AM
To: 'claimsdept@sg.cntaiping.com' <claimsdept@sg.cntaiping.com>
Cc: Catherine Chua <catherinechua@eurokars.com.sg>; Jess Francis Amurao Carlos <jess.francis@eurokars.com.sg>; Jobi Thomas <jobithomas@eurokars.com.sg>; Eva Kok <eva.kok@eurokars.com.sg>
Subject: YOUR REF: GZ4765E / OUR REF: SLA3477R THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

YOUR REF: GZ4765E / OUR REF: SLA3477R THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Dear Sir/Mdm,

Attached is the ESTIMATE, SAS REPORT, SKETCH PLAN for your perusal.

Kindly arrange survey at 27A Tanjong Penjuru on next Monday 04/11/2019 10pm – 11pm.

Best Regards,
Samuel Ng
Insurance Claims Officer
Trans Eurokars Pte Ltd

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/10/2019 10:27
Date Of Accident	25/10/2019 19:05
Exact Location Of Accident	ALONG COMMONWEALTH AVE WEST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA3477R
Insured/Policyholder	
Name Of Registered Owner	CHONG JIA LI
NRIC No	S8711051F
Email Address	JIALI.CHONG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96720293
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MAZDA
Model	2-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00001703-02
Cover Note Number	

Driver

Name of Driver	CHONG JIA LI
NRIC No	S8711051F
Date Of Birth	25/04/1987
Occupation	INDOOR
Date Of Driving Pass	30/08/2006
Driving Experience	13 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-96720293
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	JIALI.CHONG@GMAIL.COM

Address	BLK 90 DAWSON ROAD #18-12
Postcode	142090
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : SAMUEL CHEE GENDER: : MALE
Passenger 2	NAME: : CHONG JIA LING GENDER: : FEMALE
Passenger 3	NAME: : CHARLENE CHEN GENDER: : FEMALE
Passenger 4	NAME: : CHARLIE SAM CHEE GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ4765E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE

Name of Driver	SUKI BIN MUJAN
NRIC/Passport Number	S0126616J
Contact Number	9682 6437
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

VEHICLE NO: SH13477 R
ACCIDENT DATE: 25/10/2019 09:05

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

NOTE: DO NOTE THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.

Policyholder's Signature

Date & Time: 26/10/19
9:30am

Driver's Signature

(If driver is not the policyholder)
Date & Time:

CHARN'S CUSTOMCRAFT


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along commonwealth ave east on 25/10/19 at 7:05pm and the traffic light changed colour. I slowed down and came to a stop. When I looked into my rear view mirror and noticed the vehicle GZ4765E was still approaching quickly. I released my brake to move forward a little but GZ4765E still collided into my car SLA3477R.

OWN DAMAGE () 3RD PARTY CLAIM (X) REPORTING ONLY () OWN WORKSHOP ()

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 25/10/19
9:30am

Driver's Signature

(If driver is not the policyholder)
Date & Time:

CHARN'S CUSTOMER CRAFT


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along commonwealth ave east on 25/10/19 at 7:05pm and the traffic light changed colour from green to amber. I slowed down and came to a stop. When I looked into my rear view mirror and noticed the vehicle GZ4765E was still approaching quickly. I released my brake to move forward a little but GZ4765E still collided into my car SLA3477R.

OWN DAMAGE () 3RD PARTY CLAIM (X) REPORTING ONLY () OWN WORKSHOP ()

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 25/10/19
9:30am

Driver's Signature
(If driver is not the policyholder)
Date & Time:

CHARN'S CUSTOMCRAFT
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-176872

Date of Request: 26/10/2019

Your Ref No: Online Purchase

Trans Eurokars Pte Ltd
12 Sungei Kadut Ave
Singapore 729648

Dear Sir/Madam,

Enquiry Date: 26/10/2019
Enquiry By: Catherine Chua Siew Quek
TP Vehicle No: GZ4765E
Accident Date: 25/10/2019**Enquiry Result**

Mazda: SLA3477R

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GZ4765E	China Taiping Insurance (Singapore) Pte. Ltd.	05/11/2018-04/11/2019	6389 6111
GZ4765E	China Taiping Insurance (Singapore) Pte. Ltd.	05/11/2018-04/11/2019	6389 6111

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN : MOTOR CLAIMS FAX :		NAME : Ms Chong Jia Li ADDRESS : Block 90 Dawson Road #18-12 Singapore 142090 TEL : 96720293		WIP : 39220 EXCESS : DATE: 29-Oct-19	
VEH NO :	SLA3477R	DATE IN :		CONTACT PERSON :	SAMUEL
CHASSIS NO :	MM6DL2SAAGW176683	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA2	DATE REG.:	26-Feb-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	1	MDB7A-50-221BBB	de	\$ 954.50	
2	1	MKD53-50-251	de	\$ 5.40	
3	2	MDB7A-50-271	de	\$ 26.00	
4	1	MD350-51-5L0E	nn	\$ 53.00	
5	3	MGS1D-50-EM1A	nn	\$ 25.80	
6	1	MDB7A-50-350	nn	\$ 55.60	
7	7	MB45A-56-146A	nn	\$ 21.00	
8	2	M9991-00-501	nn	\$ 6.00	
9	1	MGJ21-50-049	nn	\$ 3.40	
10	1	MDB7G-68-89X 02	de	\$ 57.60	
11	1	MDB7G-68-894 02	nn	\$ 5.70	
12	1	MDB7G-68-870C02	nn	\$ 182.50	
13	10	MGJ21-68-885B02	nn	\$ 30.00	
14	1	MDBYA-70-75Z	nn	\$ 656.00	
15	1	MDBYA-71-490	nn	\$ 41.30	
16	1	MKD45-67-6NXA	nn	\$ 81.10	
17	1	MKD45-67-6NYA	nn	\$ 2.70	
18	1	MDAY0-52-61X	Ry	\$ 861.80	
19	1	MDB7A-56-951	nn	\$ 112.90	
20	1	MDB7A-56-820A	nn	\$ 190.90	
21	1	MDB7G-51-721	nn	\$ 57.90	
22	1	MDB7G-51-730	nn	\$ 58.20	
23	1	MDB7G-51-771	nn	\$ 67.60	
24	2	MGA7B-51-146	nn	\$ 6.60	
25	1	MDB7A-51-3J8	nn	\$ 48.60	
26	1	MDB7A-51-3H8	nn	\$ 48.60	
27	1	MDB7A-51-163	nn	\$ 33.50	
28	1	MDB7A-51-153	nn	\$ 33.50	
* Stone Guard LHS					
TOTAL PARTS					\$ 3,727.70

		LESS 10%		\$ 372.77
		TOTAL PARTS COST		\$ 3,354.93
<u>Labour Description</u>				
1	MZ-BR-REAR05	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID. TO REPAIR REAR FLOOR PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT. 660	3300	\$ 3,960.00
2	MZ-SP-SREAR5	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, REAR FLOOR PANEL AND BOOT LID. 630	2520	\$ 3,150.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	1w NETT ✓	\$ 660.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA. nu.	X NETT	\$ 330.00
5	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	660	\$ 990.00
6	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	180	\$ 350.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$ 250.00
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	152	\$ 250.00
9	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
10		TO SUPPLY BODY COATING.	NETT X	TBA nu.
11	MZ-BR-SUNDRI	SUNDRIES. nu	33 NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 10,390.00
TOTAL PARTS	\$ -	\$ 3,354.93
TOTAL	\$ -	\$ 13,744.93
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



TRANS EUROKARS PTE LTD



FINALIZATION COST OF REPAIRS

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN : MOTOR CLAIMS FAX :		NAME : Ms Chong Jia Li ADDRESS : Block 90 Dawson Road #18-12 Singapore 142090 TEL : 96720293		WIP : 39220 EXCESS : DATE: 29-Oct-19	
VEH NO :	SLA3477R	DATE IN :		CONTACT PERSON :	SAMUEL
CHASSIS NO :	MM6DL2SAAGW176683	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA2	DATE REG.:	26-Feb-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MDB7A-50-2218BB	\$ 954.50	\$ 954.50
2	BRACKET CENTER	1	MKD53-50-251	\$ 5.40	\$ 5.40
3	STAY, REAR BUMPER	1	MDB7A-50-271	\$ 13.00	\$ 26.00
4	REFLECTOR LHS	1	MD350-51-5L0E		\$ 53.00
5	TAPE PROTECTOR, REAR BUMPER	3	MG51D-50-EM1A	\$ 25.80	\$ 25.80
6	SHIELD SPLASH LHS	1	MDB7A-50-350		\$ 55.60
7	FASTENER, REAR BUMPER	7	MB45A-56-146A	\$ 21.00	\$ 21.00
8	GROMMET, REAR BUMPER	2	M9991-00-501	\$ 6.00	\$ 6.00
9	CLIP, REAR BUMPER	1	MGJ21-50-049	\$ 3.40	\$ 3.40
10	TRIM, END PANEL	1	MDB7G-68-89X 02	\$ 57.60	\$ 57.60
11	BEZEL, LOCK	1	MDB7G-68-894 02		\$ 5.70
12	TRIM LHS, BOOTSIDE	1	MDB7G-68-870C02		\$ 182.50
13	FASTENER, TRIM	10	MGJ21-68-885B02		\$ 30.00
14	REAR END PANEL	1	MDBYA-70-75Z	\$ 656.00	\$ 656.00
15	PLATE CORNER LHS	1	MDBYA-71-490		\$ 41.30
16	ANTENNA, KEYLESS	1	MKD45-67-6NXX		\$ 81.10
17	CLIP, ANTENNA	1	MKD45-67-6NYA		\$ 2.70
18	BOOTLID	1	MDAY0-52-61X		\$ 861.80
19	WEATHERSTRIP, BOOTLID	1	MDB7A-56-951		\$ 112.90
20	LOCK, BOOTLID	1	MDB7A-56-820A		\$ 190.90
21	ORNAMENT, MAZDA	1	MDB7G-51-721	\$ 57.90	\$ 57.90
22	MASCOT, REAR	1	MDB7G-51-730	\$ 58.20	\$ 58.20
23	ORNAMENT, SKYACTIVE	1	MDB7G-51-771	\$ 67.60	\$ 67.60
24	GROMMET, BOOTLID	2	MGA7B-51-146	\$ 6.60	\$ 6.60
25	GASKET LHS, BOOTLID	1	MDB7A-51-3J8	\$ 48.60	\$ 48.60
26	GASKET RHS, BOOTLID	1	MDB7A-51-3H8	\$ 48.60	\$ 48.60
27	GASKET LHS, TAILLAMP	1	MDB7A-51-163	\$ 33.50	\$ 33.50
28	GASKET RHS, TAILLAMP	1	MDB7A-51-153	\$ 33.50	\$ 33.50
TOTAL PARTS				\$ 2,097.20	\$ 3,727.70

		LESS 10%	\$ 209.72	\$ 372.77
		TOTAL PARTS COST	\$ 1,887.48	\$ 3,354.93
		Labour Description		
1	MZ-BR-REAR05	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID. TO REPAIR REAR FLOOR PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 3,300.00	\$ 3,960.00
2	MZ-SP-SREAR5	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, REAR FLOOR PANEL AND BOOT LID.	\$ 2,520.00	\$ 3,150.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	\$ 660.00	\$ 660.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	\$ -	\$ 330.00
5	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	\$ 660.00	\$ 990.00
6	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	\$ 180.00	\$ 350.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 150.00	\$ 250.00
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
9	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
10		TO SUPPLY BODY COATING.	\$ -	TBA
11	MZ-BR-SUNDRI	SUNDRIES.	\$ 30.00	\$ 100.00
		TOTAL LABOUR	\$ 7,830.00	\$ 10,390.00
		TOTAL PARTS	\$ 1,887.48	\$ 3,354.93
		TOTAL *	\$ 9,717.48	\$ 13,744.93
		LESS EXCESS	\$ -	\$ -
		TOTAL AFTER EXCESS	\$ 9,717.48	
		GST 7%	\$ 680.22	\$ -
		GRAND TOTAL	\$ 10,397.70	\$ -

NUMBER OF DAYS:9 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN & PH)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	04 Nov 2019		04 Nov 2019 15:58 Edit Adj Rpt	S\$9,717.48 Edit Estimates	S\$9,717.48 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	CHONG JIA LI , ID: S8711051F		
Vehicle Reg. No.:	SLA3477R	Date of Loss:	25/10/2019 19:00 - :59 [44 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D205139C02	Policy/Cover Note No.:	DMCVSN30811218011
Vehicle Reg. No. (Insured):	GZ4765E	Policy No. (Claimant):	PNPV2017-00001703-02
		Excess:	S\$0.00
Repairer:	Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ) 27A Tanjong Penjuru, 609042 West Coast - Tel: 6331 0680		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 13/11/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLA3477R (SNM19D205139C02)**
[GZ4765E]
















































TP
CHONG JIA LI
Oct 25 2019 7:00PM








[-]
Trans Eurokars Pte Ltd - Tanjong Penjuru

Upload Documents | Upload Photos | Compose New Letter































View View in Browser ▼

Assessment Reports			1 per page ▼	Thumbnail	Print
No	Finalized On	Charn's Customcraft (HQ)			
1	30/10/19 11:43	Addendum Sheet	1	Load TIF	
Photos/Images			3 per page ▼	Thumbnail	Print
No	Finalized On	Charn's Customcraft (HQ)			
1	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
2	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
3	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
4	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
5	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
6	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
7	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
8	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
9	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
10	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
11	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
12	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
13	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
14	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
15	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
16	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
17	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
18	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
19	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
20	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
21	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
22	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
23	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
24	26/10/19 11:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Charn's Customcraft (HQ)	Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/01/20 09:53	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	23/01/20 09:53	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
3	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
4	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
5	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
6	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
7	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
8	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
9	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
10	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
11	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
12	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
13	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
14	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
15	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
16	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
17	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
18	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
19	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
20	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
21	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
22	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
23	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
24	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
25	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
26	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
27	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
28	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
29	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
30	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
31	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
32	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
33	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
34	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
35	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
36	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
37	23/01/20 09:53	General View	 Load JPG	<input checked="" type="checkbox"/>
38	23/01/20 09:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	23/01/20 09:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	23/01/20 09:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	23/01/20 09:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	23/01/20 09:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	23/01/20 09:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	23/01/20 09:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	23/01/20 09:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	23/01/20 09:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	23/01/20 09:54	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Charn's Customcraft (HQ)	Thumbnail	Print
48	23/01/20 09:54	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
49	23/01/20 09:54	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
50	23/01/20 09:54	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
51	23/01/20 09:54	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Charn's Customcraft (HQ)	Thumbnail	Print
1	26/10/19 11:27	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	26/10/19 11:27	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	30/10/19 11:43	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Charn's Customcraft (HQ)	1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Charn's Customcraft (HQ)	Thumbnail	Print
1	30/10/19 11:43	Addendum Sheet	 Load TIF	
2	06/12/19 18:56	Accident Statement	 Load HTM	
3	06/12/19 18:58	Accident Statement	 Load HTM	
4	06/12/19 18:58	Accident Statement	 Load HTM	
5	06/12/19 18:59	Accident Statement	 Load HTM	
6	06/12/19 19:09	Accident Statement	 Load HTM	
7	06/12/19 19:17	Accident Statement	 Load HTM	
8	06/12/19 19:17	Accident Statement	 Load HTM	
9	06/12/19 19:18	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Charn's Customcraft (HQ)	Thumbnail	Print
1	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
18	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
19	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
20	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
21	26/10/19 11:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page		
No	Finalized On	Charn's Customcraft (HQ)		Thumbnail	Print
22	26/10/19 11:28	Accident Photo		Load JPG	
23	26/10/19 11:28	Accident Photo		Load JPG	
24	26/10/19 11:28	Accident Photo		Load JPG	
Documentation			1 per page		
No	Finalized On	Charn's Customcraft (HQ)		Thumbnail	Print
1	26/10/19 11:27	Sketch Plan		Load TIF	
2	26/10/19 11:27	Sketch Plan #2		Load TIF	
3	30/10/19 11:43	Accident Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: <input type="checkbox"/> Handling Insurer				
Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19019454/T1YF3S2

Date: 28/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30811218011

Claimant Vehicle No: SLA3477R Insured Vehicle No: GZ4765E

Date of Loss: 25/10/2019 Nature of Claim: TP Claim No: SNM19D205139C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA3477R

Make & Model: MAZDA 2, 1.5 (A) Engine No: HIDDEN

Reg. Date: 01/02/2016 (Man. Year: 2016) Chassis No: MM6DL2SAAGW176683

Colour: Grey Odometer: 45952 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,114.93	2,577.48	1,537.45	37.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,630.00	7,140.00	2,490.00	25.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,744.93	9,717.48	4,027.45	29.30
+ GST 7.00/7.00% (S\$)	962.15	680.22	281.93	29.30
Nett Amount (S\$)	14,707.08	10,397.70	4,309.38	29.30

INSPECTION

Date of Assignment: 04/11/2019

Date Inspected: 05/11/2019 Inspected At: 27A Tanjong Penjuru
Singapore 609042
Repairer: Trans Eurokars Pte Ltd

Estimated Period of Repair: 9.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jan 2020)
Parts:	143	MAZDA 2 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA3477R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	954.50 FL	*954.50 FL
2	1		*BRACKET CENTER	Deformed	5.40 FL	*5.40 FL
3	2		*STAY, REAR BUMPER	Deformed	26.00 FL	*13.00 FL
4	1		*REFLECTOR LHS	Not Necessary	53.00 FL	*- FL
5	3		*TAPE PROTECTOR, REAR BUMPER	Necessary	25.80 FL	*25.80 FL
6	1		*SHIELD SPLASH RHS	Not Necessary	55.60 FL	*- FL
7	7		*FASTENER, REAR BUMPER	Necessary	21.00 FL	*21.00 FL
8	2		*GROMMET, REAR BUMPER	Necessary	6.00 FL	*6.00 FL
9	1		*CLIP, REAR BUMPER	Necessary	3.40 FL	*3.40 FL
10	1		*TRIM, END PANEL	Deformed	57.60 FL	*57.60 FL
11	1		*BEZEL, LOCK	Not Necessary	5.70 FL	*- FL
12	1		*TRIM LHS, BOOTSIDE	Not Necessary	182.50 FL	*- FL
13	10		*FASTENER, TRIM	Not Necessary	30.00 FL	*- FL
14	1		*REAR END PANEL	Bent	656.00 FL	*656.00 FL
15	1		*PLATE CORNER LHS	Not Necessary	41.30 FL	*- FL
16	1		*ANTENNA, KEYLESS	Not Necessary	81.10 FL	*- FL
17	1		*CLIP, ANTENNA	Not Necessary	2.70 FL	*- FL
18	1		*BOOTLID	Repair	861.80 FL	*- FL
19	1		*WEATHERSTRIP, BOOTLID	Not Necessary	112.90 FL	*- FL
20	1		*LOCK, BOOTLID	Not Necessary	190.90 FL	*- FL
21	1		*ORNAMENT, MAZDA	Necessary	57.90 FL	*57.90 FL
22	1		*MASCOT, REAR	Necessary	58.20 FL	*58.20 FL
23	1		*ORNAMENT, SKYACTIVE	Necessary	67.60 FL	*67.60 FL
24	2		*GROMMET, BOOTLID	Necessary	6.60 FL	*6.60 FL
25	1		*GASKET LHS, BOOTLID	Necessary	48.60 FL	*48.60 FL
26	1		*GASKET RHS, BOOTLID	Necessary	48.60 FL	*48.60 FL
27	1		*GASKET LHS, TAILLAMP	Necessary	33.50 FL	*33.50 FL
28	1		*GASKET RHS, TAILLAMP	Necessary	33.50 FL	*33.50 FL
29	1		*REVERSE SENSORS	Not Working	660.00 FS	*660.00 FS
30	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,487.70	2,787.20
- List Item Discount on L Items 10.00/10.00% (\$\$)	372.77	209.72
Total Parts (\$\$)	4,114.93	2,577.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID. TO REPAIR REAR FLOOR PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	New	3,960.00	3,300.00
2	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL , REAR FLOOR PANEL AND BOOT LID.	New	3,150.00	2,520.00
3	TO TRANSFER REVERSE CAMERA.	New	330.00	0.00
4	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	New	990.00	660.00
5	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING.	New	350.00	180.00
6	TO CARRY-OUT BODY CAVITY PRESERVATION.	New	250.00	150.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	New	250.00	150.00
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	New	350.00	180.00
9	TO SUPPLY BODY COATING. (NPA)	New	0.00	0.00
Gross Labour Cost (\$\$)			9,630.00	7,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >