

2/03/2012

ASS. REC. BY:

REF:

C9/CT119019459/BCF362

Special Instruction:

Surveyor: Lim

ASSIGNMENT (Office)

From (Person): Chong Bnn Sen of CT1 Date/Time: 4.11.19 3.4p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SK C 4883X Insured: YQ 157X

at Workshop m/s MSM Logistics Tel: 94896649

of 160 San Ming Anticity #03-08

Policy No: DMCA SN19030419000 Claim No: SNM190205134002

Sum Insured: Excess:

Make of Veh: D.O.A.
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.P. Endorsement:

Date/Time: 4.11.19 3.28p.m Person Contacted: Mr. Chen Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate Inspection: 160 San Ming Blvd #03-08
	SKC 4883X X
	YQ 157X X
13/11/19	@ 16:19 pm checked with Mr. Chen (repairer), no estimate - Dismantle: 6/11/2019 after repair: 11/11/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Nov 2019		05 Nov 2019 10:17 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	CHEW KIM LENG , ID: S6931638G
Vehicle Reg. No.:	SKC4883X
Claim Type:	TP / SNM19D205134C02
Vehicle Reg. No. (Insured):	YQ157X
Date of Loss:	24/10/2019 13:00 - :59
Policy/Cover Note No.:	DMCVSN19030419000
Policy No. (Claimant):	5112217281
Excess:	S\$0.00
Repairer:	Msm Logistics Pte Ltd- Sin Ming (HQ) 160 Sin Ming Drive #03-08 Sin Ming Auto City, 575722 Sin Ming - Tel: 91074212
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 14/11/2019]

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Summer Lee (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 4 November, 2019 3:14 PM
To: Lua Siew Hui
Cc: Natalie Ng; Wendy Jiang; Jeffrey Tay; assignments
Subject: RE: FW: OUR REF:SNM19D205134-YQ157X-CBS- Fax Message NO.2082 [RSS/1910-7505 (MSM)(PD)]

**WITHOUT PREJUDICE
SAVE AS TO COSTS**

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Lua Siew Hui [mailto:lua_siewhui@rssolomon.com]
Sent: Monday, November 4, 2019 2:44 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Natalie Ng <natalie_ng@rssolomon.com>; Wendy Jiang <wendy_jiang@rssolomon.com>; Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>
Subject: Fwd: FW: OUR REF:SNM19D205134-YQ157X-CBS- Fax Message NO.2082 [RSS/1910-7505 (MSM)(PD)]

Dear Boon Sen,

We refer to your email of 1st November 2019 at about 1604 hrs informing that you will be appointing your in house surveyors for the PRI of our client's vehicle.

However, to-date our client's repairers have not receive calls from your surveyors for PRI to be conducted at their workshop. Full details of the workshop which were previously provided to you in our email of 1st November 2019 are append below for your easy reference:-

MSM Logistics Pte Ltd
160 Sin Ming Drive
#01-12 Sin Ming Autocity
Singapore 575722
Contact Person: Mr. Chen at Mobile: 9489 6649

#103-08

Please arrange your Surveyors to contact Mr.Chen before 5th November 2019, 10am falling which our client shall proceed with the repair of his vehicle without further reference to you. Your immediate attention into this matter is highly appreciated.

Thank you and best regards,

Lua Siew Hui | Legal Executive

R. S. Solomon LLC | 正氣律師事務所

Advocates & Solicitors

300 Beach Road The Concourse #12-03/04 Singapore 199555
t +65 6817 7498 | f +65 6292 2665 | e lua_siewhui@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information. If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system. Thank you.

----- Forwarded message -----

From: **Lua Siew Hui** <lua_siewhui@rssolomon.com>

Date: Fri, Nov 1, 2019 at 4:16 PM

Subject: Re: FW: OUR REF:SNM19D205134-YQ157X-CBS- Fax Message NO.2082 [RSS/1910-7505 (MSM)(PD)]

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Cc: <claimsdept@sg.cntaiping.com>, Wendy Jiang <wendy_jiang@rssolomon.com>, Natalie Ng <natalie_ng@rssolomon.com>

Dear Boon Sen,

We refer to your email.

We write to inform that our client will be appointing his own Surveyors.

In this respect, please arrange your surveyors to contact Mr. Chen of MSM Logistics Pte Ltd at mobile no. 9489 6649 for a pre-repair survey of our client's vehicle located at 160 Sin Ming Drive #01-12 Sin Ming Autocity Singapore 575722.

Thank you and Best Regards,

Lua Siew Hui | Legal Executive

R. S. Solomon LLC | 正氣律師事務所

Advocates & Solicitors

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e lua_siewhui@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information. If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system. Thank you.

On Fri, Nov 1, 2019 at 4:07 PM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping
SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

-----Original Message-----

From: Chong Boon Sen
Sent: Thursday, October 31, 2019 4:46 PM
To: INFO@RSSOLOMON.COM; Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>;
lua_siewhui@rssolomon.com
Subject: RE: OUR REF:SNM19D205134-YQ157X-CBS- Fax Message NO.2082

Without prejudice

Dear Sir,
LKK

STA
LBS

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping
SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

-----Original Message-----

From: Claims Dept of CTI
Sent: Thursday, October 31, 2019 4:21 PM
To: INFO@RSSOLOMON.COM; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>; lau_siewhui@rssolomon.com
Subject: OUR REF:SNM19D205134-YQ157X-CBS- Fax Message NO.2082

Dear Boon Sen,

Please conduct PRS for SKC4883X.

Note : officer in charge - Boon Sen 63896171.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping
SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: FA-X5575C-16A-CL
Sent: Thursday, October 31, 2019 12:10 PM
To: Claims Dept of CTI
Subject: FW: Fax Message NO.2082

-----Original Message-----

From: FA-X5575C-19A
Sent: Wednesday, October 30, 2019 4:08 PM
To: FA-X5575C-16A-CL
Subject: FW: Fax Message NO.2082

Maureen Ong
HR & Administration Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6111 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

-----Original Message-----

From: FA-RC6004F-16A-FN@sg.cntaiping.com [mailto:FA-RC6004F-16A-FN@sg.cntaiping.com]
Sent: Wednesday, October 30, 2019 3:58 PM
To: FA-X5575C-19A <FA-X5575C-19A@sg.cntaiping.com>
Subject: Fax Message NO.2082

This E-mail was sent from "RC6004F-16A-FN" (MP C6004ex).

Queries to: FA-RC6004F-16A-FN@sg.cntaiping.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	638G
Vehicle Details	
Vehicle No.:	SKC4883X
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Nov 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 250
Primary Colour:	Grey
Manufacturing Year:	2011
Engine No.:	27186030284814
Chassis No.:	WDD2120472A475393
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$52,881.00
Original Registration Date:	31 Aug 2011
First Registration Date:	31 Aug 2011
Transfer Count:	1
Actual ARF Paid:	\$52,881.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2021
PARF Rebate Amount:	\$29,084.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$56,889.00
COE Rebate Amount:	\$10,200.00
Total Rebate Amount:	\$39,284.00

The information contained herein is correct as at 07 Nov 2019

OK

Dep 15,850/yr

MV 52,000/2

PV 39,284/2

NV 12,716/2

TZ Lim
7/11/19

**Mercedes-Benz E-Class E250**

-

N/A

04-Aug-2011

1,796 cc

-

Luxury

SOLD

Bank Loan Interest Rate Offer From 2.48%! In House Financing! Attractive Trade In Price, All Our Car Go Thought 120 Point Check With Our In- House Workshop Buying With Peace Of Mind. Call Us Now.

Motor Universe Credit Pte Ltd

Posted: 28-Aug-2019 Tags: 2011 Mercedes-Benz E250, 2011 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz

**Mercedes-Benz E-Class E250****\$53,888****\$15,850 /yr**

01-Aug-2011

1,796 cc

178,000 km

Luxury

Available

Consignment Unit. Low Depreciation! Well Maintained By Current Owner. Carbon Fibre Boot Lip, Side Skirts, Front/Back Lip. Full Service Records, No Repairs Needed Drive With Peace Of Mind. Reluctant Sale As Owner Changing To MPV Due To New Baby. STA/Viacom Insp...

Posted: 10-Oct-2019 Tags: 2011 Mercedes-Benz E250, 2011 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz

**Mercedes-Benz E-Class E250 CGI Cabriolet****\$61,800****\$17,910 /yr**

12-Jul-2011

1,796 cc

-

Sports

Available

Satisfaction Guaranteed Upon Viewing, The Best Condition E250 Cabriolet (C&C Unit) With No More Repairs Needed. Expat Lady Owner. Road Tax Till Jan 20. Nice/New Car Number. 100% Accident Free. Price Negotiable. Best Choice For Future COE Renewal. Call Now!

Lake View Credit Pte Ltd

Posted: 03-Nov-2019 Tags: 2011 Mercedes-Benz E250, 2011 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz

**Mercedes-Benz E-Class E250 CGI****\$55,800****\$17,670 /yr**

06-Jul-2011

1,796 cc

-

Luxury

Available

Excellent Condition! Popular Model For COE Renewal Due To Its High Reliability And Comfort! Call To View Now Before It Is Too Late! In House Loan Available!

Hui Hua Credit Pte Ltd

Posted: 04-Oct-2019 Tags: 2011 Mercedes-Benz E250, 2011 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz

Save this search criteria, to get email alerts whenever a match is found.

Make: Model: Price: Depreciation: Reg Date: Eng Cap: Mileage: Veh Type: Status:

For old advertisements, view Expired ads

« Back (1 2 3) Next »

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Mercedes-Benz, Mercedes-Benz Singapore, used Mercedes-Benz Singapore, used Mercedes-Benz, used vehicles Singapore or even buy used Mercedes-Benz Singapore.

We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/10/2019 15:04
Date Of Accident	24/10/2019 13:00
Exact Location Of Accident	PASIR PANJANG WHOLESALE CENTRE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC4883X
Insured/Policyholder	
Name Of Registered Owner	CHEW KIM LENG
NRIC No	S6931638G
Email Address	JEFFREYCHEWKL@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94568173
Alternative Phone No	OFFICE-94568173

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5112217281
Cover Note Number	

Driver

Name of Driver	CHEW KIM LENG
NRIC No	S6931638G
Date Of Birth	07/09/1969
Occupation	INDOOR
Date Of Driving Pass	25/06/1990
Driving Experience	29 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94568173
Fax Number	
Contact Number	OFFICE-94568173
Email Address	JEFFREYCHEWKL@GMAIL.COM

Address	134 PUNGGOL WALK #16-24
Postcode	828778
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED - VEHICLE B HIT ONTO MY STATIONARY PARKED VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YQ157X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LIU XIANGSHI
NRIC/Passport Number	G8385338M
Contact Number	96328757 / 67764054
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

my car was parking inside the parking lot car B
hit my car. , my car is stationary.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



































...CLAIM SUBFOLDER...(Pending for Survey Report)























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Nov 2019		05 Nov 2019 10:17 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: CHEW KIM LENG , ID: S6931638G									
Vehicle Reg. No.: SKC4883X		Date of Loss: 24/10/2019 13:00 - :59 [97 Months and 24 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D205134C02		Policy/Cover Note No.: DMCVSN19030419000							
Vehicle Reg. No. (Insured): YQ157X		Policy No. (Claimant): 5112217281							
		Excess: S\$0.00							
Repairer: Msm Logistics Pte Ltd- Sin Ming (HQ) 160 Sin Ming Drive #03-08 Sin Ming Auto City, 575722 Sin Ming - Tel: 91074212									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 14/11/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


















Claim Documents

*SKC4883X (SNM19D205134C02)
[YQ157X]
TP
CHEW KIM LENG
Oct 24 2019 1:00PM
[-]
Msm Logistics Pte Ltd- Sin Ming

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	25/10/19 15:42	Accident Statement		 Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	25/10/19 15:36	Accident Photo [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>
2	25/10/19 15:36	Accident Photo [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>
3	25/10/19 15:36	Accident Photo [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>
4	25/10/19 15:36	Accident Photo [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>
5	25/10/19 15:36	Accident Photo [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>
6	25/10/19 15:36	Accident Photo [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>
7	25/10/19 15:36	Accident Photo [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>
8	25/10/19 15:36	Accident Photo [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>
9	25/10/19 15:36	Accident Photo [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>
10	25/10/19 15:36	Accident Photo [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>
11	25/10/19 15:36	Accident Photo [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>
12	25/10/19 15:36	Accident Photo [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>
13	25/10/19 15:36	Accident Photo [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>
14	25/10/19 15:36	Accident Photo [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/11/19 15:15	General View		 Load JPG	<input checked="" type="checkbox"/>
2	14/11/19 15:15	General View		 Load JPG	<input checked="" type="checkbox"/>
3	14/11/19 15:15	General View		 Load JPG	<input checked="" type="checkbox"/>
4	14/11/19 15:15	General View		 Load JPG	<input checked="" type="checkbox"/>
5	14/11/19 15:15	General View		 Load JPG	<input checked="" type="checkbox"/>
6	14/11/19 15:15	General View		 Load JPG	<input checked="" type="checkbox"/>
7	14/11/19 15:15	General View		 Load JPG	<input checked="" type="checkbox"/>
8	14/11/19 15:15	General View		 Load JPG	<input checked="" type="checkbox"/>
9	14/11/19 15:15	General View		 Load JPG	<input checked="" type="checkbox"/>
10	14/11/19 15:15	General View		 Load JPG	<input checked="" type="checkbox"/>
11	14/11/19 15:15	General View		 Load JPG	<input checked="" type="checkbox"/>
12	14/11/19 15:15	General View		 Load JPG	<input checked="" type="checkbox"/>
13	14/11/19 15:15	General View		 Load JPG	<input checked="" type="checkbox"/>
14	14/11/19 15:15	General View		 Load JPG	<input checked="" type="checkbox"/>
15	14/11/19 15:15	General View		 Load JPG	<input checked="" type="checkbox"/>
16	14/11/19 15:15	General View		 Load JPG	<input checked="" type="checkbox"/>
17	14/11/19 15:15	General View		 Load JPG	<input checked="" type="checkbox"/>
18	14/11/19 15:15	General View		 Load JPG	<input checked="" type="checkbox"/>
19	14/11/19 15:15	General View		 Load JPG	<input checked="" type="checkbox"/>
20	14/11/19 15:15	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
21	14/11/19 15:15	General View	 Load JPG	<input checked="" type="checkbox"/>
22	14/11/19 15:15	General View	 Load JPG	<input checked="" type="checkbox"/>
23	14/11/19 15:15	General View	 Load JPG	<input checked="" type="checkbox"/>
24	14/11/19 15:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	14/11/19 15:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	14/11/19 15:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	14/11/19 15:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	14/11/19 15:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	14/11/19 15:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	14/11/19 15:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	14/11/19 15:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	14/11/19 15:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	14/11/19 15:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	14/11/19 15:16	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
35	14/11/19 15:16	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
36	14/11/19 15:16	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
37	14/11/19 15:16	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
38	14/11/19 15:16	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
39	14/11/19 15:16	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
40	14/11/19 15:16	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	25/10/19 15:40	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	25/10/19 15:40	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	25/10/19 15:42	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	25/10/19 15:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	25/10/19 15:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	25/10/19 15:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	25/10/19 15:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	25/10/19 15:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	25/10/19 15:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	25/10/19 15:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	25/10/19 15:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	25/10/19 15:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	25/10/19 15:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	25/10/19 15:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	25/10/19 15:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	25/10/19 15:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	25/10/19 15:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	25/10/19 15:40	Sketch Plan	 Load TIF	
2	25/10/19 15:40	Sketch Plan #2	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT19019459/BCF3E2

Date: 15/11/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN19030419000

Claimant
Vehicle No : SKC4883XInsured
Vehicle No : YQ157X

Date of Loss: 24/10/2019

Nature of Claim: TP

Claim
No: SNM19D205134C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKC4883X

Make & Model: MERCEDES-BENZ E250, 1.8 (A)

Engine No: 27186030284814

Reg. Date: 31/08/2011 (Man. Year: 2011)

Chassis No: WDD2120472A475393

Colour: Grey

Odometer: 209757 km

Engine Capacity: 1796 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18

Rear Tyre Size: 245/40 R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 05/11/2019

Date Inspected: 05/11/2019 Inspected At:

Msm Logistics Pte Ltd- Sin Ming (HQ)
160 Sin Ming Drive #03-08 Sin Ming
Auto City
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Nov 2019)

Parts: 143 MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKC4883X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >