

ASS. REC. BY:

REF: CS/TM1 K109409 / P3f302

Special Instruction:

Surveyor: Ron

## ASSIGNMENT (Office)

From (Person): Dillen Sathlan So Selwanjoo of TMI

Date/Time: 4.11.19 4:54pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHA 3745 P

Insured: YN 6698 C

at Workshop m/s Comfortadign

Tel: 6214 8300

of 59 longg bre

Policy No: MIC00071

Claim No: M1908637

Sum Insured:

Excess:

Make of Veh:

D.O.A. 2-11-2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 5.11.19

8.59am

Person Contacted: mup'

Jumani

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHA 3745 P - CS/LAW18010854/Vuher2 RQA - 01/10/2019
	YN 6698 C - CS/MSQ K1013827/L1f302 RQA - 03/03/2019

ASS. REQ. BY **RAM**


REF

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop no: \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_

Consistent? Yes or No

GIA / PR Seen

Consistent? Yes or No

Est. Repairs:

days Res. Yes or No

Lum Sum:

% 3 Val: Yes or No

CA / REV / REP / 24 HRS

Date:

Person Contacted: \_\_\_\_\_

Vehicle IN / OUT

Veh No: **SHA 3745P** Yt Regn: **28/APR 2016**  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / **Taxi** / Prime Mover /  
 Truck / Trailer or

Make: **Hyundai i40** cc: **1685**  
 Colour: **Blue** A/C: Insured / Std / NI / NA  
 Sp. Reading: **469551** T/Ballo: Insured / Std / NI / NA

Eng/No: -  
 C/No: **KMHLBA1UMGU08T870**

Gen. Cond: Good / **Fair** / Poor / BurntSteering: **Inorder** / Jammed / Leaked / Burnt orBrake: **Inorder** / Jammed / Leaked / Burnt orModi: Nil / S/Rim / **STD A/Rim** orTyre Size: F: **205/60 R16**

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Hankook**

Front

Rear

R/Bal:

**S**

mm

R/Bal:

**S**

mm

L/Bal:

**S**

mm

L/Bal:

**S**

mm

D.O.A.

**2/11/19**

D.O.A.

**2/11/19**

Survey held at

**Comfortdelgro (Loyang)**Des. of Damages: **Frt** / Rear / O/S / **N/S** / UIC / Rooftop or**Frt of n/s front**

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

**L/S: \$2800/-****3 repair days****confirmation 7/11/19****08/11/19****Confirmed****L/S \$2,800/- @ 3 days****with Ram****( \$ 822.72 Red - 23% )****Red - 23%**

RECEIVED 08 NOV 2019

Days Of Repair: **3**Resurvey No. of Trip: **2**

Date/Time, Fee Paid by:

**08/11/19**

By:

**Typist**

Date/Time, Fee Return to:

By:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Report Format:

**Lump Sum / L.B.I: (\$ 2,800/- L/S)**

Survey Fee:

Transportation

Ft + RT: \$4

Others:

Others:

TOTAL

**240****4****244****TOKIO marine****H3**

**8/11/2019**

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Nov 2019 Sendback Est	04 Nov 2019 15:05 S\$4,039.88	04 Nov 2019 17:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

## CLAIM SUBFOLDER DETAILS

Insured:	HUPCO PTE LTD, Co. Reg. No.: 199206471G		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHA3745P	Date of Loss:	02/11/2019 15:00 - :59 [42 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1908637	Policy/Cover Note No.:	MK000771 (Comprehensive) Coverage: 19/09/2019 - 18/09/2020
Vehicle Reg. No. (Insured):	YN6698C	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/11/2019]		
Adj Asg. Remarks:	OI HAS NOT RPT THE ACCDT		

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305346234

DMER  
S  
COMFORT TRANSPORTATION PTE LTD  
7010045  
DMER NO.  
ESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
65508755 (R)  
(P) (O)

UNIT CARD NO.

REGN NO.: SHA3745P

MILEAGE

MAKE: HYUNDAI

FUEL

E.....1/2.....F

MODEL I-40

DATE/TIME IN 02.11.2019 16:30

YR OF MANU 28.04.2016

TARGET DATE


CHASSIS CODE KMHLB41UMGU087870

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 02.11.2019  
NATURE: 3P 02.11.19

S/NO LABOR CODE DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Idgement Slip

Exit Pass

o.: SHA3745P

JUMANI

Vehicle No.:

SHA3745P

Service Advisor

Signature/Date

Name of Service Advisor

Date

igned to Service Reception upon collection

To be kept by Security Guard

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd  
20 McCallum Street  
#09-01 Tokio Marine Centre  
Singapore 069046

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Dillen Senthilan so Selvarajoo

Date: 05 Nov 2019

## Preliminary Advice

Insured Vehicle No	: YN6698C	Accident Date	: 02/11/2019
TP Vehicle No	: SHA3745P	Assignment Date	: 04/11/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 3 days
Date of Inspection	: 04/11/2019		
Inspection At	: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s & n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,039.88
Revised Amount	:S\$	3,492.28
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,492.28

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : TP : WP

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	04/11/2019 09:01
Date Of Accident	02/11/2019 15:50
Exact Location Of Accident	NEW UPP CHANGI RD TWDS GEYLANG
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA3745P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

### Driver

Name of Driver	SIA KHIM CHIANG
NRIC No	S2010719G
Date Of Birth	28/12/1950
Occupation	OUTDOOR
Date Of Driving Pass	02/10/1973
Driving Experience	46 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-83894097
Fax Number	
Contact Number	
EMail Address	SIA_KHIMCHIANG@YAHOO.COM

Address	BLK 898 TAMPINES STREET 81 #10-804
Postcode	520898
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN6698C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	RIGHT REAR

No. Of Passenger (Including Driver)



## Sketch Plan Pg. 1

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMPILING TRANSPORTATION POLICE  
POLICE RECORDS MANAGEMENT CENTRE

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


3/10/19  
H. B. Mariani (2019)  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

GIA/ACC Sketch Plan Pg. 1



# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2/11/2019 at about 1550 hrs, I vehicle A were queue up at traffic light junction. There was few car ahead of me. When traffic green the road started to move, there was a big space ahead of me. Suddenly vehicle B Cuts in sharply and brush against my left front bumper and it drop.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COM-ORI TRANSPORTATION LTD  
152, PULAU TIKU, LAMPANG, MALAYSIA

Policyholder's Signature  
Date & Time:

COM-ORI TRANSPORTATION LTD

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

3/11/19.  
D. S. Maniam (ISO)

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHA 3745P

DATE 4/11/2019 14:30

MAKE :

MODEL : HYUNDAI i40

Handbook 205/60R16

KK-

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>cut</i>			\$ 544.50
	Front Bumper Bracket Top (LH) <i>xnn</i>			\$ 22.40
	Front Bumper Bracket (LH) <i>rec</i>			\$ 24.60
	Headlamp (LH) <i>scr</i>			\$ 1,388.00
	Front Fender (LH) <i>BU</i>			\$ 566.30
	Front Fender Shield (LH) <i>MIS</i>			\$ 175.90
	Front Fender Retainer <i>xnn</i>			\$ 24.60
	Front Wheel Alignment <i>cover - cut</i>			\$ 107.10
	<i>Front LH</i>			
	<b>SUB TOTAL</b>			\$ 2,853.40
	<b>LESS 20%</b>			\$ 570.68
	<b>DISCOUNTED TOTAL</b>			\$ 2,282.72
	Front Fender Advertisement Logo (LH) <i>rec</i>			\$ 100.00
	<i>merima fee - \$11/-</i>			\$ 11
				\$ 100.00
	<b>Labour Charge</b>			
	Panel Beating			\$ 560.00
	Spray Painting Charge			\$ 500.00
	Wiring			\$ 50.00
	Tuff Kote			\$ 50.00
	Frt Wheel Alignment			\$ 80.00
	<b>TOTAL LABOUR</b>			\$ 1,240.00
	<b>ESTIMATE TOTAL</b>			\$ 3,622.72

\$1052.2

\$331.4

\$662.82

\$2651.2

Nett \$90

\$280

\$400

\$30

\$30

xnn

\$3502.21

\$2800

4039.81

*6/11/19*  
*Ram (LKR)*  
*88622778 hp*  
*Parasuram@lkrato.com*  
*repairs (3)*  
*aft repair photos*  
*4/11/19 1500hrs*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Our Job Ref No 305346234

Date : 06/11/19

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : RAM

: SHA3745P

02/11/19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO --- YN6698C  
###
2. The finalized amount shall be:
  - (a) Spare Parts after List discount
  - (b) Labour Charges ###
  - Total for Part-By-Part Repair Cost** ###
  - (c) Lumpsum Repair (if applicable) N
  - Total for Lumpsum repair cost after Less: 20% \$2,800.00
  - Final Lumpsum Repair cost**

3. Estimated normal period for repairs: 3 working days

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature : 

Name : Ram

Date : 7/11/19

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Nov 2019 <a href="#">Sendback Est</a>	04 Nov 2019 15:05 <b>S\$4,039.88</b>	04 Nov 2019 17:54 <a href="#">Edit Adj Rpt</a>	<b>S\$2,800.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	HUPCO PTE LTD, Co. Reg. No.: 199206471G								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHA3745P	Date of Loss:	02/11/2019 15:00 - :59 [42 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M1908637	Policy/Cover Note No.:	MK000771 (Comprehensive) Coverage: 19/09/2019 - 18/09/2020						
Vehicle Reg. No. (Insured):	YN6698C	Policy No. (Claimant):							
		Excess:	S\$3,000.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 13/11/2019]								
Adj Asg. Remarks:	OI HAS NOT RPT THE ACCDT								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

SHA3745P (M1908637)  
[YN6698C]  
TP  
COMFORT TRANSPORTATION PTE LTD  
Nov 2 2019 3:00PM  
[HUPCO PTE LTD]  
ComfortDelGro Engineering Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	04/11/19 15:05	Repairer Estimates		Load HTM	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	05/11/19 17:59	Accident Statement From:SC - Reg. No: YN6698C, Claimant: HUPCO PTE LTD		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/11/19 16:17	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/11/19 18:10	General View		Load JPG	
2	06/11/19 18:10	General View		Load JPG	
3	06/11/19 18:10	General View		Load JPG	
4	06/11/19 18:10	General View		Load JPG	
5	06/11/19 18:10	General View		Load JPG	
6	06/11/19 18:10	General View		Load JPG	
7	06/11/19 18:10	General View		Load JPG	
8	06/11/19 18:10	General View		Load JPG	
9	06/11/19 18:10	General View		Load JPG	
10	06/11/19 18:10	General View		Load JPG	
11	06/11/19 18:10	General View		Load JPG	
12	06/11/19 18:10	General View		Load JPG	
13	06/11/19 18:10	General View		Load JPG	
14	06/11/19 18:10	General View		Load JPG	
15	06/11/19 18:10	General View		Load JPG	
16	06/11/19 18:10	General View		Load JPG	
17	06/11/19 18:10	General View		Load JPG	
18	06/11/19 18:10	General View		Load JPG	
19	06/11/19 18:10	General View		Load JPG	
20	06/11/19 18:10	General View		Load JPG	
21	06/11/19 18:10	General View		Load JPG	
22	06/11/19 18:10	General View		Load JPG	
23	06/11/19 18:10	General View		Load JPG	
24	06/11/19 18:10	General View		Load JPG	
25	06/11/19 18:10	General View		Load JPG	
26	06/11/19 18:10	General View		Load JPG	
27	06/11/19 18:10	General View		Load JPG	
28	06/11/19 18:10	General View		Load JPG	
29	06/11/19 18:11	General View		Load JPG	
30	06/11/19 18:11	General View		Load JPG	
31	06/11/19 18:11	General View		Load JPG	
32	06/11/19 18:11	General View		Load JPG	
33	06/11/19 18:11	General View		Load JPG	
34	06/11/19 18:11	General View		Load JPG	
35	06/11/19 18:11	General View		Load JPG	
36	07/11/19 09:40	Reinspection Photo		Load JPG	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
37	07/11/19 09:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
38	07/11/19 09:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
39	07/11/19 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
40	07/11/19 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
41	07/11/19 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
42	07/11/19 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
43	07/11/19 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
44	07/11/19 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
45	07/11/19 09:41	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
46	07/11/19 09:41	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
47	07/11/19 09:41	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
48	07/11/19 09:41	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
49	07/11/19 09:41	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
50	07/11/19 09:41	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print
1	12/11/19 15:52	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee		Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	04/11/19 15:06	E-filed GIA report		Load PDF	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	05/11/19 18:01	TP - SHA3745P - Singapore Accident Statement		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI19019499/FSF3E2

Date: 14/11/2019

## REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MK000771

Claimant Vehicle No : SHA3745P

Insured Vehicle No : YN6698C

Date of Loss: 02/11/2019

Nature of Claim: TP Claim No: M1908637

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHA3745P

Make &amp; Model: HYUNDAI I40, 1.7 D CRDi (A)

Engine No: D4FDGU613756

Reg. Date: 28/04/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMGU087870

Colour: Blue

Odometer: 469551 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

## CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Hankook 5 mm

Rear Left Side: Hankook 5 mm

Front Right Side: Hankook 5 mm

Rear Right Side: Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,788.88	2,741.28	47.60	1.71
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,240.00	740.00	500.00	40.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,039.88</b>	<b>3,492.28</b>	<b>547.60</b>	<b>13.55</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,800.00</b>		
<b>(S\$)</b>	4,039.88	2,800.00	1,239.88	30.69
<b>+ GST 7.00/7.00% (S\$)</b>	282.79	196.00	86.79	30.69
<b>Nett Amount (S\$)</b>	<b>4,322.67</b>	<b>2,996.00</b>	<b>1,326.67</b>	<b>30.69</b>

## INSPECTION

Date of Assignment: 04/11/2019 Present Location:

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 04/11/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: Hiew May Fung



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 14 Nov 2019)
<b>Parts:</b>	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHA3745P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cut	1,052.20 FL	*1,052.20 FL
2	1		*FRT BUMPER UPR BRKT LH	Not Necessary	22.40 FL	*- FL
3	1		*FRT BUMPER BRKT LH	Necessary	24.60 FL	*24.60 FL
4	1		*HEADLAMP LH	Scratched	1,388.00 FL	*1,388.00 FL
5	1		*FRT FENDER LH	Buckled	566.30 FL	*566.30 FL
6	1		*FRT FENDER SHIELD LH	Missing	175.90 FL	*175.90 FL
7	1		*FRT FENDER RETAINER LH	Not Necessary	24.60 FL	*- FL
8	1		*FRT WHEEL CAP LH	Cut	107.10 FL	*107.10 FL
9	1		*FRT FENDER ADVERTISEMENT STICKER LH	Necessary	100.00 F	*90.00 FS
					<b>Sub Total (S\$)</b>	<b>3,461.10 3,404.10</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>672.22 662.82</b>
					<b>Total Parts (S\$)</b>	<b>2,788.88 2,741.28</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	560.00	280.00
2	SPRAY PAINTING	New	500.00	400.00
3	WIRING CHECK	New	50.00	30.00
4	TUFF KOTE	New	50.00	30.00
5	WHEEL ALIGNMENT	New	80.00	0.00
Gross Labour Cost (S\$)			<b>1,240.00</b>	<b>740.00</b>

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;