

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

Bok Seng Logistics Pte Ltd
No 5 Tuas Ave 3
Singapore 639405
No 6 Tuas Ave 5 Gate 4
Attention : Motor Claim Department
Contact : 6416 1975 Fax No : 6861 3508

Estimate : ES002996
Date : 04/11/2019
Vehicle Num. : SJD9668A
Make/Model : HONDA FIT 1.3A
Chassis/Eng# :
Accident Date : 01/11/2019
Claim No :
Reference : SKR19957
Policy No. : D18MPC0001414 01

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

Chassis: GE61019020

- | S/N | Quantity | Particular |
|-----|----------|-----------------------------|
| 1 | 1 | FRONT BUMPER |
| 2 | 2 | BUMPER SIDE BRACKET |
| 3 | 6 | BUMPER CLIP |
| 4 | 1 | HEADLAMP, RHS |
| 5 | 1 | HEADLAMP BRACKET RH |
| 6 | 1 | BUMPER REINFORCEMENT |
| 7 | 1 | MUDGUARD, RHS |
| 8 | 1 | MUDGUARD INNER GARNISH |
| 9 | 6 | MUDGUARD INNER GARNISH CLIP |
| 10 | 1 | FRONT DOOR, RHS |
| 11 | 1 | SIDE MIRROR, RHS |
| 12 | 1 | LOWER GARNISH |
| 13 | 1 | WASHER TANK |
| 14 | 1 | AIR-CON CONDENSER |
| 15 | 1 | BUMPER SPOTLAMP |
| 16 | 1 | HEADLAMP, LHS |

548.20	823.50	cre -
105.20	210.40	de -
5.00	30.00	rec -
620	985.20	cre -
	198.50	cre -
351	431.20	bt -
	381.20	Rx
	167.30	de -
5.00	30.00	rec -
859.60	343.20	bt -
451.30	551.20	✓
	343.20	Rx
	198.20	de -
	762.20	dd -
	198.20	xm
620	985.20	cre -

List Total S\$:
* Hands 20% ~~15.00~~ Discount S\$:

5096.70
20% - 4077.36
6498.84

LABOUR :
TO PANEL BEAT AND REPAIR FRONT BODY

700
850.00

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

Bok Seng Logistics Pte Ltd
No 5 Tuas Ave 3
Singapore 639405
No 6 Tuas Ave 5 Gate 4
Attention : Motor Claim Department
Contact : 6416 1975 Fax No. : 6861 3508

Estimate : ES002996

Date : 04/11/2019
Vehicle Num. : SJD9668A
Make/Model : HONDA FIT 1.3A
Chassis/Eng# :
Accident Date : 01/11/2019
Claim No. :
Reference : SKR1995Y
Policy No. : D18MPC0001414_01

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS

TO DISMANTLE/REPLACE AIR-CON CONDENSER
TO TOP-UP GAS

TO SPRAY PAINTING

TOWING CHARGES

LOSS OF USE : 7 DAYS @ S\$120/DAY

Labour Total S\$:

100✓
150.00

750
950.00

60.00 x m

2010.00 1550

Link & its Consultants hence notify the Reparer of the following:

- * To inspect before spray painting
- * To inspect damaged part during resurvey
- * To inspect and confirm the confirmation
- * To inspect and confirm "Without Prejudice" basis
- * To inspect and confirm the damaged
- * To inspect and confirm the damaged and
- * To inspect and confirm the damaged and

Acknowledged by Reparer
Signature:
Date:

Tan Jia 97445249
'WP'
5/11/19 @ 220 / m
Resurvey after repair
5 days
Sincere & Reliable to work

Total S\$: 8,508.84

4077.36
1550

5627.36

45945.00
5 days

SIN SHENG ENGINEERING SERVICES