





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/11/2019

User ID : CatherineLee

Section A - Accident Details		
Registration Number	SG3030G	
Case Reference Number	BUS/10/19/1085	
Registration Date	1/2/2019	
Company Type	SMRT Buses Ltd	
Make	B5LH	
Model	VOLVO - B5LH AUTO	
Name of Driver	Cheong Chee Seng	
Type of Accident	Head To Side	
Accident Date and Time	31/10/2019 8:00 PM	
Accident Reported Date and Time	1/11/2019 2:53 PM	
Is Surveyor Required?	Yes	
Survey by		
Vehicle is Towed Back?	No	
Towed Back Date and Time		
Replacement Vehicle issued?	No	
Job Card Number	24104120	
Special Instruction to ARC, if any	SG3030G-LEFT FRONT PORTION SMN4209L (TP) INSURED WITH AIG	
Prepared Date and Time	2/11/2019 10:36 AM	
Chassis Number	YV3T1U226KA193060	
Mileage		
Work Shop		
Repair Completion Date and Time		

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$1,590.00
Total Spray Cost	\$1,282.00	\$1,112.00
Total Spare Part Cost	\$150.00	\$150.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,552.00	\$2,852.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Boon Chew Tay	STEVE CHEN
ARC / Surveyor Sign Off Date	02/11/2019 10:54 AM	05/11/2019 10:09 AM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/11/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION FRONT TO REAR	\$2,120.00	\$1,590.00
Total Labour	\$2,120.00	\$1,590.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$1,282.00	\$1,112.00
Total Spray Painting & Panel Beating	\$1,282.00	\$1,112.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER SG LOVE	1.00	\$75.00	0.00	\$75.00	Replace	Replace
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	Replace
Total					\$150.00		\$150.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
50 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 04/11/2019

User ID : BoonChewTay

Section A - Accident Details

Registration Number	SG3030G
Case Reference Number	BUS/10-19/1085
Registration Date	1/2/2019
Company Type	SMRT Buses Ltd
Make	B5LH
Model	VOLVO - B5LH AUTO
Name of Driver	Cheong Chew Seng
Type of Accident	Head To Side
Accident Date and Time	31/10/2019 8:00 PM
Accident Reported Date and Time	1/11/2019 2:53 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24104120
Special Instruction to ARC, if any	SG3030G-LEFT FRONT PORTION SMN4209L (TP) INSURED WITH AIG
Prepared Date and Time	2/11/2019 10:36 AM
Chassis Number	YV3T1U226KA193060
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$1,282.00	\$0.00
Total Spare Part Cost	\$150.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,552.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	02/11/2019 10:54 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

4/11/19, 2.30pm
Stereo (CLKK) w/L Repair
L/S
R/L AL SPY
3 days



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/11/2019

User ID : BoonChewTay

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
TO REPAIR LH PORTION FRONT TO REAR		\$2,120.00				1590			
Total Labour		\$2,120.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$1,282.00				1112			
Total Spray Painting & Panel Beating		\$1,282.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER SG LOVE	1.00	\$75.00	0.00	\$75.00	Replace	ARC
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	ARC
Total					\$150.00		\$150.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									