

ASS. REC. BY:

REF: CS/CT1191/19539/Q- f301 Special Instruction:

SURVAYOR Sun Pin ASSIGNMENT (Office)From (Person): Chong Bron Sen of CT1 Date/Time: 5.11.19 2.46pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PC F38A Insured: CB 8833Pat Workshop m/s Connet 3 Tel: 98509666of NO 566 woodland roadPolicy No: \_\_\_\_\_ Claim No: SNMIAD20526

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 4.11.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 5.11.19 3.05pm Person Contacted: Winnu Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	PC F38A - CS/EG1 7002972 / K1062 R.A - 06/12/2016
	CB 8833P - CS 3/AXA 1400267 / Agell - 1 R.A - 20/01/2018
4/12/19	LS \$7950 confirmed by email (Red 10,574, 5790)

AGS REC. BY: Sun PinREF: CT1

## ASSIGNMENT

From:

Date:

8.11.2019

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

PC 738 A

at Workshop m/s

Connect 3

of

566 woodland Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

1000A.M and wally

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

PC 738 A

Yr Regn:

25/JUL/2011Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

King Long XM6117K. c.c 6693

Colour

Multicolour

A/C:

Insured / Std / NI / NA

Sp. Reading

59 0456.

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

LA6R1ESH4BB101467.Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or Steel Rim

Tyre Size:

F: 275 / 80 R22.5R: 275 / 80 R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

04/11/2019

D.O.I.

08/11/2019

Survey held at

Connect 3.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front Right

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Sun Pin,pls check parts prices & see  
my remarks.

RECEIVED 05 DEC 2019

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2) slp - typist

Pay Form:

menmen

Lump Sum / U.C. /

7950/2

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

220220

## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Tuesday, 5 November 2019 2:46 PM  
**To:** Winnie Chai  
**Cc:** Jeffrey Tay; assignments  
**Subject:** RE: OUR REF: SNM19D205216CB8833P-CBS- Request for pre repair inspection for accident involving PC738A & CB8833P ( yr insured ) on 04/11/19

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s Ikk AUTO CONSULTANTS to survey your client's vehicle.

Aside to Ikk AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

### Chong Boon Sen

Claims Executive  
Department

### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**From:** Winnie Chai [mailto:connect3winnie@gmail.com]  
**Sent:** Tuesday, November 5, 2019 2:31 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Cc:** Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>  
**Subject:** Re: OUR REF: SNM19D205216CB8833P-CBS- Request for pre repair inspection for accident involving PC738A & CB8833P ( yr insured ) on 04/11/19

LKK pls

On Tue, Nov 5, 2019 at 2:28 PM Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)> wrote:

Without prejudice

Dear Sir,

LKK

STA

LBS

**Chong Boon Sen**

Claims Executive

Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Claims Dept of CTI

**Sent:** Tuesday, November 5, 2019 1:49 PM

**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; Jeffrey Tay <[Jeffrey.Tay@sg.cntaiping.com](mailto:Jeffrey.Tay@sg.cntaiping.com)>; [connect3winnie@gmail.com](mailto:connect3winnie@gmail.com)

**Subject:** OUR REF: SNM19D205216CB8833P-CBS- Request for pre repair inspection for accident involving PC738A & CB8833P ( yr insured ) on 04/11/19

Dear Boon Sen,

Please conduct PRS for PC738A.

Note : officer in charge – Boon Sen 63896171.

Thank you

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平狮城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Winnie Chai [<mailto:connect3winnie@gmail.com>]

**Sent:** Tuesday, November 05, 2019 10:53 AM

**To:** Claims Dept of CTI

**Subject:** Request for pre repair inspection for accident involving PC738A & CB8833P ( yr insured ) on 04/11/19

Morning

Attached is the GIA & estimate for yr ref.

Pls kindly assign yr surveyor down for the survey.

Thanks

--

Winnie Chai


Connect3

HP:9850-9666

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



--  
Winnie Chai  
Connect3  
HP:9850-9666

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	070M
<b>Vehicle Details</b>	
Vehicle No.:	PC738A
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Nov 2019
Vehicle Make:	KING LONG
Vehicle Model:	XMQ6117K
Primary Colour:	Multicolor
Manufacturing Year:	2011
Engine No.:	ISBE428521985382
Chassis No.:	LA6R1FSH4BB101467
Maximum Power Output:	-
Open Market Value:	\$108,123.00
Original Registration Date:	25 Jul 2011
First Registration Date:	25 Jul 2011
Transfer Count:	1
Actual ARF Paid:	\$5,407.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	24 Jul 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$31,089.00
COE Rebate Amount:	\$5,290.00
<b>Total Rebate Amount:</b>	<b>\$5,290.00</b>

The information contained herein is correct as at 11 Nov 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/11/2019 10:36
Date Of Accident	04/11/2019 16:10
Exact Location Of Accident	MARSILING HEAVY VEH CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC738A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	REN QUAN TRANSPORT
Co Reg No	52896070M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96659336

### Vehicle Particulars

Manufacturer	KING LONG
Model	XMQ6117K-6.7 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	VFX/P1656875
Cover Note Number	

### Driver

Name of Driver	GAO YUMING
Passport No/FIN	G2892662L
Date Of Birth	26/01/1975
Occupation	OUTDOOR
Date Of Driving Pass	19/12/2016
Driving Experience	2 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-81766760
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	NA
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 04/11/19 @ 11:00HRS, I HAVE PARKED MY BUS PC738A AT CARPARK LOT AT MARSILING HEAVY VEHICLE CARPARK AND WENT OFF. WHEN I COLLECT MY BUS AROUND 17:00HRS, I REALIZED ANOTHER BUS CB8833P HAS HIT ONTO MY BUS FRONT PORTION.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	CB8833P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	AXA INSURANCE PTE LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Winnie Chai  
Connect3


Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

A = PC738A

B = CB8833P



marshaling heavy veh CP.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 04/11/19 @ 11:00hrs. I have parked my bus PC738A @ carpark lot @ marshaling heavy vehicle carpark & went off. When I collect my bus around 17:00hrs, I realized another bus CB8833P has hit onto my bus front portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*Y. J. 2. 19*

Winnie Chai  
Connect3

Reporting Centre Personnel's Signature  
Name:  
NRIC/TIN No.:



### CONNECT 3

566 Woodlands Road ( Mandai Estate ) Singapore 728697  
Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L  
G S T : 5 3 3 6 0 0 6 1 L

QT19/PC738A/TPC-598

<b>China Taiping Insurance (Singapore) Pte Ltd</b>
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

Dear Sir

Cost of Repair to Vehicle PC738A

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$\$)	AMOUNT (\$\$)	
①.	Front windscreen / CRA	1	3,800.00	3,800.00	3,100
②.	Front windscreen inner seal / Nec	1	780.00	780.00	550
3.	Front windscreen moulding / Nec	1	650.00	650.00	500
④.	Front RH rear view mirror assy / B.R.	1	1,350.00	1,350.00	1,200
5.	Front RH wiper arm & blade / SCR	1	186.00	186.00	160
6.	Front RH wiper hub cover / CRU.	1	58.00	58.00	/
7.	Front RH headlamp X SVC	1	1,450.00	1,450.00	
8.	Front panel X R.	1	4,200.00	4,200.00	
⑨.	Front bumper / CRU.	1	1,650.00	1,650.00	1,450
10.	Front RH bumper bracket / Nec	1	550.00	550.00	400
11.	Sealant windscreen / Nec. (SN)	8	40.00	320.00	/
⑫.	Labour to remove & refit front windscreen / Nec	1	1,000.00	1,000.00	700
13.	Check wiring / Nec	1	30.00	30.00	/
14.	Labour charges 5PCS	1	1,500.00	1,500.00	1,300
15.	Spray painting	1	1,000.00	1,000.00	900

7,418  
Part discount 10%  
6,676.20  
N = 320  
L = 2,930  
QUOTATION 9,926.20  
- 20%  
7,940.96

L/S = 7,950

	<b>SUB-TOTAL</b>	<b>S\$18,524.00</b>
--	------------------	---------------------

- Price before 7% gst

Thank you  
Yours faithfully,



Winnie Chai  
HP: 9850-9666



*[Handwritten signature]* 12/11/19

Repair days - 7 days.

Sun Pm

Lump sum

After spray photo.

TP without prejudice.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

• **Oi Sun Pin (LKK Auto)**

---

**From:** Winnie Chai <connect3winnie@gmail.com>  
**Sent:** Wednesday, 4 December, 2019 9:42 AM  
**To:** Oi Sun Pin (LKK Auto)  
**Subject:** Re: REMINDER - Finalization for PC738A

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

ok cfm

On Tue, Dec 3, 2019 at 6:27 PM Oi Sun Pin (LKK Auto) <[sunpin@lkkauto.com](mailto:sunpin@lkkauto.com)> wrote:

Dear Winnie,

Please refer our finalize adjustment estimate update. L/S amount \$7,950, Repair day 7 days. (Lump sum repair, before gst). If agree please update.

Thank you.

Best Regards,

**Oi Sun Pin** | Assistant Automotive Assessor

**LKK Auto Consultants**

Phone: 6256 3561 | Email: [Sunpin@lkkauto.com](mailto:Sunpin@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Winnie Chai [<mailto:connect3winnie@gmail.com>]  
**Sent:** Monday, 25 November, 2019 9:52 AM  
**To:** Oi Sun Pin (LKK Auto)  
**Subject:** REMINDER - Finalization for PC738A

Hi Sun Pin

Pls kindly revert on the correct finalization.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Nov 2019		12 Nov 2019 15:29 <a href="#">Edit Adj Rpt</a>	<b>\$7,950.00</b> <a href="#">Edit Estimates</a>	<b>\$7,950.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>





























  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: -, Co. Reg. No.: -									
Main Claimant: <b>REN QUAN TRANSPORT</b> , Co. Reg. No.: 52896070M									
Vehicle Reg. No.: <b>PC738A</b>		Date of Loss: 04/11/2019 16:00 - :59 [99 Months and 10 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / SNM19D205216C02</b>		Policy/Cover Note No.: <b>DMB1SN30203419011</b>							
Vehicle Reg. No. (Insured): <b>CB8833P</b>		Policy No. (Claimant): <b>VFX/P1656875</b>							
		Excess: <b>\$0.00</b>							
Repairer: <b>Connect3 (HQ)</b> 566 Woodlands Road, 728697 Woodlands - Tel: 98509666									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]									
Claimant's Insurer: <b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>OI SUN PIN</b> ] ... [Final Rpt due 21/11/2019]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

















## Claim Documents

\*PC738A (SNM19D205216C02)  
[CB8833P]  
TP  
REN QUAN TRANSPORT  
Nov 4 2019 4:00PM  
[-]  
Connect3

Upload Documents			Upload Photos			Compose New Letter			View <span>View in Browser</span>		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Connect3 (HQ)							Thumbnail	Print	
1	05/11/19 10:44	Accident Statement							Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Connect3 (HQ)							Thumbnail	Print	
1	05/11/19 10:44	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
2	05/11/19 10:44	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
3	05/11/19 10:44	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
4	05/11/19 10:44	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
5	05/11/19 10:44	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
6	05/11/19 10:44	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
7	05/11/19 10:44	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
8	05/11/19 10:44	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
9	05/11/19 10:44	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
10	05/11/19 10:44	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
11	05/11/19 10:44	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
12	05/11/19 10:44	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
13	05/11/19 10:44	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
14	05/11/19 10:44	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
15	05/11/19 10:44	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
16	05/11/19 10:44	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	19/11/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
2	19/11/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
3	19/11/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
4	19/11/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
5	19/11/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
6	19/11/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
7	19/11/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
8	19/11/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
9	19/11/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
10	19/11/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
11	19/11/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
12	19/11/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
13	19/11/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
14	19/11/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
15	19/11/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
16	19/11/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
17	19/11/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Connect3 (HQ)	Thumbnail	Print
18	19/11/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
19	19/11/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
20	19/11/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
21	19/11/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
22	19/11/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
23	19/11/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
24	19/11/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
25	19/11/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
26	19/11/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
27	19/11/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
28	19/11/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
29	19/11/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
30	19/11/19 17:41	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
31	19/11/19 17:57	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
32	19/11/19 17:59	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
33	19/11/19 17:59	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
34	19/11/19 17:59	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
35	19/11/19 17:59	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
36	19/11/19 17:59	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
37	19/11/19 17:59	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
38	19/11/19 17:59	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
39	19/11/19 17:59	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
40	19/11/19 17:59	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
41	19/11/19 17:59	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Connect3 (HQ)	Thumbnail	Print
1	05/11/19 10:42	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	05/11/19 10:42	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	05/11/19 10:43	AXA FORM [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	05/11/19 10:43	AXA FORM [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Connect3 (HQ)	Thumbnail	Print
1	05/11/19 10:44	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Connect3 (HQ)	Thumbnail	Print
1	05/11/19 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	05/11/19 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	05/11/19 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	05/11/19 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	05/11/19 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	05/11/19 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	05/11/19 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	05/11/19 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	05/11/19 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	05/11/19 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	05/11/19 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	05/11/19 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	05/11/19 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	05/11/19 10:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	05/11/19 10:44	Accident Photo	 Load JPG	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Connect3 (HQ)		Thumbnail	Print
					<input checked="" type="checkbox"/>
16	05/11/19 10:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Connect3 (HQ)		Thumbnail	Print
1	05/11/19 10:42	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	05/11/19 10:42	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>
3	05/11/19 10:43	AXA FORM		Load JPG	<input checked="" type="checkbox"/>
4	05/11/19 10:43	AXA FORM		Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119019539/QVF3E2

Date: 05/12/2019

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN30203419011

Claimant Vehicle No : PC738A Insured Vehicle No : CB8833P

Date of Loss: 04/11/2019 Nature of Claim: TP Claim No: SNM19D205216C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **PC738A**

Make & Model: KING LONG XMQ6117K, 6.7 (A) Engine No: ISBE428521985382

Reg. Date: 25/07/2011 (Man. Year: 2011) Chassis No: LA6R1FSH4BB101467

Colour: Multi-colour Odometer: 590456 km

Engine Capacity: 6693 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 275/80 R22.5 Rear Tyre Size: 275/80 R22.5

Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm

Front Right Side: Pirelli 5 mm Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,994.00	6,996.20	7,997.80	53.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	2,930.00	600.00	17.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>18,524.00</b>	<b>9,926.20</b>	<b>8,597.80</b>	<b>46.41</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,950.00</b>		
<b>(S\$)</b>	18,524.00	7,950.00	10,574.00	57.08
<b>+ GST 7.00/7.00% (S\$)</b>	1,296.68	556.50	740.18	57.08
<b>Nett Amount (S\$)</b>	<b>19,820.68</b>	<b>8,506.50</b>	<b>11,314.18</b>	<b>57.08</b>

## INSPECTION

Date of Assignment: 12/11/2019

Date Inspected: 08/11/2019 Inspected At: Connect3 (HQ)  
566 Woodlands Road  
Singapore 728697

Estimated Period of Repair: 7.0 days

Adjuster: OI SUN PIN

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 05 Dec 2019)	
<b>Parts:</b>	N/A	KING LONG XMQ6117K 6.7 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PC738A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Cracked	3,800.00 F	*3,100.00 FL
2	1		*FRONT WINDSCREEN INNER SEAL	Necessary	780.00 F	*550.00 FL
3	1		*FRONT WINDSCREEN MOULDING	Necessary	650.00 F	*500.00 FL
4	1		*FRONT RH REAR VIEW MIRROR ASSY	Broken	1,350.00 F	*1,200.00 FL
5	1		*FRONT RH WIPER ARM & BLADE	Scratched	186.00 F	*160.00 FL
6	1		*FRONT RH WIPER HUB COVER	Crushed	58.00 F	*58.00 FL
7	1		*FRONT RH HEADLAMP	Serviceable	1,450.00 F	*- FL
8	1		*FRONT PANEL	Repair	4,200.00 F	*- FL
9	1		*FRONT BUMPER	Crushed	1,650.00 F	*1,450.00 FL
10	1		*FRONT RH BUMPER BRACKET	Necessary	550.00 F	*400.00 FL
11	8		*SEALANT WINDSCREEN	Necessary	320.00 FS	*320.00 FS
					<b>Sub Total (\$\$)</b>	<b>14,994.00 7,738.00</b>
					<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00 741.80</b>
					<b>Total Parts (\$\$)</b>	<b>14,994.00 6,996.20</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE & REFIT FRONT WINDSCREEN	New	1,000.00	700.00
2	CHECK WIRING	New	30.00	30.00
3	LABOUR CHARGES	New	1,500.00	1,300.00
4	SPRAY PAINTING	New	1,000.00	900.00
Gross Labour Cost (\$\$)			<b>3,530.00</b>	<b>2,930.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >