

ASS. REC. BY:

REF: CS/CT119019556/ Qs f302 Special Instruction:

Surveyor: Sun Pin

ASSIGNMENT (Office)

From (Person): Tang Hock Lye of CT1 Date/Time: 5.11.19 3.15p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PC L933M Insured: PA 90604

at Workshop m/s Connect 3 Tel: 98509666

of 566 woodland Road

Policy No: Claim No: SNM190205180

Sum Insured: Excess:

Make of Veh: D.O.A. 31.10.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 5.11.19 3.43pm Person Contacted: Winnie Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	PC L933M - NBA / INC 1301132814 D.O.A - 21/10/2018
	PA 90604 - CS3 / CT1190091921 Gcd302 D.O.A - 17/05/2019

ASS. REC. BY: Sun PmREF: CT2

ASSIGNMENT

From:

Date:

19. Nov. 2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

PC 6933M

at Workshop m/s

Connects 3

of

566 Woodland Rd

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

10-309-m Amur Waiting

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

'up'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

PC 6933MYr Regn: 14/Apr/2015Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

King long XM6129K. c.c. 8849

Colour

Multicolour.A/C: Insured / Std / NI / NA

Sp. Reading

221683T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

LA6A1KBK6EB403283Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or Steel Rim

Tyre Size:

F: 205/80 R22.5R: 205/80 R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 31/10/2019D.O.I. 19/11/2019

Survey held at

Connect 3.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 16 DEC 2019

Confirm with Winnie

Finalize \$ 5,800 @ 5 day (L/S)

(\$ 4,230.00 Red - 42%)

Date/Time, File Pass to?

16/12/19

1)

Type: 4

: Preli. Report



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Rep. Form:

Lump Sum / L/S: C

\$ 5,800/- 4s

220
220

13/12/2019

13/12/2019

Nivitha (LKK Auto)

From: Tang Hock Lye <hocklye.tang@sg.cntaiping.com>
Sent: Tuesday, 5 November 2019 3:15 PM
To: Winnie Chai
Cc: Claims Dept of CTI; Jeffrey Tay; assignments@lkkauto.com
Subject: RE: OUR REF: SNM19D205180-PA9060Y-CML- Request for pre repair inspection for accident involving PC6933M & PA9060Y (yr insured) 31/10/19on

WITHOUT PREJUDICE

Hi Winnie

We refer to your email below.

Without admission of liability, we are agreeable to Direct settlement subject to consistency of damages base on LKK Auto findings with supporting documents.

By copy to LKK: Please assist to arrange for PRS survey.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Winnie Chai <connect3winnie@gmail.com>
Sent: Tuesday, November 5, 2019 3:05 PM
To: Tang Hock Lye <hocklye.tang@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D205180-PA9060Y-CML- Request for pre repair inspection for accident involving PC6933M & PA9060Y (yr insured) 31/10/19on

Hi Ben

No surveyor from LKK contacted me for the survey.

Pls kindly assist as LKK stated there is no assignment assigned to them for this case.

Thanks

On Mon, Nov 4, 2019 at 7:43 PM Winnie Chai <connect3winnie@gmail.com> wrote:

Hi Ben

We would like Calvin Ikk to attend the survey

Thanks & regards

On 4 Nov 2019, at 5:54 PM, Tang Hock Lye <hocklye.tang@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Winnie

We refer to your email of 04.11.19.

We would like to conduct pre-repair survey of the vehicle at the appointed workshop.

We propose the following list of surveyors to be nominated as the Single Joint Expert to conduct survey of the claimant's vehicle:-

1. ADRIAN LING	6. KENNETH KONG
2. Kelvin Ang	7. SIMON HO
3. SEE CHEW SENG	8. CHUA WEIJIE
4. MOHD FADHILAH BIN OSMAN	9. MARCUS CHUA
5. XING QUO QIANG	10. HENRY NG

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

As per the NIMA Protocol, the survey by our appointed surveyor would include survey of your vehicle pre-repair, after it is dismantled, and post repairs. Hence, you need to provide us / our surveyors with the list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.

As stated above, please inform us and our surveyor after the claimant's vehicle had been repaired so that our surveyor can carry out post repair inspection before the vehicle is returned to your client. Please co-ordinate with our surveyor immediately after the repair is completed.

Thank you.

Best Regards

Ben Tang

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #XX-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城
Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Monday, November 4, 2019 5:30 PM

To: Tang Hock Lye <hocklye.tang@sg.cntaiping.com>; Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>; connect3winnie@gmail.com

Subject: OUR REF: SNM19D205180-PA9060Y-CML- Request for pre repair inspection for accident involving PC6933M & PA9060Y (yr insured) 31/10/19on

Dear Ben,

Please conduct PRS for PC6933M.

Note : officer in charge – Ben Tang 63896175.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城
Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Winnie Chai [<mailto:connect3winnie@gmail.com>]

Sent: Monday, 4 November, 2019 3:32 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: connect3lau@gmail.com

Subject: Request for pre repair inspection for accident involving PC6933M & PA9060Y (yr insured)
31/10/19on

Hi

Attached is the GIA report & estimate for yr ref.

Pls kindly assign yr surveyor down for the survey.

Thanks

--

Winnie Chai

Connect3

HP:9850-9666

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

--

Winnie Chai

Connect3

HP:9850-9666

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	002G
Vehicle Details	
Vehicle No.:	PC6933M
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Nov 2019
Vehicle Make:	KING LONG
Vehicle Model:	XMQ6129K DIESEL AUTO 51 SEATERS
Primary Colour:	Multicolor
Manufacturing Year:	2015
Engine No.:	ISL89E5320B22084071
Chassis No.:	LA6A1KBK6EB403283
Maximum Power Output:	-
Open Market Value:	\$145,703.00
Original Registration Date:	14 Apr 2015
First Registration Date:	14 Apr 2015
Transfer Count:	2
Actual ARF Paid:	\$7,286.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Apr 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$55,011.00
COE Rebate Amount:	\$29,700.00
Total Rebate Amount:	\$29,700.00

The information contained herein is correct as at 20 Nov 2019

OK

Oi Sun Pin (LKK Auto)

From: Winnie Chai <connect3winnie@gmail.com>
Sent: Wednesday, 11 December, 2019 10:32 AM
To: Oi Sun Pin (LKK Auto)
Subject: Re: Finalization for PC6933M

Noted.

On Wed, Dec 11, 2019 at 9:23 AM Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com> wrote:

Dear Winnie,

Please refer our finalize adjustment estimate update (PC 6933M). L/S amount \$5,800, Repair day 5 days. (Lump sum repair, before gst). If agree please update.

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Winnie Chai [mailto:connect3winnie@gmail.com]
Sent: Tuesday, 10 December, 2019 11:22 AM
To: Oi Sun Pin (LKK Auto); Celine Fong (LKKAuto); Olivia Lau (LKKAuto)
Subject: final Reminder - Finalization for PC6933M

Hi Sun Pin

Pls kindly revert on the finalization.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/11/2019 14:20
Date Of Accident	31/10/2019 06:50
Exact Location Of Accident	AT ANG MO KIO AVE 1 HEAVY VEHICLE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC6933M
Insured/Policyholder	
Name Of Registered Owner	GTS TRAVEL PTE LTD
Co Reg No	201312002G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83041121
Alternative Phone No	OFFICE-83041121

Vehicle Particulars

Manufacturer	KING LONG
Model	XMQ6129K DIESEL AUTO 51 SEATERS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5068503350-04
Cover Note Number	

Driver

Name of Driver	LAU LIANG MENG
NRIC No	S1470495G
Date Of Birth	29/07/1961
Occupation	OUTDOOR
Date Of Driving Pass	01/04/2010
Driving Experience	9 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83041121
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	APT BLK 405 ANG MO KIO AVENUE 10 #08-669
Postcode	560405
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PA9060Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Responsible Person's Signature
Name:
NRIC/FIN No.:



Scanned with
CamScanner

SKETCH PLAN



A - PC 6933M

B - PA 90605

Amk Ave 1 Heavy Vehicle Car Park

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 31/10/19 around 06:5hrs at Amk Ave 1 Heavy Vehicle Car Park
 My Bus PA 6933M was traveling straight, suddenly Veh B
 PA 90605 reversed out from parking lot collided onto my Bus
 right portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Signature
 Date & Time:



Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/TIN No.:



Scanned with
 CamScanner

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

QT19/PC6933M/TPC-596

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Rd #15-02

Springleaf Tower

Singapore 079909

QUOTATION

5,821.6

L/S = 5,800

Dear Sir

Cost of Repair to Vehicle PC6933M

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$\$)	AMOUNT (\$\$)
1.	RH side guard blue color	1	550.00	550.00
2.	RH side guard chrome color	1	780.00	780.00
3.	RH side panel	1	4,200.00	4,200.00
4.	Sealant	10	40.00	400.00
5.	Labour to remove & refit RH side glasses to assist repair 2psc.	1	600.00	600.00
6.	Labour charges	1	1,500.00	1,500.00
7.	Spray painting + sticker.	1	2,000.00	2,000.00
SUB-TOTAL				SS10,030.00

- Price before 7% gst

Thank you
Yours faithfully,Winnie Chai
HP: 9850-9666

[Signature]
25/11/19

Repair days - 5 days.

Lump Sum

After paint photo

Sun Pin (Lkk)

19/11/2019

10.00 A.M.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Dec 2019		12 Dec 2019 19:11 Edit Adj Rpt	\$5,800.00 Edit Estimates	\$5,800.00 View Rpt		Pending for Survey Report Cancel Case








Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	GTS TRAVEL PTE LTD , Co. Reg. No.: 201312002G								
Vehicle Reg. No.:	PC6933M	Date of Loss:	31/10/2019 06:00 - :59 [54 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D205180C02	Policy/Cover Note No.:	DMB1SN30494119011						
Vehicle Reg. No. (Insured):	PA9060Y	Policy No. (Claimant):	5068503350-04						
		Excess:	\$0.00						
Repairer:	Connect3 (HQ) 566 Woodlands Road, 728697 Woodlands - Tel: 98509666								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Final Rpt due 23/12/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PC6933M (SNM19D205180C02)
[PA9060Y]
TP
GTS TRAVEL PTE LTD
Oct 31 2019 6:00AM
[-]
Connect3

Upload Documents Upload Photos Compose New Letter		View View in Browser
Assessment Reports		1 per page <input type="checkbox"/>
No	Finalized On	Hua Hong Pte Ltd (Sungei Kadut)
1	04/11/19 14:30	Accident Statement
		Thumbnail <input type="checkbox"/> Load HTM
Photos/Images		3 per page <input type="checkbox"/>
No	Finalized On	Hua Hong Pte Ltd (Sungei Kadut)
1	04/11/19 14:29	Accident Photo [Linked Accident Report Documents]
		Thumbnail <input type="checkbox"/> Load JPG
2	04/11/19 14:29	Accident Photo [Linked Accident Report Documents]
		Thumbnail <input type="checkbox"/> Load JPG
3	04/11/19 14:29	Accident Photo [Linked Accident Report Documents]
		Thumbnail <input type="checkbox"/> Load JPG
4	04/11/19 14:29	Accident Photo [Linked Accident Report Documents]
		Thumbnail <input type="checkbox"/> Load JPG
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	13/12/19 09:12	Chassis Number
		Thumbnail <input type="checkbox"/> Load JPG
2	13/12/19 09:12	Odometer Reading
		Thumbnail <input type="checkbox"/> Load JPG
3	13/12/19 09:12	General View
		Thumbnail <input type="checkbox"/> Load JPG
4	13/12/19 09:12	General View
		Thumbnail <input type="checkbox"/> Load JPG
5	13/12/19 09:12	General View
		Thumbnail <input type="checkbox"/> Load JPG
6	13/12/19 09:12	General View
		Thumbnail <input type="checkbox"/> Load JPG
7	13/12/19 09:12	General View
		Thumbnail <input type="checkbox"/> Load JPG
8	13/12/19 09:12	General View
		Thumbnail <input type="checkbox"/> Load JPG
9	13/12/19 09:12	General View
		Thumbnail <input type="checkbox"/> Load JPG
10	13/12/19 09:12	General View
		Thumbnail <input type="checkbox"/> Load JPG
11	13/12/19 09:12	General View
		Thumbnail <input type="checkbox"/> Load JPG
12	13/12/19 09:12	General View
		Thumbnail <input type="checkbox"/> Load JPG
13	13/12/19 09:12	General View
		Thumbnail <input type="checkbox"/> Load JPG
14	13/12/19 09:12	General View
		Thumbnail <input type="checkbox"/> Load JPG
15	13/12/19 09:12	General View
		Thumbnail <input type="checkbox"/> Load JPG
16	13/12/19 09:12	General View
		Thumbnail <input type="checkbox"/> Load JPG
17	13/12/19 09:12	General View
		Thumbnail <input type="checkbox"/> Load JPG
18	13/12/19 09:12	General View
		Thumbnail <input type="checkbox"/> Load JPG
19	13/12/19 09:12	General View
		Thumbnail <input type="checkbox"/> Load JPG
20	13/12/19 09:12	General View
		Thumbnail <input type="checkbox"/> Load JPG
21	13/12/19 09:13	After Repair Photo
		Thumbnail <input type="checkbox"/> Load JPG
22	13/12/19 09:13	After Repair Photo
		Thumbnail <input type="checkbox"/> Load JPG
23	13/12/19 09:13	After Repair Photo
		Thumbnail <input type="checkbox"/> Load JPG
24	13/12/19 09:13	After Repair Photo
		Thumbnail <input type="checkbox"/> Load JPG
25	13/12/19 09:13	After Repair Photo
		Thumbnail <input type="checkbox"/> Load JPG
26	13/12/19 09:13	After Repair Photo
		Thumbnail <input type="checkbox"/> Load JPG
Documentation		1 per page <input type="checkbox"/>
No	Finalized On	Hua Hong Pte Ltd (Sungei Kadut)
1	04/11/19 14:28	Accident Sketch Plan [Linked Accident Report Documents]
		Thumbnail <input type="checkbox"/> Load TIF
2	04/11/19 14:28	Accident Sketch Plan [Linked Accident Report Documents]
		Thumbnail <input type="checkbox"/> Load TIF

Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hua Hong Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	04/11/19 14:30	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hua Hong Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	04/11/19 14:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	04/11/19 14:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	04/11/19 14:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	04/11/19 14:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hua Hong Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	04/11/19 14:28	Accident Sketch Plan	 Load TIF	
2	04/11/19 14:28	Accident Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119019556/QSF3E2

Date: 17/12/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN30494119011
Claimant Vehicle No :	PC6933M	Insured Vehicle No :	PA9060Y
Date of Loss:	31/10/2019	Nature of Claim:	TP
		Claim No:	SNM19D205180C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC6933M	Engine No:	ISL89E5320B22084071
Make & Model:	KING LONG XMQ6129K, 8.8 (A)	Chassis No:	LA6A1KBK6EB403283
Reg. Date:	14/04/2015 (Man. Year: 2015)	Odometer:	221683 km
Colour:	Multi-colour		
Engine Capacity:	8849 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/80 R22.5	Rear Tyre Size:	205/80 R22.5
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,930.00	4,477.00	1,453.00	24.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	2,800.00	1,300.00	31.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,030.00	7,277.00	2,753.00	27.45
Approved Total (Overridden) (\$\$)		5,800.00		
(\$\$)	10,030.00	5,800.00	4,230.00	42.17
+ GST 7.00/7.00% (\$\$)	702.10	406.00	296.10	42.17
Nett Amount (\$\$)	10,732.10	6,206.00	4,526.10	42.17

INSPECTION

Date of Assignment:	12/12/2019	Inspected At:	Connect3 (HQ)
Date Inspected:	19/11/2019		566 Woodlands Road
			Singapore 728697
Estimated Period of Repair:	5.0 days		

Adjuster: OI SUN PIN

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 Dec 2019)	
Parts:	N/A	KING LONG XMQ6129K 8.8 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC6933M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH SIDE GUARD BLUE COLOR	Scratched	550.00 F	*550.00 FL
2	1		*RH SIDE GUARD CHROME COLOR	Cracked	780.00 F	*780.00 FL
3	1		*RH SIDE PANEL	Dented	4,200.00 F	*3,200.00 FL
4	10		*SEALANT	Necessary	400.00 FS	*400.00 FS
					Sub Total (\$\$)	5,930.00 4,930.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 453.00
					Total Parts (\$\$)	5,930.00 4,477.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT RH SIDE GLASSES TO ASSIST REPAIR	New	600.00	600.00
2	LABOUR CHARGES	New	1,500.00	1,000.00
3	SPRAY PAINTING + STICKER	New	2,000.00	1,200.00
Gross Labour Cost (\$\$)			4,100.00	2,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >