

ASS. REC. BY:

REF:

CS/INC19019560/Evd302

Special Instruction:

Survey: Steve

ASSIGNMENT (Office)

From (Person): Hazalysa St/Inhlm

of INC

Date/Time: 10:01am @ 5/11/19

Estimated Cost:

Bill to:

OD/TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDE 2368C

Insured:

SKQ 8799J

at Workshop m/s

SMPT

Tel:

8858 3566

of

Go woodlands Ind. park E4

Policy No:

Claim No:

MT/1069721-002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

2/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:40am @ 5/11/19

Person Contacted:

Mr. Jeph

Vehicle IN/OUT

Date/Time

Action/Instruction

Eliminate ✓

SDE 2368C - X

Bureau

Steve

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SDE 2368 C Yr Regn: 2/3/18
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Shuttle Hybrid c.c. 1496
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 37704 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 CiNo: GA 71120297
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 185/60R15
 R: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 2/11/19 D.O.I. 5/11/19 1140Am

Survey held at SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

MK-7SK 18/11/19 Finalize Contin 4350, 5 days (Red 9731.73, 6910)

RECEIVED 19 NOV 2019

Date/Time, File Pass to?

☐ : Prol. Report
☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee: 240

Date/Time, File Return to?

2) Klu - typist

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Transportation:
) S + RS, SI
) Probe
) Others

Report Format: TP
 Lump Sum / I.B.I: (\$ 4350/-)

TOTAL

240

Nivitha (LKK Auto)

From: Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>
Sent: Wednesday, 6 November 2019 9:13 AM
To: Admin-D (LKKAuto); assignments
Cc: Hazalysa Binte Ibrahim
Subject: FW: TP CASES FARMED OUT TO LKK ON 05/11/2019

Dear LKK,

RE-send with details.

Thank you.

Warmest Regards

Hazalysa Bte Ibrahim
Admin Assistant
Motor Department
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 5 November 2019 10:49 AM
To: Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>; assignments <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 05/11/2019

Dear Hazalysa,

Thank you for the assignment.

Please be informed that SJN6248X (HUI YANG MOTOR) the vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hazalya Binte Ibrahim [mailto:hazalya.ibrahim@income.com.sg]

Sent: Tuesday, 5 November 2019 10:01 AM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>

Subject: TP CASES FARMED OUT TO LKK ON 05/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	David Phua	MT/1069328-002	SMA1928H	AUTOMOTIVE REPAIR CENTRE PTE. LTD.	38 WOODLANDS INDUSTRIAL PARK E1 #05-18 SINGAPORE 757700	Lin Shu Juan / 6468 8834	10:00-16:00	SJX695A	30/10/19	
2	Eric Tang	MT/1069802-002	SMG3831H	JWG INTERNATIONAL PTE. LTD	10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPPOINT	/ 6909 8882		SHB8339R	04/11/19	

3	Fiona Shen	MT/1069712-002	SMI97895	JWG INTERNATIONAL PTE. LTD	SINGAPORE 568047	10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 ANK AUTOPOINT SINGAPORE 568047	/ 6909 8882	SH2763B	02/11/19		
4	Jared Liu	MT/1068817-002	PC81K	SERVE YOU MOTOR SERVICE	BLK 5033 #01-265 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569536	10:00-12:00	Elaine Chia / 9239 3188	SJG7545T	22/10/19		
5	David Phua	MT/1069721-002	SDE2368C	SMRT AUTOMOTIVE SERVICES PTE LTD	WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	10:00-12:00	Peh Eng Hock / 88583566	SKG8799J	02/11/19	68662673 (88583566) or 65555556 (Esther)	
6	Fiona Shen	MT/1065847-003	SIN6248X	HUI YANG MOTOR SERVICE	176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721		Bel / 64515752	SIV4202Z	05/10/19		
7	Charlotte Chew	MT/1067762-002	SLV3347Y	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE		Steven / 82636295	SHC6277T	20/10/19		
8	Helena Tan	MT/1067921-002	SMK7021G	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE		Steven / 82636295	SJUB146G	22/10/19		
9	Chryllis Quah	MT/1069704-002	SLO5075U	TTS EUROCAR'S PTE LTD	383 SIN MING DRIVE TTS CENTRE SINGAPORE 575717	15:00-16:00	M.L.Kavi / 97637000	SLC2471C	02/11/19		

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	974C
Vehicle Details	
Vehicle No.:	SDE2368C
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	LEB6324851
Chassis No.:	GP71120207
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$23,922.00
Original Registration Date:	02 Mar 2018
First Registration Date:	02 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$5,491.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Mar 2028
PARF Rebate Amount:	\$4,118.00
Intended COE Rebate Details	
COE Expiry Date:	01 Mar 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$44,000.00
COE Rebate Amount:	\$35,501.00
Total Rebate Amount:	\$39,619.00

The information contained herein is correct as at 05 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/11/2019 09:55
Date Of Accident	02/11/2019 09:20
Exact Location Of Accident	KJE EXIT TO CHOA CHU KANG DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDE2368C
Insured/Policyholder	
Name Of Registered Owner	ANG CHIN HUANG
NRIC No	S1589974C
Email Address	BENSONANG@SMRT.COM.SG
Mobile Phone No	(LOCAL) +65-97713881
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE HYBRID-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ19-001180
Cover Note Number	

Driver

Name of Driver	ANG CHIN HUANG
NRIC No	S1589974C
Date Of Birth	29/03/1963
Occupation	INDOOR
Date Of Driving Pass	19/12/1989
Driving Experience	29 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97713881
Fax Number	
Contact Number	OFFICE-80000000
Email Address	BENSONANG@SMRT.COM.SG

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ONG SIEW BEE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS STATIONARY ALONG CHOA CHU KANG DRIVE WITH ONE PASSENGER ON BOARD AS IT WAS THE RED TRAFFIC LIGHT. WHEN THE TRAFFIC LIGHT TURNED GREEN, FRONT CAR MOVED AND BEFORE I COULD MOVE I FELT AN IMPACT AT THE REAR OF MY VEHICLE. A VEHICLE SKG8799J HAD COLLIDED ONTO THE REAR OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKG8799J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN BOON GEE
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

- Nature Of Damage
- No. Of Passenger (Including Driver)

Choa Chu Kang Drive

A- SDE 2368C
B- SKG8799J

[illegible]

I/We declare the foregoing particulars are true in every respect.

$\frac{1}{2} \times 11$

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]
4/11/2019

Accident Photo



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Photo



Accident Photo




SMRT Vehicle Repair Estimate

Group : Buses / Taxis / Private Car
 Reg. No. : SDE 2368 C
 Make / Model : HONDA SHUTTLE
 Chassis No : _____
 Name of Driver : _____
 Date/Time of Accident : _____
 Surveyor is Required ? **YES / NO**
 If Yes, VICOM / LKK / AIS / Others MSIG : _____
 Vehicle is Towed Back ? **YES / NO** Date / Time : _____
 Accident reporting date : _____
 Type of Accident : Skid / Head-Rear / Head-On / Side Swipe / Others
 Special Instruction to ARC, if any :
INSURANCE LUMP SUM

Ref. No. : _____
 Reg. Date : _____
 Mileage : _____
 Rental/Replacement Vehicle : **Yes**

The damages on the vehicle are as indicated in the following diagram :



Signed : _____ Date : _____

Accident Repair Job Card No : _____ Date Prepared : _____

Summary of Repair Estimates Repair Completed : _____

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labour Charges	\$ 1,000.00	\$ -
Total Spray Painting Charges :	\$ 800.00	\$ -
Total Material Charges	\$ 11,401.73	\$ -
Other Charges	\$ 880.00	\$ -
TOTAL	\$ 14,081.73	\$ -

Lump Sum Repair, if any : _____

No. of Repair Days : [] days [] days

Signature : Prepared by _____ Adjusted by _____

QN No. _____ Invoice No. _____

Signed : _____ Date : _____


 Steve (LKK)
 8322 8813
 Steve.cheng@lkk.com

w/L M/L 5/11/19, 11:30 am
 5 days
 L/S
 Rj AL spray

Part 1 - Labour Works

Job Scope	Quotation from ARC	
To remove and renew rear damaged parts.replace realigned all affected parts	\$ 1,000.00	800
Total Labour Cost	\$ 1,000.00	\$

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	
To respray affected areas	\$ 800.00	600
Spray Painting	\$ 800.00	

L- 1400

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Page ()

Job Scope	Quotation from ARC	
To tuffcoat affect areas	\$ 200.00	30 n/c
To remove and refit interior upholstery	\$ 100.00	30 n/c
To remover /refit wiring check	\$ 60.00	30 n/c
To remove/replace rear silencer box	\$ 100.00	X NN
To remove/replace reverse sensors	\$ 100.00	20 n/c
To remove and replace rear windscreen	\$ 120.00	/ n/c
To remove and re-install renew video camera	\$ 100.00	50 n/c
To remove and replace tail gate mechanism	\$ 100.00	50 n/c
Total Other Costs	\$ 880.00	

Part 4 - Spare Parts / Material Usage

N- 330

To be completed by Service Advisor, ARC

Part Number	Parts Description	Qty	Cost Price (\$)	COST PLUS 10%	Final Price (\$)	Repair (R) Replace (/)	Not Rep
1	TAIL GATE / 00 1195/	1	\$ 1,350.20	10%	\$ 1,485.22		
2	TAIL GATE WEATHERSTRIP / n/c 235/	1	\$ 285.10	10%	\$ 313.61		
3	TAIL GATE TOP LOCK / OT 175/	1	\$ 254.10	10%	\$ 279.51		
4	TAIL GATE TRIM COVER X NN	1	\$ 325.90	10%	\$ 358.49		
5	TAIL GATE LOGO X NN	1	\$ 55.80	10%	\$ 61.38		
6	TAIL GATE EMBLEM SHUTTLE / n/c	1	\$ 68.90	10%	\$ 75.79		
7	TAIL GATE EMBLEM HYBRID / n/c	1	\$ 105.20	10%	\$ 115.72		
8	TAIL GATE WINDSCREEN MOULDING / n/c 195/	2	\$ 267.30	10%	\$ 294.03		
9	TAIL GATE MOULDING / n/c	1	\$ 395.40	10%	\$ 434.94		
10	TAIL GATE REFLECTOR X NN	2	\$ 591.60	10%	\$ 650.76		
11	REAR BUMPER / 00 1150/	1	\$ 1,309.90	10%	\$ 1,440.89		
12	REAR BUMPER SIDE RETAINER / OR	2	\$ 119.60	10%	\$ 131.56		
13	REAR BUMPER TOW COVER X NN	1	\$ 42.30	10%	\$ 46.53		
14	REAR BUMPER REFLECTOR X NN	2	\$ 220.80	10%	\$ 242.88		
15	REAR BUMPER REFLECTOR COVER X NN	2	\$ 141.20	10%	\$ 155.32		
16	REAR TAIL LAMP X NN	2	\$ 791.80	10%	\$ 870.98		
17	REAR END PANEL / 00	1	\$ 481.60	10%	\$ 529.76		
18	REAR END PANEL TOP GARNISH / 284	1	\$ 155.20	10%	\$ 170.72		

Steve Chen (LKK Auto)

From: Peh Eng Hock (Auto Svcs/ARC/ARC/Taxis) <PehEngHock@smrt.com.sg>
Sent: Monday, November 18, 2019 9:22 AM
To: Steve Chen (LKK Auto)
Subject: RE: SDE2368C - Finalize

Hi Steve,

Ok, confirmed. finalize \$4350 (L/S, before GST). 5 repair days.

Thank you

Regards
Peh Eng Hock

-----Original Message-----

From: Steve Chen (LKK Auto) [<mailto:SteveChen@lkkauto.com>]
Sent: 18 November 2019 08:52
To: Peh Eng Hock (Auto Svcs/ARC/ARC/Taxis)
Subject: SDE2368C - Finalize

Dear Mr Peh,

Kindly follow up the finalize.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Steve Chen (LKK Auto)
Sent: Monday, November 11, 2019 7:10 PM
To: Peh Eng Hock (Auto Svcs/ARC/ARC/Taxis)
Cc: Veron Chen
Subject: SDE2368C - Finalize

Dear Mr Peh,

Kindly refer our finalize \$4350 (L/S, before GST). 5 repair days.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19019560/Evd3e2

73 BRAS BASAH ROAD

Date: 26-11-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN : DAVID PHUA

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKG 8799J	Veh. Inspected	SDE 2368C
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1069721-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	05/11/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GP71120207	Colour	BLACK
Odometer	37704 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	CONTINENTAL	5 mm
L/H Front Tyre	185/60 R15	CONTINENTAL	5 mm
R/H Rear Tyre	185/60 R15	CONTINENTAL	5 mm
L/H Rear Tyre	185/60 R15	CONTINENTAL	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	02/11/2019	Inspect Date / Time	05/11/2019 (11:40 AM)
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDE 2368C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAIL GATE	DENTED	1,350.20	1,193.00
1	TAIL GATE WEATHERSTRIP	NECESSARY	285.10	235.00
1	TAIL GATE TOP LOCK	BENT	254.10	175.00
1	TAIL GATE TRIM COVER	NOT NECESSARY	325.90	-
1	TAIL GATE LOGO	NOT NECESSARY	55.80	-
1	TAIL GATE EMBLEM SHUTTLE	NECESSARY	68.90	68.90
1	TAIL GATE EMBLEM HYBRID	NECESSARY	105.20	105.20
1	TAIL GATE WINDSCREEN MOULDING	NECESSARY	267.30	195.00
1	TAIL GATE MOULDING	NECESSARY	395.40	395.40
2	TAIL GATE REFLECTOR	NOT NECESSARY	591.60	-
1	REAR BUMPER	DENTED	1,309.90	1,150.00
2	REAR BUMPER SIDE RETAINER	BROKEN	119.60	119.60
1	REAR BUMPER TOW COVER	NOT NECESSARY	42.30	-
2	REAR BUMPER REFLECTOR	NOT NECESSARY	220.80	-
2	REAR BUMPER REFLECTOR COVER	NOT NECESSARY	141.20	-
2	REAR TAIL LAMP	NOT NECESSARY	791.80	-
1	REAR END PANEL	DENTED	481.60	481.60
1	REAR END PANEL TOP GARNISH	CRUSHED	155.20	155.20
1	REAR FLOOR PANEL SIDE BOARD RH	NOT NECESSARY	375.90	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	770.20	-
1	REAR FLOOR PANEL TRAY	NOT NECESSARY	355.10	-
1	REAR SILENCER BOX	NOT NECESSARY	855.30	-
1	REAR SILENCER TOP SEAL	NOT NECESSARY	155.90	-
	LESS 20% DISCOUNT		-	-854.78
	COST PLUS 10%		947.43	-
			10,421.73	3,419.12
SPECIAL NETT ITEMS				
1	TAIL GATE WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
8	REAR BUMPER CLIP (SN)	NECESSARY	40.00	30.00

Report Ref No. CS/INC19019560/Evd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR TAIL LAMP CLIP (SN)	NOT NECESSARY	10.00	-
1	REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR REVERSE CAMERA (SN)	NOT NECESSARY	550.00	-
			980.00	270.00
	LABOUR			
	TO REMOVE AND RENEW REAR DAMAGED PARTS:REPLACE REALIGNED ALL AFFECTED PARTS.		1,000.00	800.00
	TO RESPRAY AFFECTED AREAS.		800.00	600.00
	TO TUFFCOAT AFFECT AREAS.		200.00	30.00
	TO REMOVE AND REFIT INTERIOR UPHOLSTERY.		100.00	30.00
	TO REMOVER / REFIT WIRING CHECK.		60.00	30.00
	TO REMOVE / REPLACE REAR SILENCER BOX.	NOT NECESSARY	100.00	-
	TO REMOVE / REPLACE REVERSE SENSORS.		100.00	20.00
	TO REMOVE AND REPLACE REAR WINDSCREEN.		120.00	120.00
	TO REMOVE AND RE-INSTALL RENEW VIDEO CAMERA.		100.00	50.00
	TO REMOVE AND REPLACE TAIL GATE MECHANISM.		100.00	50.00
			2,680.00	1,730.00
GRAND TOTAL			14,081.73	5,419.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				4,350.00

Report Ref No. CS/INC19019560/Evd3e2

CHEN TSUE YEE
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.