



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Ref: CS/INC19019563/Nvd3e2

Date: 23-04-2020



ATTN : FIONA SHEN

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 2763B	Veh. Inspected	SMJ 9789S
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1069712-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	05/11/2019

#### 2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E200 AVG AUTO	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WDD2130422A398568	Colour	WHITE
Odometer	28851 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 R19	PIRELLI	5 mm
L/H Front Tyre	245/40 R19	PIRELLI	5 mm
R/H Rear Tyre	245/40 R19	PIRELLI	5 mm
L/H Rear Tyre	245/40 R19	PIRELLI	5 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--------------------------------------------------------------------------------------

#### 5. General Information

Accident Date	02/11/2019	Inspect Date / Time	05/11/2019 ( 05:19 PM )
Survey held at	JWG INTERNATIONAL PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
----------------------------------------------------------------------------------------------------------------------------------------

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------