

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H

Blk 10, Ang Mo Kio Ind Park 2A,

#03-08 AMK AutoPoint,

Singapore 568047

H/P: 9069 7882 Fax: 6909 9592

E-Mail: jwg.claims@yahoo.com

DATE : 4/11/2019

VEHICLE NO : SMJ 9789 S
MODEL : MERCEDES E200
CHASSIS NO :

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER SUPPORT BAR	1	\$ -	\$ 1480.70 800
2	FRONT BUMPER SUPPORT BAR BRACKET	1	\$ -	\$ 988.00 400
3	REAR SENSOR DETECTOR CONTROL MODULE	2	\$ 1475.00	\$ 2950.00 1,500

TOTAL PRICE \$ -
LESS 10% \$ -
SUB TOTAL PRICE \$ -

P \$61,686.40
Less 10% \$55,517.76

S/N \$30,740.00

L \$5,530.00

T \$91,787.76

WS \$73,430.20

≈ \$73,400.00

10 working days

PARTS : \$30,116.00

LESS 10% : \$27,104.40

S/NETT : \$16,600.00

LABOUR \$3,890.00

TOTAL \$47,594.40

LESS LIS 20% \$38,075.52

\$38,100.00 / 10 Days

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: