

ASS. REC. BY:

REF: es|INC19019565/ Kvd3n2 Special Instruction:

Garage: LennahASSIGNMENT (Office)From (Person): Huzalya B Ibrahim of INC Date/Time: 1001am 5/11

Estimated Cost: _____ Bill to: _____

OI / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SJN 6248X Insured: SJV 42022at Workshop m/s Hui Yang Motor Tel: 64515752of Blk 176 Sin Ming Drxe #04-02/03Policy No: _____ Claim No: M1/1065847-003

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 5/10/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 11:03am 5/11/19 Person Contacted: Bel Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>Follow up</u> ✓
	<u>SJN 6248X - X</u>
<u>22/11</u>	<u>11 Pm @ 26001 email & confirm (Ref 179143, 4170)</u>

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STN 6248X

Yr Regn:

02 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy A/T

c.c

1598

Colour:

M. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

294896

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MRO 537EE108140631

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: West 16/14

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

3

mm

Rear

R/Bal.

6

mm

L/Bal.

3

mm

L/Bal.

6

mm

D.O.A.

5/10/19

D.O.I.

8/11/19

Survey held at

11:05am

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 22 NOV 2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 22/11 - typist

Report Format :

Lump Sum / I.B.I: (\$

TP

2600/-

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

250

Nivitha (LKK Auto)

From: Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>
Sent: Wednesday, 6 November 2019 9:13 AM
To: Admin-D (LKKAuto); assignments
Cc: Hazalysa Binte Ibrahim
Subject: FW: TP CASES FARMED OUT TO LKK ON 05/11/2019

Dear LKK,

RE-send with details.

Thank you.

Warmest Regards

Hazalysa Bte Ibrahim
Admin Assistant
Motor Department
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 5 November 2019 10:49 AM
To: Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>; assignments <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 05/11/2019

Dear Hazalysa,

Thank you for the assignment.

Please be informed that SJN6248X (HUI YANG MOTOR) the vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hazalya Binte Ibrahim [mailto:hazalya.ibrahim@income.com.sg]

Sent: Tuesday, 5 November 2019 10:01 AM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>

Subject: TP CASES FARMED OUT TO LKK ON 05/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	David Phua	MT/1069328-002	5MA1928H	AUTOMOTIVE REPAIR CENTRE PTE. LTD.	38 WOODLANDS INDUSTRIAL PARK E1 #05-18 SINGAPORE 757700	Lin Shu Juan / 6468 8834	10:00-16:00	SJN695A	30/10/19	
2	Eric Tang	MT/1069802-002	5MG3831H	JWG INTERNATIONAL PTE. LTD	10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT	/ 6909 8882		SHB8339R	04/11/19	

3	Fiona Shen	MT/1069712-002	SMJ97895	JWG INTERNATIONAL PTE. LTD	SINGAPORE 568047	10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047	/ 6909 8882	SH2763B	02/11/19		
4	Jared Liu	MT/1068817-002	PC81K	SERVE YOU MOTOR SERVICE	BLK 5033 #01-265 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569536	Elaine Chia / 9239 3188	10:00-12:00	SJG7545T	22/10/19		
5	David Phua	MT/1068721-002	5DE2368C	SMRT AUTOMOTIVE SERVICES PTE LTD	WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Peh Eng Hock / 88583566	10:00-12:00	SKG8799J	02/11/19	68662673 (88583566) or 65555556 (Esther)	
6	Fiona Shen	MT/1065847-003	SIN6248X	HUI YANG MOTOR SERVICE	176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721	Bel / 64515752		SIV42022	05/10/19		
7	Charlotte Chew	MT/1067762-002	SLV3347Y	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		SHC6277T	20/10/19		
8	Helena Tan	MT/1067921-002	SMK7021G	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		SIU8146G	22/10/19		
9	Chryllis Quah	MT/1069704-002	SLQ5075U	TTS EUROCAR PTE LTD	383 SIN MING DRIVE TTS CENTRE SINGAPORE 575717	Ms.Kavi / 97637000	15:00-16:00	SLC2471C	02/11/19		

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg

income
made efficient



in with
you

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	374C
Vehicle Details	
Vehicle No.:	SJN6248X
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	3ZZ4866850
Chassis No.:	MR053ZEE106140631
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,990.00
Original Registration Date:	23 Feb 2009
First Registration Date:	23 Feb 2009
Transfer Count:	1
Actual ARF Paid:	\$16,990.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Feb 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$12,864.00
COE Rebate Amount:	\$11,045.00
Total Rebate Amount:	\$11,045.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 07 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/10/2019 17:06
Date Of Accident	05/10/2019 12:40
Exact Location Of Accident	ALONG CTE TOWARDS MERCHANT RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN6248X
Insured/Policyholder	
Name Of Registered Owner	ST RENT & DRIVE PTE LTD
Co Reg No	201615374C
Email Address	HUI_YANG_MOTOR@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-81096825
Alternative Phone No	OFFICE-81096825

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5107704384 (TP)
Cover Note Number	

Driver

Name of Driver	SARAVANAN S/O MUTHUVERAN
NRIC No	S8520418A
Date Of Birth	02/07/1985
Occupation	OUTDOOR
Date Of Driving Pass	05/07/2014
Driving Experience	5 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81096825
Fax Number	
Contact Number	OTHERS-81096825
Email Address	SARAVANAN.MUTHUVEERAN@HOTMAIL.COM

Address BLK 51 MARINE TERRACE #02-171
Postcode 440051
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 4
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3
Passenger 1
NAME: : UNKNOWN
GENDER: : MALE
Passenger 2
NAME: : UNKNOWN
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT ATTACHED.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJV4202Z
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver SOH HOON LAM
NRIC/Passport Number
Contact Number
Address
Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHC5422Y
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver TAN HIAN NGEE
NRIC/Passport Number
Contact Number 96773406
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLU7791B
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver LIM YI RU
NRIC/Passport Number
Contact Number 90880804
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

23 OCT 2019

23/10/2019




Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

Veh A. SIN 6248X
 Veh B - SIN 42022
 Veh C. SIN 54204
 Veh D - SIN 7791B



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 05/10/19 @ 12:40pm, my vehicle A (SIN 6248X) was travelling at (TE Expressway) before exit Merchant Road & Chuan Hoo Ave entrance left lane of the major Road. Suddenly I heard Iron Brake sound & heard being behind the Road while travelling. I saw it through my rear mirror. Vehicle B (SIN 42022) to my understanding had a collision earlier which makes him unstable to control his vehicle where leads him till to the road shoulder where I was about to "Exit". Vehicle B had hit my Vehicle A rear left passenger door, left side mirror. When I get down from my vehicle A, then I realise there are total 4 cars involve in this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

23 OCT 2019



Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514666

GST Reg No. 201629438M

NTUC
06/11/19
(Wed)

05/10/2019

Owner: ST RENT & DRIVE PTE LTD

Not Withstand
L1 Reg @ 2600/r
Returning After Rain
4 days

ESTIMATE TO REPAIR TOYOTA ALITS - SJN6248X

1pc	rear LH door
2pcs	rear LH door firm sticker @\$181.50
1pc	rear LH door handle
1pc	rear LH door handle cover
1pc	rear LH door protector
1pc	rear LH door protector chrome
1pc	rear LH door top moulding
1pc	rear LH door inner lock
1pc	rear LH door inner rubber
1pc	rear LH door glass gear & motor
1pc	LH side skirt

B ₁	\$	685.25	—
M ₂	\$	363.00	—
D ₁	\$	281.50	—
L ₂	\$	121.50	X
B ₂	\$	181.25	—
B ₃	\$	121.50	—
L ₂	\$	181.85	X
D ₂	\$	281.50	—
90.75 SJN D ₁ /L ₁	\$	181.50	50 pin
D ₁ /J ₁ M	\$	481.50	—
CM	\$	481.55	—

less 25%

\$	3,361.90
\$	840.48
\$	2,521.43

tuffkote
wiring
spray painting
labour charges
Total

\$	150.00	301
\$	120.00	201
\$	800.00	6001
\$	800.00	4001
\$	4,391.43	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT				
NTUC INCOME INSURANCE CO-OPERATIVE LTD 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 ATTN: FIONA SHEN		Ref: CS/INC19019565/Kvd3n2 Date: 25-11-2019 Code: INC		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJV 4202Z	Veh. Inspected	SJN 6248X
	Policy No.		Coverage (\$)	0.00
	Claim No.	MT/1065847-003	Excess (\$)	0.00
	Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	05/11/2019
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	MR053ZEE106140631	Colour	METALLIC BLUE
	Odometer	294896 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WEST LAKE	3 mm
	L/H Front Tyre	195/65 R15	WEST LAKE	3 mm
	R/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm
	L/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/10/2019	Inspect Date / Time	06/11/2019 (11:05 AM)
	Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 6248X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR LH DOOR	BENT	685.25	685.25
2	REAR LH DOOR FIRM STICKER @\$181.50	NECESSARY	363.00	363.00
1	REAR LH DOOR HANDLE	DISTORTED	281.50	281.50
1	REAR LH DOOR HANDLE COVER	SERVICEABLE	121.50	-
1	REAR LH DOOR PROTECTOR	BENT	181.25	181.25
1	REAR LH DOOR PROTECTOR CHROME	BENT	121.50	121.50
1	REAR LH DOOR TOP MOULDING	SERVICEABLE	181.85	-
1	REAR LH DOOR INNER LOCK	DENTED	281.50	281.50
1	REAR LH DOOR GLASS GEAR & MOTOR	DISTORTED / JAMMED	481.50	481.50
1	LH SIDE SKIRT	CRACKED	481.55	481.55
	LESS 25% DISCOUNT		-795.10	-719.26
			2,385.30	2,157.79
1	REAR LH DOOR INNER RUBBER (50%)(SN)	DENTED / CUT	181.50	90.75
	LESS 25% DISCOUNT		-45.38	-
			136.12	90.75
LABOUR				
	TUFFKOTE.		150.00	30.00
	WIRING.		120.00	20.00
	SPRAY PAINTING.		800.00	600.00
	LABOUR CHARGES.		800.00	400.00
	-		-	-
	-		-	-
	-		-	-
			1,870.00	1,050.00
GRAND TOTAL			4,391.42	3,298.54
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,600.00

Report Ref No. CS/INC19019565/Kvd3n2



Report Ref No. CS/INC19019565/Kvd3n2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

A handwritten signature in black ink, appearing to be 'K.K. Lau'.

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.