

ASS. REC. BY:

REF:

CS/INC19019566/Kyd302

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Hazelysa bt Ibrahim

of INC

Date/Time: 10 01 am @ 5/1/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLV 3347Y

Insured:

SHC 6277T

at Workshop m/s

Thiam Heng Huat

Tel:

8263 6295

of

176 Sin Ming Drive # 05-14

9639 1626

Policy No:

Claim No:

MP/1067762-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11.17 am @ 5/1/19

Person Contacted:

Steven

Vehicle IN / OUT

Date/Time

Action/Instruction

Estimate

~~SLV 3347Y~~ ✓

SLV 3347Y-X

5/1 6/1 Pm @ 550d e.mail (Red \$13201-00, 70%)

+hh176@yahoo.com

ASS. REC. BY:

REF: INC1

Kenneth

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Thiam Heng Huat  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 05 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLV 33474 Yr Regn: 12, 17  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Traller or Wajan  
 Make: Hiq Carers c.c. 1685  
 Colour: M. Gray A/C: Insured / Std / NI / NA  
 Sp. Reading: 139496 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: KNA14U815VJ 7195302  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modl: Nil / S/Rlm / STD A/Rlm or  
 Tyre Size: F: 205/55R16  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Neutan  
 Front R/Bal. 9 mm Rear R/Bal. 9 mm  
 L/Bal. 9 mm L/Bal. 9 mm  
 D.O.A. 20/10/19 D.O.I. 3/11/19  
 Survey held at \_\_\_\_\_ 11:27AM  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
1st o/s door  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>File pass to GIA &amp; EM not ready</u>

RECEIVED 14 JAN 2020

Date/Time, File Pass to?  : Prell. Report  
 : Final Report

1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) 14/1/20 Typist

Days Of Repair: 5  
 Resurvey No. of Trlp: 2

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech Invs (\$)  
 : Weekend (\$)

Survey Fee: 250

Transportation:	
S - RS. SI	
Fuel/Oil	
Others	
TOTAL	<u>250</u>

Report Format :  
 Lump Sum / I.B.I: (\$ \$5500/-)

---

**Nivitha (LKK Auto)**

**From:** Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>  
**Sent:** Wednesday, 6 November 2019 9:13 AM  
**To:** Admin-D (LKKAuto); assignments  
**Cc:** Hazalya Binte Ibrahim  
**Subject:** FW: TP CASES FARMED OUT TO LKK ON 05/11/2019

Dear LKK,

RE-send with details.

Thank you.

Warmest Regards

**Hazalya Bte Ibrahim**  
Admin Assistant  
Motor Department  
[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
**Find out more at [income.com.sg/careers](http://income.com.sg/careers)**

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

---

**From:** Admin-D (LKKAuto) [mailto:[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)]  
**Sent:** Tuesday, 5 November 2019 10:49 AM  
**To:** Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** Thio Tse Kiat <[tsekiat.thio@income.com.sg](mailto:tsekiat.thio@income.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 05/11/2019

Dear Hazalya,

Thank you for the assignment.

Please be informed that SJN6248X (HUI YANG MOTOR) the vehicle is not in the workshop, repairer will arrange.

Best Regards

**G.NIVITHA**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Hazalya Binte Ibrahim [mailto:[hazalya.ibrahim@income.com.sg](mailto:hazalya.ibrahim@income.com.sg)]

**Sent:** Tuesday, 5 November 2019 10:01 AM

**To:** Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Cc:** Thio Tse Kiat <[tsekiat.thio@income.com.sg](mailto:tsekiat.thio@income.com.sg)>; Hazalya Binte Ibrahim <[hazalya.ibrahim@income.com.sg](mailto:hazalya.ibrahim@income.com.sg)>

**Subject:** TP CASES FARMED OUT TO LKK ON 05/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng instruction :-

SN	OIC	Claim No.	Vehicle	Workshop Name	Workshop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	David Phua	MT/1069328-002	SMA1928H	AUTOMOTIVE REPAIR CENTRE PTE. LTD.	38 WOODLANDS INDUSTRIAL PARK E1 #05-18 SINGAPORE 757700	Lin Shu Juan / 6468 8834	10:00-16:00	SJX695A	30/10/19	
2	Eric Tang	MT/1069802-002	SMG3831H	JWG INTERNATIONAL PTE. LTD	10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT	/ 6909 8882		SHB8339R	04/11/19	

3	Fiona Shen	MT/1069712-002	SMJ9789S	JWG INTERNATIONAL PTE. LTD	SINGAPORE 568047 10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047	/ 6909 8882	SH2763B	02/11/19	
4	Jared Liu	MT/1068817-002	PC81K	SERVE YOU MOTOR SERVICE	BLK 5033 #01-265 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569536	Elaine Chia / 9239 3188	5IG7545T	22/10/19	
5	David Phua	MT/1069721-002	SDE2368C	SMRT AUTOMOTIVE SERVICES PTE LTD	WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Peh Eng Hock / 88583566	SKG8799J	02/11/19	68662673 ( 88583566 ) or 65555556 ( Esther )
6	Fiona Shen	MT/1065847-003	SJING248X	HUI YANG MOTOR SERVICE	176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721	Bel / 64515752	SIV4202Z	05/10/19	
7	Charlotte Chew	MT/1067762-002	SLV3347Y	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295	SHC6277T	20/10/19	
8	Helena Tan	MT/1067921-002	SMK7021G	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295	SIU8146G	22/10/19	
9	Chryllis Quah	MT/1069704-002	SLQ5075U	TTS EUROCAR S PTE LTD	383 SIN MING DRIVE TTS CENTRE SINGAPORE 575717	Ms. Kavi / 97637000	SLC2471C	02/11/19	15:00-16:00

**Please contact workshops.**

Please revert to officer-in-charge after survey.

Thank you.

Warmest Regards

**Hazalya Bte Ibrahim**  
Admin Assistant  
Motor Department  
T +65 6430 7902  
[www.income.com.sg](http://www.income.com.sg)

**income**  
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
**Find out more at [income.com.sg/careers](http://income.com.sg/careers)**

**in** with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

---

#### Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

**Disclaimer**

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/10/2019 17:36
Date Of Accident	20/10/2019 23:40
Exact Location Of Accident	BAYFRONT AVENUE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV3347Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	BIS MOTORING PTE LTD
Co Reg No	20135055D
Email Address	DENNIS.DENG@MUNICHAUTCARE.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-96826300

### Vehicle Particulars

Manufacturer	KIA
Model	CARENS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

### Driver

Name of Driver	SAFARI BIN SAMBIRI
NRIC No	S7321087I
Date Of Birth	16/06/1973
Occupation	OUTDOOR
Date Of Driving Pass	18/08/1994
Driving Experience	25 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82276734
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 170C PUNGGOL FIELD #10-697
Postcode	823170
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TECK GHEE NEIGHBOURHOOD POLICE POST
Police Station Address	<b>ROAD:</b> BLK 321 ANG MO KIO STREET 31 , <b>POSTCODE:</b> 560321 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-4599999 - <b>FAX NO:</b> 64574478
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN / POLICE REPORT NO: T/20191021/2126

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH WORKSHOP
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC6277T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	SAFARI BIN SAMBIRI
Approximate Age	46
Injuries Sustain	
Injured person in which vehicle?	SLV3347Y
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 170C PUNGGOL FIELD #10-697
Postcode	823170

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time

21 OCT 2019

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Jenny Lim







**SINGAPORE  
POLICE FORCE**



T/20191021/2126

2 of 4

Police Station Of Origin:  
Teck Ghee NPP  
321 Ang Mo Kio Street 31 SINGAPORE  
560321  
Tel No: 1800-4599999

Report No. T/20191021/2126

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver:			
Name	CHOW CHUNG CHUCK	ID No.	S1753110G
Related Vehicle	SHC6277T (Car)	Contact No.	91063328
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver:			
Name	SAFARI BIN SAMBIRI	ID No.	S7321087I
Related Vehicle	SLV3347Y (Car)	Contact No.	82276734
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	21/10/2019	Date Discharge	21/10/2019
No. of Days granted Medical Leave	05	Degree of Injury	NIL

**Brief Details.**

I am working as a Grab Driver for about 3 years; I am currently driving car SLV3347Y. On 20/10/2019 at about 1900hrs, I started my Grab driver duties.

On 21/10/2019 at about 2330hrs, I finished alighting my passenger at Intercontinental Hotel. At about 2340hrs while I was driving along Bayfront Avenue (Towards Temasek Avenue); I observed that my car boot indicator is lighted. As such, I proceed to the left most lane to stop and make a check. I switched on my hazard light. After finish checking my car boot, I proceed back to my car; however, the driver-side door is still opened. Subsequently, a Taxi (SHC6277T) hit onto my driver-side door, I believed that the taxi might have cut into my lane and hit onto my car door.

The Taxi stopped in-front and we exchanged particulars; and took photos of the accident scene. No Police / Ambulance attended as both of us has no injury complaints at that point of time. Both of us activated tow-truck; and I left the scene after which. My car sustained damages on the driver side door, window was smashed.

On 21/10/2019 at about 0600hrs when I was at home, I felt a pain on my neck and shoulder area. I proceed to Mount Alvernia Hospital and was given 5 days Outpatient Sick Leave.

I am lodging this report as I was involved in a Traffic Accident and given 5 days Medical Leave.



**SINGAPORE  
POLICE FORCE**



T/20191021/2126

Police Station Of Origin:  
Teck Ghee NPP  
321 Ang Mo Kio Street 31 SINGAPORE  
560321  
Tel No: 1800-4599999

3 of 4

Report No. T/20191021/2126

CONTINUATION OF REPORT



**SINGAPORE  
POLICE FORCE**



T/20191021/2126

4 of 4

Report No. T/20191021/2126

Police Station Of Origin:  
Teck Ghee NPP  
321 Ang Mo Kio Street 31 SINGAPORE  
560321  
Tel No: 1800-4599999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / SI AHMAD YAZID BIN MOHAMED	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 21/10/2019 16:27
Officer In Charge Of Case: TP / AEIT / SSI 2 YEO GEAK ENG CECILIA Contact No.: 65476404	Classification Of Case:  SN 085
Authentication Stamp NP168	 Singapore Police Force



Repair Estimate

34	Front door speaker o/s	Sm	1	\$ 156.00	\$ 156.00	X
35	Front door window regulator o/s	Bj	1	\$ 379.00	\$ 379.00	X
36	Front door window regulator motor o/s	Sm	1	\$ 443.00	\$ 443.00	X
<b>Subtotal</b>					<b>\$ 14,340.00</b>	
<b>List discount</b>					<b>10.00%</b>	
<b>Total</b>					<b>\$ 12,906.00</b>	

Special nett items						
No.	Parts description		QTY	UNIT PRICE	AMOUNT	
1	Front bumper clips	nn	10	\$ 4.50	\$ 45.00	X
2	Front door wire harness o/s	Sm	1	\$ 350.00	\$ 350.00	X
3	Front fender cowling clips o/s	nn	8	\$ 4.50	\$ 36.00	X
4	Front door inner trim board clips o/s	nn	12	\$ 4.50	\$ 54.00	X
5	Front alloy wheel o/s	Sm	1	\$ 450.00	\$ 450.00	X
6	Front tyre o/s	Sm	1	\$ 280.00	\$ 280.00	X
7	Front fender quarter glass moulding o/s	nn	1	\$ 130.00	\$ 130.00	X
8	Front fender quarter glass sealant o/s	nn	1	\$ 100.00	\$ 100.00	301n
9	Front door window solar film o/s	nn	1	\$ 200.00	\$ 200.00	X
10	Front fender quarter glass solar film o/s	nn	1	\$ 150.00	\$ 150.00	X
11	Sundries	nn	1	\$ 50.00	\$ 50.00	X
<b>Total</b>					<b>\$ 1,845.00</b>	

Labour				
No.	Description	Work unit	Amount	
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	8	\$ 1,600.00	500l
2	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check functions.	0.25	\$ 50.00	20l
3	To remove and refit o/s front door components to replace o/s front door, check alignment.	0.5	\$ 100.00	60l
4	To disconnect door wire harness of electrical component to facilitate repairs, reconnect and check functions of power windows.	0.25	\$ 50.00	X
5	To remove and replace o/s front rim. To perform tyre balancing.	0.25	\$ 50.00	X
6	To remove and refit o/s front undercarriage for replacement of parts.	1	\$ 200.00	X
7	To conduct computerized wheel alignment.	0.5	\$ 100.00	X
8	Supply spray paint material and necessary items to respray front bumper, o/s front fender, o/s front door and other affected area / panel.	8	\$ 1,600.00	900l
9	To rust proof all affected portions after repair.	0.5	\$ 100.00	60l
10	To clean interior & remove broken glasses fragments	0.5	\$ 100.00	30l
<b>Total labour</b>			<b>\$ 3,950.00</b>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**Estimate Grand Total \$ 18,701.00**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19019566/Kyd3e2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 03-02-2020



ATTN: CHARLOTTE CHEW

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 6277T	Veh. Inspected	SLV 3347Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1067762-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	05/11/2019

#### 2. Vehicle Particulars & Condition

Make & Model	KIA CARENS (A)	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KNAHU815VJ7195302	Colour	METALLIC GREY
Odometer	139496 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	NEUTON	9 mm
L/H Front Tyre	205/55 R16	NEUTON	9 mm
R/H Rear Tyre	205/55 R16	NEUTON	9 mm
L/H Rear Tyre	205/55 R16	NEUTON	9 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S DOOR.  
DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	20/10/2019	Inspect Date / Time	05/11/2019 ( 11:27 AM )
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>5 Working Days</b>
-------------------------------------	-----------------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 3347Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	984.00	-
2	FRONT BUMPER SIDE RETAINER @\$56.00	SERVICEABLE	112.00	-
1	HEADLAMP O/S	SERVICEABLE	1,958.00	-
1	HEADLAMP LOWER BRACKET O/S	SERVICEABLE	42.00	-
1	FRONT FENDER O/S	BENT	764.00	764.00
1	FRONT FENDER COWLING O/S	SERVICEABLE	187.00	-
1	FRONT SHOCK ABSORBER O/S	SERVICEABLE	385.00	-
1	FRONT SHOCK ABSORBER TOP MOUNTING O/S	SERVICEABLE	68.00	-
1	FRONT SHOCK ABSORBER TOP BEARING O/S	SERVICEABLE	42.00	-
1	FRONT KNUCKLE ARM O/S	SERVICEABLE	280.00	-
1	FRONT KNUCKLE BEARING O/S	SERVICEABLE	165.00	-
1	FRONT LOWER ARM O/S	SERVICEABLE	250.00	-
1	ANTI ROLL BAR ENDLINK O/S	SERVICEABLE	135.00	-
1	WING MIRROR ASSY O/S	SERVICEABLE	677.00	-
1	WING MIRROR OUTER COVER O/S	SERVICEABLE	163.00	-
1	FRONT DOOR O/S	BENT	1,540.00	1,540.00
1	FRONT DOOR OUTER MOULDING O/S	BUCKLED	147.00	147.00
1	FRONT DOOR WINDOW RUN CHANNEL O/S	DISTORTED	122.00	122.00
1	FRONT DOOR LOWER WEATHERSEAL O/S	CUT	60.00	60.00
2	FRONT DOOR HINGE O/S @\$135.00	BENT	270.00	270.00
1	FRONT DOOR CHECKER O/S	DISTORTED	54.00	54.00
1	FRONT DOOR INNER TRIMBOARD O/S	CRACKED	614.00	614.00
1	ROCKER PANEL O/S	TO REPAIR SEE LABOUR	867.00	-
1	B PILLAR O/S	TO REPAIR SEE LABOUR	757.00	-
1	FRONT DOOR WEATHERSTRIP OUTER O/S	SERVICEABLE	245.00	-
1	FRONT DOOR WEATHERSTRIP INNER O/S	SERVICEABLE	321.00	-
1	FRONT DOOR LOCK O/S	DENTED	286.00	286.00
1	FRONT DOOR OUTER HANDLE O/S	SERVICEABLE	179.00	-
1	FRONT DOOR KEY CYLINDER O/S	JAMMED	227.00	227.00

Report Ref No. CS/INC19019566/Kyd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR WINDOW GLASS O/S	SHATTERED	773.00	773.00
1	FRONT FENDER QUARTER GLASS O/S	SERVICEABLE	389.00	-
1	FRONT FENDER QUARTER GLASS CHROME GARNISH O/S	SERVICEABLE	196.00	-
1	FRONT DOOR HANDLE INNER BRACKET O/S	SERVICEABLE	103.00	-
1	FRONT DOOR SPEAKER O/S	SERVICEABLE	156.00	-
1	FRONT DOOR WINDOW REGULATOR O/S	BENT	379.00	379.00
1	FRONT DOOR WINDOW REGULATOR MOTOR O/S	JAMMED	443.00	443.00
	LESS 10% DISCOUNT		-1,434.00	-567.90
			12,906.00	5,111.10
	<b><u>SPECIAL NETT ITEMS</u></b>			
10	FRONT BUMPER CLIPS @\$4.50 (SN)	NOT NECESSARY	45.00	-
1	FRONT DOOR WIRE HARNESS O/S (SN)	SERVICEABLE	350.00	-
8	FRONT FENDER COWLING CLIPS O/S @\$4.50 (SN)	NOT NECESSARY	36.00	-
12	FRONT DOOR INNER TRIM BOARD CLIPS O/S @\$4.50 (SN)	NECESSARY	54.00	54.00
1	FRONT ALLOY WHEEL O/S (SN)	SERVICEABLE	450.00	-
1	FRONT TYRE O/S (SN)	SERVICEABLE	280.00	-
1	FRONT FENDER QUARTER GLASS MOULDING O/S (SN)	DENTED	130.00	130.00
1	FRONT FENDER QUARTER GLASS SEALANT O/S (SN)	NECESSARY	100.00	30.00
1	FRONT DOOR WINDOW SOLAR FILM O/S (SN)	NOT NECESSARY	200.00	-
1	FRONT FENDER QUARTER GLASS SOLAR FILM O/S (SN)	NOT NECESSARY	150.00	-
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
			1,845.00	214.00
	<b><u>LABOUR</u></b>			
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, ROCKER PANEL O/S AND B PILLAR O/S.		1,600.00	500.00
	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS.}		50.00	20.00

Report Ref No. CS/INC19019566/Kyd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISCONNECT DOOR WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS OF POWER WINDOWS. )		50.00	-
	TO REMOVE AND REFIT O/S FRONT DOOR COMPONENTS TO REPLACE O/S FRONT DOOR, CHECK ALIGNMENT.		100.00	60.00
	TO REMOVE AND REPLACE O/S FRONT RIM. TO PERFORM TYRE BALANCING.	NOT NECESSARY	50.00	-
	TO REMOVE AND REFIT O/S FRONT UNDERCARRIAGE FOR REPLACEMENT OF PARTS.	NOT NECESSARY	200.00	-
	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY FRONT BUMPER, O/S FRONT FENDER, O/S FRONT DOOR AND OTHER AFFECTED AREA / PANEL.		1,600.00	900.00
	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR.		100.00	60.00
	TO CLEAN INTERIOR & REMOVE BROKEN GLASSES FRAGMENTS.		100.00	30.00
			3,950.00	1,570.00
<b>GRAND TOTAL</b>			<b>18,701.00</b>	<b>6,895.10</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>5,500.00</b>

Report Ref No. CS/INC19019566/Kyd3e2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.